SERIAL: AAK1758523624

MOTOR VEHICLE VALUATION & INSPECTION

CERTIFICATE

FULL MECHANICAL

This is to certify that the vehicle

Registration Number :	**KDU 001A**
Vehicle Make :	**TOYOTA**
Vehicle Model Number :	**ALLION**
Chassis Number :	**KTOO1888**
Year of Manufacture :	**2018**

Has been inspected and assessed by AA of Kenya and valued at (Kshs)

3,430,000.00

(THREE MILLION FOUR HUNDRED THIRTY THOUSAND ONLY)

A detailed report is attached.

Valuation & Inspection Manager

AA KENYA P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer

Date : 30/09/2025

SERIAL: AAK1758523624

MOTOR VEHICLE VALUATION & INSPECTION
FULL MECHANICAL

Insured Name: Samuel Ndegwa Tel: +254726159307 Email: samsoftware2018@gmail.com
Insurer: APA Insurance Limited Policy No: PL2828823

A Brief Examination and Road Test have been carried out on the following vehicle and the findings are as follows:-

Reg: KDU 001A	Make: TOYOTA	Model: ALLION	Color: Grey
YOM: 2018	Country: Japanese	Chassis: KTOO1888	
Drive: NA	Capacity: 2500	Engine No:	
Registration Date:			

No assessment comments available

Extras:
sunroof, Leather Seats

Remarks
Serviceable

Examiners prices (Kshs) of separately insurable items
NA

Examiner's Opinion (Kshs):
2,744,000.00 (TWO MILLION SEVEN HUNDRED FORTY FOUR THOUSAND)

Valuation & Inspection Manager

AA KENYA P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer

Date : 30/09/2025

INSPECTION IMAGES


LOGBOOK



KRA PIN



VIN PLATE



REAR RIGHT TYRE



FRONT LEFT TYRE



ID



Valuation & Inspection Manager

Valuation & Inspection Officer

Date : 30/09/2025

INSPECTION IMAGES (CONTINUED)

FRONT RIGHT TYRE



REAR LEFT TYRE



ENGINE



INSURANCE STICKER



Valuation & Inspection Manager

Valuation & Inspection Officer

Date : 30/09/2025

Terms & Conditions

The examiners take every care & precaution during inspections but the AA cannot accept responsibility for claims arising as a result of latent defects or matters of opinion

The AA reserves the right to decline to examine or to report on any vehicle not of standard production or one which has not been in regular road use.

The examination to which this report refers is external only and does not involve dismantling or disturbing any structure, assembly, component or internal mechanism.

Only limited road test is undertaken.

Vehicles over 5 years and those that have been subjected to abnormal use may have serious defects which may not be detected by external examination. The AA will not be held responsible for liability arising out of this.

No indication can be given of the availability of the spare parts for the particular make or model of a vehicle.

Parts that are excessively contaminated by oil or dirt may not be properly examined.

The assessed value given after a brief examination and road test is consistent with the age and condition of the said vehicle. However, it must be emphasized that it bears no relationship with any agreement between buyer and seller which is entirely dependent on willingness of the two parties to a greater or lesser degree.

Where it is stated in the inspection report that some information was supplied by AA a third party, the AA Kenya will not be held responsible for the reliability of the information, if found to be incorrect.

Re-examination after repairs will be carried out at a fee.

The assessed value is based on the date of first registration and the odometer reading being genuine.

Valuation & Inspection Manager

AA KENYA
P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer

Date : 30/09/2025

COMPREHENSIVE MECHANICAL INSPECTION REPORT

This comprehensive mechanical inspection report provides detailed assessment of all major vehicle components and systems. The inspection follows standardized procedures to evaluate the condition and functionality of each inspected item.

ASSESSMENT CRITERIA LEGEND

SATISFACTORY	Component is in good working condition
ATTENTION REQUIRED	Minor issues requiring attention in near future
IMMEDIATE ATTENTION	Issues requiring prompt attention
DANGEROUS/UNROADWORTHY	Critical safety issues - immediate repair required
NOT CHECKED	Component was not inspected

POSITION CODES

LF = Left Front | RF = Right Front | LR = Left Rear | RR = Right Rear | F = Front | R = Rear | L = Left | C = Center

Valuation & Inspection Manager

AA KENYA P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer

Date : 30/09/2025

A: BODY WORK

1. DOORS

LF (Left Front): ACCEPTABLE FOR AGE AND MILEAGE RECORDED

Note: This part is in a good condition

RF (Right Front): ACCEPTABLE FOR AGE AND MILEAGE RECORDED

Note: This part is in a good condition

2. DOOR LOCKS

Not inspected

3. WINDOWS

Not inspected

4. WINDOW WINDERS

Not inspected

5. QUARTER LIGHT GLASS

Not inspected

6. WINGS OR WING AREA

Not inspected

7. QUARTER PANELS

Not inspected

8. BOOT OR TAILGATE LOCK

Not inspected

9. BOOT INTERIOR

Not inspected

10. BONNET PANEL

Not inspected

11. BONNET LOCK

Not inspected

12. RADIATOR GRILLE

Not inspected

13. ROOF

Not inspected

14. WINDSCREEN

Not inspected

15. REAR WINDOW

Not inspected

Valuation & Inspection Manager

AA KENYA
P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer

Date : 30/09/2025

16. BODY SILLS

Not inspected

17. JACKING POINTS

Not inspected

18. EXTERNAL MIRRORS

Not inspected

19. WING & BOOT MIRROR

Not inspected

20. BUMPERS

Not inspected

21. BUMPER VALANCE

Not inspected

22. SEATS

Not inspected

23. BODY KIT AND PARKING SENSORS

Not inspected

24. UPHOLSTERY

Not inspected

25. AIR BAGS

Not inspected

26. ROOF LINING

Not inspected

27. UNDERLAY

Not inspected

28. FLOOR

Not inspected

29. INTERNAL MIRRORS

Not inspected

30. SUN ROOFS / PANORAMIC ROOF

Not inspected

31. WOOD WORK

Not inspected

32. PAINT WORK: LUSTRE

Not inspected

Valuation & Inspection Manager

AA KENYA
P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer

Date : 30/09/2025

33. PAINT WORK: COLOUR VARIATION

Not inspected

34. PAINT WORK: REPAIR MATCHING

Not inspected

35. IS THERE EVIDENCE OF ACCIDENT DAMAGE?

Not inspected

36. IS DAMAGE REPAIR WORK SATISFACTORY?

Not inspected

Valuation & Inspection Manager

AA KENYA
P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer

Date : 30/09/2025

B: WHEELS

1. WHEEL TYPE

Not inspected

2. WHEEL CONDITION

Not inspected

3. CONDITION OF BODY KIT / FENDERS AND WHEEL CAPS

Not inspected

Valuation & Inspection Manager

AA KENYA
P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer

Date : 30/09/2025

C: TYRES

Valuation & Inspection Manager

AA KENYA
P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer

Date : 30/09/2025

D: COOLING SYSTEM

Valuation & Inspection Manager

AA KENYA
P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer

Date : 30/09/2025

E: ENGINE

Valuation & Inspection Manager

AA KENYA
P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer

Date : 30/09/2025

F: ELECTRICAL EQUIPMENT

Valuation & Inspection Manager

AA KENYA
P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer

Date : 30/09/2025

G: FUEL SYSTEM

Valuation & Inspection Manager

AA KENYA
P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer

Date : 30/09/2025

H: FRAME, UNDERSIDE, EXHAUST

Valuation & Inspection Manager

AA KENYA
P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer

Date : 30/09/2025

I: REAR SUSPENSION

Valuation & Inspection Manager

AA KENYA
P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer

Date : 30/09/2025

J: FRONT SUSPENSION AND STEERING

Valuation & Inspection Manager

AA KENYA
P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer

Date : 30/09/2025

K: GEAR BOX

Valuation & Inspection Manager

AA KENYA
P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer

Date : 30/09/2025

L: CLUTCH OR TORQUE CONVERTER

Valuation & Inspection Manager

AA KENYA
P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer

Date : 30/09/2025

M: TRANSMISSION AND FINAL DRIVE

Valuation & Inspection Manager

AA KENYA
P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer

Date : 30/09/2025

N: BRAKES

Valuation & Inspection Manager

AA KENYA
P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer

Date : 30/09/2025

O: INSTRUMENTS AND ACCESSORIES

Valuation & Inspection Manager

AA KENYA
P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer

Date : 30/09/2025

Q: ROAD TEST

Valuation & Inspection Manager

AA KENYA
P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer

Date : 30/09/2025