



VEHICLE INSPECTION SHEET

Ref: PS-1046-INS-01

14 Sept 2026, 12:28 PM

Polish Station

CUSTOMER

Mr. Nusry Latheef Wickramasinghe

Phone: +94 77 123 4567

VEHICLE

2019 Toyota Corolla Altis

WP CAB-4471 Colour: Pearl White

Chassis/VIN: MR053CM3X02123456

ODOMETER: 84,230 km KEYS: 2 STARTS NORMALLY: Yes

Warning lights: tpms

E ☒ ☒ ☐ ☐ F

FRONT

11

1

2

REAR

10

6

TOP

7

13

LEFT PROFILE

8

3

4

12

RIGHT PROFILE

9

14

5

0 Minor 0 Moderate 0 Severe

DAMAGE DETAIL				
#	VIEW	TYPE	SEVERITY	NOTE
1	front	Scratch	Minor	Light scuff near fog lamp
2	front	Chip	Minor	Stone chip on bumper
3	left	Dent	Moderate	Door dent, approx 3cm, no paint break
4	left	Scratch	Minor	Scratch along rear door
5	right	Swirl	Minor	Light swirl marks on rear quarter panel
6	rear	Crack	Severe	Rear bumper crack near reflector, structural
7	top	Paint defect	Minor	Faded clear coat on roof edge
8	left	Rust	Moderate	Surface rust near front wheel arch
9	right	Missing part	Severe	Missing wheel arch trim clip
10	rear	Scuff	Minor	Scuff on rear bumper corner
11	front	Crack	Moderate	Small crack in headlight lens
12	left	Dent	Minor	Small door edge ding

12 of 14 recorded defects shown — full record via QR.

INVENTORY & SYSTEMS		present/working	absent/faulty	n/a
LOOSE ITEMS		CONDITION FLAGS		
✓ floor mats front	SYSTEMS CHECKED	✗ pet hair		
✓ floor mats rear		✗ kerbed alloys		
✗ boot mat				
✓ spare wheel				
✓ wheel jack				
✓ wheel brace				
✗ first aid kit				
✓ umbrella				
✓ phone holder				
✓ dash cam				
✓ charger cables				
✗ sunshade				
✓ parking rfid tag				
✓ personal belongings				
CUSTOMER PRIORITY				
	✓ ac cooling			
	✓ heater			
	✓ all power windows			
	✓ power mirrors			
	✗ wipers			
	✓ washer jets			
	✓ exterior lights			
	✓ interior lights			
	✓ horn			
	✓ audio head unit			
	✗ speakers			
	✓ reverse camera			
	✓ boot release			
	✓ central locking			

Please pay extra attention to the swirl marks on the bonnet and both front doors — customer is very particular about the paint finish and has...

Even though precautions are taken, we are unable to monitor valuables left inside the car, customer is kindly adviced to remove all possessions in the unfortunate event that an accident occurs during repair work or road testing, those will be repaired as per your insurance policy, I hereby authorize above listed repair work to be carried out and give authority to Polish Station to road test the said vehicle, if needed

I certify there are no valuables in the car.

Inspected by: Ibrahim Ifham

Date/Time: 14 Sept 2026, 12:28 PM

