



VEHICLE INSPECTION SHEET

Ref: PS-1046-INS-01
14 Sept 2026, 12:28 PM

Polish Station

CUSTOMER

Mr. Nusry Latheef Wickramasinghe

Phone: +94 77 123 4567

VEHICLE

2019 Toyota Corolla Altis

WP CAB-4471 Colour: Pearl White

Chassis/VIN: MR053CM3X02123456

ODOMETER: 84,230 km KEYS: 2 STARTS NORMALLY: Yes

Warning lights: tpms



FRONT

11

1

2

REAR

10

6

TOP

7

13

LEFT PROFILE

8

3

4

12

RIGHT PROFILE

9

14

5

0 Minor 0 Moderate 0 Severe

DAMAGE DETAIL				
#	VIEW	TYPE	SEVERITY	NOTE
1	front	Scratch	Minor	Light scuff near fog lamp
2	front	Chip	Minor	Stone chip on bumper
3	left	Dent	Moderate	Door dent, approx 3cm, no paint break
4	left	Scratch	Minor	Scratch along rear door
5	right	Swirl	Minor	Light swirl marks on rear quarter panel
6	rear	Crack	Severe	Rear bumper crack near reflector, structural
7	top	Paint defect	Minor	Faded clear coat on roof edge
8	left	Rust	Moderate	Surface rust near front wheel arch
9	right	Missing part	Severe	Missing wheel arch trim clip
10	rear	Scuff	Minor	Scuff on rear bumper corner
11	front	Crack	Moderate	Small crack in headlight lens
12	left	Dent	Minor	Small door edge ding

12 of 14 recorded defects shown — full record via QR.

INVENTORY & SYSTEMS		present/working	absent/faulty	n/a
LOOSE ITEMS				
✓	floor mats front	✓	ac cooling	✗ pet hair
✓	floor mats rear	✓	heater	✗ kerbed alloys
✗	boot mat	✓	all power windows	
✓	spare wheel	✓	power mirrors	
✓	wheel jack	✗	wipers	
✓	wheel brace	✓	washer jets	
✗	first aid kit	✓	exterior lights	
✓	umbrella	✓	interior lights	
✓	phone holder	✓	horn	
✓	dash cam	✓	audio head unit	
✓	charger cables	✗	speakers	
✗	sunshade	✓	reverse camera	
✓	parking rfid tag	✓	boot release	
✓	personal belongings	✓	central locking	
CUSTOMER PRIORITY				

Please pay extra attention to the swirl marks on the bonnet and both front doors — customer is very particular about the paint finish and has...

Polish Station takes reasonable precautions but cannot monitor items left inside the vehicle. Customers are asked to remove all personal belongings before handover. The vehicle condition recorded above reflects our inspection at the time and date stated. Polish Station is authorised to carry out the detailing work listed, and to move the vehicle within our premises as required to complete it. Defects not recorded above were not visible at inspection.



Inspected by: Ibrahim Ifham

Date/Time: 14 Sept 2026, 12:28 PM