



VITAN CONSULTANTS

ARCHITECTS & INTERIOR DESIGNERS

5TH FLOOR, MIDTOWN EMBASSY, BEHIND VASANT VALLEY BUS DEPOT,
OPP. NARAYANA SCHOOL, VASANT VALLEY, GANDHARE KALYAN (W).

TEJAS ANIL NIRGUDE
B. ARCH & INTERIOR DESIGNER

E-mail : vitanconsultants@yahoo.com
M.:8451985999

Annexure A

FORM 1

[see Regulation 3]

ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of Ongoing Project and for withdrawal of Money
from Designated Account)

Date: 31/12/2025

To,

REGENCY NIRMAN LTD

THANE, MAHARASHTRA, 421002

Subject : Certificate of percentage of Work of completion of construction work of **Regency Luxuria Phase I** having Maha RERA Registration Number **P51700031251** (Only Applicable after project Registration) being developed by **REGENCY NIRMAN LTD**

Sir,

I/We **VITAN CONSULTANTS** have undertaken assignment as Architect /Licensed Surveyor of certifying Percentage of completion of Construction Work of **Regency Luxuria Phase I** having Maha RERA Registration Number **P51700031251** (Only Applicable after project Registration, being developed by **REGENCY NIRMAN LTD**)

Based on Site Inspection, with respect to Layout / each of the Building/Wing of the aforesaid Real Estate Project I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project under Maha RERA is as per Table A here in below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.



VITAN CONSULTANTS

ARCHITECTS & INTERIOR DESIGNERS

5TH FLOOR, MIDTOWN EMBASSY, BEHIND VASANT VALLEY BUS DEPOT,
OPP. NARAYANA SCHOOL, VASANT VALLEY, GANDHARE KALYAN (W).

TEJAS ANIL NIRGUDE
B. ARCH & INTERIOR DESIGNER

E-mail : vitanconsultants@yahoo.com
M.:8451985999

Table A

Layout/Building/Wing Number: Building No 4/NA

Sr. No.	Tasks/Activity	% of Actual Work Done (As on date of the Certificate)
(1)	(2)	(3)
1	Excavation	100.00
2	Basements (if any)	100.00
3	Podiums (if any)	100.00
4	Plinth,	100.00
5	Stilt Floor	100.00
6	Slabs of Super Structure	100.00
7	Internal walls ,Internal plaster, Floorings, Floor sand windows within Flats/Premises	100.00
8	Sanitary Fitting within the Flat/Premises	100.00
9	Staircases ,lifts Well sand Lobbies at each Floor level Over head and Underground Water Tanks	100.00
10	External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/wing.	100.00
11	Installation of Lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to complete project as per specifications in agreement of Sale. Any other activities.	100.00



VITAN CONSULTANTS

ARCHITECTS & INTERIOR DESIGNERS

5TH FLOOR, MIDTOWN EMBASSY, BEHIND VASANT VALLEY BUS DEPOT,
OPP. NARAYANA SCHOOL, VASANT VALLEY, GANDHARE KALYAN (W).

TEJAS ANIL NIRGUDE
B. ARCH & INTERIOR DESIGNER

E-mail : vitanconsultants@yahoo.com
M.:8451985999

Layout/Building/Wing Number: Building No 4/NA

Sr. No.	Tasks/Activity	% of Actual Work Done (As on date of the Certificate)
(1)	(2)	(3)
1	Excavation	100.00
2	Basements (if any)	100.00
3	Podiums (if any)	100.00
4	Plinth,	100.00
5	Stilt Floor	100.00
6	Slabs of Super Structure	100.00
7	Internal walls, Internal plaster, Floorings ,Floors and windows within Flats/Premises	100.00
8	Sanitary Fitting within the Flat/Premises	100.00
9	Staircases, lifts Wells and Lobbies at each Floor level Over head and Underground Water Tanks	100.00
10	External plumbing and external plaster ,elevation, completion of terraces with waterproofing of the Building/wing.	100.00
11	Installation of Lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to complete project as per specifications in agreement of Sale. Any other activities.	100.00



VITAN CONSULTANTS

ARCHITECTS & INTERIOR DESIGNERS

5TH FLOOR, MIDTOWN EMBASSY, BEHIND VASANT VALLEY BUS DEPOT,
OPP. NARAYANA SCHOOL, VASANT VALLEY, GANDHARE KALYAN (W).

TEJAS ANIL NIRGUDE
B. ARCH & INTERIOR DESIGNER

E-mail : vitanconsultants@yahoo.com
M.:8451985999

Table B-Common Areas (Internal and External Development Works) in respect of Registered Phase / Project Number)

Sr.No	Common areas and facilities	Is Available (Yes / No)	% of Actual Work Done (As on date of the Certificate)	Details
(1)	(2)	(3)	(4)	(5)
1	Internal Roads & Footpaths	Yes	80.00	-
2	Water Supply	Yes	100.00	-
3	Sewerage (Chamber, Lines, Septic Tank, STP)	Yes	100.00	-
4	Storm Water Drains	Yes	100.00	-
5	Landscaping & Tree Planting	Yes	40.00	-
6	Street Lighting	Yes	60.00	-
7	Community Buildings	Yes	65.00	-
8	Treatment And Disposal Of Sewage And Sullage Water	Yes	80.00	-
9	Solid Waste Management And Disposal	Yes	80.00	-
10	Water conservation / Rain water harvesting	Yes	80.00	-
11	Energy management	Yes	90.00	Solar Water Heater
12	Fire protection and fire safety requirements	Yes	100.00	-
13	Electrical meter room, sub-station, receiving station	Yes	90.00	-
14	Aggregate area of recreational Open Space	Yes	20.00	-
15	Open Parking	Yes	0.00	-

Yours Faithfully

VITAN CONSULTANTS

TEJAS A. NIRGUDE
Architect
CA/2019/106930

Date of Certificate:

Agreed and accepted by:

Signature of Promoter

Name: REGENCY NIRMAN LTD

Date: