



Anish & Associates

Licensed Surveyor & Consulting Engineer

Date - 06.03.2023

To,

**S3 Smart Spaces Private limited,
7th Floor, Dheeraj chambers,
9 Hazarimal Somani Marg,
Next to Sterling Cinema, Near CSMT Station,
Fort Mumbai – 400 001.**

Subject: Certificate of percentage of completion of construction work of **S3 SKYGREENS (Previously known as Blossom, Plot A – Bldg. No. 2)** having MahaRERA Registration Number (Yet to be obtained) on land bearing S. No. 102 (new), 51 (old), H. No. 26, S. No. 88 (new), 69 (old), H. No. 13; Village: Mire, S. No. 11 (new), 76 (old), H. NO. 1, 2; Village: Mahajanwadi being developed by **S3 Smart Spaces Private Limited.**

Sir,

We **Anish and Associates** have undertaken assignment as Consulting Engineer/Licensed Surveyor of the certifying Percentage of completion of construction work of **S3 SKYGREENS (Previously known as Blossom, Plot A – Bldg. No. 2)** having MahaRERA Registration Number (Yet to be obtained.) on land bearing S. No. 102 (new), 51 (old), H. No. 26, S. No. 88 (new), 69 (old), H. No. 13; Village: Mire, S. No. 11 (new), 76 (old), H. NO. 1, 2; Village: Mahajanwadi

Based on site inspection, with respect to Layout/each of the building/Wing of the aforesaid Real Estate Project, we certify that as on the date of this certificate, the percentage of work done for each of the building/Wing of the Real Estate Project under MahaRERA is as per Table A herein Below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

Table A

Building No.2 / S3 SKYGREENS

Sr. No.	Tasks / Activity	Percentage of Actual work Done (As on Date of the Certificate)
1	Excavation	100%
2	Basement (If Any)	0%
3	Podiums (If Any)	0%
4	Plinth	0%
5	Stilt Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows with Flat/ Premises	0%
8	Sanitary Fitting within the Flat/Premises	0%
9	Staircases, Lifts, Wells and Lobbies at each floor Level Overhead and underground Water Tanks	0%
10	External Plumbing and External Plaster. Elevation, Completion of terraces with waterproofing of the building/Wing.	0%
11	Installation of lifts, Water pumps, Fire Fighting and Equipment's as per CFO NOC, Electrical Fittings, Mechanical equipment, compliance to conditions of environmental/CRZ NOC, Finishing the entrance lobby's, plinth protection paving of area appurtenant to Building/Wing, compound Wall and all other requirements as may be required to complete project as per Specifications in agreement of sale. Any other Activities.	0%



..2..



Anish & Associates

Licensed Surveyor & Consulting Engineer

..2..

TABLE B

Common Areas (Internal and External Development Works) in respect of the Registered Phase/Project Number.

Sr.No.	Common area and Facilities	Proposed (Yes/No)	Percentage of Actual work Done (As on Date of the Certificate)	Details
1	Internal Roads & footpaths	No	0	
2	Water Supply	Yes	0	By MBMC (After OC)
3	Sewerage (Chamber Lines, Septic Tank, STP)	Yes	0	
4	Storm Water Drains	Yes	0	
5	Landscaping and tree Planning.	Yes	0	
6	Street Lighting	No	0	
7	Community Building (Club House Common for full layout)	Yes	100%	Clubhouse
8	Treatment and Disposal of Sewerage and sullage Water	Yes	0	STP
9	Solid Waste Management and Disposal.	Yes	0	OWC
10	Water conservation/ Rain water harvesting.	Yes	0	
11	Energy Management	Yes	0	Solar
12	Fire Protection and Fire Safety requirements	Yes	0	As per CFO NOC
13	Electrical meter room, Substation, receiving Station.	Yes	0	
14	Others		0	

Yours Faithfully,

For Anish & Associates

Anil P. Motiramani

Lic. No. MB/MNP/NR/2647/2020-21



Agreed and accepted by

Signature of Promoter

Name:

Date -

