



VITAN CONSULTANTS

ARCHITECTS & INTERIOR DESIGNERS

5TH FLOOR, MIDTOWN EMBASSY, BEHIND VASANT VALLEY BUS DEPOT,
OPP. NARAYANA SCHOOL, VASANT VALLEY, GANDHARE KALYAN (W). M.: 8451985999

E-mail : vitanconsultants@yahoo.com

ANIL R. NIRGUDE

DIP. ARCH. A.I.I.A

TEJAS A. NIRGUDE

B. ARCH & INTERIOR DESIGNER

Annexure A
FORM 1 {See Regulation 3}
ARCHITECT'S CERTIFICATE

Date: 30/06/2025

To
M/S. KAPLESHWARA HOMES LLP.
Through Partner Mr. Vicky Prakash Kukreja
Shop No.2, Hariom Apartment
Near - Chopra court
Ulhasnagar - 421003

Subject: Certificate of Percentage of Completion of Construction work of Building
"Kapleshwara Residency "Phase of the Project [Maha RERA Registration No.
P51700049543] situated on the plot bearing Survey No. 84 (New), 119 (Old) H.No. 6C,
Village - Golivli, Taluka - Kalyan Thane, PIN - 421301; admeasuring area 6606.75
sq.mts. Being developed by M/s. Kapleshwara Homes LLP.

Sir,

I, TEJAS A. Nirgude have undertaken assignment as Architect / Licensed Surveyor of
certifying Percentage of Completion of Construction Work of the Building "Kapleshwara
Residency " [Maha RERA Registration No P51700049543] situated on the plot bearing ,
84 (New), 119 (Old) H.No. 6C, Village - Golivli, Taluka - Kalyan Thane, PIN - 421301;
admeasuring area 6606.75 sq.mts. Being developed by M/s. Kapleshwara Homes LLP.

Based on Site Inspection , with respect to each of the Building/Wing of the aforesaid Real
Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for
each of the building/Wing of the Real Estate Project under Maha RERA is as per table A
herein below. The percentage of the work executed with respect to each of the activity of the
entire phase is detailed in Table B.



VITAN CONSULTANTS

ARCHITECTS & INTERIOR DESIGNERS

5TH FLOOR, MIDTOWN EMBASSY, BEHIND VASANT VALLEY BUS DEPOT,
OPP. NARAYANA SCHOOL, VASANT VALLEY, GANDHARE KALYAN (W). M.: 8451985999

E-mail : vitanconsultants@yahoo.com

ANIL R. NIRGUDE

DIP. ARCH. A.I.I.A

TEJAS A. NIRGUDE

B. ARCH & INTERIOR DESIGNER

..2..

TABLE - A

Building - A - Sanction: Gr. (p), St.(p) + 4 Podium +5th (p) to 9th (p)+ 10th To 25th Floor.

Sr.No.	Tasks/Activity	% of work done
1	Excavation	100%
2	1 number of Plinth	100%
3	4 number of Podiums	100%
4	1 Stilt Floor	0%
5	26 number of Slabs of Super Structure	96%
6	Internal walls, Internal Plaster, Floorings within Flats, Premises, Doors and Windows to each of the Flat/Premises	38%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings with the Flat/Premises	0%
8	Staircases, Lifts, Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground water tanks	0%
9	The external Plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	40%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment/CRZ NOC , Finishing to entrance lobby/s plinth protection, paying of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to obtain Occupation / Completion Certificate	0%

TABLE - A

Building - B - Sanction: Gr. (p), St: (p) + 4 Podiums +5th to 25 + 26th (p) Floor

Sr.No.	Tasks/Activity	% of work done
1	Excavation	100%
2	1 number of Plinth	100%
3	4 number of Podiums	100%
4	1 Stilt Floor	0%
5	27 number of Slabs of Super Structure	92%
6	Internal walls, Internal Plaster, Floorings within Flats, Premises, Doors and Windows to each of the Flat/Premises	36%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings with the Flat/Premises	0%
8	Staircases, Lifts, Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground water tanks	0%
9	The external Plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	40%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment/CRZ NOC , Finishing to entrance lobby/s plinth protection, paying of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to obtain Occupation / Completion Certificate	0%



VITAN CONSULTANTS

ARCHITECTS & INTERIOR DESIGNERS

5TH FLOOR, MIDTOWN EMBASSY, BEHIND VASANT VALLEY BUS DEPOT,
OPP. NARAYANA SCHOOL, VASANT VALLEY, GANDHARE KALYAN (W). M.: 8451985999

E-mail : vitanconsultants@yahoo.com

ANIL R. NIRGUDE

DIP. ARCH. A.I.I.A

TEJAS A. NIRGUDE

B. ARCH & INTERIOR DESIGNER

TABLE - A

Building - C - Sanction: Gr. (p) + St. (p) + 4 Podiums +5th to 25th+ 26th (p) Floor

Sr.No.	Tasks/Activity	% of work done
1	Excavation	100%
2	1 number of Plinth	100%
3	4 number of Podiums	0%
4	1 Stilt Floor	0%
5	27 number of Slabs of Super Structure (proposed)	7 %
6	Internal walls, Internal Plaster, Floorings within Flats, Premises, Doors and Windows to each of the Flat/Premises	0%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings with the Flat/Premises	0%
8	Staircases, Lifts, Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground water tanks	0%
9	The external Plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment/CRZ NOC , Finishing to entrance lobby/s plinth protection, paying of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to obtain Occupation / Completion Certificate	0%

TABLE - B

Internal & External Development works in Respect of the entire Registered Phase :

S. No.	Common areas and Facilities, Amenities	Proposed (Yes/No)	% of Work done	Details
1.	Internal Roads & Footpaths	NO	--	
2.	Water Supply	YES	0%	
3.	Sewerage (Chamber, Lines, Septic Tank, STP)	YES	0%	
4.	Storm Water Drains	YES	0%	
5.	Landscaping & Tree Planting	YES	0%	
6.	Street Lighting	NO	--	
7.	Community Buildings	YES	--	
8.	Treatment and disposal of sewage and sullage water	YES	--	
9.	Solid Waste management & Disposal	YES	--	
10.	Water conservation, Rainwater harvesting	YES	0%	
11.	Energy management	YES	0%	SOLAR PANELS
12.	Fire protection and fire safety requirements	YES	0%	
13.	Electrical meter room, sub-station, receiving station	YES	0%	METER ROOM
14.	Others (Option to Add more)	NO	--	

VITAN CONSULTANTS

TEJAS A. NIRGUDE

Architect

License No. CA/2019/106930

Agreed and Accepted by:

Signature of Partner

Name:

Date