


Architect's Certificate*		
Report for quarter ending		Dec-23
Subject		Certificate of progress of construction work
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans	
Sr. No.	Particulars	Information
1.	Project/Phase of the project	<i>PALM HILLS- B9-01, B9-02, B10-01, B-10-02, B-10-03, B11-01, B11-02, A1-01, A1-02, A1-03, A1-04, A1-05, A2-04, A2-05, A4-01, A4-02, COMMUNITY BUILDING. MLCP. SHOPPING.</i>
2.	Location	SECTOR-77, GURUGRAM
3.	Licensed area in acres	29.34675 ACRES
4.	Area for registration in acres	11.22 ACRES (45425.87 Sq Mtrs)
5.	HARERA registration no.	Regd No. 256 of 2017 dated 03.10.2017
6.	Name of licensee	56 of 2009 dated 31-08-09 & License No. 62 of 2013 dated 05-08-2013
7.	Name of collaborator	ROBIN SOFTWARE LLP and OTHERS
8.	Name of developer	EMAAR INDIA LTD (Formerly Known as EMAAR MGF LAND LIMITED)
2.	Details related to inspection are as under	
1.	Date of certifying of percentage of construction work/ site inspection	01-Jan-24
2.	Name of Architect/ Architect's firm	Mr. Pankaj Sanon / ARCOP Associates
3.	Date of site inspection	31-Dec-23



3.	Following technical professionals are appointed by promoter: - (as applicable)	
	Sr. No.	Consultants
	1.	Site engineer
	2.	Structural consultant
	3.	Proof consultant
	4.	MEP consultant
4.	5.	Site supervisor/incharge
I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.		
I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.		

Date : 11-1-2024	 Yours faithfully,  Signature & name (in block letters) with stamp of architect
Place: Gurugram	
Council of Architect (CoA): Registration No.	
Council of Architect (CoA): Registration valid till (Date)	

CA/2001-28681

31-12-2032

ARCHITECTURE

Table – A

Table – A					
Building/ Tower no.					
(to be prepared separately for each building/ tower in the project/ phase of the project)			A4-01		
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work	
1	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	-	60.50	0%	
2	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	-	222.72	0%	
3	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	-	31.69	0%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	48.01	0%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	67.22	0%
4	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	1.09	271.23	0%
	4.2	External (plaster, painting, facade, etc.)	0.45	79.62	1%




Tower no. A4-01

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Completed		100%	
2.	Laying of foundation					
	(i)	Raft	Completed		100%	
	(ii)	Pile	NA		NA	
3.	Number of basement(s)		NA		NA	
	(i)	Basement Level 1	NA		NA	
	(ii)	Basement level 2*	NA		NA	
4.	Waterproofing of the above sub-structure (wherever applicable)		Completed		100%	
	Super-Structure Status					
5.	Total floors in the tower/building		G+10		100%	
6.	Total area on each floor		316.857 Sq.Mt		100%	
7.	Stilt Floor/ Ground Floor		Stilt floor		100%	
8.	Status of laying of slabs floor wise		Completed		100%	
	Cumulative number of slabs in the building/tower 11 laid by end of quarter		Completed		100%	
9.	Status of construction					
	(i)	Walls on floors	Completed		100%	
	(ii)	Staircase	Completed		100%	
	(iii)	Lift wells along with water proofing	Completed		100%	
	(iv)	Lift lobbies/ common areas floor wise	Completed		100%	
10.	Fixing of door and window frames in flats/ units		Completed		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Completed	Completed	100%	100%
	(ii)	Electrical works including wiring	Completed	Completed	100%	100%
	(iii)	Plumbing works	Completed	Completed	100%	100%
12.	Status of wall plastering					
	(i)	External plaster	Completed		100%	
	(ii)	Internal plaster	Completed		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Completed		100%	
	(ii)	In kitchen	Completed		100%	
14.	Status of flooring					
	(i)	Common areas	Completed		100%	
	(ii)	Units/ flats	Completed		100%	



Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls	Completed	100%
	(ii)	External walls	Completed	100%
16.	Status of finishing			
	(i)	Staircase with railing	Completed	100%
	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Completed	100%
	(ii)	Sanitary fixtures	Completed	100%
	(iii)	Modular kitchen	N/A	N/A
	(iv)	Electrical fittings/ lighting	N/A	N/A
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lifts installation	Completed	100%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	NA	N/A
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Completed	100%
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Completed	100%
18.	Waterproofing of terraces		Completed	100%
19.	Entrance lobby finishing		Completed	100%
20.	Status of construction of compound wall		Completed	100%


Note: (*) extend rows as per requirement.



ARCHITECTURE


Table – A

Table – A					
Building/ Tower no.			A4-02		
(to be prepared separately for each building/ tower in the project/ phase of the project)					
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		-	60.39	0%
2	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		-	222.32	0%
3	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	-	31.63	0%
	3.2	Electrical (conducting, wiring, fixtures, etc.)	-	47.93	0%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	67.10	0%
4	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	1.09	270.77	0%
	4.2	External (plaster, painting, facade, etc.)	0.45	79.48	1%



Tower no. A4-02

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Completed		100%	
2.	Laying of foundation					
	(i)	Raft	Completed		100%	
	(ii)	Pile	NA		NA	
3.	Number of basement(s)		NA		NA	
	(i)	Basement Level 1	NA		NA	
	(ii)	Basement level 2*	NA		NA	
4.	Waterproofing of the above sub-structure (wherever applicable)		Completed		100%	
	Super-Structure Status					
5.	Total floors in the tower/building		G+10		100%	
6.	Total area on each floor		316.857 Sq.Mt		100%	
7.	Stilt Floor/ Ground Floor		Stilt floor		100%	
8.	Status of laying of slabs floor wise		Completed		100%	
	Cumulative number of slabs in the building/tower 11 laid by end of quarter		Completed		100%	
9.	Status of construction					
	(i)	Walls on floors	Completed		100%	
	(ii)	Staircase	Completed		100%	
	(iii)	Lift wells along with water proofing	Completed		100%	
	(iv)	Lift lobbies/ common areas floor wise	Completed		100%	
10.	Fixing of door and window frames in flats/ units		Completed		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Completed	Completed	100%	100%
	(ii)	Electrical works including wiring	Completed	Completed	100%	100%
	(iii)	Plumbing works	Completed	Completed	100%	100%
12.	Status of wall plastering					
	(i)	External plaster	Completed		100%	
	(ii)	Internal plaster	Completed		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Completed		100%	
	(ii)	In kitchen	Completed		100%	
14.	Status of flooring					
	(i)	Common areas	Completed		100%	
	(ii)	Units/ flats	Completed		100%	



Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls	Completed	100%
	(ii)	External walls	Completed	100%
16.	Status of finishing			
	(i)	Staircase with railing	Completed	100%
	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Completed	100%
	(ii)	Sanitary fixtures	Completed	100%
	(iii)	Modular kitchen	N/A	N/A
	(iv)	Electrical fittings/ lighting	N/A	N/A
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lifts installation	Completed	100%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	NA	N/A
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Completed	100%
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Completed	100%
18.	Waterproofing of terraces		Completed	100%
19.	Entrance lobby finishing		Completed	100%
20.	Status of construction of compound wall		Completed	100%

Note: (*) extend rows as per requirement.



ARCHITECTURE

Table – A

Table – A					
Building/ Tower no.			B9-01		
(to be prepared separately for each building/ tower in the project/ phase of the project)					
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		-	44.06	0%
2	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		-	162.20	0%
3	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	-	23.08	0%
	3.2	Electrical (conducting, wiring, fixtures, etc.)	-	34.97	0%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	48.96	0%
4	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	1.09	202.03	1%
	4.2	External (plaster, painting, facade, etc.)	0.45	59.54	1%





Tower no. B9-01

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Completed		100%	
2.	Laying of foundation					
	(i)	Raft	Completed		100%	
	(ii)	Pile	NA		NA	
3.	Number of basement(s)		NA		NA	
	(i)	Basement Level 1	NA		NA	
	(ii)	Basement level 2*	NA		NA	
4.	Waterproofing of the above sub-structure (wherever applicable)		Completed		100%	
	Super-Structure Status					
5.	Total floors in the tower/building		G+10		100%	
6.	Total area on each floor		316.857 Sq.Mt		100%	
7.	Stilt Floor/ Ground Floor		Stilt floor		100%	
8.	Status of laying of slabs floor wise		Completed		100%	
	Cumulative number of slabs in the building/tower 11 laid by end of quarter		Completed		100%	
9.	Status of construction					
	(i)	Walls on floors	Completed		100%	
	(ii)	Staircase	Completed		100%	
	(iii)	Lift wells along with water proofing	Completed		100%	
	(iv)	Lift lobbies/ common areas floor wise	Completed		100%	
10.	Fixing of door and window frames in flats/ units		Completed		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Completed	Completed	100%	100%
	(ii)	Electrical works including wiring	Completed	Completed	100%	100%
	(iii)	Plumbing works	Completed	Completed	100%	100%
12.	Status of wall plastering					
	(i)	External plaster	Completed		100%	
	(ii)	Internal plaster	Completed		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Completed		100%	
	(ii)	In kitchen	Completed		100%	
14.	Status of flooring					
	(i)	Common areas	Completed		100%	
	(ii)	Units/ flats	Completed		100%	



Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls	Completed	100%
	(ii)	External walls	Completed	100%
16.	Status of finishing			
	(i)	Staircase with railing	Completed	100%
	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Completed	100%
	(ii)	Sanitary fixtures	Completed	100%
	(iii)	Modular kitchen	N/A	N/A
	(iv)	Electrical fittings/ lighting	N/A	N/A
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lifts installation	Completed	100%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	NA	N/A
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Completed	100%
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Completed	100%
18.	Waterproofing of terraces		Completed	100%
19.	Entrance lobby finishing		Completed	100%
20.	Status of construction of compound wall		Completed	100%

Note: (*) extend rows as per requirement.



ARCHITECTURE


Table – A

Table – A					
Building/ Tower no.			B10-03		
(to be prepared separately for each building/ tower in the project/ phase of the project)					
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		-	43.04	0%
2	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		-	158.44	0%
3	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	-	22.54	0%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	34.16	0%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	47.82	0%
4	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	1.09	197.63	1%
	4.2	External (plaster, painting, facade, etc.)	0.45	58.24	1%





Tower no. B10-03

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Completed		100%	
2.	Laying of foundation					
	(i)	Raft	Completed		100%	
	(ii)	Pile	NA		NA	
3.	Number of basement(s)		NA		NA	
	(i)	Basement Level 1	NA		NA	
	(ii)	Basement level 2*	NA		NA	
4.	Waterproofing of the above sub-structure (wherever applicable)		Completed		100%	
	Super-Structure Status					
5.	Total floors in the tower/building		G+10		100%	
6.	Total area on each floor		316.857 Sq.Mt		100%	
7.	Stilt Floor/ Ground Floor		Stilt floor		100%	
8.	Status of laying of slabs floor wise		Completed		100%	
	Cumulative number of slabs in the building/tower 11 laid by end of quarter		Completed		100%	
9.	Status of construction					
	(i)	Walls on floors	Completed		100%	
	(ii)	Staircase	Completed		100%	
	(iii)	Lift wells along with water proofing	Completed		100%	
	(iv)	Lift lobbies/ common areas floor wise	Completed		100%	
10.	Fixing of door and window frames in flats/ units		Completed		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Completed	Completed	100%	100%
	(ii)	Electrical works including wiring	Completed	Completed	100%	100%
	(iii)	Plumbing works	Completed	Completed	100%	100%
12.	Status of wall plastering					
	(i)	External plaster	Completed		100%	
	(ii)	Internal plaster	Completed		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Completed		100%	
	(ii)	In kitchen	Completed		100%	
14.	Status of flooring					
	(i)	Common areas	Completed		100%	
	(ii)	Units/ flats	Completed		100%	



Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls	Completed	100%
	(ii)	External walls	Completed	100%
16.	Status of finishing			
	(i)	Staircase with railing	Completed	100%
	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Completed	100%
	(ii)	Sanitary fixtures	Completed	100%
	(iii)	Modular kitchen	N/A	N/A
	(iv)	Electrical fittings/ lighting	N/A	N/A
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lifts installation	Completed	100%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	NA	N/A
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Completed	100%
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Completed	100%
18.	Waterproofing of terraces		Completed	100%
19.	Entrance lobby finishing		Completed	100%
20.	Status of construction of compound wall		Completed	100%

Note: (*) extend rows as per requirement.



ARCHITECTURE

Table – A

Table – A					
Building/ Tower no.			B10-02		
(to be prepared separately for each building/ tower in the project/ phase of the project)					
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		-	43.08	0%
2	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		-	158.61	0%
3	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	-	22.57	0%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	34.19	0%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	47.87	0%
4	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	1.09	197.83	1%
	4.2	External (plaster, painting, facade, etc.)	0.45	58.30	1%




Tower no. B10-02

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Completed		100%	
2.	Laying of foundation					
	(i)	Raft	Completed		100%	
	(ii)	Pile	NA		NA	
3.	Number of basement(s)		NA		NA	
	(i)	Basement Level 1	NA		NA	
	(ii)	Basement level 2*	NA		NA	
4.	Waterproofing of the above sub-structure (wherever applicable)		Completed		100%	
	Super-Structure Status					
5.	Total floors in the tower/building		G+10		100%	
6.	Total area on each floor		316.857 Sq.Mt		100%	
7.	Stilt Floor/ Ground Floor		Stilt floor		100%	
8.	Status of laying of slabs floor wise		Completed		100%	
	Cumulative number of slabs in the building/tower 11 laid by end of quarter		Completed		100%	
9.	Status of construction					
	(i)	Walls on floors	Completed		100%	
	(ii)	Staircase	Completed		100%	
	(iii)	Lift wells along with water proofing	Completed		100%	
	(iv)	Lift lobbies/ common areas floor wise	Completed		100%	
10.	Fixing of door and window frames in flats/ units		Completed		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Completed	Completed	100%	100%
	(ii)	Electrical works including wiring	Completed	Completed	100%	100%
	(iii)	Plumbing works	Completed	Completed	100%	100%
12.	Status of wall plastering					
	(i)	External plaster	Completed		100%	
	(ii)	Internal plaster	Completed		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Completed		100%	
	(ii)	In kitchen	Completed		100%	
14.	Status of flooring					
	(i)	Common areas	Completed		100%	
	(ii)	Units/ flats	Completed		100%	



Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls	Completed	100%
	(ii)	External walls	Completed	100%
16.	Status of finishing			
	(i)	Staircase with railing	Completed	100%
	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Completed	100%
	(ii)	Sanitary fixtures	Completed	100%
	(iii)	Modular kitchen	N/A	N/A
	(iv)	Electrical fittings/ lighting	N/A	N/A
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lifts installation	Completed	100%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	NA	N/A
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Completed	100%
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Completed	100%
18.	Waterproofing of terraces		Completed	100%
19.	Entrance lobby finishing		Completed	100%
20.	Status of construction of compound wall		Completed	100%

Note: (*) extend rows as per requirement.




ARCHITECTURE


Table – A

Table – A					
Building/ Tower no.					
(to be prepared separately for each building/ tower in the project/ phase of the project)			B10-01		
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work	
1	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	-	43.16	0%	
2	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	-	158.91	0%	
3	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	-	22.61	0%
	3.2	Electrical (conducting, wiring, fixtures, etc.)	-	34.26	0%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	47.96	0%
4	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	1.09	198.18	1%
	4.2	External (plaster, painting, facade, etc.)	0.45	58.40	1%



Tower no. B10-01

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Completed		100%	
2.	Laying of foundation					
	(i)	Raft	Completed		100%	
	(ii)	Pile	NA		NA	
3.	Number of basement(s)		NA		NA	
	(i)	Basement Level 1	NA		NA	
	(ii)	Basement level 2*	NA		NA	
4.	Waterproofing of the above sub-structure (wherever applicable)		Completed		100%	
	Super-Structure Status					
5.	Total floors in the tower/building		G+10		100%	
6.	Total area on each floor		316.857 Sq.Mt		100%	
7.	Stilt Floor/ Ground Floor		Stilt floor		100%	
8.	Status of laying of slabs floor wise		Completed		100%	
	Cumulative number of slabs in the building/tower 11 laid by end of quarter		Completed		100%	
9.	Status of construction					
	(i)	Walls on floors	Completed		100%	
	(ii)	Staircase	Completed		100%	
	(iii)	Lift wells along with water proofing	Completed		100%	
	(iv)	Lift lobbies/ common areas floor wise	Completed		100%	
10.	Fixing of door and window frames in flats/ units		Completed		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Completed	Completed	100%	100%
	(ii)	Electrical works including wiring	Completed	Completed	100%	100%
	(iii)	Plumbing works	Completed	Completed	100%	100%
12.	Status of wall plastering					
	(i)	External plaster	Completed		100%	
	(ii)	Internal plaster	Completed		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Completed		100%	
	(ii)	In kitchen	Completed		100%	
14.	Status of flooring					
	(i)	Common areas	Completed		100%	
	(ii)	Units/ flats	Completed		100%	



Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls	Completed	100%
	(ii)	External walls	Completed	100%
16.	Status of finishing			
	(i)	Staircase with railing	Completed	100%
	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Completed	100%
	(ii)	Sanitary fixtures	Completed	100%
	(iii)	Modular kitchen	N/A	N/A
	(iv)	Electrical fittings/ lighting	N/A	N/A
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lifts installation	Completed	100%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	NA	N/A
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Completed	100%
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Completed	100%
18.	Waterproofing of terraces		Completed	100%
19.	Entrance lobby finishing		Completed	100%
20.	Status of construction of compound wall		Completed	100%

Note: (*) extend rows as per requirement.



ARCHITECTURE


Table – A

Table – A					
Building/ Tower no.			B9-02		
(to be prepared separately for each building/ tower in the project/ phase of the project)					
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		-	43.65	0%
2	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		-	160.71	0%
3	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	-	22.87	0%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	34.65	0%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	48.50	0%
4	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	1.09	200.28	1%
	4.2	External (plaster, painting, facade, etc.)	0.45	59.02	1%

Handwritten signature of Pankaj Samon. Below it is a circular official stamp of the Council of Architecture, Registration No. CA/2001/28681, Registered Architect.

Tower no. B9-02

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Completed		100%	
2.	Laying of foundation					
	(i)	Raft	Completed		100%	
	(ii)	Pile	NA		NA	
3.	Number of basement(s)		NA		NA	
	(i)	Basement Level 1	NA		NA	
	(ii)	Basement level 2*	NA		NA	
4.	Waterproofing of the above sub-structure (wherever applicable)		Completed		100%	
	Super-Structure Status					
5.	Total floors in the tower/building		G+10		100%	
6.	Total area on each floor		316.857 Sq.Mt		100%	
7.	Stilt Floor/ Ground Floor		Stilt floor		100%	
8.	Status of laying of slabs floor wise		Completed		100%	
	Cumulative number of slabs in the building/tower 11 laid by end of quarter		Completed		100%	
9.	Status of construction					
	(i)	Walls on floors	Completed		100%	
	(ii)	Staircase	Completed		100%	
	(iii)	Lift wells along with water proofing	Completed		100%	
	(iv)	Lift lobbies/ common areas floor wise	Completed		100%	
10.	Fixing of door and window frames in flats/ units		Completed		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Completed	Completed	100%	100%
	(ii)	Electrical works including wiring	Completed	Completed	100%	100%
	(iii)	Plumbing works	Completed	Completed	100%	100%
12.	Status of wall plastering					
	(i)	External plaster	Completed		100%	
	(ii)	Internal plaster	Completed		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Completed		100%	
	(ii)	In kitchen	Completed		100%	
14.	Status of flooring					
	(i)	Common areas	Completed		100%	
	(ii)	Units/ flats	Completed		100%	



Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls	Completed	100%
	(ii)	External walls	Completed	100%
16.	Status of finishing			
	(i)	Staircase with railing	Completed	100%
	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Completed	100%
	(ii)	Sanitary fixtures	Completed	100%
	(iii)	Modular kitchen	N/A	N/A
	(iv)	Electrical fittings/ lighting	N/A	N/A
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lifts installation	Completed	100%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	NA	N/A
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Completed	100%
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Completed	100%
18.	Waterproofing of terraces		Completed	100%
19.	Entrance lobby finishing		Completed	100%
20.	Status of construction of compound wall		Completed	100%


Note: (*) extend rows as per requirement.



ARCHITECTURE

Table – A

Table – A					
Building/ Tower no.			A1-01		
(to be prepared separately for each building/ tower in the project/ phase of the project)					
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		-	53.68	0%
2	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		-	197.63	0%
3	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	-	28.12	0%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	42.61	0%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	59.65	0%
4	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	1.09	242.51	0.45%
	4.2	External (plaster, painting, facade, etc.)	0.45	71.59	0.63%



 PANKAJ CANON
 Council of
 Architecture
 Registration No.
 CA/2001/28681
 REGISTERED ARCHITECT


Tower no. A1-01

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Completed		100%	
2.	Laying of foundation					
	(i)	Raft	Completed		100%	
	(ii)	Pile	NA		NA	
3.	Number of basement(s)		NA		NA	
	(i)	Basement Level 1	NA		NA	
	(ii)	Basement level 2*	NA		NA	
4.	Waterproofing of the above sub-structure (wherever applicable)		Completed		100%	
	Super-Structure Status					
5.	Total floors in the tower/building		G+9		100%	
6.	Total area on each floor		316.857 Sq.Mt		100%	
7.	Stilt Floor/ Ground Floor		Stilt floor		100%	
8.	Status of laying of slabs floor wise		Completed		100%	
	Cumulative number of slabs in the building/tower 10 laid by end of quarter		Completed		100%	
9.	Status of construction					
	(i)	Walls on floors	Completed		100%	
	(ii)	Staircase	Completed		100%	
	(iii)	Lift wells along with water proofing	Completed		100%	
	(iv)	Lift lobbies/ common areas floor wise	Completed		100%	
10.	Fixing of door and window frames in flats/ units		Completed		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Completed	Completed	100%	100%
	(ii)	Electrical works including wiring	Completed	Completed	100%	100%
	(iii)	Plumbing works	Completed	Completed	100%	100%
12.	Status of wall plastering					
	(i)	External plaster	Completed		100%	
	(ii)	Internal plaster	Completed		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Completed		100%	
	(ii)	In kitchen	Completed		100%	
14.	Status of flooring					
	(i)	Common areas	Completed		100%	
	(ii)	Units/ flats	Completed		100%	



Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls	Completed	100%
	(ii)	External walls	Completed	100%
16.	Status of finishing			
	(i)	Staircase with railing	Completed	100%
	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Completed	100%
	(ii)	Sanitary fixtures	Completed	100%
	(iii)	Modular kitchen	N/A	N/A
	(iv)	Electrical fittings/ lighting	N/A	N/A
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lifts installation	Completed	100%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	NA	N/A
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Completed	100%
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Completed	100%
18.	Waterproofing of terraces		Completed	100%
19.	Entrance lobby finishing		Completed	100%
20.	Status of construction of compound wall		Completed	100%

Note: (*) extend rows as per requirement.



ARCHITECTURE


Table – A

Table – A				
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			A2-04	
A1	Cumulative progress of the project/phase at the end of the quarter.			
Sr. No.	Project components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	-	53.94	0%
2	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	-	198.57	0%
3	MEP			
	3.1 Mechanical (lifts, ventilation, etc.)	-	28.25	0%
	3.2 Electrical (conduiting, wiring, fixtures, etc.)	-	42.81	0%
	3.3 Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	59.93	0%
4	Finishing			
	4.1 Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	1.09	243.60	0%
	4.2 External (plaster, painting, facade, etc.)	0.45	71.60	1%




Tower no. A2-04

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Completed		100%	
2.	Laying of foundation					
	(i)	Raft	Completed		100%	
	(ii)	Pile	NA		NA	
3.	Number of basement(s)		NA		NA	
	(i)	Basement Level 1	NA		NA	
	(ii)	Basement level 2*	NA		NA	
4.	Waterproofing of the above sub-structure (wherever applicable)		Completed		100%	
	Super-Structure Status					
5.	Total floors in the tower/building		G+9		100%	
6.	Total area on each floor		316.857 Sq.Mt		100%	
7.	Stilt Floor/ Ground Floor		Stilt floor		100%	
8.	Status of laying of slabs floor wise		Completed		100%	
	Cumulative number of slabs in the building/tower 10 laid by end of quarter		Completed		100%	
9.	Status of construction					
	(i)	Walls on floors	Completed		100%	
	(ii)	Staircase	Completed		100%	
	(iii)	Lift wells along with water proofing	Completed		100%	
	(iv)	Lift lobbies/ common areas floor wise	Completed		100%	
10.	Fixing of door and window frames in flats/ units		Completed		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Completed	Completed	100%	100%
	(ii)	Electrical works including wiring	Completed	Completed	100%	100%
	(iii)	Plumbing works	Completed	Completed	100%	100%
12.	Status of wall plastering					
	(i)	External plaster	Completed		100%	
	(ii)	Internal plaster	Completed		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Completed		100%	
	(ii)	In kitchen	Completed		100%	
14.	Status of flooring					
	(i)	Common areas	Completed		100%	
	(ii)	Units/ flats	Completed		100%	



Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls	Completed	100%
	(ii)	External walls	Completed	100%
16.	Status of finishing			
	(i)	Staircase with railing	Completed	100%
	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Completed	100%
	(ii)	Sanitary fixtures	Completed	100%
	(iii)	Modular kitchen	N/A	N/A
	(iv)	Electrical fittings/ lighting	N/A	N/A
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lifts installation	Completed	100%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	NA	N/A
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Completed	100%
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Completed	100%
18.	Waterproofing of terraces		Completed	100%
19.	Entrance lobby finishing		Completed	100%
20.	Status of construction of compound wall		Completed	100%


Note: (*) extend rows as per requirement.



ARCHITECTURE


Table – A

Table – A					
Building/ Tower no.			A1-02		
(to be prepared separately for each building/ tower in the project/ phase of the project)					
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		-	53.93	0%
2	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		-	198.54	0%
3	MEP				
	3.1	Mechanical (m/s, ventilation, etc.)	-	28.25	0%
	3.2	Electrical (conducting, wiring, fire alarm etc.)	-	42.80	0%
	3.3	Firefighting (piping, pumps and pump room, fire alarm etc.)	-	59.92	0%
4	Finishing				
	4.1	Internal (plaster, m/s, flooring, painting, etc. within walls and ceiling)	1.09	243.57	0%
	4.2	External (plaster, painting, facade etc.)	0.45	71.59	1%




Tower no. A1-02

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Completed		100%	
2.	Laying of foundation					
	(i)	Raft	Completed		100%	
	(ii)	Pile	NA		NA	
3.	Number of basement(s)		NA		NA	
	(i)	Basement Level 1	NA		NA	
	(ii)	Basement level 2*	NA		NA	
4.	Waterproofing of the above sub-structure (wherever applicable)		Completed		100%	
	Super-Structure Status					
5.	Total floors in the tower/building		G+9		100%	
6.	Total area on each floor		316.857 Sq.Mt		100%	
7.	Stilt Floor/ Ground Floor		Stilt floor		100%	
8.	Status of laying of slabs floor wise		Completed		100%	
	Cumulative number of slabs in the building/tower 10 laid by end of quarter		Completed		100%	
9.	Status of construction					
	(i)	Walls on floors	Completed		100%	
	(ii)	Staircase	Completed		100%	
	(iii)	Lift wells along with water proofing	Completed		100%	
	(iv)	Lift lobbies/ common areas floor wise	Completed		100%	
10.	Fixing of door and window frames in flats/ units		Completed		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Completed	Completed	100%	100%
	(ii)	Electrical works including wiring	Completed	Completed	100%	100%
	(iii)	Plumbing works	Completed	Completed	100%	100%
12.	Status of wall plastering					
	(i)	External plaster	Completed		100%	
	(ii)	Internal plaster	Completed		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Completed		100%	
	(ii)	In kitchen	Completed		100%	
14.	Status of flooring					
	(i)	Common areas	Completed		100%	
	(ii)	Units/ flats	Completed		100%	



Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls	Completed	100%
	(ii)	External walls	Completed	100%
16.	Status of finishing			
	(i)	Staircase with railing	Completed	100%
	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Completed	100%
	(ii)	Sanitary fixtures	Completed	100%
	(iii)	Modular kitchen	N/A	N/A
	(iv)	Electrical fittings/ lighting	N/A	N/A
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lifts installation	Completed	100%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	NA	N/A
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Completed	100%
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Completed	100%
18.	Waterproofing of terraces		Completed	100%
19.	Entrance lobby finishing		Completed	100%
20.	Status of construction of compound wall		Completed	100%

Note: (*) extend rows as per requirement.



ARCHITECTURE

Table – A

Table – A					
Building/ Tower no.			A1-03		
(to be prepared separately for each building/ tower in the project/ phase of the project)					
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		-	53.92	0%
2	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		-	198.52	0%
3	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	-	28.25	0%
	3.2	Electrical (conducting, wiring, fixtures, etc.)	-	42.80	0%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	59.92	0%
4	Finishing				
	4.1	Internal (plaster, tiling, flooring, painting, etc. within units and common areas)	1.09	243.54	0%
	4.2	External (plaster, painting, facade, etc.)	0.45	71.58	1%




Tower no. A1-03

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Completed		100%	
2.	Laying of foundation					
	(i)	Raft	Completed		100%	
	(ii)	Pile	NA		NA	
3.	Number of basement(s)		NA		NA	
	(i)	Basement Level 1	NA		NA	
	(ii)	Basement level 2*	NA		NA	
4.	Waterproofing of the above sub-structure (wherever applicable)		Completed		100%	
	Super-Structure Status					
5.	Total floors in the tower/building		G+9		100%	
6.	Total area on each floor		316.857 Sq.Mt		100%	
7.	Stilt Floor/ Ground Floor		Stilt floor		100%	
8.	Status of laying of slabs floor wise		Completed		100%	
	Cumulative number of slabs in the building/tower 10 laid by end of quarter		Completed		100%	
9.	Status of construction					
	(i)	Walls on floors	Completed		100%	
	(ii)	Staircase	Completed		100%	
	(iii)	Lift wells along with water proofing	Completed		100%	
	(iv)	Lift lobbies/ common areas floor wise	Completed		100%	
10.	Fixing of door and window frames in flats/ units		Completed		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Completed	Completed	100%	100%
	(ii)	Electrical works including wiring	Completed	Completed	100%	100%
	(iii)	Plumbing works	Completed	Completed	100%	100%
12.	Status of wall plastering					
	(i)	External plaster	Completed		100%	
	(ii)	Internal plaster	Completed		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Completed		100%	
	(ii)	In kitchen	Completed		100%	
14.	Status of flooring					
	(i)	Common areas	Completed		100%	
	(ii)	Units/ flats	Completed		100%	



Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls	Completed	100%
	(ii)	External walls	Completed	100%
16.	Status of finishing			
	(i)	Staircase with railing	Completed	100%
	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Completed	100%
	(ii)	Sanitary fixtures	Completed	100%
	(iii)	Modular kitchen	N/A	N/A
	(iv)	Electrical fittings/ lighting	N/A	N/A
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lifts installation	Completed	100%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	NA	N/A
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Completed	100%
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Completed	100%
18.	Waterproofing of terraces		Completed	100%
19.	Entrance lobby finishing		Completed	100%
20.	Status of construction of compound wall		Completed	100%

Note: (*) extend rows as per requirement.




ARCHITECTURE

Table – A

Table – A					
Building/ Tower no.			A1-04		
(to be prepared separately for each building/ tower in the project/ phase of the project)					
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		-	53.91	0%
2	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		-	198.47	0%
3	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	-	28.24	0%
	3.2	Electrical (conducting, wiring, fixtures, etc.)	-	42.79	0%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	59.90	0%
4	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	1.09	243.48	0%
	4.2	External (plaster, painting, facade, etc.)	0.45	71.56	1%


Tower no. A1-04

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Completed		100%	
2.	Laying of foundation					
	(i)	Raft	Completed		100%	
	(ii)	Pile	NA		NA	
3.	Number of basement(s)		NA		NA	
	(i)	Basement Level 1	NA		NA	
	(ii)	Basement level 2*	NA		NA	
4.	Waterproofing of the above sub-structure (wherever applicable)		Completed		100%	
	Super-Structure Status					
5.	Total floors in the tower/building		G+9		100%	
6.	Total area on each floor		316.857 Sq.Mt		100%	
7.	Stilt Floor/ Ground Floor		Stilt floor		100%	
8.	Status of laying of slabs floor wise		Completed		100%	
	Cumulative number of slabs in the building/tower 10 laid by end of quarter		Completed		100%	
9.	Status of construction					
	(i)	Walls on floors	Completed		100%	
	(ii)	Staircase	Completed		100%	
	(iii)	Lift wells along with water proofing	Completed		100%	
	(iv)	Lift lobbies/ common areas floor wise	Completed		100%	
10.	Fixing of door and window frames in flats/ units		Completed		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Completed	Completed	100%	100%
	(ii)	Electrical works including wiring	Completed	Completed	100%	100%
	(iii)	Plumbing works	Completed	Completed	100%	100%
12.	Status of wall plastering					
	(i)	External plaster	Completed		100%	
	(ii)	Internal plaster	Completed		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Completed		100%	
	(ii)	In kitchen	Completed		100%	
14.	Status of flooring					
	(i)	Common areas	Completed		100%	
	(ii)	Units/ flats	Completed		100%	



Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls	Completed	100%
	(ii)	External walls	Completed	100%
16.	Status of finishing			
	(i)	Staircase with railing	Completed	100%
	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Completed	100%
	(ii)	Sanitary fixtures	Completed	100%
	(iii)	Modular kitchen	N/A	N/A
	(iv)	Electrical fittings/ lighting	N/A	N/A
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lifts installation	Completed	100%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	NA	N/A
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Completed	100%
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Completed	100%
18.	Waterproofing of terraces		Completed	100%
19.	Entrance lobby finishing		Completed	100%
20.	Status of construction of compound wall		Completed	100%

Note: (*) extend rows as per requirement.



ARCHITECTURE

Table – A

Table – A					
Building/ Tower no.			A2-05		
(to be prepared separately for each building/ tower in the project/ phase of the project)					
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work	
1	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	-	53.88	0%	
2	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	-	198.34	0%	
3	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	-	28.22	0%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	42.76	0%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	59.86	0%
4	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	1.09	243.33	0%
	4.2	External (plaster, painting, facade, etc.)	0.45	71.52	1%





Tower no. A2-05

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Completed		100%	
2.	Laying of foundation					
	(i)	Raft	Completed		100%	
	(ii)	Pile	NA		NA	
3.	Number of basement(s)		NA		NA	
	(i)	Basement Level 1	NA		NA	
	(ii)	Basement level 2*	NA		NA	
4.	Waterproofing of the above sub-structure (wherever applicable)		Completed		100%	
	Super-Structure Status					
5.	Total floors in the tower/building		G+9		100%	
6.	Total area on each floor		316.857 Sq.Mt		100%	
7.	Stilt Floor/ Ground Floor		Stilt floor		100%	
8.	Status of laying of slabs floor wise		Completed		100%	
	Cumulative number of slabs in the building/tower 10 laid by end of quarter		Completed		100%	
9.	Status of construction					
	(i)	Walls on floors	Completed		100%	
	(ii)	Staircase	Completed		100%	
	(iii)	Lift wells along with water proofing	Completed		100%	
	(iv)	Lift lobbies/ common areas floor wise	Completed		100%	
10.	Fixing of door and window frames in flats/ units		Completed		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Completed	Completed	100%	100%
	(ii)	Electrical works including wiring	Completed	Completed	100%	100%
	(iii)	Plumbing works	Completed	Completed	100%	100%
12.	Status of wall plastering					
	(i)	External plaster	Completed		100%	
	(ii)	Internal plaster	Completed		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Completed		100%	
	(ii)	In kitchen	Completed		100%	
14.	Status of flooring					
	(i)	Common areas	Completed		100%	
	(ii)	Units/ flats	Completed		100%	



Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls	Completed	100%
	(ii)	External walls	Completed	100%
16.	Status of finishing			
	(i)	Staircase with railing	Completed	100%
	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Completed	100%
	(ii)	Sanitary fixtures	Completed	100%
	(iii)	Modular kitchen	N/A	N/A
	(iv)	Electrical fittings/ lighting	N/A	N/A
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lifts installation	Completed	100%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	NA	N/A
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Completed	100%
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Completed	100%
18.	Waterproofing of terraces		Completed	100%
19.	Entrance lobby finishing		Completed	100%
20.	Status of construction of compound wall		Completed	100%

Note: (*) extend rows as per requirement.



ARCHITECTURE


Table – A

Table – A					
Building/ Tower no.					
(to be prepared separately for each building/ tower in the project/ phase of the project)			A1-05		
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work	
1	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	-	53.90	0%	
2	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	-	198.41	0%	
3	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	-	28.23	0%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	42.78	0%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	59.89	0%
4	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	1.09	243.42	0%
	4.2	External (plaster, painting, facade, etc.)	0.45	71.54	1%



Tower no. A1-05

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Completed		100%	
2.	Laying of foundation					
	(i)	Raft	Completed		100%	
	(ii)	Pile	NA		NA	
3.	Number of basement(s)		NA		NA	
	(i)	Basement Level 1	NA		NA	
	(ii)	Basement level 2*	NA		NA	
4.	Waterproofing of the above sub-structure (wherever applicable)		Completed		100%	
	Super-Structure Status					
5.	Total floors in the tower/building		G+9		100%	
6.	Total area on each floor		316.857 Sq.Mt		100%	
7.	Stilt Floor/ Ground Floor		Stilt floor		100%	
8.	Status of laying of slabs floor wise		Completed		100%	
	Cumulative number of slabs in the building/tower 10 laid by end of quarter		Completed		100%	
9.	Status of construction					
	(i)	Walls on floors	Completed		100%	
	(ii)	Staircase	Completed		100%	
	(iii)	Lift wells along with water proofing	Completed		100%	
	(iv)	Lift lobbies/ common areas floor wise	Completed		100%	
10.	Fixing of door and window frames in flats/ units		Completed		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Completed	Completed	100%	100%
	(ii)	Electrical works including wiring	Completed	Completed	100%	100%
	(iii)	Plumbing works	Completed	Completed	100%	100%
12.	Status of wall plastering					
	(i)	External plaster	Completed		100%	
	(ii)	Internal plaster	Completed		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Completed		100%	
	(ii)	In kitchen	Completed		100%	
14.	Status of flooring					
	(i)	Common areas	Completed		100%	
	(ii)	Units/ flats	Completed		100%	



Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls	Completed	100%
	(ii)	External walls	Completed	100%
16.	Status of finishing			
	(i)	Staircase with railing	Completed	100%
	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Completed	100%
	(ii)	Sanitary fixtures	Completed	100%
	(iii)	Modular kitchen	N/A	N/A
	(iv)	Electrical fittings/ lighting	N/A	N/A
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lifts installation	Completed	100%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	NA	N/A
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Completed	100%
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Completed	100%
18.	Waterproofing of terraces		Completed	100%
19.	Entrance lobby finishing		Completed	100%
20.	Status of construction of compound wall		Completed	100%

Note: (*) extend rows as per requirement.



ARCHITECTURE

Table – A

Table – A					
Building/ Tower no.			B11-01		
(to be prepared separately for each building/ tower in the project/ phase of the project)					
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		-	52.44	0%
2	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		-	193.06	0%
3	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	-	27.47	0%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	41.62	0%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	58.27	0%
4	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	1.09	237.23	0%
	4.2	External (plaster, painting, facade, etc.)	0.45	69.73	1%




Tower no. B11-01

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Completed		100%	
2.	Laying of foundation					
	(i)	Raft	Completed		100%	
	(ii)	Pile	NA		NA	
3.	Number of basement(s)		NA		NA	
	(i)	Basement Level 1	NA		NA	
	(ii)	Basement level 2*	NA		NA	
4.	Waterproofing of the above sub-structure (wherever applicable)		Completed		100%	
	Super-Structure Status					
5.	Total floors in the tower/building		G+11		100%	
6.	Total area on each floor		227.592 Sq.Mt		100%	
7.	Stilt Floor/ Ground Floor		Stilt floor		100%	
8.	Status of laying of slabs floor wise		Completed		100%	
	Cumulative number of slabs in the building/tower 12 laid by end of quarter		Completed		100%	
9.	Status of construction					
	(i)	Walls on floors	Completed		100%	
	(ii)	Staircase	Completed		100%	
	(iii)	Lift wells along with water proofing	Completed		100%	
	(iv)	Lift lobbies/ common areas floor wise	Completed		100%	
10.	Fixing of door and window frames in flats/ units		Completed		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Completed	Completed	100%	100%
	(ii)	Electrical works including wiring	Completed	Completed	100%	100%
	(iii)	Plumbing works	Completed	Completed	100%	100%
12.	Status of wall plastering					
	(i)	External plaster	Completed		100%	
	(ii)	Internal plaster	Completed		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Completed		100%	
	(ii)	In kitchen	Completed		100%	
14.	Status of flooring					
	(i)	Common areas	Completed		100%	
	(ii)	Units/ flats	Completed		100%	



Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls	Completed	100%
	(ii)	External walls	Completed	100%
16.	Status of finishing			
	(i)	Staircase with railing	Completed	100%
	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Completed	100%
	(ii)	Sanitary fixtures	Completed	100%
	(iii)	Modular kitchen	N/A	N/A
	(iv)	Electrical fittings/ lighting	N/A	N/A
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lifts installation	Completed	100%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	NA	N/A
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Completed	100%
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Completed	100%
18.	Waterproofing of terraces		Completed	100%
19.	Entrance lobby finishing		Completed	100%
20.	Status of construction of compound wall		Completed	100%

Note: (*) extend rows as per requirement.



ARCHITECTURE

Table – A

Table – A					
Building/ Tower no.			B11-02		
(to be prepared separately for each building/ tower in the project/ phase of the project)					
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		-	52.49	0%
2	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		-	193.23	0%
3	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	-	27.49	0%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	41.66	0%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	58.32	0%
4	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	1.09	237.43	0%
	4.2	External (plaster, painting, facade, etc.)	0.45	69.79	1%




Tower no. B11-02

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Completed		100%	
2.	Laying of foundation					
	(i)	Raft	Completed		100%	
	(ii)	Pile	NA		NA	
3.	Number of basement(s)		NA		NA	
	(i)	Basement Level 1	NA		NA	
	(ii)	Basement level 2*	NA		NA	
4.	Waterproofing of the above sub-structure (wherever applicable)		Completed		100%	
	Super-Structure Status					
5.	Total floors in the tower/building		G+11		100%	
6.	Total area on each floor		227.592 Sq.Mt		100%	
7.	Stilt Floor/ Ground Floor		Stilt floor		100%	
8.	Status of laying of slabs floor wise		Completed		100%	
	Cumulative number of slabs in the building/tower 12 laid by end of quarter		Completed		100%	
9.	Status of construction					
	(i)	Walls on floors	Completed		100%	
	(ii)	Staircase	Completed		100%	
	(iii)	Lift wells along with water proofing	Completed		100%	
	(iv)	Lift lobbies/ common areas floor wise	Completed		100%	
10.	Fixing of door and window frames in flats/ units		Completed		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Completed	Completed	100%	100%
	(ii)	Electrical works including wiring	Completed	Completed	100%	100%
	(iii)	Plumbing works	Completed	Completed	100%	100%
12.	Status of wall plastering					
	(i)	External plaster	Completed		100%	
	(ii)	Internal plaster	Completed		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Completed		100%	
	(ii)	In kitchen	Completed		100%	
14.	Status of flooring					
	(i)	Common areas	Completed		100%	
	(ii)	Units/ flats	Completed		100%	



Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls	Completed	100%
	(ii)	External walls	Completed	100%
16.	Status of finishing			
	(i)	Staircase with railing	Completed	100%
	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Completed	100%
	(ii)	Sanitary fixtures	Completed	100%
	(iii)	Modular kitchen	N/A	N/A
	(iv)	Electrical fittings/ lighting	N/A	N/A
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lifts installation	Completed	100%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	NA	N/A
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Completed	100%
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Completed	100%
18.	Waterproofing of terraces		Completed	100%
19.	Entrance lobby finishing		Completed	100%
20.	Status of construction of compound wall		Completed	100%

Note: (*) extend rows as per requirement.



ARCHITECTURE


Table – A

Table – A					
Building/ Tower no.		Shops			
(to be prepared separately for each building/ tower in the project/ phase of the project)					
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work	
1	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	18.84	18.84	100%	
2	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	69.35	69.35	100%	
3	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	9.87	9.87	100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	14.95	14.95	100%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	20.93	20.93	100%
4	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	81.03	81.03	100%
	4.2	External (plaster, painting, facade, etc.)	23.92	23.92	100%




Shops

Sr. No.	Tasks/ Activity.		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Completed		100%	
2.	Laying of foundation					
	(i)	Raft	Completed		100%	
	(ii)	Pile	NA		NA	
3.	Number of basement(s)		NA		NA	
	(i)	Basement Level 1	NA		NA	
	(ii)	Basement level 2*	NA		NA	
4.	Waterproofing of the above sub-structure (wherever applicable)		Completed		100%	
	Super-Structure Status					
5.	Total floors in the tower/building		Ground Floor		100%	
6.	Total area on each floor		Completed		100%	
7.	Stilt Floor/ Ground Floor		Completed		100%	
8.	Status of laying of slabs floor wise		Completed		100%	
	Cumulative number of slabs in the building/tower 1 laid by end of quarter		Completed		100%	
9.	Status of construction					
	(i)	Walls on floors	Completed		100%	
	(ii)	Staircase	NA		N/A	
	(iii)	Lift wells along with water proofing	NA		N/A	
	(iv)	Lift lobbies/ common areas floor wise	NA		N/A	
10.	Fixing of door and window frames in flats/ units		Completed		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Completed	Completed	100%	100%
	(ii)	Electrical works including wiring	Completed	Completed	100%	100%
	(iii)	Plumbing works	Completed	Completed	100%	100%
12.	Status of wall plastering					
	(i)	External plaster	Completed		100%	
	(ii)	Internal plaster	Completed		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Completed		100%	
	(ii)	In kitchen	NA		N/A	
14.	Status of flooring					
	(i)	Common areas	Completed		100%	
	(ii)	Units/ flats	Completed		100%	



Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls	Completed	100%
	(ii)	External walls	Completed	100%
16.	Status of finishing			
	(i)	Staircase with railing	NA	N/A
	(ii)	Lift wells	NA	N/A
	(iii)	Lift lobbies/ common areas floor wise	NA	N/A
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Completed	100%
	(ii)	Sanitary fixtures	Completed	100%
	(iii)	Modular kitchen	N/A	N/A
	(iv)	Electrical fittings/ lighting	N/A	N/A
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lifts installation	NA	N/A
	(vii)	Overhead tanks	NA	N/A
	(viii)	Underground water tank	NA	N/A
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Completed	100%
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Completed	100%
18.	Waterproofing of terraces		Completed	100%
19.	Entrance lobby finishing		Completed	100%
20.	Status of construction of compound wall		Completed	100%

Note: (*) extend rows as per requirement.



Note: (*) extend rows as per requirement.

Table – B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage work done	of	remarks
B-1	Services				
1.	Internal roads & pavements	Yes	100%		
2.	Parking	Yes	100%		
	Covered no.	Yes	100%		
	Open no.	Yes	100%		
3.	Water supply	Yes	100%		
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%		
5.	Storm water drains	Yes	100%		
6.	Landscaping & tree plantation	Yes	100%		
7.	Parks and playgrounds	Yes	100%		
	Fixing of children play equipment's	Yes	100%		
	Benches	Yes	100%		
8.	Shopping area	Yes	100%		
9.	Street lighting/ electrification	Yes	100%		
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	100%		
11.	Solid waste management & disposal	Yes	100%		
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	100%		
13.	Energy management (solar)	Yes	100%		
14.	Fire protection and fire safety requirements	Yes	100%		
15.	Electrical meter room, sub-station, receiving station	Yes	100%		
16.	Other (option to add more)	No	NA		
B-2	Community building to be transferred to RWA				
17.	Community centre	Yes	100%		
18.	others	No	NA		
B-3	Community buildings not to be transferred to RWA/competent authority				
19.	Schools	Yes	100%		
20.	Dispensary	No	NA		
21.	Club	No	NA		
22.	Others	No	NA		
B-4	Services/ facilities to be transferred to competent authority				
23.	*				

Note: (*) extend as per requirement

