



M-9/36 B DLF City 2 Gurugram 122002 Haryana India

EMAIL:- Anoopkumararchitects@gmail.com

PHONE:- +91-9999555494

Architecture | Interiors | Landscape | Planning

Architect's Certificate		
Report for quarter ending		30.09.2025
Subject	Certificate of progress of construction work	
1	I/we have (Without Prejudice) undertaken assignment as engineer for certifying percentage of completion of construction work of the above-mentioned project as per the approved plans and approved structural drawings duly vetted by the proof consultant.	
	Sr. No.	Particulars
	1	Project/phase of the project
	2	Location
	3	Licensed area in acres
	4	Area for registration in acres
	5	HARERA registration no.
	6	Name of licensee
	7	Name of collaborator
2	Details related to inspection are as under	
	1	Date of certifying of percentage of construction work/ site inspection
	2	Name of Architect/ Architect's firm
	3	Date of site inspection
3	Following technical professionals are appointed by promoter: - (as applicable)	
	Sr. No.	Consultants
	1	Site engineer
	2	Structural consultant
	3	Proof consultant
	4	MEP consultant
4	I (Without Prejudice) certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.	
	I (Without Prejudice) also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B	
Date: 15.10.2025		Yours faithfully,  Ar. Anoop Kumar Taank
Place: Gurugram		
Council of Architects (CoA) registration No. :		CA/2018/96240
Council of architects (CoA) registration valid till (date) :		31.12.2031

Table-A

Building/ Tower no.		Block-B			
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		-	913.86	100.00%
2	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		-	1,758.58	100.00%
3	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	-	91.37	100.00%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	182.76	100.00%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	182.76	100.00%
4	Finishing				
	4.1	Internal (plaster, tiling, flooring, painting, etc. within units and common areas)	-	727.97	100.00%
	4.2	External (plaster, painting, facade, etc.)	-	342.76	100.00%
Total			-	4,200.06	100.00%
Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work	
	Sub-Structure Status				
1	Excavation		Completed	100%	
2	Laying of foundation		Completed	100%	
	i	Raft	Completed	100%	
	ii	Pile	NA	NA	
3	Number of basement(s)		NA	NA	
4	Waterproofing of the above sub-structure (wherever applicable)		Completed	100%	
	Super-Structure Status		Completed	100.00%	
5	Total floors in the tower/ building		G+3		
6	Total area on floors				
7	Stilt floor/ ground floor				
8	Status of laying of slabs floor wise (Cumulative number of slabs in the building/ tower Ground + 3 rd)		Completed	100%	
9	Status of construction				
	i	Walls on floors	Completed	100%	
	ii	Staircase	Completed	100%	
	iii	Lift wells along with water proofing	Completed	100%	
	iv	Lift lobbies/ common areas floor wise	Completed	100%	
10.	Fixing of door and window frames in flats/ units		Completed	100%	
11	Status of MEP		Internal (within flat) and External works	Internal (within Unit) and External works	
	i	Mechanical works	Completed	100%	
	ii	Electrical works including wiring	Completed	100%	
	iii	Plumbing works	Completed	100%	
12	Status of wall plastering		Completed	100%	




	i	Internal plaster	Completed	100%
	ii	External plaster	Completed	100%
13	Status of wall tiling			
	i	In bathroom	Completed	100%
	ii	In kitchen	Completed	100%
14	Status of flooring			
	i	Common areas	Completed	100%
	ii	Units/ flats	Completed	100%
15	Status of white washing			
	i	Internal walls	Completed	100%
	ii	External walls	Completed	100%
16	Status of finishing			
	i	Staircase with railing	Completed	100%
	ii	Lift wells	Completed	100%
	iii	Lift lobbies/ common areas floor wise	Completed	100%
17	Status of installation (within flat/unit)			
	i	Doors and windows panels	Completed	100%
	ii	Sanitary fixtures	Completed	100%
	iii	Modular kitchen	NA	
	iv	Electrical fittings/ lighting	Completed	100%
	v	Gas piping (if any)	NA	
	(other than flat/units)			
	vi	Lifts installation	Completed	100%
	vii	Overhead tanks	Completed	100%
	viii	Underground water tank	Completed	100%
	ix	Firefighting fitting and equipment's as per CFO NOC	Completed	100%
	x	Electrical fittings in common areas	Completed	100%
	xi	Compliance to conditions of environment/ CRZ NOC	Completed	100%
18	Waterproofing of terraces		Completed	100%
19	Entrance lobby finishing		Completed	100%
20	Status of construction of compound wall		Completed	100%

Building/ Tower no.		Block-C		
A1	Cumulative progress of the project/phase at the end of the quarter.			
Sr. No.	Project components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1	<u>Sub structure</u> (inclusive of excavation, foundation, basements, water proofing, etc.)	-	646.77	100.00%
2	<u>Super structure</u> (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	-	1,293.55	100.00%
3	<u>MEP</u>			
	3.1 Mechanical (lifts, ventilation, etc.)	-	64.68	100.00%
	3.2 Electrical (conduiting, wiring, fixtures, etc.)	-	121.26	100.00%
	3.3 Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	129.35	100.00%
4	<u>Finishing</u>			
	4.1 Internal (plaster, tiling, flooring, painting, etc. within units and common areas)	-	727.74	100.00%




4.2	External (plaster, painting, facade, etc.)		-	242.59	100.00%
Total			-	3,225.94	100.00%
Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work	
	<u>Sub-Structure Status</u>				
1	Excavation		Completed	100%	
	Laying of foundation		Completed	100%	
2	i	Raft	Completed	100%	
	ii	Pile	NA	NA	
3	Number of basement(s)		NA	NA	
4	Waterproofing of the above sub-structure (wherever applicable)		Completed	100%	
	<u>Super-Structure Status</u>		Completed	100.00%	
5	Total floors in the tower/ building		G+3		
6	Total area on floors				
7	Stilt floor/ ground floor				
8	Status of laying of slabs floor wise (Cumulative number of slabs in the building/ tower Ground + 3 rd)		Completed	100%	
	Status of construction				
9	i	Walls on floors	Completed	100%	
	ii	Staircase	Completed	100%	
	iii	Lift wells along with water proofing	Completed	100%	
	iv	Lift lobbies/ common areas floor wise	Completed	100%	
10.	Fixing of door and window frames in flats/ units		Completed	100%	
11	Status of MEP		Internal (within flat) and External works	Internal (within Unit) and External works	
	i	Mechanical works	Completed	100%	
	ii	Electrical works including wiring	Completed	100%	
	iii	Plumbing works	Completed	100%	
12	Status of wall plastering		Completed	100%	
	i	Internal plaster	Completed	100%	
	ii	External plaster	Completed	100%	
13	Status of wall tiling				
	i	In bathroom	Completed	100%	
	ii	In kitchen	Completed	100%	
14	Status of flooring				
	i	Common areas	Completed	100%	
	ii	Units/ flats	Completed	100%	
15	Status of white washing				
	i	Internal walls	Completed	100%	
	ii	External walls	Completed	100%	
16	Status of finishing				
	i	Staircase with railing	Completed	100%	
	ii	Lift wells	Completed	100%	
	iii	Lift lobbies/ common areas floor wise	Completed	100%	
17	Status of installation (within flat/unit)				
	i	Doors and windows panels	Completed	100%	
	ii	Sanitary fixtures	Completed	100%	
	iii	Modular kitchen	NA		
	iv	Electrical fittings/ lighting	Completed	100%	
	v	Gas piping (if any)	NA		
	(other than flat/units)				
	vi	Lifts installation	Completed	100%	
	vii	Overhead tanks	Completed	100%	




	viii	Underground water tank	Completed	100%
	ix	Firefighting fitting and equipment's as per CFO NOC	Completed	100%
	x	Electrical fittings in common areas	Completed	100%
	xi	Compliance to conditions of environment/ CRZ NOC	Completed	100%
18	Waterproofing of terraces		Completed	100%
19	Entrance lobby finishing		Completed	100%
20	Status of construction of compound wall		Completed	100%

Building/ Tower no.		Block-D			
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		-	783.97	100.00%
2	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		-	1,567.95	100.00%
3	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	-	78.41	100.00%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	156.78	100.00%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	156.78	100.00%
4	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	-	881.89	100.00%
	4.2	External (plaster, painting, facade, etc.)	-	267.55	100.00%
Total			-	3,893.33	100.00%
Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work	
	Sub-Structure Status				
1	Excavation		Completed	100%	
2	Laying of foundation		Completed	100%	
	i	Raft	Completed	100%	
	ii	Pile	NA	NA	
3	Number of basement(s)		NA	NA	
4	Waterproofing of the above sub-structure (wherever applicable)		Completed	100%	
	Super-Structure Status		Completed	100.00%	
5	Total floors in the tower/ building		G+3		
6	Total area on floors				
7	Stilt floor/ ground floor				
8	Status of laying of slabs floor wise (Cumulative number of slabs in the building/ tower Ground + 3 rd)		Completed	100%	
9	Status of construction				
	i	Walls on floors	Completed	100%	
	ii	Staircase	Completed	100%	
	iii	Lift wells along with water proofing	Completed	100%	
	iv	Lift lobbies/ common areas floor wise	Completed	100%	



10.	Fixing of door and window frames in flats/ units		Completed	100%
11	Status of MEP		Internal (within flat) and External works	Internal (within Unit) and External works
	i	Mechanical works	Completed	100%
	ii	Electrical works including wiring	Completed	100%
	iii	Plumbing works	Completed	100%
12	Status of wall plastering		Completed	100%
	i	Internal plaster	Completed	100%
	ii	External plaster	Completed	100%
13	Status of wall tiling			
	i	In bathroom	Completed	100%
	ii	In kitchen	Completed	100%
14	Status of flooring			
	i	Common areas	Completed	100%
	ii	Units/ flats	Completed	100%
15	Status of white washing			
	i	Internal walls	Completed	100%
	ii	External walls	Completed	100%
16	Status of finishing			
	i	Staircase with railing	Completed	100%
	ii	Lift wells	Completed	100%
	iii	Lift lobbies/ common areas floor wise	Completed	100%
17	Status of installation (within flat/unit)			
	i	Doors and windows panels	Completed	100%
	ii	Sanitary fixtures	Completed	100%
	iii	Modular kitchen	NA	
	iv	Electrical fittings/ lighting	Completed	100%
	v	Gas piping (if any)	NA	
	(other than flat/units)			
	vi	Lifts installation	Completed	100%
	vii	Overhead tanks	Completed	100%
	viii	Underground water tank	Completed	100%
	ix	Firefighting fitting and equipment's as per CFO NOC	Completed	100%
	x	Electrical fittings in common areas	Completed	100%
	xi	Compliance to conditions of environment/ CRZ NOC	Completed	100%
18	Waterproofing of terraces		Completed	100%
19	Entrance lobby finishing		Completed	100%
20	Status of construction of compound wall		Completed	100%

Building/ Tower no.	Block-E			
A1	Cumulative progress of the project/phase at the end of the quarter.			
Sr. No.	Project components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	-	386.12	100.00%
2	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	-	772.24	100.00%



3	MEP			
	3.1	Mechanical (lifts, ventilation, etc.)	-	38.61
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	77.22
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	77.22
4	Finishing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	-	434.41
	4.2	External (plaster, painting, facade, etc.)	-	144.84
Total			-	1,930.66
Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
1	Excavation		Completed	100%
	Laying of foundation		Completed	100%
2	i	Raft	Completed	100%
	ii	Pile	NA	NA
3	Number of basement(s)		NA	NA
4	Waterproofing of the above sub-structure (wherever applicable)		Completed	100%
	Super-Structure Status		Completed	100.00%
5	Total floors in the tower/ building		G+3	
6	Total area on floors			
7	Stilt floor/ ground floor			
8	Status of laying of slabs floor wise (Cumulative number of slabs in the building/ tower Ground + 3 rd)		Completed	100%
	Status of construction			
9	i	Walls on floors	Completed	100%
	ii	Staircase	Completed	100%
	iii	Lift wells along with water proofing	Completed	100%
	iv	Lift lobbies/ common areas floor wise	Completed	100%
10.	Fixing of door and window frames in flats/ units		Completed	100%
11	Status of MEP		Internal (within flat) and External works	Internal (within Unit) and External works
	i	Mechanical works	Completed	100%
	ii	Electrical works including wiring	Completed	100%
	iii	Plumbing works	Completed	100%
12	Status of wall plastering		Completed	100%
	i	Internal plaster	Completed	100%
	ii	External plaster	Completed	100%
13	Status of wall tiling			
	i	In bathroom	Completed	100%
	ii	In kitchen	Completed	100%
14	Status of flooring			
	i	Common areas	Completed	100%
	ii	Units/ flats	Completed	100%
15	Status of white washing			
	i	Internal walls	Completed	100%
	ii	External walls	Completed	100%
16	Status of finishing			
	i	Staircase with railing	Completed	100%
	ii	Lift wells	Completed	100%



	iii	Lift lobbies/ common areas floor wise	Completed	100%
	Status of installation (within flat/unit)			
	i	Doors and windows panels	Completed	100%
	ii	Sanitary fixtures	Completed	100%
	iii	Modular kitchen	NA	
	iv	Electrical fittings/ lighting	Completed	100%
	v	Gas piping (if any)	NA	
17	(other than flat/units)			
	vi	Lifts installation	Completed	100%
	vii	Overhead tanks	Completed	100%
	viii	Underground water tank	Completed	100%
	ix	Firefighting fitting and equipment's as per CFO NOC	Completed	100%
	x	Electrical fittings in common areas	Completed	100%
	xi	Compliance to conditions of environment/ CRZ NOC	Completed	100%
18	Waterproofing of terraces		Completed	100%
19	Entrance lobby finishing		Completed	100%
20	Status of construction of compound wall		Completed	100%

Table – A				
Building/ Tower no.		Block-A		
A1	Cumulative progress of the project/phase at the end of the quarter.			
Sr. No.	Project components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1	<u>Sub structure</u> (inclusive of excavation, foundation, basements, water proofing, etc.)		172.00	100.00%
2	<u>Super structure</u> (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		772.24	100.00%
3	<u>MEP</u>			
	3 Mechanical (lifts, ventilation, etc.)		3.86	40.00%
	3 Electrical (conducting, wiring, fixtures, etc.)		7.72	32.00%
	3 Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)		7.72	33.00%
4	<u>Finishing</u>			
	4 Internal (plaster, tiling, flooring, painting, etc. within units and common areas)			0.00%
	4 External (plaster, painting, facade, etc.)			0.00%
Total			963.54	55.06%
Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	<u>Sub-Structure Status</u>			
1	Excavation		Completed	100%
2	Laying of foundation		Completed	100%
	i	Raft	Completed	100%
	ii	Pile	NA	NA
3	Number of basement(s)		NA	NA
4	Waterproofing of the above sub-structure (wherever applicable)		Completed	100%
	<u>Super-Structure Status</u>		Completed	100.00%



5	Total floors in the tower/ building	G+3	
6	Total area on floors		
7	Stilt floor/ ground floor		
8	Status of laying of slabs floor wise (Cumulative number of slabs in the building/ tower Ground + 3 rd)	Completed	100%
9	Status of construction		
	i Walls on floors	Not Started	0%
	ii Staircase	Not Started	0%
	iii Lift wells along with water proofing	Not Started	0%
	iv Lift lobbies/ common areas floor wise	Not Started	0%
10.	Fixing of door and window frames in flats/ units	Not Started	0%
11	Status of MEP	Internal (within flat) and External works	Internal (within Unit) and External works
	i Mechanical works	Under-Prog	10%
	ii Electrical works including wiring	Under-Prog	10%
	iii Plumbing works	Under-Prog	10%
12	Status of wall plastering	Not Started	0%
	i Internal plaster	Not Started	0%
	ii External plaster	Not Started	0%
13	Status of wall tiling		
	i In bathroom	Not Started	0%
	ii In kitchen	Not Started	0%
14	Status of flooring		
	i Common areas	Not Started	0%
	ii Units/ flats	Not Started	0%
15	Status of white washing		
	i Internal walls	Not Started	0%
	ii External walls	Not Started	0%
16	Status of finishing		
	i Staircase with railing	Not Started	0%
	ii Lift wells	Not Started	0%
	iii Lift lobbies/ common areas floor wise	Not Started	0%
17	Status of installation (within flat/unit)		0
	i Doors and windows panels	Not Started	0%
	ii Sanitary fixtures	Not Started	0%
	iii Modular kitchen	NA	
	iv Electrical fittings/ lighting	Not Started	0%
	v Gas piping (if any)	NA	
	(other than flat/units)		
	vi Lifts installation	Not Started	0%
	vii Overhead tanks	Not Started	0%
	viii Underground water tank	Not Started	0%
	ix Firefighting fitting and equipment's as per CFO NOC	Not Started	0%
	x Electrical fittings in common areas	Not Started	0%
	xi Compliance to conditions of environment/ CRZ NOC	Not Started	0%
18	Waterproofing of terraces	Not Started	0%
19	Entrance lobby finishing	Not Started	0%
20	Status of construction of compound wall	Not Started	0%



Table - B				
Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	Remarks
B-1	Services			
1	Internal roads and pavements	Yes	100%	COMPLETED
2	Water supply system	Yes	100%	COMPLETED
3	Storm water drainage	Yes	100%	COMPLETED
4	Electricity supply system	Yes	100%	COMPLETED
5	Sewerage system	Yes	100%	COMPLETED
6	Street lighting	Yes	100%	COMPLETED
7	Security and fire-fighting	Yes	100%	COMPLETED
8	Play grounds and parks	Yes	100%	COMPLETED
9	Renewable energy system	Yes	100%	COMPLETED
10	STP	Yes	100%	COMPLETED
11	Underground water tank	Yes	100%	COMPLETED
12	Rain water harvesting	Yes	100%	COMPLETED
13	Electrical Sub Station	Yes	100%	COMPLETED
14	Construction of circulation road (such as 18m/24m/30m as per conditions of license) Other	Yes	100%	COMPLETED

Overall % of Completion of Project	95%
------------------------------------	-----

