

ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of Ongoing Project and for withdrawal of Money from Designated Account)

Date: 01-01-2026

No.: CANARY/PC/2026-27/01

Subject: Certificate of Percentage of Completion of Construction Work of Prateek Canary No. of Building(s)/ 05 Block(s) of the Phase 01(Out of 02 phases) and 04 Block(s) of the Phase 2(Out of 02 phases) of the Project [UPRERAPRJ591510] situated on the Khasra No/ Plot no PART OF PLOT NO.- SC-02/A-7, Sector-150, Noida.

Demarcated by its boundaries (latitude and longitude of the end points) 28°25'16.03"N 77°29'26.41"E to the North 28°25'10.63"N 77°29'30.15"E to the South 28°25'14.72"N 77°29'34.16"E to the East 28°25'13.32"N 77°29'22.72"E to the West of village NA Tehsil Dadri Competent/ Development authority NOIDA AUTHORITY District GAUTAM BUDDHA NAGAR PIN 201301 admeasuring 50790.00 sq.mts. area being developed by M/s STRONGBIZ PROPBUILD PVT. LTD.

We M/s _ARCMAN DESIGN STUDIO have undertaken assignment as Architect/Licensed Surveyor of certifying Percentage of Completion Work of the PRATEEK CANARY Building(s)/ 09 Block / Tower (s) of two Phases of the Project, situated on the Khasra No/ Plot no SC-02/ A-7, SECTOR-150, NOIDA of village NA tehsil DADRI competent/ development authority NOIDA AUTHORITY District GAUTAM BUDDHA NAGAR PIN- 201301 admeasuring 50790.00 sq.mts. area being developed by [M/s STRONGBIZ PROPBUILD PVT. LTD.]

Following technical professionals are appointed by owner / Promotor:

- (i) M/s Anuj Agarwal Architects and Design Concept By M/S Architect Hafeez Contractor as L.S. / Architect.
- (ii) M/s VMS Consultant Pvt. Ltd. as Structural Consultant
- (iii) M/s CESPL as MEP Consultant
- (iv) Shri Rajesh Kumar Agarwal as Site Supervisor

Based on Site Inspection, with respect to each of the Buildings /Blocks/Towers of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the Buildings /Blocks/Towers of the Real Estate Project as registered vide number UPRERAPRJ591510 under UPRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in the Table B.

TABLE A
TOWER A (PHASE I)

S No.	Task/Activity	Percentage Work Done
1	Excavation	100%
2	<u>1</u> number of Basement(s) and Plinth	100%
3	<u>N/A</u> number of Podiums	N/A
4	Stilt Floor	100%
5	27 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	75%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	0%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	95%
9	The external plumbing and external plaster, Elevation, completion of terraces with waterproofing of the Building /Block/Tower	90%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	60%



TABLE A
TOWER B (PHASE 1)

S No.	Task/Activity	Percentage Work Done
1	Excavation	100%
2	<u>1</u> number of Basement(s) and Plinth	100%
3	<u>N/A</u> number of Podiums	N/A
4	Stilt Floor	100%
5	28 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	75%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	0%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	95%
9	The external plumbing and external plaster, Elevation, completion of terraces with waterproofing of the Building /Block/Tower	90%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	50%



TABLE A
TOWER C (PHASE I)

S No.	Task/Activity	Percentage Work Done
1	Excavation	100%
2	<u>1</u> number of Basement(s) and Plinth	100%
3	<u>N/A</u> number of Podiums	N/A
4	Stilt Floor	100%
5	28 number of Slabs of Super Structure	84%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	45%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	0%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	60%
9	The external plumbing and external plaster, Elevation, completion of terraces with waterproofing of the Building /Block/Tower	10%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	0%



TABLE A
TOWER D (PHASE I)

S No.	Task/Activity	Percentage Work Done
1	Excavation	100%
2	<u>1</u> number of Basement(s) and Plinth	100%
3	<u>N/A</u> number of Podiums	N/A
4	Stilt Floor	100%
5	28 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	75%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	0%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	80%
9	The external plumbing and external plaster, Elevation, completion of terraces with waterproofing of the Building /Block/Tower	50%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	0%



TABLE A
TOWER E (PHASE I)

S No.	Task/Activity	Percentage Work Done
1	Excavation	100%
2	<u>1</u> number of Basement(s) and Plinth	100%
3	<u>N/A</u> number of Podiums	N/A
4	Stilt Floor	100%
5	28 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	75%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	0%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	80%
9	The external plumbing and external plaster, Elevation, completion of terraces with waterproofing of the Building /Block/Tower	50%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	0%

TABLE A
TOWER F (PHASE II)

S No.	Task/Activity	Percentage Work Done
1	Excavation	100%
2	<u>1</u> number of Basement(s) and Plinth	100%
3	<u>N/A</u> number of Podiums	N/A
4	Stilt Floor	100%
5	28 number of Slabs of Super Structure	96%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	60%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	0%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	65%
9	The external plumbing and external plaster, Elevation, completion of terraces with waterproofing of the Building /Block/Tower	20%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	0%

TABLE A
TOWER G (PHASE II)

S No.	Task/Activity	Percentage Work Done
1	Excavation	100%
2	<u>1</u> number of Basement(s) and Plinth	100%
3	<u>N/A</u> number of Podiums	N/A
4	Stilt Floor	100%
5	28 number of Slabs of Super Structure	93%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	60%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	0%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	65%
9	The external plumbing and external plaster, Elevation, completion of terraces with waterproofing of the Building /Block/Tower	20%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	0%



TABLE A
TOWER H (PHASE II)

S No.	Task/Activity	Percentage Work Done
1	Excavation	100%
2	<u>1</u> number of Basement(s) and Plinth	100%
3	<u>N/A</u> number of Podiums	0%
4	Stilt Floor	100%
5	28 number of Slabs of Super Structure	61%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	25%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	0%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	45%
9	The external plumbing and external plaster, Elevation, completion of terraces with waterproofing of the Building /Block/Tower	0%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	0%



TABLE A
TOWER I (PHASE II)

S No.	Task/Activity	Percentage Work Done
1	Excavation	100%
2	<u>1</u> number of Basement(s) and Plinth	100%
3	<u>N/A</u> number of Podiums	0%
4	Stilt Floor	100%
5	28 number of Slabs of Super Structure	21%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	0%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	0%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	15%
9	The external plumbing and external plaster, Elevation, completion of terraces with waterproofing of the Building /Block/Tower	0%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment's as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipment's, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	0%



TABLE B

Internal & External Development Works in Respect of the Entire Registered Phase

	Common Areas and Facilities, Amenities	Proposed (Yes/No)	Details	Percentage of Work done
1	Internal Roads & Footpaths	YES	WORK IN PROGRESS	35%
2	Water Supply	YES	WORK IN PROGRESS	25%
3	Sewerage (chamber, lines, Septic Tank, STP)	YES	WORK IN PROGRESS	25%
4	Strom Water Drains	YES	WORK IN PROGRESS	35%
5	Landscaping & Tree Planting	YES	WORK IN PROGRESS	15%
6	Street Lighting	YES	WORK IN PROGRESS	15%
7	Community Buildings	YES	WORK IN PROGRESS	60%
8	Treatment and disposal of sewage and sullage water	YES	WORK IN PROGRESS	15%
9	Solid Waste management & Disposal	YES	NOT START YET	0%
10	Water conservation, Rain water harvesting	YES	WORK IN PROGRESS	25%
11	Energy management	YES	NOT START YET	0%
12	Fire protection and fire safety requirements	YES	NOT START YET	0%
13	Electrical meter room, sub-station, receiving station	YES	NOT START YET	0%
14	Other (Option to Add more)	NO	N/A	N/A

M/S ARCMAN DESIGN STUDIO




SAFDAR MD ALAM

COA NO.: CA/2009/46562

studio@arcman.in

+91.9891603321

D-256 T/F L/P, Abul Fazal Enclave Part-1,
Jamia Nagar, New Delhi-110025, India.