



ninth street architects

Email-Id:-free.walls08@gmail.com

Ph. 9979855707,7573014431

ARCHITECT'S CERTIFICATE

Form-1

(To be submitted at the time of Registration of Ongoing Project and for withdrawal of Money from Designated Account)

Date:- 02/01/2019

Architect Sourabh A. Verma -(COA No-CA/2003/32415)
(CoA) Registration valid till (Date) :- 31/12/2025

To,
ESSEM INFRA PRIVATE LIMITED
Ganesh Corporate House,
100 Ft. Hebatpur-Thaltej Road,
Nr. Sola Bridge, Off S.G Highway, Thaltej
Ahmedabad GJ 380054

Subject: Certificate of Percentage of Completion of Construction Work of "Maple Tree" , 12 No. of Building(s) Wing(s) (Block-A,B,C,D,E,F,G,H,I,J,K & L) of the Phase- ----- of the Project (GujRERA Reg. No. : **PR/GJ/AHMEDABAD/ AHMADABAD CITY/ AUDA/MAA00012 /240817**) situated on the Final Plot No. 104/1/B

demarcated by its boundaries (latitude and longitude of the end points) 23° 03'23.67" N, 72°31'41.48" E to the North, 23°03'14.65" N, 72°31'46.56" E to the South, 23°03'21.97" N, 72°31'44.59" E to the East , 23°03'18.82" N, 72°31'38.49" E to the West, Village -Thaltej, Taluka-Ghatlodiya, District-Ahmedabad, PIN-380054 admeasuring 31,804 sq.mts. area being developed by Essem Infra Private Limited.

Sir,

We "9th Street Architects" have undertaken assignment as Architect of certifying Percentage of Completion of Construction Work of of "Maple Tree" , 12 No. of Building(s) Wing(s) (Block-A,B,C,D,E,F,G,H,I,J,K & L) of the Phase-Ist of the Project the Project, situated on the Final Plot No. : 104/1/B of Village-Thaltej, Taluka-Ghatlodiya, District-Ahmedabad, PIN 380054 admeasuring 31,804 sq.mts. area being developed by Essem Infra Private Limited as per the approved plan.

1. Following technical professionals are appointed by Owner/Promoter:-

- (i) Shri AMIT B.RAMI as Engineer
- (ii) M/s. Dimension Consultant as Structural Consultant
- (iii) M/s.Aqua Utility Designs & Management Pvt.Ltd. as Plumbing Consultant
- (iv) M/s.Transenergy as Electrical Consultant
- (v) M/s.Design Tech HVAC Solution as HVAC Consultant
- (iv) Shri Manish Visavadiya as Site Supervisor/Clerk of Works

Based on Site Inspection, by undersigned on 29/12/2018 date and with respect to each of the Building/Wing of the plots as the case may be of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/wing of the Real Estate Project as registered vide number PR/GJ/AHMEDABAD/AHMADABAD CITY/AUDA/MAA00012/240817 under GujRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table A and B.

M/s 9TH Street Architects

architecture - furniture
Partner

unbox

501,Vrundavan Enclave,Nr. Shell Petrol Pump,A.E.C.Cross Road,132 Feet Ring Road,Naranpura. Ah-380013,



ninth street architects

Email-Id:-free.walls08@gmail.com

Ph. 9979855707, 7573014431

Date:- 02/01/2019

Table – A
Building/Wing Number: A

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	<u>2</u> number of Basement(s) and Plinth	100%
3	0 number of Podiums	NA
4	Stilt Floor	NA
5	<u>14</u> number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

Building/Wing Number: B

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	<u>2</u> number of Basement(s) and Plinth	100%
3	0 number of Podiums	NA
4	Stilt Floor	NA
5	<u>14</u> number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

M/s BTH Street Architects

architecture + furniture

unbox

501, Vrundavan Enclave, Near Shell Petrol Pump, A.E.C. Cross Road, 132 Feet Ring Road, Naranpura. Ah-380013.

Date:- 02/01/2019

Building/Wing Number: C

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	<u>2</u> number of Basement(s) and Plinth	100%
3	0 number of Podiums	NA
4	Stilt Floor	NA
5	<u>14</u> number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

Building/Wing Number: D

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	<u>2</u> number of Basement(s) and Plinth	100%
3	0 number of Podiums	NA
4	Stilt Floor	NA
5	<u>14</u> number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

M/s 9TH Street Architects

architecture + furniture

unbox

501, Vrundavan Enclave, Nr. Shell Petrol Pump, A.E.C. Cross Road, 132 Feet Ring Road, Naranpura. Ah-380013,



ninth street architects

Email-Id:-free.walls08@gmail.com
Ph. 9979855707,7573014431

Date:- 02/01/2019

Building/Wing Number: E

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	<u>2</u> number of Basement(s) and Plinth	100%
3	0 number of Podiums	NA
4	Stilt Floor	100%
5	<u>14</u> number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

Building/Wing Number: E

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	<u>2</u> number of Basement(s) and Plinth	100%
3	0 number of Podiums	NA
4	Stilt Floor	100%
5	<u>14</u> number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

M/s 9TH Street Architects

architecture + furniture
Partner

unbox

501, Vrundavan Enclave, Nr. Shell Petrol Pump, A.E.C. Cross Road, 132 Feet Ring Road, Naranpura. Ah-380013,



ninth street architects

Email-Id:-free.walls08@gmail.com

Ph. 9979855707,7573014431

Date:- 02/01/2019

Building/Wing Number: G

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	<u>2</u> number of Basement(s) and Plinth	100%
3	0 number of Podiums	NA
4	Stilt Floor	100%
5	<u>14</u> number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

Building/Wing Number: H

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	<u>2</u> number of Basement(s) and Plinth	100%
3	0 number of Podiums	NA
4	Stilt Floor	100%
5	<u>14</u> number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

M/s 9TH Street Architects

architecture & furniture
partner

unbox

501, Vrundavan Enclave, Nr. Shell Petrol Pump, A.E.C. Cross Road, 132 Feet Ring Road, Naranpura. Ah-380013, ..



ninth street architects

Email-Id: -free.walls08@gmail.com

Ph. 9979855707, 7573014431

Date:- 02/01/2019

Building/Wing Number: 1

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	<u>2</u> number of Basement(s) and Plinth	100%
3	0 number of Podiums	NA
4	Stilt Floor	100%
5	8 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

Building/Wing Number: 1

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	<u>2</u> number of Basement(s) and Plinth	100%
3	0 number of Podiums	NA
4	Stilt Floor	100%
5	<u>14</u> number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

M/s 9TH Street Architects

architecture + furniture

unbox

501, Vrundavan Enclave, Nr. Shell Petrol Pump, A.E.C. Cross Road, 132 Feet Ring Road, Naranpura. Ah-380013,

Date:- 02/01/2019

Building/Wing Number: K

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	<u>2</u> number of Basement(s) and Plinth	100%
3	0 number of Podiums	NA
4	Stilt Floor	100%
5	<u>14</u> number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

Table – A Building/Wing Number: L

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	<u>2</u> number of Basement(s) and Plinth	100%
3	0 number of Podiums	NA
4	Stilt Floor	100%
5	<u>14</u> number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

M/s 9TH Street Architects

architecture

unbox

Date:- 02/01/2019

Table - B

Internal & External Development Works in Respect of the entire Registered Phase

Sr. No	Common areas and Facilities Amenities	Proposed (Yes/No)	Percentage of work done	Remarks
1	Internal Roads & Footpaths	Yes	100%	
2	Water Supply	Yes	100%	
3	Sewerage (chamber, lines, Septic Tank, STP)	Yes	100%	Septic Tank & STP is not Applicable
4	Storm Water Drains	Yes	100%	
5	Landscaping & Tree Planting	Yes	100%	
6	Street Lighting	Yes	100%	
7	Community Buildings	Yes	100%	
8	Treatment and disposal of sewage and sullage water /STP	No	NA	
9	Solid Waste Management & Disposal	No	NA	
10	Water Conservation, Rain Water Harvesting , Percolating Well/Pit	Yes	100%	Provision for Percolating well Only
11	Energy Management	No	NA	
12	Fire Protection and Fire Safety Requirements	Yes	100%	
13	Electrical Meter Room, Sub-station, Receiving Station	Yes	100%	
14	Compound Wall	Yes	100%	

Project 100% completed.

Yours Faithfully,

M/s 9TH Street Architects