

Architect's Certificate*		
Report for quarter ending		'Oct to Dec' 2025
Subject		Certificate of Percentage of completion of construction work of the project at the end of the quarter
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans	
Sr.No.	Particulars	Information
1.	Project/Phase of the project	M3M PARAGON57
2.	Location	Sector 57, Gurugram, Haryana
3.	Licensed area in acres	3.16 Acres
4.	Area for registration in acres	3.16 Acres
5.	HARERA registration no.	RC/REP/HARERA/GGM/651/383/2022/126 dated 23.12.2022 (Registration no 126 of 2022 dated 23.12.2022)
6.	Name of licensee	M/s. Paryapt Infrastructure Pvt. Ltd.
7.	Name of collaborator	-
8.	Name of developer	M/s. Paryapt Infrastructure Pvt. Ltd.
2.	Details related to inspection are as under	
1.	Date of certifying of percentage of construction work/ site inspection	02.01.2026
2.	Name of Architect/ Architect's firm	Ar. Ashish Sawe
3.	Date of site inspection	02.01.2026
3.	Following technical professionals are appointed by promoter: - (as applicable)	
Sr.No.	Consultants	Name
1.	Site engineer	Sheshanath Singh
2.	Structural consultant	BMSF DESIGN Under GPM
3.	Proof consultant	YG CONSULTING & ENGINEERS LLP
4.	MEP consultant	V. S. Kukreja Under GPM
5.	Site supervisor/incharge	-

4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.

Date: 02.01.2026

Yours faithfully,

Place : Gurugram

Name :-**Ar. ASHISH SAWE**

Stamp :



Council of architects (CoA)

Registration no.:CA/2001/28463

Council of architects (CoA) Registration valid till (date): 31-12-2033

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		858 Commercial Units			
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr.N o.	Project components		Work done value during the quarter (Sq. Mt.)	Cumulative work done value till date (Sq. Mt.)	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		-	18,626	100%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		1038	34281	66%
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	705	28221	40%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	2116	30338	43%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	705	27516	39%
4.	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	1038	18697	36%
	4.2	External (plaster, painting, facade, etc.)	1558	18178	35%
Sr.No.	Tasks/Activity		Description of work done		(%) of total proposed work
	Sub-Structure Status				
1.	Excavation		Complete		100%
2.	Laying of foundation				
	(i)	Raft	Complete		100%
	(ii)	Pile	Complete		100%
3.	Number of basement(s) (2)				
	(i)	Basement Level 1	Complete		100%



	(ii)	Basement level 2*	Complete		100%	
4.	Waterproofing of the above sub-structure (wherever applicable)		Under Progress		41%	
	Super-Structure Status					
5.	Total floors in the tower/ building		14 floors		64%	
6.	Total area on each floor		As per approved building plans		NA	
7.	Stilt floor/ ground floor		Under Progress		82%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower laid by end of quarter		Under Progress		61%	
9.	Status of construction					
	(i)	Walls on floors	Under Progress		52%	
	(ii)	Staircase	Under Progress		51%	
	(iii)	Lift wells along with water proofing	Under Progress		42%	
	(iv)	Lift lobbies/ common areas floor wise	Under Progress		44%	
10.	Fixing of door and window frames in flats/ units		N.A.		N.A.	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Under Progress		40%	
	(ii)	Electrical works including wiring	Under Progress		43%	
	(iii)	Plumbing works	Under Progress		39%	
12.	Status of wall plastering					
	(i)	External plaster	Under Progress		35%	
	(ii)	Internal plaster	Under Progress		36%	
13.	Status of wall tiling					
	(i)	In bathroom	Under Progress		34%	
	(ii)	In kitchen	N.A.		0%	
14.	Status of flooring					
	(i)	Common areas	Under Progress		42%	
	(ii)	Units/ flats	Started		3%	
Sr.No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
15.	Status of white washing					



	(i)	Internal walls	Under Progress	35%	
	(ii)	External walls	Under Progress	38%	
16.	Status of finishing				
	(i)	Staircase with railing	Under Progress	33%	
	(ii)	Lift wells	Under Progress	40%	
	(iii)	Lift lobbies/ common areas floor wise	Under Progress	42%	
17.	Status of installation				
	(within flat/unit)				
	(i)	Doors and windows panels	Not Started	0%	
	(ii)	Sanitary fixtures	Under Progress	32%	
	(iii)	Modular kitchen	Not Started	0%	
	(iv)	Electrical fittings/ lighting	Under Progress	44%	
	(v)	Gas piping (if any)	Under Progress	41%	
	(other than flat/units)				
	(vi)	Lifts installation	Under Progress	39%	
	(vii)	Overhead tanks	Not Started	0%	
	(viii)	Underground water tank	Not Started	0%	
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Under Progress	49%	
	(x)	Electrical fittings in common areas	Under Progress	39%	
	(xi)	Compliance to conditions of environment/ CRZNOC	6 Months Compliance Done	N.A.	
18.	Waterproofing of terraces		Under Progress	37%	
19.	Entrance lobby finishing		Under Progress	36%	
20.	Status of construction of compound wall		Not Started	0%	
Sr. No.	Common areas and facilities amenities		Proposed (Yes/ No)	Percentage of work done	Remarks
B-1	Services				
1.	Internal roads & pavements		Yes	0%	Not Started
2.	Parking		Yes	0%	Not Started
	Covered no.		Yes	0%	Not Started
	Open		Yes	0%	Not Started



3.	Water supply	Yes	0%	Not Started
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	27%	Under Progress
5.	Storm water drains	Yes	0%	Not Started
6.	Landscaping & tree plantation	Yes	0%	Not Started
7.	Parks and playgrounds	Yes	0%	Not Started
	Fixing of children play equipment's	Yes	0%	Not Started
	Benches	Yes	0%	Not Started
8.	Shopping area	Yes	0%	Not Started
9.	Street lighting/ electrification	Yes	0%	Not Started
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	0%	Not Started
11.	Solid waste management & disposal	Yes	0%	Not Started
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	0%	Not Started
13.	Energy management (solar)	Yes	0%	Not Started
14.	Fire protection and fire safety requirements	Yes	0%	Not Started
15.	Electrical meter room, sub-station, receiving station	Yes	0%	Not Started
16.	Other (Gas Tank,HSD Tank)	No	N.A.	N.A.
B-2	Community building to be transferred to RWA			
17.	Community centre	No	N.A.	N.A.
18.	others(Gas Tank,HSD Tank)	No	N.A.	N.A.
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	No	N.A.	N.A.
20.	Dispensary	No	N.A.	N.A.
21.	Club	No	N.A.	N.A.
22.	Others(Gas Tank,HSD Tank)	No	N.A.	N.A.
B-4	Services/ facilities to be transferred to competent authority			
23.	*	No	N.A.	N.A.

End of Report

