

Annexure A

Report for quarter ending		Dec'2024
Subject		Certificate of progress of construction work
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans	
Sr. No.	Particulars	Information
1.	Project/Phase of the project	Central Park Flower Valley – Floors and Villas
2.	Location	Sector 32 Sohana, Gurgaon
3.	Licensed area in acres	Sector 29, 30, 32 & 33 Sohana, Gurgaon
4.	Area for registration in acres	14.4938 Acre
5.	HARERA registration no.	99 of 2022
6.	Name of licensee	
7.	Name of collaborator	M/s St. Patricks Realty Pvt. Ltd
8.	Name of developer	M/s St. Patricks Realty Pvt. Ltd
2.	Details related to inspection are as under	
1.	Date of certifying of percentage of construction work/ site inspection	01 Jan 25
2.	Name of Architect/ Architect's firm	Gian P. Mathur & Associates Pvt. Ltd.
3.	Date of site inspection	01 Jan 25

GIAN P. MATHUR
ARCHITECT
B. Arch., M. G. A. I. I. A
CA No. 80/5769

GIAN P. MATHUR & ASSOCIATES (P) LTD.

C-55, East Of Kailash, New Delhi- 110065

T: 46599599 | F: 46599512

E: info@gpmindia.com | W: www.gpmindia.com

3.	Following technical professionals are appointed by promoter: - (as applicable)		
	Sr. No.	Consultants	Name
	1.	Site engineer	Ashok Gautam
	2.	Structural consultant	Gian P. Mathur & Associates Pvt. Ltd.
	3.	Proof consultant	N/A
	4.	MEP consultant	M/s V Consulting
	5.	Site supervisor/incharge	K P Singh
4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.		
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.		

Date

: 01 Jan 25

GIAN P. MATHUR
ARCHITECT
 B. Arch., M.C.A. I.I.A
 Yours faithfully,
 CH. NO. 10/5769

Place: Gurugram

Signature & name (in block letters) with
 stamp of architect

Council of architects (CoA) :
 registration no.

Council of architects (CoA) :
 registration valid till (date)

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			Flamingo Floors		
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		ZERO	1097.72	100%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		ZERO	4365.48	100%
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	NA	NA	NA
	3.2	Electrical (conducting, wiring, fixtures, etc.)	ZERO	653.19	100.00%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	ZERO	1052.06	100.00%
	3.4	HVAC Works	ZERO	984.66	100.00%
4.	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	ZERO	3642.21	100.00%
	4.2	External (plaster, painting, facade, etc.)	ZERO	364.95	100.00%
5.		Other items	30	5097.58	117.92%

GIAN P. MATHUR
ARCHITECT
 B. Arch., M.C.A. I.I.A
 CA No. 805769

TABLE A

Tasks / Activity		FLAMINGO FLOOR (I & II)			
		Description of Work Done		Percentage of Total Proposed Work	
Sub-Structure Status					
Excavation		Completed		100%	
Laying of Foundation					
(i)	Raft	Completed		100%	
(ii)	Pile	N/A		N/A	
Number of basement (s)					
(i)	Basement Level 1	Completed		100%	
(ii)	Basement Level 2	N/A		N/A	
Waterproofing of above sub-structure (wherever applicable)		Completed		100%	
Super-Structure Status					
Total floors in the tower/building		G+2		100%	
Total area on each floor					
Stilt floor / Ground floor		Completed		100%	
Status of laying of slabs floor wise					
Cumulative number of slabs in the building / tower Laid by the end of quarter		all slabs completed		100%	
Status of Construction					
(i)	Walls on floor	Completed		100%	
(ii)	Staircase	Completed		100%	
(iii)	Lift wells along with water proofing	Completed		100%	
(iv)	Lift lobbies / common areas floor wise	Completed		100%	
Fixing of door and window frames in flats / units		Completed		100%	
Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
(i)	Mechanical works	Done	N/A	100%	N/A
(ii)	Electrical works including wiring	Done	N/A	100%	N/A
(iii)	Plumbing works	Done	N/A	100%	N/A

GIAN P. MATHUR
ARCHITECT
B. Arch., M.C.A., I.I.A.
CA No. 80/5769

Status of Wall Plastering					
(i)	External plaster	N/A	N/A	N/A	N/A
(ii)	Internal plaster	N/A	N/A	N/A	N/A
Status of Wall Tiling					
(i)	In bathroom	Done	N/A	100%	N/A
(ii)	In kitchen	Done	N/A	100%	N/A
Status of Flooring					
(i)	Common areas	N/A	Done	N/A	100%
(ii)	Units / flats	Done	N/A	100%	N/A
Status of white washing					
(i)	Internal walls	Done	N/A	100%	N/A
(ii)	External walls	N/A	Done	N/A	100%
Status of finishing					
(i)	Staircase with railing	N/A	DONE	N/A	100%
(ii)	Lift wells	N/A	N/A	N/A	N/A
(iii)	Lift lobbies / common areas floor wise	N/A	N/A	N/A	N/A
Status of installation					
(within flat / unit)					
(i)	Doors & windows panels	DONE	N/A	100%	N/A
(ii)	Sanitary fixtures	Done	N/A	100%	N/A
(iii)	Modular kitchen	Done	N/A	100%	N/A
(iv)	Electrical fittings / lighting	Done	N/A	100%	N/A
(v)	Gas piping (if any)	N/A	N/A	N/A	N/A
(other than flat / units)					
(vi)	Lifts installation	N/A	N/A	N/A	N/A
(vii)	Overhead tanks	N/A	DONE	N/A	100%
(viii)	Underground water tanks	N/A	N/A	N/A	N/A
(ix)	Firefighting fitting and equipment's as per CFO NOC	N/A	N/A	N/A	N/A
(x)	Electrical fittings in common areas	N/A	Done	N/A	100%
(xi)	Compliance to conditions of environment / CRZ NOC	DONE	DONE	100%	100%
Waterproofing of terraces		N/A	DONE	N/A	100%

GIAN P. MATHUR
 ARCHITECT
 B. Arch., M.C.A., I.I.T.
 CA No. 80/5759

Entrance lobby finishing	N/A	N/A	N/A	N/A
Status of construction of compound wall	N/A	DONE	N/A	100%

Table – A				
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		Cerise Floors		
A1	Cumulative progress of the project/phase at the end of the quarter.			
Sr. No.	Project components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	ZERO	374.16	100%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	ZERO	2622.05	100%
3.	MEP			
	3.1 Mechanical (lifts, ventilation, etc.)	ZERO	798.40	100%
	3.2 Electrical (conduiting, wiring, fixtures, etc.)	ZERO	273.91	100%
	3.3 Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	ZERO	471.73	100%
	3.5 HVAC Works	ZERO	388.34	100%
4.	Finishing			
	4.1 Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	ZERO	1882.38	100%
	4.2 External (plaster, painting, facade, etc.)	ZERO	315.80	100%
5.	Other items	288.9	2464.72	253%

GIAN P. MATAR
ARCHITECT
B. Arch., M.C.A. I.I.A
CA No. 89/5769

		CERISE			
Tasks / Activity		Description of Work Done		Percentage of Total Proposed Work	
Sub-Structure Status					
Excavation		DONE		100%	
Laying of Foundation					
(i)	Raft	DONE		100%	
(ii)	Pile	N/A		N/A	
Number of basement (s)					
(i)	Basement Level 1	N/A		N/A	
(ii)	Basement Level 2	N/A		N/A	
Waterproofing of above sub-structure (wherever applicable)		DONE		100%	
Super-Structure Status					
Total floors in the tower/building		S+4		100%	
Total area on each floor					
Stilt floor / Ground floor		Completed		100%	
Status of laying of slabs floor wise					
Cumulative number of slabs in the building / tower Laid by the end of quarter		all slabs completed		100%	
Status of Construction					
(i)	Walls on floor	Completed		100%	
(ii)	Staircase	Completed		100%	
(iii)	Lift wells along with water proofing	Completed		100%	
(iv)	Lift lobbies / common areas floor wise	Completed		99%	
Fixing of door and window frames in flats / units		WIP		99%	
Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
(i)	Mechanical works	WIP	WIP	98%	98%
(ii)	Electrical works including wiring	WIP	N/A	98%	N/A
(iii)	Plumbing works	WIP	N/A	98%	N/A
Status of Wall Plastering					
(i)	External plaster	N/A	DONE	N/A	100%

GIAN P. MATHUR
 ARCHITECT
 B. Arch., M.C.A. I.I.A
 CA No. 80/5769

(ii)	Internal plaster	DONE	N/A	100%	N/A
Status of Wall Tiling					
(i)	In bathroom	WIP	N/A	100%	N/A
(ii)	In kitchen	WIP	N/A	98%	N/A
Status of Flooring					
(i)	Common areas	N/A	WIP	N/A	100%
(ii)	Units / flats	WIP	N/A	100%	N/A
Status of white washing					
(i)	Internal walls	DONE	N/A	99%	N/A
(ii)	External walls	N/A	WIP	N/A	98%
Status of finishing					
(i)	Staircase with railing	N/A	WIP	N/A	100%
(ii)	Lift wells	N/A	WIP	N/A	100%
(iii)	Lift lobbies / common areas floor wise	N/A	WIP	N/A	99%
Status of installation					
(within flat / unit)					
(i)	Doors & windows panels	WIP	N/A	99%	N/A
(ii)	Sanitary fixtures	WIP	N/A	0%	N/A
(iii)	Modular kitchen	WIP	N/A	98%	N/A
(iv)	Electrical fittings / lighting	WIP	N/A	0%	N/A
(v)	Gas piping (if any)	WIP	N/A	98%	N/A
(other than flat / units)					
(vi)	Lifts installation	N/A	WIP	N/A	98%
(vii)	Overhead tanks	N/A	DONE	N/A	100%
(viii)	Underground water tanks	N/A	N/A	N/A	N/A
(ix)	Firefighting fitting and equipment's as per CFO NOC	N/A	N/A	N/A	N/A
(x)	Electrical fittings in common areas	N/A	WIP	N/A	0%
(xi)	Compliance to conditions of environment / CRZ NOC	DONE	DONE	100%	100%
Waterproofing of terraces		N/A	N/A	DONE	N/A
Entrance lobby finishing		N/A	N/A	WIP	N/A
Status of construction of compound wall		N/A	N/A	DONE	N/A

GIAN P. MATHUR
 ARCHITECT
 B. Arch., M.C.A., I.I.A.
 CA No. 80/5769

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)				Clover Floors	
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		ZERO	224.10	100%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		ZERO	692.09	100%
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	ZERO	173.32	100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	ZERO	102.50	100%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	ZERO	193.71	100%
	3.4	HVAC works	ZERO	132.05	100%
4.	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	ZERO	659.50	105%
	4.2	External (plaster, painting, facade, etc.)	ZERO	146.14	125%
5.		Other items	360.63	1241.03	323%

GIAN P. MATHUR
 ARCHITECT
 B. Arch., M.C.A. I.I.A
 CA No. 80/5769

CLOVER FLOORS					
Tasks / Activity		Description of Work Done		Percentage of Total Proposed Work	
Sub-Structure Status					
Excavation		Completed		100%	
Laying of Foundation					
(i)	Raft	Completed		100%	
(ii)	Pile	N/A		N/A	
Number of basement (s)					
(i)	Basement Level 1	Completed		100%	
(ii)	Basement Level 2	N/A		N/A	
Waterproofing of above sub-structure (wherever applicable)		Completed		100%	
Super-Structure Status					
Total floors in the tower/building		S+4		100%	
Total area on each floor					
Stilt floor / Ground floor		Completed		100%	
Status of laying of slabs floor wise					
Cumulative number of slabs in the building / tower Laid by the end of quarter		all slabs completed		100%	
Status of Construction					
(i)	Walls on floor	Done		100%	
(ii)	Staircase	Done		100%	
(iii)	Lift wells along with water proofing	Done		100%	
(iv)	Lift lobbies / common areas floor wise	Done		100%	
Fixing of door and window frames in flats / units		Done		100%	
Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
(i)	Mechanical works	Done	Done	100%	100%
(ii)	Electrical works including wiring	Done	N/A	100%	N/A
(iii)	Plumbing works	Done	N/A	100%	N/A
Status of Wall Plastering					
(i)	External plaster	N/A	DONE	N/A	100%

GIAN P. MATHUR
ARCHITECT
B. Arch., M.C.A. I.T.A
CA No. 80/5769

(ii)	Internal plaster	DONE	N/A	100%	N/A
Status of Wall Tiling					
(i)	In bathroom	Done	N/A	100%	N/A
(ii)	In kitchen	Done	N/A	100%	N/A
Status of Flooring					
(i)	Common areas	N/A	Done	N/A	100%
(ii)	Units / flats	Done	N/A	100%	N/A
Status of white washing					
(i)	Internal walls	DONE	N/A	100%	N/A
(ii)	External walls	N/A	Done	N/A	100%
Status of finishing					
(i)	Staircase with railing	N/A	DONE	N/A	100%
(ii)	Lift wells	N/A	DONE	N/A	100%
(iii)	Lift lobbies / common areas floor wise	N/A	Done	N/A	100%
Status of installation					
(within flat / unit)					
(i)	Doors & windows panels	Done	N/A	100%	N/A
(ii)	Sanitary fixtures	Done	N/A	100%	N/A
(iii)	Modular kitchen	Done	N/A	100%	N/A
(iv)	Electrical fittings / lighting	Done	N/A	100%	N/A
(v)	Gas piping (if any)	Done	N/A	100%	N/A
(other than flat / units)					
(vi)	Lifts installation	N/A	Done	N/A	100%
(vii)	Overhead tanks	N/A	DONE	N/A	100%
(viii)	Underground water tanks	N/A	N/A	N/A	N/A
(ix)	Firefighting fitting and equipment's as per CFO NOC	N/A	N/A	N/A	N/A
(x)	Electrical fittings in common areas	N/A	Done	N/A	100%
(xi)	Compliance to conditions of environment / CRZ NOC	DONE	DONE	100%	100%
Waterproofing of terraces		N/A	N/A	DONE	N/A
Entrance lobby finishing		N/A	N/A	Done	N/A
Status of construction of compound wall		N/A	N/A	N/A	N/A

GIAN P. MATHUR
 ARCHITECT
 B. Arch., M.E.A. I.I.T.
 CA No. 80/5769

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			Villas		
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		ZERO	387.32	100%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		ZERO	1280.16	100%
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	NA	NA	NA
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	ZERO	131.97	100%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	ZERO	292.04	100%
	3.4	HVAC works	ZERO	138.24	100%
4.	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common arcas)	ZERO	1029.56	100%
	4.2	External (plaster, painting, facade, etc.)	ZERO	166.14	100%
5.		Other items	ZERO	1538.93	114%

GIAN P. MATHUR
 ARCHITECT
 B. Arch., M.C.A. I.I.A
 CA No. 80/5769

		VILLAS			
Tasks / Activity		Description of Work Done		Percentage of Total Proposed Work	
Sub-Structure Status					
Excavation		Completed		100%	
Laying of Foundation					
(i)	Raft	Completed		100%	
(ii)	Pile	N/A		N/A	
Number of basement (s)					
(i)	Basement Level 1	N/A		N/A	
(ii)	Basement Level 2	N/A		N/A	
Waterproofing of above sub-structure (wherever applicable)		Completed		100%	
Super-Structure Status					
Total floors in the tower/building		G+1		100%	
Total area on each floor					
Stilt floor / Ground floor		Completed		100%	
Status of laying of slabs floor wise					
Cumulative number of slabs in the building / tower Laid by the end of quarter		all slabs completed		100%	
Status of Construction					
(i)	Walls on floor	Completed		100%	
(ii)	Staircase	Completed		100%	
(iii)	Lift wells along with water proofing	Completed		100%	
(iv)	Lift lobbies / common areas floor wise	Completed		100%	
Fixing of door and window frames in flats / units		Completed		100%	
Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
(i)	Mechanical works	Done	N/A	100%	N/A
(ii)	Electrical works including wiring	Done	N/A	100%	N/A
(iii)	Plumbing works	Done	N/A	100%	N/A
Status of Wall Plastering					
(i)	External plaster	N/A	DONE	N/A	100%

GIAN P. MATHUR
ARCHITECT
B. Arch., M.C.A. I.I.T
CA No. 80/5769

(ii)	Internal plaster	Done	N/A	100%	N/A
Status of Wall Tiling					
(i)	In bathroom	DONE	N/A	100%	N/A
(ii)	In kitchen	DONE	N/A	100%	N/A
Status of Flooring					
(i)	Common areas	N/A	DONE	N/A	100%
(ii)	Units / flats	DONE	N/A	100%	N/A
Status of white washing					
(i)	Internal walls	DONE	N/A	100%	N/A
(ii)	External walls	N/A	DONE	N/A	100%
Status of finishing					
(i)	Staircase with railing	DONE	N/A	100%	N/A
(ii)	Lift wells	DONE	N/A	100%	N/A
(iii)	Lift lobbies / common areas floor wise	N/A	N/A	N/A	N/A
Status of installation					
(within flat / unit)					
(i)	Doors & windows panels	DONE	N/A	100%	N/A
(ii)	Sanitary fixtures	DONE	N/A	100%	N/A
(iii)	Modular kitchen	DONE	N/A	100%	N/A
(iv)	Electrical fittings / lighting	DONE	N/A	100%	N/A
(v)	Gas piping (if any)	N/A	N/A	N/A	N/A
(other than flat / units)					
(vi)	Lifts installation	N/A	N/A	N/A	N/A
(vii)	Overhead tanks	N/A	DONE	N/A	100%
(viii)	Underground water tanks	N/A	N/A	N/A	N/A
(ix)	Firefighting fitting and equipment's as per CFO NOC	N/A	N/A	N/A	N/A
(x)	Electrical fittings in common areas	N/A	DONE	N/A	100%
(xi)	Compliance to conditions of environment / CRZ NOC	DONE	DONE	100%	100%
Waterproofing of terraces		N/A	DONE	N/A	100%
Entrance lobby finishing		N/A	DONE	N/A	100%
Status of construction of compound wall		N/A	DONE	N/A	100%

GIAN P. MATHUR
ARCHITECT
B. Arch., M. C.A., I.I.A
CA No. 80/5769

Table – B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	Remarks
B-1	Services			
1.	Internal roads & pavements	NA	NA	
2.	Parking	NA	NA	
	Covered no.	NA	NA	
	Open no.	NA	NA	
3.	Water supply	NA	NA	
4.	Sewerage (chamber, lines, septic tanks, STP)	NA	NA	
5.	Storm water drains	NA	NA	
6.	Landscaping & tree plantation	NA	NA	
7.	Parks and playgrounds	NA	NA	
	Fixing of children play equipment's	NA	NA	
	Benches	NA	NA	
8.	Shopping area	NA	NA	
9.	Street lighting/ electrification	NA	NA	
10.	Treatment and disposal of sewage and sullage water/ STP	NA	NA	
11.	Solid waste management & disposal	NA	NA	
12.	Water conservation, rain water, harvesting, percolating well/ pit	NA	NA	
13.	Energy management (solar)	NA	NA	
14.	Fire protection and fire safety requirements	NA	NA	
15.	Electrical meter room, sub-station, receiving station	NA	NA	
16.	Other (option to add more)			
B-2	Community building to be transferred to RWA			
17.	Community centre			
18.	Others			
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools			
20.	Dispensary			
21.	Club			
22.	Others			
B-4	Services/ facilities to be transferred to competent authority			
23.	*			

Note: (*) extend as per requirement

GIAN P. MATHUR
ARCHITECT
 B. Arch., M.C.A. I.I.A
 CA No. 80/5769