

**INDIVALE ADVISORS PRIVATE LIMITED**

Regd. Address: B1/H3, MOHAN CO-OPERATIVE INDUSTRIAL AREA MATHURA RD, BLOCK B NEW DELHI 110044

Email : Indivalueadvisors@gmail.com Mobile +91-7044091174

CIN : U74999DL2021PTC381050

AIVAPL/09/12/2025/Whiteland Blissville

Architect's Certificate		
Report for quarter ending	Oct to Dec" 2025	
Subject	Certificate of progress of construction work	
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans	
Sr. No.	Particulars	Information
1.	Project/Phase of the project	Whiteland Blissville
2.	Location	Sector 76, Gurugram
3.	Licensed area in acres	7.3187 Acres
4.	Area for registration in acres	1.9256 Acres
5.	HARERA registration No.	79 of 2022 and 111 of 2022
6.	Name of licensee	M/s Whiteland Corporation Private Limited
7.	Name of collaborator	NA
8.	Name of developer	M/s Whiteland Corporation Private Limited
2.	Details related to inspection are as under	
1.	Date of certifying of percentage of construction work/ site inspection	02.01.2026
2.	Name of Architect/ Architect's firm	Ar. Ashish Sawe
3.	Date of site inspection	31.12.2025
3.	Following technical professionals are appointed by promoter: - (as applicable)	
Sr. No.	Consultants	Name
1.	Site engineer	Mr. Om Prakash Yadav
2.	Structural consultant	M/s. Vintech Consultants
3.	Proof consultant	-
4.	MEP consultant	M/s. Sanelac consultants Private Limited
5.	Site supervisor/in charge	Mr. Om Prakash Yadav



4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.

Date: 02.01.2026

Yours faithfully,

Name: - **Ar. ASHISH SAWE**

Stamp :

Place : Gurugram

Council of Architecture (CoA)

Registration no. : CA/2001/28463

(CoA)

Registration valid till (date) : 31.12-2033



Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			Whiteland Blissville, Sector - 76 Residential Colony under, RC 79 of 2022, 55 Plots 220 Floors		
A1 Cumulative progress of the project/phase at the end of the quarter.					
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date sq.m.	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		40	4084	100%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		264	13111	99%
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	661	4631	35%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	1720	5029	38%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	1588	5029	38%
4.	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	1588	5559	42%
	4.2	External (plaster, painting, facade, etc.)	1589	5559	42%
Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work	
	Sub-Structure Status				
1.	Excavation		completed	100%	
2.	Laying of foundation for Infra				
	(i)	Raft	completed	100%	
	(ii)	Pile	N.A	N.A	



3.	Number of basement(s) . .			
	(i)	Basement Level 1	completed	100%
	(ii)	Basement level 2*	N.A.	N.A.
4.	Waterproofing of the above sub-structure (wherever applicable)		Work in progress	95%
	Super-Structure Status			
5.	Total floors in the tower/ building /Plots		Work in progress	96%
6.	Total area on each floor		Work in progress	96%
7.	Stilt floor/ ground floor		Work in progress	94%
8.	Status of laying of slabs floor wise (1 st Floor)		Work in progress	97%
	Status of laying of slabs floor wise (2 nd Floor)		Work in progress	98%
	Status of laying of slabs floor wise (3 rd Floor)		Work in progress	98%
	Status of laying of slabs floor wise (4 th Floor)		Work in progress	98%
	Cumulative number of slabs in the building/ tower laid by end of quarter		Work in progress	99%
9.	Status of construction			
	(i)	Walls on floors	Work in progress	98%
	(ii)	Staircase	Work in progress	98%
	(iii)	Lift wells along with water proofing	Work in progress	98%
	(iv)	Lift lobbies/ common areas floor wise	Work in progress	98%
10.	Fixing of door and window frames in flats/ units		Work in progress	35%
11.	Status of MEP		Internal (within flat)	External works
	(i)	Mechanical works	Work in progress	35%
	(ii)	Electrical works including wiring	Work in progress	38%
	(iii)	Plumbing works	Work in progress	38%
12.	Status of wall plastering			
	(i)	External plaster	Work in progress	42%



	(ii)	Internal plaster	Work in progress	42%
13.	Status of wall tiling			
	(i)	In bathroom	Work in progress	10%
	(ii)	In kitchen	Started	5%
14.	Status of flooring			
	(i)	Common areas	Started	9%
	(ii)	Units/ flats	Started	9%
15.	Status of white washing			
	(i)	Internal walls	Work in progress	25%
	(ii)	External walls	Work in progress	25%
16.	Status of finishing			
	(i)	Staircase with railing	Work in progress	58%

	(ii)	Lift wells	Work in progress	55%
	(iii)	Lift lobbies/ common areas floor wise	Work in progress	56%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Work in progress	15%
	(ii)	Sanitary fixtures	Not Started	0%
	(iii)	Modular kitchen	Not Started	0%
	(iv)	Electrical fittings/ lighting	Not Started	0%
	(v)	Gas piping (if any)	Not Started	0%
	(other than flat/units)			
	(vi)	Lifts installation	Not Started	0%
	(vii)	Overhead tanks	Not Started	0%
	(viii)	Underground water tank	Not Started	0%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Not Started	0%
	(x)	Electrical fittings in common areas	Not Started	0%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Not Started	0%
18.	Waterproofing of terraces			



19.	Entrance lobby finishing	0%	0%
20.	Status of construction of compound wall	0%	0%

Note: (*) extend rows as per requirement.

Table-B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services			
1.	Internal roads & pavements	Yes	26%	Work in progress
2.	Parking	Yes	0%	Yet to be Started
	Covered no. . Not Started	No		
	Open no. . Not Started	Yes		Yet to be Started
3.	Water supply	Yes	15%	Work in progress
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	30%	Work in progress
5.	Storm water drains	Yes	20%	Work in progress
6.	Landscaping & tree plantation	Yes	0%	Yet to be Started
7.	Parks and playgrounds	No		
	Fixing of children play equipment's	No		
	Benches	No		
8.	Shopping area	No		
9.	Street lighting/ electrification	Yes	0%	Yet to be Started
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	0%	Yet to be Started
11.	Solid waste management & disposal	Yes	0%	Yet to be Started
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	0%	Yet to be Started
13.	Energy management (solar)	Yes	0%	Yet to be Started
14.	Fire protection and fire safety requirements	Yes	15%	Work in progress
15.	Electrical meter room, sub-station, receiving station	Yes	0%	Yet to be Started
16.	Other (option to add more)			



B-2	Community building to be transferred to RWA			
17.	Community centre	N.A.	N.A.	
18.	Others	N.A.	N.A.	
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	N.A.	N.A.	
20.	Dispensary	N.A.	N.A.	
21.	Club	N.A.	N.A.	
22.	Others	N.A.	N.A.	
B-4	Services/ facilities to be transferred to competent authority			
23.	*			

-----END of Report-----

