



Architect's Certificate ¹		
Subject		Certificate of progress of construction work
1. I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans		
Sr. No.	Particulars	Information
1.	Project/Phase of the project	NANDAKA
2.	Location	Sector-84, Gurugram
3.	Licensed area in acres	8.34375 Acres
4.	Area for registration in acres	5.8406 Acres
5.	HARERA registration No.	96 of 2023
6.	Name of licensee	Ganga Global Homes Pvt. Ltd.
7.	Name of collaborator	-
8.	Name of developer	Ganga Global Homes Pvt. Ltd.
2. Details related to inspection are as under		
1.	Date of certifying of percentage of construction work/ site inspection	30 th September 2025
2.	Name of Architect/ Architect's firm	One Point Design
3.	Date of site inspection	30 th September 2025
3. Following technical professionals are appointed by promoter: - (as applicable)		
Sr. No.	Consultants	Name
1.	Site Engineer	Vipin Kumar Singh
2.	Structural consultant	NNC DESIGN INTERNATIONAL
3.	Proof consultant	PARESH AND ASSOCIATES
4.	MEP consultant	PARADISE CONSULTANTS
5.	Site supervisor/in charge	Manoj Attri
4. I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction ,infrastructure works and internal development works areas per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.		
5. I also certify that as on the date ,the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.		
Date:	04.10.2025	Yours faithfully, Signature & name (in block letters) with stamp of architect Avanika Vashisth CA/2018/91670
Place:	Gurugram	
Council of Architects (CoA) registration No.:	CA/2018/91670	
Council of architects (CoA) registration valid till (date):	December 2029	

Annexure -A

Name of the Project	Status of project (Extent of development carried out till date along with details of the same and extent of development pending)	Original time period disclosed to allottee for completion of project at the time of sale	Delay in completion of project	Time period within which the Promoter undertakes to complete the project
NANDAKA	Extent of development carried out till date- 30.09.2025 Structure- 27.00% Overall- 24.50%	23.02.2028	No Delay	23.02.2028
	Details of development carried out till date Tower 1 - 15.00% Tower 2 - 6.00% Tower 3 - 6.00% Tower 4 - 0.00%			
	Extent of development Pending Structure- 73.00% Overall- 75.50%			


Avanika Vashisth
CA 3018/91670



Table A					
Building/ Tower No. (to be prepared separately for each building/ tower in the project/ phase of the project)			TOWER-1		
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		18 %	14%	10%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		2 %	1 %	1 %
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	0 %	0 %	0 %
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0 %	0 %	0 %
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0 %	0 %	0 %
4.	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0 %	0 %	0 %
	4.2	External (plaster, painting, facade, etc.)	0 %	0 %	0 %
Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work	
	Sub-Structure Status				
1.	Excavation		Basement & Raft Excavation	100 %	
2.	Laying of foundation				
	(i)	Raft	100%	100%	
	(ii)	Pile	NA	NA	
3.	Number of basement(s)				
	(i)	Basement Level 1	100%	100%	
	(ii)	Basement level 2*	100 %	100 %	

Avanika Vashisth
CA/2018/91670



4.	Waterproofing of the above sub-structure (wherever applicable)	0%	0%
Super-Structure Status			
5.	Total floors in the tower/ building	G+45+2 BASEMENTS	
6.	Total area on each floor		
7.	Stilt floor/ ground floor	YES	
8.	Status of laying of slabs floor wise	0%	0%
	Cumulative number of slabs in the building/ tower laid by end of quarter	0%	0%
9.	Status of construction		
	(i) Walls on floors	0%	0%
	(ii) Staircase	0%	0%
	(iii) Lift wells along with water proofing	0%	0%
	(iv) Lift lobbies/ common areas floor wise	0%	0%
10.	Fixing of door and window frames in flats/ units	0%	0%
11.	Status of MEP	Internal (within flat)	External works
	(i) Mechanical works	0%	0%
	(ii) Electrical works including wiring	0%	0%
	(iii) Plumbing works	0%	0%
12.	Status of wall plastering		
	(i) External plaster	0%	0%
	(ii) Internal plaster	0%	0%
13.	Status of wall tiling		
	(i) In bathroom	0%	0%
	(ii) In kitchen	0%	0%
14.	Status of flooring		
	(i) Common areas	0%	0%
	(ii) Units/ flats	0%	0%
15.	Status of white washing		
	(i) Internal walls	0%	0%
	(ii) External walls	0%	0%
16.	Status of finishing		
	(i) Staircase with railing	0%	0%
	(ii) Lift wells	0%	0%
	(iii) Lift lobbies/ common areas floor wise	0%	0%

Avanika Vashishth
CA/2018/91670

17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	NA	NA
	(ii)	Sanitary fixtures	NA	NA
	(iii)	Modular kitchen	NA	NA
	(iv)	Electrical fittings/ lighting	NA	NA
	(v)	Gas piping (if any)	NA	NA
	(other than flat/units)			
	(vi)	Lifts installation	0%	0%
	(vii)	Overhead tanks	0%	0%
	(viii)	Underground water tank	0%	0%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	0%	0%
	(x)	Electrical fittings in common areas	0%	0%
	(xi)	Compliance to conditions of environment/ CRZ NOC	0%	0%
18.	Waterproofing of terraces		0%	0%
19.	Entrance lobby finishing		0%	0%
20.	Status of construction of compound wall		0%	0%


 Avanika Vashisth
 CA/2018/91670

Table A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			TOWER-2		
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		13 %	10%	8 %
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		0 %	0 %	0 %
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	0 %	0 %	0 %
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0 %	0 %	0 %
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0 %	0 %	0 %
4.	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0 %	0 %	0 %
	4.2	External (plaster, painting, facade, etc.)	0 %	0 %	0 %
Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work	
	Sub-Structure Status				
1.	Excavation		Basement & Raft Excavation	100%	
2.	Laying of foundation				
	(i)	Raft	100%	100%	
	(ii)	Pile	NA	NA	
3.	Number of basement(s)				
	(i)	Basement Level 1	70%	70%	
	(ii)	Basement level 2*	100%	100%	

Avanika Vashisth
CA/2018/91670

4.	Waterproofing of the above sub-structure (wherever applicable)	0%	0%
	Super-Structure Status		
5.	Total floors in the tower/ building	G+45+2 BASEMENTS	
6.	Total area on each floor		
7.	Stilt floor/ ground floor	YES	
8.	Status of laying of slabs floor wise	0%	0%
	Cumulative number of slabs in the building/ tower laid by end of quarter	0%	0%
9.	Status of construction		
	(i) Walls on floors	0%	0%
	(ii) Staircase	0%	0%
	(iii) Lift wells along with water proofing	0%	0%
	(iv) Lift lobbies/ common areas floor wise	0%	0%
10.	Fixing of door and window frames in flats/ units	0%	0%
11.	Status of MEP	Internal (within flat)	External works
	(i) Mechanical works	0%	0%
	(ii) Electrical works including wiring	0%	0%
	(iii) Plumbing works	0%	0%
12.	Status of wall plastering		
	(i) External plaster	0%	0%
	(ii) Internal plaster	0%	0%
13.	Status of wall tiling		
	(i) In bathroom	0%	0%
	(ii) In kitchen	0%	0%
14.	Status of flooring		
	(i) Common areas	0%	0%
	(ii) Units/ flats	0%	0%
15.	Status of white washing		
	(i) Internal walls	0%	0%
	(ii) External walls	0%	0%
16.	Status of finishing		
	(i) Staircase with railing	0%	0%
	(ii) Lift wells	0%	0%
	(iii) Lift lobbies/ common areas floor wise	0%	0%
17.	Status of installation		

Avanika Vashisth
CA/2016/91679



	(within flat/unit)		
(i)	Doors and windows panels	NA	NA
(ii)	Sanitary fixtures	NA	NA
(iii)	Modular kitchen	NA	NA
(iv)	Electrical fittings/ lighting	NA	NA
(v)	Gas piping (if any)	NA	NA
	(other than flat/units)		
(vi)	Lifts installation	0%	0%
(vii)	Overhead tanks	0%	0%
(viii)	Underground water tank	0%	0%
(ix)	Firefighting fitting and equipment's as per CFO NOC	0%	0%
(x)	Electrical fittings in common areas	0%	0%
(xi)	Compliance to conditions of environment/ CRZ NOC	0%	0%
18.	Waterproofing of terraces	0%	0%
19.	Entrance lobby finishing	0%	0%
20.	Status of construction of compound wall	0%	0%


 Avanika Vashisth
 CA/2018/91670



Table A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			TOWER-3		
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		10 %	8 %	7 %
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		0 %	0 %	0 %
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	0 %	0 %	0 %
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0 %	0 %	0 %
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0 %	0 %	0 %
4.	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0 %	0 %	0 %
	4.2	External (plaster, painting, facade, etc.)	0 %	0 %	0 %
Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work	
	Sub-Structure Status				
1.	Excavation		Basement & Raft Excavation	100%	
2.	Laying of foundation				
	(i)	Raft	100%	100%	
	(ii)	Pile	0%	0%	
3.	Number of basement(s)				
	(i)	Basement Level 1	70%	70%	
	(ii)	Basement level 2*	100%	100%	


 Avanika Vashisth
 CA/2018/91670



4.	Waterproofing of the above sub-structure (wherever applicable)		0%	0%
	Super-Structure Status			
5.	Total floors in the tower/ building		G+45+2 BASEMENTS	
6.	Total area on each floor			
7.	Stilt floor/ ground floor		YES	
8.	Status of laying of slabs floor wise		0%	0%
	Cumulative number of slabs in the building/ tower laid by end of quarter		0%	0%
9.	Status of construction			
	(i)	Walls on floors	0%	0%
	(ii)	Staircase	0%	0%
	(iii)	Lift wells along with water proofing	0%	0%
	(iv)	Lift lobbies/ common areas floor wise	0%	0%
10.	Fixing of door and window frames in flats/ units		0%	0%
11.	Status of MEP		Internal (within flat)	External works
	(i)	Mechanical works	0%	0%
	(ii)	Electrical works including wiring	0%	0%
	(iii)	Plumbing works	0%	0%
12.	Status of wall plastering			
	(i)	External plaster	0%	0%
	(ii)	Internal plaster	0%	0%
13.	Status of wall tiling			
	(i)	In bathroom	0%	0%
	(ii)	In kitchen	0%	0%
14.	Status of flooring			
	(i)	Common areas	0%	0%
	(ii)	Units/ flats	0%	0%
15.	Status of white washing			
	(i)	Internal walls	0%	0%
	(ii)	External walls	0%	0%
16.	Status of finishing			
	(i)	Staircase with railing	0%	0%
	(ii)	Lift wells	0%	0%
	(iii)	Lift lobbies/ common areas floor wise	0%	0%
17.	Status of installation			

Avanika Vashisth
CA/2018/91670



	(within flat/unit)		
(i)	Doors and windows panels	NA	NA
(ii)	Sanitary fixtures	NA	NA
(iii)	Modular kitchen	NA	NA
(iv)	Electrical fittings/ lighting	NA	NA
(v)	Gas piping (if any)	NA	NA
	(other than flat/units)		
(vi)	Lifts installation	0%	0%
(vii)	Overhead tanks	0%	0%
(viii)	Underground water tank	0%	0%
(ix)	Firefighting fitting and equipment's as per CFO NOC	0%	0%
(x)	Electrical fittings in common areas	0%	0%
(xi)	Compliance to conditions of environment/ CRZ NOC	0%	0%
18.	Waterproofing of terraces	0%	0%
19.	Entrance lobby finishing	0%	0%
20.	Status of construction of compound wall	0%	0%


 Avanika Vashisth
 CA/2018/91670



Table A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			TOWER-4		
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		0 %	0 %	0 %
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		0 %	0 %	0 %
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	0 %	0 %	0 %
	3.2	Electrical (conducting, wiring, fixtures, etc.)	0 %	0 %	0 %
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0 %	0 %	0 %
4.	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0 %	0 %	0 %
	4.2	External (plaster, painting, facade, etc.)	0 %	0 %	0 %
Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work	
	Sub-Structure Status				
1.	Excavation		96%	97%	
2.	Laying of foundation				
	(i)	Raft	0%	0%	
	(ii)	Pile	0%	0%	
3.	Number of basement(s)				
	(i)	Basement Level 1	0%	0%	
	(ii)	Basement level 2*	0%	0%	


 Avanika Vashisth
 CA/2018/91670



4.	Waterproofing of the above sub-structure (wherever applicable)	0%	0%
Super-Structure Status			
5.	Total floors in the tower/ building	G+45+2 BASEMENTS	
6.	Total area on each floor		
7.	Stilt floor/ ground floor	YES	
8.	Status of laying of slabs floor wise	0%	0%
	Cumulative number of slabs in the building/ towerlaid by end of quarter	0%	0%
9.	Status of construction		
	(i) Walls on floors	0%	0%
	(ii) Staircase	0%	0%
	(iii) Lift wells along with water proofing	0%	0%
	(iv) Lift lobbies/ common areas floor wise	0%	0%
10.	Fixing of door and window frames in flats/ units	0%	0%
11.	Status of MEP	Internal (within flat)	External works
	(i) Mechanical works	0%	0%
	(ii) Electrical works including wiring	0%	0%
	(iii) Plumbing works	0%	0%
12.	Status of wall plastering		
	(i) External plaster	0%	0%
	(ii) Internal plaster	0%	0%
13.	Status of wall tiling		
	(i) In bathroom	0%	0%
	(ii) In kitchen	0%	0%
14.	Status of flooring		
	(i) Common areas	0%	0%
	(ii) Units/ flats	0%	0%
15.	Status of white washing		
	(i) Internal walls	0%	0%
	(ii) External walls	0%	0%
16.	Status of finishing		
	(i) Staircase with railing	0%	0%
	(ii) Lift wells	0%	0%
	(iii) Lift lobbies/ common areas floor wise	0%	0%
17.	Status of installation		

Avanika Vashishth
CA/2018/91670



	(within flat/unit)		
(i)	Doors and windows panels	NA	NA
(ii)	Sanitary fixtures	NA	NA
(iii)	Modular kitchen	NA	NA
(iv)	Electrical fittings/ lighting	NA	NA
(v)	Gas piping (if any)	NA	NA
	(other than flat/units)		
(vi)	Lifts installation	0%	0%
(vii)	Overhead tanks	0%	0%
(viii)	Underground water tank	0%	0%
(ix)	Firefighting fitting and equipment's as per CFO NOC	0%	0%
(x)	Electrical fittings in common areas	0%	0%
(xi)	Compliance to conditions of environment/ CRZ NOC	0%	0%
18.	Waterproofing of terraces	0%	0%
19.	Entrance lobby finishing	0%	0%
20.	Status of construction of compound wall	0%	0%


 Avanika Vashisth
 CA/2018/91670



Table – B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	Remarks
B-1	Services			
1.	Internal roads & pavements	NO		
2.	Parking	YES	0%	
	Covered no.			
	Open no.			
3.	Water supply	YES	0%	
4.	Sewerage (chamber, lines, septic tanks, STP)	YES	0%	
5.	Storm water drains	YES	0%	
6.	Landscaping & tree plantation	YES	0%	
7.	Parks and playgrounds	NO		
	Fixing of children play equipment's	NO		
	Benches	YES	0%	
8.	Shopping area	YES	0%	COMMERCIAL
9.	Street lighting/ electrification	YES	0%	
10.	Treatment and disposal of sewage and sullage water/ STP	YES	0%	
11.	Solid waste management & disposal	YES	0%	
12.	Water conservation, rain water, harvesting, percolating well/ pit	NO		
13.	Energy management (solar)	YES	0%	
14.	Fire protection and fire safety requirements	YES	0%	
15.	Electrical meter room, sub-station, receiving station	YES	0%	
16.	Other (option to add more)			
B-2	Community building to be transferred to RWA			
17.	Community centre	NO		
18.	Others			
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	NO		
20.	Dispensary	NO		
21.	Club	NO		
22.	Others			
B-4	Services/ facilities to be transferred to competent authority			
23.	*			

Note: (*) extend as per requirements

Avanika Vashisth
CA/2018/91670