

Architect's Certificate		
Report for quarter ending		31.12.2025
Subject	Certificate of progress of construction work	
1	I/we have undertaken assignment as engineer for certifying percentage of completion of construction work of the above-mentioned project as per the approved plans and approved structural drawings duly vetted by the proof consultant.	
	Sr. No.	Particulars
	1	Project/phase of the project
	2	Location
	3	Licensed area in acres
	4	Area for registration in acres
	5	HARERA registration no.
	6	Name of licensee
	7	Name of collaborator
	8	Name of developer
2	Details related to inspection are as under	
	1	Date of certifying of percentage of construction work/ site inspection
	2	Name of Architect/ Architect's firm
	3	Date of site inspection
3	Following technical professionals are appointed by promoter: - (as applicable)	
	Sr. No.	Consultants
	1	Site engineer
	2	Structural consultant
	3	Proof consultant
	4	MEP consultant
	5	Quantity surveyor
4	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.	
5	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and tableB	

RAJEEV AGARWAL, ARCHITECTS

Date: 07.01.2026	Yours faithfully,  RAJEEV KUMAR AGARWAL ARCHITECT CA/88/11915 Ar. Rajeev Agarwal
Place: Gurugram	
Council of Architects (CoA) registration No.. :	CA/88/11915
Council of architects (CoA) registration valid till (date) :	31.12.2028

Table – A					
Building/ Tower no.			Tower-1		
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1	<u>Sub structure</u>		0	928.48	90.00%
	(inclusive of excavation, foundation, basements, water proofing, etc.)				
2	<u>Super structure</u>		254.20	566.90	20.61%
	(slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)				
3	<u>MEP</u>				
	3.1	Mechanical (lifts, ventilation, etc.)	-	-	0.00%
	3.2	Electrical (conducting, wiring, fixtures, etc.)	-	-	0.00%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	-	0.00%
4	<u>Finishing</u>				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	-	-	0.00%
	4.2	External (plaster, painting, facade, etc.)	-	-	0.00%
Over all % of completion of Tower					21.74%
Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work	
	<u>Sub-Structure Status</u>				
1	Excavation		Completed	100%	
2	Laying of foundation		Completed	100%	
	i	Raft	Completed	100%	
	ii	Pile			
3	Number of basement(s)				

	i	Basement Level 1	Completed	100%
	ii	Basement level 2*	Completed	100%
4	Waterproofing of the above sub-structure (wherever applicable)		Under progress	40%
	Super-Structure Status		Under progress	0%
5	Total floors in the tower/ building		S+24	
6	Total area on each floor			Sq Mtr
7	Stilt floor			Sq Mtr
8	Status of laying of slabs floor wise (Cumulative number of slabs in the building/ tower Stilt +First Floor roof slab completed) 6 th start		Under progress	25%
9	Status of construction			0%
	i	Walls on floors	Under progress	20%
	ii	Staircase	Under progress	20%
	iii	Lift wells along with water proofing	Under progress	20%
	iv	Lift lobbies/ common areas floor wise	Yet not Started	0%
10.	Fixing of door and window frames in flats/ units		Yet not Started	
11	Status of MEP		Status	Internal (within flat) and External works
	i	Mechanical works	Yet not Started	0.00%
	ii	Electrical works including wiring	Yet not Started	0.00%
	iii	Plumbing works	Yet not Started	0.00%
12	Status of wall plastering			
	i	Internal plaster	Yet not Started	0.00%
	ii	External plaster	Yet not Started	0.00%
13	Status of wall tiling			
	i	In bathroom	Yet not Started	0.00%
	ii	In kitchen	Yet not Started	0.00%
14	Status of flooring			
	i	Common areas	Yet not Started	0.00%
	ii	Units	Yet not Started	0.00%
15	Status of white washing			
	i	Internal walls	Yet not Started	0.00%
	ii	External walls	Yet not Started	0.00%
16	Status of finishing			

	i	Staircase with railing	Yet not Started	0.00%
	ii	Lift wells	Yet not Started	0.00%
	iii	Lift lobbies/ common areas floor wise	Yet not Started	0.00%
	Status of installation (within flat/unit)		Yet not Started	0.00%
	i	Doors and windows panels	Yet not Started	0.00%
	ii	Sanitary fixtures	Yet not Started	0.00%
	iii	Modular kitchen	Yet not Started	0.00%
	iv	Electrical fittings/ lighting	Yet not Started	0.00%
	v	Gas piping (if any)	Yet not Started	
	(other than flat/units)			
17	vi	Lifts installation	Yet not Started	0.00%
	vii	Overhead tanks	Yet not Started	0.00%
	viii	Underground water tank	Yet not Started	0.00%
	ix	Firefighting fitting and equipment's as per CFO NOC	Yet not Started	0.00%
	x	Electrical fittings in common areas	Yet not Started	0.00%
	xi	Compliance to conditions of environment/ CRZ NOC	Completed	100.00%
18	Waterproofing of terraces		Yet not Started	0.00%
19	Entrance lobby finishing		Yet not Started	0.00%
20	Status of construction of compound wall		Yet not Started	0.00%

Table – A

Building/ Tower no.		Tower-2		
A1	Cumulative progress of the project/phase at the end of the quarter.			
Sr. No.	Project components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1	<u>Sub structure</u>	-	827.87	90.00%
	(inclusive of excavation, foundation, basements, water proofing, etc.)			
2	<u>Super structure</u>	226.66	505.47	21.61%

	(slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)			
3	MEP			
	3.1	Mechanical (lifts, ventilation, etc.)	-	0.00%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	0.00%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	0.00%
4	Finishing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	-	0.00%
	4.2	External (plaster, painting, facade, etc.)	-	0.00%
Over all % of completion of Tower				21.74%
Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
1	Excavation		Completed	100%
2	Laying of foundation		Completed	100%
	i	Raft	Completed	100%
	ii	Pile		
3	Number of basement(s)			
	i	Basement Level 1	Completed	100%
	ii	Basement level 2*	Completed	100%
4	Waterproofing of the above sub-structure (wherever applicable)		Under progress	30%
	Super-Structure Status		Under progress	11%
5	Total floors in the tower/ building		S+24	
6	Total area on each floor			Sq Mtr
7	Stilt floor			Sq Mtr
8	Status of laying of slabs floor wise (Cumulative number of slabs in the building/ tower Stilt +First Floor roof slab completed) 6 th start		Under progress	25%
9	Status of construction			
	i	Walls on floors	Under progress	20%
	ii	Staircase	Under progress	20%

	iii	Lift wells along with water proofing	Yet not Started	20%
	iv	Lift lobbies/ common areas floor wise	Yet not Started	0%
10.	Fixing of door and window frames in flats/ units		Yet not Started	
11	Status of MEP		Status	Internal (within flat) and External works
	i	Mechanical works	Yet not Started	0.00%
	ii	Electrical works including wiring	Yet not Started	0.00%
	iii	Plumbing works	Yet not Started	0.00%
12	Status of wall plastering			
	i	Internal plaster	Yet not Started	0.00%
	ii	External plaster	Yet not Started	0.00%
13	Status of wall tiling			
	i	In bathroom	Yet not Started	0.00%
	ii	In kitchen	Yet not Started	0.00%
14	Status of flooring			
	i	Common areas	Yet not Started	0.00%
	ii	Units	Yet not Started	0.00%
15	Status of white washing			
	i	Internal walls	Yet not Started	0.00%
	ii	External walls	Yet not Started	0.00%
16	Status of finishing			
	i	Staircase with railing	Yet not Started	0.00%
	ii	Lift wells	Yet not Started	0.00%
	iii	Lift lobbies/ common areas floor wise	Yet not Started	0.00%
17	Status of installation (within flat/unit)		Yet not Started	0.00%
	i	Doors and windows panels	Yet not Started	0.00%
	ii	Sanitary fixtures	Yet not Started	0.00%
	iii	Modular kitchen	Yet not Started	0.00%
	iv	Electrical fittings/ lighting	Yet not Started	0.00%
	v	Gas piping (if any)	Yet not Started	
	(other than flat/units)			
	vi	Lifts installation	Yet not Started	0.00%
	vii	Overhead tanks	Yet not Started	0.00%
	viii	Underground water tank	Yet not Started	0.00%
	ix	Firefighting fitting and equipment's as per CFO NOC	Yet not Started	0.00%

	x	Electrical fittings in common areas	Yet not Started	0.00%
	xi	Compliance to conditions of environment/ CRZ NOC	Completed	100.00%
18		Waterproofing of terraces	Yet not Started	0.00%
19		Entrance lobby finishing	Yet not Started	0.00%
20		Status of construction of compound wall	Yet not Started	0.00%

Table – A				
Building/ Tower no.		Community/Club House		
A1	Cumulative progress of the project/phase at the end of the quarter.			
Sr. No.	Project components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1	<u>Sub structure</u>	-	-	0.00%
	(inclusive of excavation, foundation, basements, water proofing, etc.)			
2	<u>Super structure</u>		-	0.00%
	(slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)			
3	<u>MEP</u>			
	3.1 Mechanical (lifts, ventilation, etc.)	-	-	0.00%
	3.2 Electrical (conduiting, wiring, fixtures, etc.)	-	-	0.00%
	3.3 Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	-	0.00%
4	<u>Finishing</u>			
	4.1 Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	-	-	0.00%

	4.2	External (plaster, painting, facade, etc.)	-	-	0.00%
Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work	
	Sub-Structure Status				
1	Excavation		Yet not Started	0%	
2	Laying of foundation		Yet not Started	0%	
	i	Raft	Yet not Started	0%	
	ii	Pile	NA	NA	
3	Number of basement(s)				
	i	Basement Level 1	Yet not Started	0%	
	ii	Basement level 2*	Yet not Started	0%	
4	Waterproofing of the above sub-structure (wherever applicable)		Yet not Started	0%	
	Super-Structure Status		Yet not Started	0%	
5	Total floors in the tower/ building				
6	Total area on each floor			Sq Mtr	
7	Ground floor			Sq Mtr	
8	Status of laying of slabs floor wise (Cumulative number of slabs in the building/ tower Ground+ no Slab till)		Yet not Started	0%	
9	Status of construction			0%	
	i	Walls on floors	Yet not Started	0%	
	ii	Staircase	Yet not Started	0%	
	iii	Lift wells along with water proofing	Yet not Started	0%	
	iv	Lift lobbies/ common areas floor wise	Yet not Started	0%	
10.	Fixing of door and window frames in flats/ units		Yet not Started		
11	Status of MEP		Status	Internal (within flat) and External works	
	i	Mechanical works	Yet not Started	0.00%	
	ii	Electrical works including wiring	Yet not Started	0.00%	
	iii	Plumbing works	Yet not Started	0.00%	
12	Status of wall plastering				
	i	Internal plaster	Yet not Started	0.00%	
	ii	External plaster	Yet not Started	0.00%	
13	Status of wall tiling				
	i	In bathroom	Yet not Started	0.00%	
	ii	In kitchen	Yet not Started	0.00%	

14	Status of flooring			
	i	Common areas	Yet not Started	0.00%
	ii	Units	Yet not Started	0.00%
15	Status of white washing			
	i	Internal walls	Yet not Started	0.00%
	ii	External walls	Yet not Started	0.00%
16	Status of finishing			
	i	Staircase with railing	Yet not Started	0.00%
	ii	Lift wells	Yet not Started	0.00%
	iii	Lift lobbies/ common areas floor wise	Yet not Started	0.00%
17	Status of installation		Yet not Started	0.00%
	(within flat/unit)			
	i	Doors and windows panels	Yet not Started	0.00%
	ii	Sanitary fixtures	Yet not Started	0.00%
	iii	Modular kitchen	Yet not Started	0.00%
	iv	Electrical fittings/ lighting	Yet not Started	0.00%
	v	Gas piping (if any)	Yet not Started	
	(other than flat/units)			
	vi	Lifts installation	Yet not Started	0.00%
	vii	Overhead tanks	Yet not Started	0.00%
	viii	Underground water tank	Yet not Started	0.00%
	ix	Firefighting fitting and equipment's as per CFO NOC	Yet not Started	0.00%
18	x	Electrical fittings in common areas	Yet not Started	0.00%
	xi	Compliance to conditions of environment/ CRZ NOC	Yet not Started	0.00%
18	Waterproofing of terraces		Yet not Started	0.00%
19	Entrance lobby finishing		Yet not Started	0.00%
20	Status of construction of compound wall		Yet not Started	0.00%


RAJEEV KUMAR AGARWAL
ARCHITECT CA/88/11915
 Seal & Signature of Architect

Table - B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	Remarks
B-1	Services			
1	Internal roads and pavements	Yes	0%	yet not started
2	Water supply system	Yes	0%	yet not started
3	Storm water drainage	Yes	0%	yet not started
4	Sewerage system	Yes	0%	yet not started
5	Street lighting	Yes	0%	yet not started
6	Play grounds and parks	Yes	0%	yet not started
7	Electricity Supply System	Yes	0%	yet not started
8	Security and fire-fighting	Yes	0%	yet not started
9	Renewable energy system	Yes	0%	yet not started
10	Parking	Yes	0%	yet not started
11	STP	Yes	0%	yet not started
12	Underground water tank	Yes	0%	yet not started
13	Rain water harvesting	Yes	0%	yet not started
14	Electrification Cost	Yes	0%	yet not started
	Total IDW		0%	
B-2	Community			
16	Community Building/Club House	Yes	0%	yet not started
	Total Community Construction	NA	0%	yet not started

Over All Percentage of Completion of Project

19.09%



RAJEEV KUMAR AGARWAL
ARCHITECT CA/88/11915
Seal & Signature of Architect