

Annexure A

Architect's Certificate		
Report for quarter ending		Dec 2025
Subject		Certificate of progress of construction work
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans	
	Sr. No.	Particulars
		Information
	1.	Project/Phase of the project
		Indiabulls Estate & Club-I
	2.	Location
		Sector 104 - Gurugram
	3.	Licensed area in acres
		34.0229 (Total Plot Area)
	4.	Area for registration in acres
		11.6211
	5.	HARERA registration no.
		RC/REP/HARERA/GGM/897/629/2024/124
	6.	Name of licensee
		License No. 246/2007, 56/2011, 37/2012, 66/2012, 67/2012, 43/2014 & 44/2014
	7.	Name of collaborator
		M/s. Juventus Estate Limited
	8.	Name of developer
		M/s. Indiabulls Pharmacare Limited
2.	Details related to inspection are as under	
	1.	Date of certifying of percentage of construction work/ site inspection
		10 th Jan 2026
	2.	Name of Architect/ Architect's firm
		For M/S _____
	3.	Date of site inspection
		10 th Jan 2026

Ar. Ravinder Kumar
CA/2012/55971
Mob.: 9871004573

Annexure A

3.	Following technical professionals are appointed by promoter: - (as applicable)		
	Sr. No.	Consultants	Name
	1.	Site engineer	Mr. Hemant Garg
	2.	Structural consultant	Baldrige & Associates Structural Engineering Pvt. Ltd.
	3.	Proof consultant	Thornton Tomasetti India LLP
	4.	MEP consultant	AEON Integrated Building Design Consultants LLP
	5.	Site in charge	Mr. Hemant Garg
4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.		
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.		

Date	10 th Jan 2026	Yours faithfully,
Place	: Gurugram	
Council of architects (CoA) registration no.	:	
Council of architects (CoA) registration valid till (date)	:	

Ar. Ravinder Kumar
CA/2012/55971
Mob.: 9871004573

Table – A

Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		1		
A1	Cumulative progress of the project/phase at the end of the quarter.			
Sr. No.	Project components	Work done value during the quarter (Lac)	Cumulative work done value till date (Lac)	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	28	332	1.75%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	0	0	0%
3.	MEP			
	3.1 Mechanical (lifts, ventilation, etc.)	0	0	0%
	3.2 Electrical (conduiting, wiring, fixtures, etc.)	0	0	0%
	3.3 Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0	0	0%
4.	Finishing			
	4.1 Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0	0	0%
	4.2 External (plaster, painting, facade, etc.)	0	0	0%

Ar. Ravinder Kumar
CA/2012/55971
Mob.: 9871004573

Ar. Ravinder Kumar
CA/2012/55971
Mob.: 9871004573

Annexure A

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		WIP		35%	
2.	Laying of foundation					
	(i)	Raft	Yet to start		0%	
	(ii)	Pile	Yet to start		4%	
3.	Number of basement(s)					
	(i)	Basement Level 1			12%	
	(ii)	Basement level 2			12%	
	(iii)	Basement level 3			N/A	
4.	Waterproofing of the above sub-structure (wherever applicable)				0%	
	Super-Structure Status					
5.	Total floors in the tower/ building				0%	
6.	Total area on each floor				0%	
7.	Stilt floor/ ground floor				0%	
8.	Status of laying of slabs floor wise				0%	
	Cumulative number of slabs in the building/ tower 1B laid by end of quarter				0%	
9.	Status of construction					
	(i)	Walls on floors			0%	
	(ii)	Staircase			0%	
	(iii)	Lift wells along with water proofing			0%	
	(iv)	Lift lobbies/ common areas floor wise			0%	
10.	Fixing of door and window frames in flats/ units				0%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works			0%	
	(ii)	Electrical works including wiring			0%	
	(iii)	Plumbing works			0%	
12.	Status of wall plastering					
	(i)	External plaster			0%	
	(ii)	Internal plaster			0%	
13.	Status of wall tiling				0%	
	(i)	In bathroom				

Ar. Ravinder Kumar
CA/2012/55971
Mob : 9871004

Ar. Ravinder Kumar
CA/2012/55971
Mob.: 9871004573

Annexure A

	(ii)	In kitchen		0%
14.		Status of flooring		
	(i)	Common areas		0%
	(ii)	Units/ flats		0%
15.		Status of white washing		
	(i)	Internal walls		0%
	(ii)	External walls		0%
16.		Status of finishing		
	(i)	Staircase with railing		0%
	(ii)	Lift wells		0%
	(iii)	Lift lobbies/ common areas floor wise		0%
17.		Status of installation		
		(within flat/unit)		
	(i)	Doors and windows panels		0%
	(ii)	Sanitary fixtures		0%
	(iii)	Modular kitchen		0%
	(iv)	Electrical fittings/ lighting		0%
	(v)	Gas piping (if any)		0%
		(other than flat/units)		
	(vi)	Lifts installation		0%
	(vii)	Overhead tanks		0%
	(viii)	Underground water tank		0%
	(ix)	Firefighting fitting and equipment's as per CFO NOC		0%
	(x)	Electrical fittings in common areas		0%
	(xi)	Compliance to conditions of environment/ CRZ NOC		0%
18.		Waterproofing of terraces		0%
19.		Entrance lobby finishing		0%
20.		Status of construction of compound wall		0%

Note: (*) extend rows as per requirement.

Ar. Ravinder Kumar
CA/2012/55971
Mob.: 9871004573

Table – A				
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			2	
A1	Cumulative progress of the project/phase at the end of the quarter.			
Sr. No.	Project components	Work done value during the quarter (Lac)	Cumulative work done value till date (Lac)	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	26	312	1.75%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	0	0	0%
3.	MEP			
3.1	Mechanical (lifts, ventilation, etc.)	0	0	0%
3.2	Electrical (conduiting, wiring, fixtures, etc.)	0	0	0%
3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0	0	0%
4.	Finishing			
4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0	0	0%
4.2	External (plaster, painting, facade, etc.)	0	0	0%

Ar. Ravinder Kumar
CA/2012/55971
Mob.: 9871004573

Annexure A

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		WIP		35%	
2.	Laying of foundation					
	(iii)	Raft	Yet to start		0%	
	(iv)	Pile	Yet to start		4%	
3.	Number of basement(s)					
	(iv)	Basement Level 1			12%	
	(v)	Basement level 2			12%	
	(vi)	Basement level 3			N/A	
4.	Waterproofing of the above sub-structure (wherever applicable)				0%	
	Super-Structure Status					
5.	Total floors in the tower/ building				0%	
6.	Total area on each floor				0%	
7.	Stilt floor/ ground floor				0%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower 1B laid by end of quarter				0%	
9.	Status of construction					
	(v)	Walls on floors			0%	
	(vi)	Staircase			0%	
	(vii)	Lift wells along with water proofing			0%	
	(viii)	Lift lobbies/ common areas floor wise			0%	
10.	Fixing of door and window frames in flats/ units				0%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(iv)	Mechanical works			0%	
	(v)	Electrical works including wiring			0%	
	(vi)	Plumbing works			0%	
12.	Status of wall plastering					
	(iii)	External plaster			0%	
	(iv)	Internal plaster			0%	
13.	Status of wall tiling					
	(iii)	In bathroom			0%	

Annexure A

	(iv)	In kitchen		0%
14.		Status of flooring		
	(iii)	Common areas		0%
	(iv)	Units/ flats		0%
15.		Status of white washing		
	(iii)	Internal walls		0%
	(iv)	External walls		0%
16.		Status of finishing		
	(iv)	Staircase with railing		0%
	(v)	Lift wells		0%
	(vi)	Lift lobbies/ common areas floor wise		0%
17.		Status of installation		
		(within flat/unit)		
	(xii)	Doors and windows panels		0%
	(xiii)	Sanitary fixtures		0%
	(xiv)	Modular kitchen		0%
	(xv)	Electrical fittings/ lighting		0%
	(xvi)	Gas piping (if any)		0%
		(other than flat/units)		
	(xvii)	Lifts installation		0%
	(xviii)	Overhead tanks		0%
	(xix)	Underground water tank		0%
	(xx)	Firefighting fitting and equipment's as per CFO NOC		0%
	(xxi)	Electrical fittings in common areas		0%
	(xxii)	Compliance to conditions of environment/ CRZ NOC		0%
18.		Waterproofing of terraces		0%
19.		Entrance lobby finishing		0%
20.		Status of construction of compound wall		0%

Note: (*) extend rows as per requirement.

Ar. Ravinder Kumar
CA/2012/55971
Mob.: 9871004573

Table – A				
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		3		
A1	Cumulative progress of the project/phase at the end of the quarter.			
Sr. No.	Project components	Work done value during the quarter (lac)	Cumulative work done value till date (lac)	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	28	332	1.75%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	0	0	0%
3.	MEP			
	3.1 Mechanical (lifts, ventilation, etc.)	0	0	0%
	3.2 Electrical (conduiting, wiring, fixtures, etc.)	0	0	0%
	3.3 Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0	0	0%
4.	Finishing			
	4.1 Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0	0	0%
	4.2 External (plaster, painting, facade, etc.)	0	0	0%
Ar. Ravinder Kumar CA/2012/55971 Mob.: 9871004573				

Annexure A

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		WIP		35%	
2.	Laying of foundation					
	(v)	Raft	Yet to start		0%	
	(vi)	Pile	Yet to start		7%	
3.	Number of basement(s)					
	(vii)	Basement Level 1			12%	
	(viii)	Basement level 2			12%	
	(ix)	Basement level 3			N/A	
4.	Waterproofing of the above sub-structure (wherever applicable)				0%	
	Super-Structure Status					
5.	Total floors in the tower/ building				0%	
6.	Total area on each floor				0%	
7.	Stilt floor/ ground floor				0%	
8.	Status of laying of slabs floor wise				0%	
	Cumulative number of slabs in the building/ tower 1B laid by end of quarter				0%	
9.	Status of construction					
	(ix)	Walls on floors			0%	
	(x)	Staircase			0%	
	(xi)	Lift wells along with water proofing			0%	
	(xii)	Lift lobbies/ common areas floor wise			0%	
10.	Fixing of door and window frames in flats/ units				0%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(vii)	Mechanical works			0%	
	(viii)	Electrical works including wiring			0%	
	(ix)	Plumbing works			0%	
12.	Status of wall plastering					
	(v)	External plaster			0%	
	(vi)	Internal plaster			0%	
13.	Status of wall tiling					
	(v)	In bathroom			0%	

Ar. Ravinder Kumar
CA/2012/55971
Mob.: 9871004579

Ar. Ravinder Kumar
CA/2012/55971
Mob.: 9871004573

Annexure A

	(vi)	In kitchen		0%
14.		Status of flooring		
	(v)	Common areas		0%
	(vi)	Units/ flats		0%
15.		Status of white washing		
	(v)	Internal walls		0%
	(vi)	External walls		0%
16.		Status of finishing		
	(vii)	Staircase with railing		0%
	(viii)	Lift wells		0%
	(ix)	Lift lobbies/ common areas floor wise		0%
17.		Status of installation		
		(within flat/unit)		0%
	(xxiii)	Doors and windows panels		0%
	(xxiv)	Sanitary fixtures		0%
	(xxv)	Modular kitchen		0%
	(xxvi)	Electrical fittings/ lighting		0%
	(xxvi)	Gas piping (if any)		0%
		(other than flat/units)		0%
	(xxvi)	Lifts installation		0%
	(xxix)	Overhead tanks		0%
	(xxx)	Underground water tank		0%
	(xxxi)	Firefighting fitting and equipment's as per CFO NOC		0%
	(xxxi)	Electrical fittings in common areas		0%
	(xxxi)	Compliance to conditions of environment/ CRZ NOC		0%
18.		Waterproofing of terraces		0%
19.		Entrance lobby finishing		0%
20.		Status of construction of compound wall		0%

Note: (*) extend rows as per requirement.

Ar. Ravinder Kumar
CA/2012/55971
Mob.: 9871004573