

Architect's Certificate		
Report for quarter ending		31st December 2024
Subject		Certificate of progress of construction work
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans	
Sr. No.	Particulars	Information
1.	Project/Phase of the project	WATERFALL RESIDENCE / PHASE-1
2.	Location	SECTOR-36A, MANESAR GURUGRAM
3.	Licensed area in acres	25.10 Acres
4.	Area for registration in acres	5.4375 Acres
5.	HARERA registration no.	- RC/REP/HARERA/GGM/2018/03 dated 08.05.2018 - RC/EXT./2024/16 dated 30.07.2024
6.	Name of licensee	KRISUMI CORPORATION PRIVATE LIMITED
7.	Name of collaborator	Not applicable
8.	Name of developer	KRISUMI CORPORATION PRIVATE LIMITED
2.	Details related to inspection are as under	
1.	Date of certifying of percentage of construction work/ site inspection	31st December 2024
2.	Name of Architect/ Architect's firm	Ar.Krishna Kumar Sharma
3.	Date of site inspection	07.01.2025


 Ar. (E.) Krishna Kumar Sharma
 B Arch, B.Tech (Civil), AMIE (Civil)
 Chartered Engineer (India)
 IOV-Registered Valuer
 Reg No.-CA/2022/149900

3.	Following technical professionals are appointed by promoter: - (as applicable)		
	Sr. No.	Consultants	Name
	1.	Site engineer	MR. PRATAP KUMAR PATRO
	2.	Structural consultant	M/S PERCEPTIVE IDEAS CONSULTING ENGINEERS PRIVATE LIMITED
	3.	Proof consultant	M/s Isha Consultants (P) Ltd
	4.	MEP consultant	M/S THINKBIM TECHNICAL SERVICES PVT LTD.
	5.	Site supervisor/in charge	MR. PRATAP KUMAR PATRO
4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.		
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.		

Date:07.01.2025

Place: Gurgaon


 Yours faithfully,
Ar. (Er.) Krishna Kumar Sharma
 B Arch, B.Tech (Civil), AMIE (Civil)
 Chartered Engineer (India)
 IOV-Registered Valuer
 Reg No.-CA/2022/149900
(Ar.Krishna Kumar Sharma)


Council of architects (CoA) :
registration no. **CA/2022/149900**

Council of architects (CoA) :
registration valid till (date)


Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			Tower A		
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (Inclusive of excavation, foundation, basements, water proofing, etc.)		NIL	Rs. 7.13 Crore	100%
2.	Super structure (Slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		Rs. 0.01 Crore	Rs. 22.73 Crore	100%
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	Rs. 1.09 Crore	Rs. 8.11 Crore	100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	Rs. 0.00 Crore	Rs. 4.67 Crore	100%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	Rs. 0.02 Crore	Rs. 4.30 Crore	100%
4.	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	Rs. 3.44 Crore	Rs. 15.10 Crore	100%
	4.2	External (plaster, painting, facade, etc.)	Rs. 3.84 Crore	Rs. 8.65 Crore	100%
Ar. (Er.) Krishna Kumar Sharma B Arch, B Tech (Civil), M Eng (Struct)					


Ar. (Er.) Krishna Kumar Sharma
B.Arch, B.Tech (Civil), AMIE (Civil)
 Chartered Engineer (India)
 IOV-Registered Valuer
 Reg No.-CA/2022/149900


Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation				100%	
2.	Laying of foundation					
	(i)	Raft			100%	
	(ii)	Pile				
3.	Number of basement(s)				02 Nos	
	(i)	Basement Level 1			100%	
	(ii)	Basement level 2*			100%	
4.	Waterproofing of the above sub-structure (wherever applicable)				100%	
	Super-Structure Status					
5.	Total floors in the tower/ building				Tower A – G+24	
6.	Total area on each floor				Tower A – 1527 Sqm	
7.	Stilt floor/ ground floor				100%	
8.	Status of laying of slabs floor wise				100%	
	Cumulative number of slabs in the building/ tower A ..laid by end of quarter				24	
9.	Status of construction					
	(i)	Walls on floors			100%	
	(ii)	Staircase			100%	
	(iii)	Lift wells along with water proofing			100%	
	(iv)	Lift lobbies/ common areas floor wise			100%	
10.	Fixing of door and window frames in flats/ units				100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works			100%	
	(ii)	Electrical works including wiring			100%	
	(iii)	Plumbing works			100%	
12.	Status of wall plastering					
	(i)	External plaster			100%	
	(ii)	Internal plaster			100%	
13.	Status of wall tiling					
	(i)	In bathroom			100%	
	(ii)	In kitchen			100%	
14.	Status of flooring					
	(i)	Common areas			100%	
	(ii)	Units/ flats			100%	


 Ar. (Er.) Krishna Kumar Sharma
 B.Arch, B.Tech (Civil), AMIE (Civil)
 Chartered Engineer (India)
 IOV-Registered Valuer
 Reg No.-CA/2022/149900

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls		100%
	(ii)	External walls		100%
16.	Status of finishing			
	(i)	Staircase with railing		100%
	(ii)	Lift wells		100%
	(iii)	Lift lobbies/ common areas floor wise		100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels		100%
	(ii)	Sanitary fixtures		100%
	(iii)	Modular kitchen		100%
	(iv)	Electrical fittings/ lighting		100%
	(v)	Gas piping (if any)		100%
	(other than flat/units)			
	(vi)	Lifts installation		100%
	(vii)	Overhead tanks		100%
	(viii)	Underground water tank		100%
	(ix)	Firefighting fitting and equipment's as per CFO NOC		100%
	(x)	Electrical fittings in common areas		100%
	(xi)	Compliance to conditions of environment/ CRZ NOC		100%
18.	Waterproofing of terraces			100%
19.	Entrance lobby finishing			100%
20.	Status of construction of compound wall		Shang	100%



Ar. (E.T.) Krishna Kumar Sharma
 B Arch, B.Tech (Civil), AMIE (Civil)
 Chartered Engineer (India)
 IOV-Registered Valuer
 Reg No.-CA/2022/149900


Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			Tower B		
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		NIL	Rs. 7.13 Crore	100%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		Rs. 0.02 Crore	Rs. 25.94 Crore	100%
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	Rs. 2.84 Crore	Rs. 9.26 Crore	100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	Rs. 0.11 Crore	Rs. 5.33 Crore	100%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	Rs. 0.30 Crore	Rs. 4.90 Crore	100%
4.	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	Rs. 7.05 Crore	Rs. 17.23 Crore	100%
	4.2	External (plaster, painting, facade, etc.)	Rs. 4.96 Crore	Rs. 9.87 Crore	100%
Sharma					


Ar. (Er.) Krishna Kumar Sharma
B Arch, B.Tech (Civil), AMIE (Civil)
Chartered Engineer (India)
IOV-Registered Valuer
Reg No.-CA/2022/149900

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation				100%	
2.	Laying of foundation					
	(i)	Raft			100%	
	(ii)	Pile				
3.	Number of basement(s)				02 Nos	
	(i)	Basement Level 1			100%	
	(ii)	Basement level 2*			100%	
4.	Waterproofing of the above sub-structure (wherever applicable)				100%	
	Super-Structure Status					
5.	Total floors in the tower/ building				Tower B – G+27	
6.	Total area on each floor				Tower B – 1527 Sqm	
7.	Stilt floor/ ground floor				100%	
8.	Status of laying of slabs floor wise				100%	
	Cumulative number of slabs in the building/ tower B ..laid by end of quarter				27	
9.	Status of construction					
	(i)	Walls on floors			100%	
	(ii)	Staircase			100%	
	(iii)	Lift wells along with water proofing			100%	
	(iv)	Lift lobbies/ common areas floor wise			100%	
10.	Fixing of door and window frames in flats/ units				100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works			100%	
	(ii)	Electrical works including wiring			100%	
	(iii)	Plumbing works			100%	
12.	Status of wall plastering					
	(i)	External plaster			100%	
	(ii)	Internal plaster			100%	
13.	Status of wall tiling					
	(i)	In bathroom			100%	
	(ii)	In kitchen			100%	
14.	Status of flooring					
	(i)	Common areas			100%	
	(ii)	Units/ flats	Sharma		100%	



Ar. (E.T.) Krishna Kumar Sharma
 B Arch, B.Tech (Civil), AMIE (Civil)
 Chartered Engineer (India)
 IOV-Registered Valuer
 Reg No.-CA/2022/149900

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls		100%
	(ii)	External walls		100%
16.	Status of finishing			
	(i)	Staircase with railing		100%
	(ii)	Lift wells		100%
	(iii)	Lift lobbies/ common areas floor wise		100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels		100%
	(ii)	Sanitary fixtures		100%
	(iii)	Modular kitchen		100%
	(iv)	Electrical fittings/ lighting		100%
	(v)	Gas piping (if any)		100%
	(other than flat/units)			
	(vi)	Lifts installation		100%
	(vii)	Overhead tanks		100%
	(viii)	Underground water tank		100%
	(ix)	Firefighting fitting and equipment's as per CFO NOC		100%
	(x)	Electrical fittings in common areas		100%
	(xi)	Compliance to conditions of environment/ CRZ NOC		100%
18.	Waterproofing of terraces			100%
19.	Entrance lobby finishing			100%
20.	Status of construction of compound wall		Ar. (Er.) Krishna Kumar Sharma	100%


Ar. (Er.) Krishna Kumar Sharma
 B.Arch., B.Tech (Civil), AMIE (Civil)
 Chartered Engineer (India)
 IOV-Registered Valuer
 Reg No.-CA/2022/149900

Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			Tower C		
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		NIL	Rs. 8.10 Crore	100%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		Rs. 1.25 Crore	Rs. 36.96 Crore	100%
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	Rs. 5.16 Crore	Rs. 13.19 Crore	100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	Rs. 0.09 Crore	Rs. 7.50 Crore	100%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	Rs. 0.01 Crore	Rs. 6.99 Crore	100%
4.	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	Rs. 5.80 Crore	Rs. 24.55 Crore	100%
	4.2	External (plaster, painting, facade, etc.)	Rs. 7.83 Crore	Rs. 14.07 Crore	100%

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation				100%	
2.	Laying of foundation					
	(i)	Raft			100%	
	(ii)	Pile				
3.	Number of basement(s)				02 Nos	
	(i)	Basement Level 1			100%	
	(ii)	Basement level 2*			100%	
4.	Waterproofing of the above sub-structure (wherever applicable)				100%	
	Super-Structure Status					
5.	Total floors in the tower/ building				Tower C – G+34	
6.	Total area on each floor				Tower C – 1868 Sqm	
7.	Stilt floor/ ground floor				100%	
8.	Status of laying of slabs floor wise				100%	
	Cumulative number of slabs in the building/ tower C ..laid by end of quarter				34	
9.	Status of construction					
	(i)	Walls on floors			100%	
	(ii)	Staircase			100%	
	(iii)	Lift wells along with water proofing			100%	
	(iv)	Lift lobbies/ common areas floor wise			100%	
10.	Fixing of door and window frames in flats/ units				100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works			100%	
	(ii)	Electrical works including wiring			100%	
	(iii)	Plumbing works			100%	
12.	Status of wall plastering					
	(i)	External plaster			100%	
	(ii)	Internal plaster			100%	
13.	Status of wall tiling					
	(i)	In bathroom			100%	
	(ii)	In kitchen			100%	
14.	Status of flooring					
	(i)	Common areas			100%	
	(ii)	Units/ flats			100%	


Ar. (Er.) Krishna Kumar Sharma
 B.Arch, B.Tech (Civil), AMIE (Civil)
 Chartered Engineer (India)
 IOV-Registered Valuer
 Reg No.-CA/2022/149900

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls		100%
	(ii)	External walls		100%
16.	Status of finishing			
	(i)	Staircase with railing		100%
	(ii)	Lift wells		100%
	(iii)	Lift lobbies/ common areas floor wise		100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels		100%
	(ii)	Sanitary fixtures		100%
	(iii)	Modular kitchen		100%
	(iv)	Electrical fittings/ lighting		100%
	(v)	Gas piping (if any)		100%
	(other than flat/units)			
	(vi)	Lifts installation		100%
	(vii)	Overhead tanks		100%
	(viii)	Underground water tank		100%
	(ix)	Firefighting fitting and equipment's as per CFO NOC		100%
	(x)	Electrical fittings in common areas		100%
	(xi)	Compliance to conditions of environment/ CRZ NOC		100%
18.	Waterproofing of terraces			100%
19.	Entrance lobby finishing			100%
20.	Status of construction of compound wall		Ar. (Er.) Krishna Kumar Sharma	100%



 Ar. (Er.) Krishna Kumar Sharma
 B Arch, B.Tech (Civil), AMIE (Civil)
 Chartered Engineer (India)
 IOV-Registered Valuer
 Reg No.-CA/2022/149900

Table – B				
Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services			
1.	Internal roads & pavements	YES	100%	
2.	Parking			
	Covered no. 663	YES	100%	
	Open no. 97	YES	100%	
	Under Stilt no. 33	YES	100%	
3.	Water supply	YES	100%	
4.	Sewerage (chamber, lines, septic tanks, STP)	YES	100%	
5.	Storm water drains	YES	100%	
6.	Landscaping & tree plantation	YES	100%	
7.	Parks and playgrounds	YES	0%	
	Fixing of children play equipment's	NO	NA	Children's Play area proposed
	Benches	YES	0%	
8.	Shopping area	YES	100%	
9.	Street lighting/ electrification	YES	100%	
10.	Treatment and disposal of sewage and sullage water/ STP	YES	100%	
11.	Solid waste management & disposal	YES	100%	
12.	Water conservation, rain water, harvesting, percolating well/ pit	YES	100%	
13.	Energy management (solar)	YES	100%	
14.	Fire protection and fire safety requirements	YES	100%	
15.	Electrical meter room, sub-station, receiving station	YES	100%	
B-2	Community building to be transferred to RWA			
17.	Community Centre	YES	100%	
18.	Others	YES	0%	
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	NO		
20.	Dispensary	NO		
21.	Club	NO		
22.	Others	NO		
B-4	Services/ facilities to be transferred to competent authority			
23.	*			

Note: (*) extend as per requirement


 Ar. (Er.) Krishna Kumar Sharma
 B Arch, B.Tech (Civil), AMIE (Civil)
 Chartered Engineer (India)
 IOV-Registered Valuer
 Reg No.-CA/2022/149900