

DEEPAK VASHISHTHA

Architect's Certificate

As on Date	31.03.2025	
Subject	Certificate of progress of construction work	
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans	
	Sr. No.	Particulars
	Information	
	1.	Project/Phase of the project
	2.	Location
	3.	Licensed area in acres
	4.	Area for registration in acres
	5.	HARERA registration no.
	6.	Name of licensee
	7.	Name of collaborator
2.	Details related to inspection are as under	
	1.	Date of certifying of percentage of construction work/ site inspection
	2.	Name of Architect/ Architect's firm
	3.	Date of site inspection


Deepak Vashista
CA/2003/32557

3.	Following technical professionals are appointed by promoter: - (as applicable)		
	Sr. No.	Consultants	Name
	1.	Site engineer	Mr. Subhit Nirankari
	2.	Structural consultant	Mr. Ramphool Bairwa
	3.	Proof consultant	Mr. Ramphool Bairwa
	4.	MEP consultant	Mr. Davinder Bajaj
	5.	Site supervisor/in charge	Mr. Rahul Bhatnagar
4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.		
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.		

Date 08.04.2025

Yours faithfully,


Deepak Vashista
CA/2003/32557

Place: New Delhi

Signature & name (in block letters) with
stamp of architect

Council of architects (CoA) :
Registration no.

Council of architects (CoA) :
Registration valid till (date)

Physical Progress for Tower wise- T-8 as on date 31.03.2025

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total	
	Sub-Structure Status					
1.	Excavation		Completed		100%	
2.	Laying of foundation					
	(i)	Raft	Completed		100%	
	(ii)	Pile	N/A			
3.	Number of basement(s)					
	(i)	Basement Level 1	Completed		100%	
	(ii)	Basement level 2*	N/A			
4.	Waterproofing of the above sub-structure (wherever applicable)		Completed		100%	
	Super-Structure Status					
5.	Total floors in the tower/ building		B+G+19 Floor		100%	
6.	Total area on each floor		605.68		100%	
7.	Stilt floor/ ground floor		627.54		100%	
8.	Status of laying of slabs floor wise		Completed		100%	
	Slab Works		Completed		100%	
9.	Status of construction					
	(i)	Walls on floors	Completed		100%	
	(ii)	Staircase	Completed		100%	
	(iii)	Lift wells along with water proofing	Completed		100%	
	(iv)	Lift lobbies/ common areas floor wise	Completed		100%	
10.	Fixing of door and window frames in flats/ units		Completed		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flats)	External works
	(i)	Mechanical works	Completed		100%	
	(ii)	Electrical works including wiring	Completed		100%	

	(iii)	Plumbing works	Completed	100%
12.	Status of wall plastering			
	(i)	External plaster	Completed	100%
	(ii)	Internal plaster	Completed	100%
13.	Status of wall tiling			
	(i)	In bathroom	Completed	100%
	(ii)	In kitchen	Completed	100%
14.	Status of flooring			
	(i)	Common areas	Completed	100%
	(ii)	Units/ flats	Completed	100%
15.	Status of white washing			
	(i)	Internal walls	Completed	100%
	(ii)	External walls	Completed	100%
16.	Status of finishing			
	(i)	Staircase with railing	Completed	100%
	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Completed	100%
	(ii)	Sanitary fixtures	98 units fixed out of 119 units	82%
	(iii)	Modular kitchen	N/A	
	(iv)	Electrical fittings/ lighting	100 units fixed out of 119 units	92%
	(v)	Gas piping (if any)	N/A	
	(other than flat/units)			
	(vi)	Lifts installation	Completed	100%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	Completed	100%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Yes	
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Yes	
18.	Waterproofing of terraces		Completed	100%

19.	Entrance lobby finishing	Completed	100%
20.	Status of construction of compound wall	Completed	100%



Deepak Vashista
CA/2003/32557

Physical Progress for Tower wise- T-9 as on 31.03.2025

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total	
	Sub-Structure Status					
1.	Excavation		Completed		100%	
2.	Laying of foundation					
	(i)	Raft	Completed		100%	
	(ii)	Pile	N/A			
3.	Number of basement(s)					
	(i)	Basement Level 1	Completed		100%	
	(ii)	Basement level 2*	N/A			
4.	Waterproofing of the above sub-structure (wherever applicable)		Completed		100%	
	Super-Structure Status					
5.	Total floors in the tower/ building		B+G+19 Floor		100%	
6.	Total area on each floor		605.68		100%	
7.	Stilt floor/ ground floor		627.84		100%	
8.	Status of laying of slabs floor wise		Completed		100%	
	Slab Works		Completed		100%	
9.	Status of construction					
	(i)	Walls on floors	Completed		100%	
	(ii)	Staircase	Completed		100%	
	(iii)	Lift wells along with water proofing	Completed		100%	
	(iv)	Lift lobbies/ common areas floor wise	Completed		100%	
10.	Fixing of door and window frames in flats/ units					
11.	Status of MEP		Internal (within flat)	External works	Internal (within flats)	External works
	(i)	Mechanical works	Completed		100%	
	(ii)	Electrical works including wiring	Completed		100%	
	(iii)	Plumbing works	Completed		100%	

12.	Status of wall plastering			
	(i)	External plaster	Completed	100%
	(ii)	Internal plaster	Completed	100%
13.	Status of wall tiling			
	(i)	In bathroom	Completed	100%
	(ii)	In kitchen	Completed	100%
14.	Status of flooring			
	(i)	Common areas	Completed	100%
	(ii)	Units/ flats	Completed	100%
15.	Status of white washing			
	(i)	Internal walls	Completed	100%
	(ii)	External walls	Completed	100%
16.	Status of finishing			
	(i)	Staircase with railing	Completed	100%
	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Completed	100%
	(ii)	Sanitary fixtures	98 units fixed out of 118 units	85%
	(iii)	Modular kitchen	N/A	
	(iv)	Electrical fittings/ lighting	99 units fixed out of 118 units	86%
	(v)	Gas piping (if any)	N/A	
	(other than flat/units)			
	(vi)	Lifts installation	Completed	100%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	Completed	100%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Yes	
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Yes	
18.	Waterproofing of terraces		Completed	100%
19.	Entrance lobby finishing		Completed	100%

20.	Status of construction of compound wall	Completed	100%
-----	---	-----------	------



Deepak Ashista
CA/2003/32557

Progress for Tower wise- T-10 as on 31.03.2025

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total		
	Sub-Structure Status					
1.	Excavation		Completed	100%		
2.	Laying of foundation					
	(i)	Raft	Completed	100%		
	(ii)	Pile	N/A			
3.	Number of basement(s)					
	(i)	Basement Level 1	Completed	100%		
	(ii)	Basement level 2*	N/A			
4.	Waterproofing of the above sub-structure (wherever applicable)		Completed	100%		
	Super-Structure Status					
5.	Total floors in the tower/ building		B+G+19 Floor	100%		
6.	Total area on each floor		606.08	100%		
7.	Stilt floor/ ground floor		627.54	100%		
8.	Status of laying of slabs floor wise		Completed	100%		
	Slab Works		Completed	100%		
9.	Status of construction					
	(i)	Walls on floors	Completed	100%		
	(ii)	Staircase	Completed	100%		
	(iii)	Lift wells along with water proofing	Completed	100%		
	(iv)	Lift lobbies/ common areas floor wise	Completed	100%		
10.	Fixing of door and window frames in flats/ units		Completed			
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Completed		100%	
	(ii)	Electrical works including wiring	Completed		100%	
	(iii)	Plumbing works	Completed		100%	

12.	Status of wall plastering			
	(i)	External plaster	Completed	100%
	(ii)	Internal plaster	Completed	100%
13.	Status of wall tiling			
	(i)	In bathroom	Completed	100%
	(ii)	In kitchen	Completed	100%
14.	Status of flooring			
	(i)	Common areas	Completed	100%
	(ii)	Units/ flats	Completed	100%
15.	Status of white washing			
	(i)	Internal walls	Completed	100%
	(ii)	External walls	Completed	100%
16.	Status of finishing			
	(i)	Staircase with railing	Completed	100%
	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Completed	100%
	(ii)	Sanitary fixtures	98 units fixed out of 119 units	81%
	(iii)	Modular kitchen	N/A	
	(iv)	Electrical fittings/ lighting	99 units fixed out of 119 units	86%
	(v)	Gas piping (if any)	N/A	
	(other than flat/units)			
	(vi)	Lifts installation	Completed	100%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	Completed	100%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Yes	
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Yes	
18.	Waterproofing of terraces		Completed	100%
19.	Entrance lobby finishing		Completed	100%

20.	Status of construction of compound wall	Completed	100%
-----	---	-----------	------



Deepak Ashista
CA/2003/32557

Progress for Tower wise- T-11 as on 31.03.2025

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total	
	Sub-Structure Status					
1.	Excavation		Completed		100%	
2.	Laying of foundation					
	(i)	Raft	Completed		100%	
	(ii)	Pile	N/A			
3.	Number of basement(s)					
	(i)	Basement Level 1	Completed		100%	
	(ii)	Basement level 2*	N/A			
4.	Waterproofing of the above sub-structure (wherever applicable)		Completed		100%	
	Super-Structure Status					
5.	Total floors in the tower/ building		B+G+ 19 Floor		100%	
6.	Total area on each floor		605.65		100%	
7.	Stilt floor/ ground floor		627.54		100%	
8.	Status of laying of slabs floor wise		Completed		100%	
	Slab Works		Completed		100%	
9.	Status of construction					
	(i)	Walls on floors	Completed		100%	
	(ii)	Staircase	Completed		100%	
	(iii)	Lift wells along with water proofing	Completed		100%	
	(iv)	Lift lobbies/ common areas floor wise	Completed		100%	
10.	Fixing of door and window frames in flats/ units		Completed		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Completed		100%	
	(ii)	Electrical works including wiring	Completed		100%	
	(iii)	Plumbing works	Completed		100%	

12.	Status of wall plastering		Completed	100%
	(i)	External plaster	Completed	100%
	(ii)	Internal plaster	Completed	100%
13.	Status of wall tiling			
	(i)	In bathroom	Completed	100%
	(ii)	In kitchen	Completed	100%
14.	Status of flooring			
	(i)	Common areas	Completed	100%
	(ii)	Units/ flats	Completed	100%
15.	Status of white washing			
	(i)	Internal walls	Completed	100%
	(ii)	External walls	Completed	100%
16.	Status of finishing			
	(i)	Staircase with railing	Completed	100%
	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Completed	100%
	(ii)	Sanitary fixtures	99 units fixed out of 119 units	87%
	(iii)	Modular kitchen	N/A	
	(iv)	Electrical fittings/ lighting	100 units fixed out of 119 units	89%
	(v)	Gas piping (if any)	N/A	
	(other than flat/units)			
	(vi)	Lifts installation	Completed	100%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	Completed	100%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Yes	
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Yes	
18.	Waterproofing of terraces		Completed	100%
19.	Entrance lobby finishing		Completed	100%

20.	Status of construction of compound wall	Completed	100%
-----	---	-----------	------



Deepak Ashista
CA/2003/32557

Progress for Tower wise- T-12 as on 31.03.2025

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total		
	Sub-Structure Status					
1.	Excavation		Completed	100%		
2.	Laying of foundation					
	(i)	Raft	Completed	100%		
	(ii)	Pile	N/A			
3.	Number of basement(s)					
	(i)	Basement Level 1	Completed	100%		
	(ii)	Basement level 2*	N/A			
4.	Waterproofing of the above sub-structure (wherever applicable)		Completed	100%		
	Super-Structure Status					
5.	Total floors in the tower/ building		B+G+19 Floor	100%		
6.	Total area on each floor		606.08	100%		
7.	Stilt floor/ ground floor		627.54	100%		
8.	Status of laying of slabs floor wise		Completed	100%		
	Slab Works		Completed	100%		
9.	Status of construction					
	(i)	Walls on floors	Completed	100%		
	(ii)	Staircase	Completed	100%		
	(iii)	Lift wells along with water proofing	Completed	100%		
	(iv)	Lift lobbies/ common areas floor wise	Completed	100%		
10.	Fixing of door and window frames in flats/ units		Completed	100%		
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Completed		100%	
	(ii)	Electrical works including wiring	Completed		100%	
	(iii)	Plumbing works	Completed		100%	

12.	Status of wall plastering			
	(i)	External plaster	Completed	100%
	(ii)	Internal plaster	Completed	100%
13.	Status of wall tiling			
	(i)	In bathroom	Completed	100%
	(ii)	In kitchen	Completed	100%
14.	Status of flooring			
	(i)	Common areas	Completed	100%
	(ii)	Units/ flats	Completed	100%
15.	Status of white washing			
	(i)	Internal walls	Completed	100%
	(ii)	External walls	Completed	100%
16.	Status of finishing			
	(i)	Staircase with railing	Completed	100%
	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Completed	100%
	(ii)	Sanitary fixtures	98 units fixed out of 118 units	84%
	(iii)	Modular kitchen	N/A	
	(iv)	Electrical fittings/ lighting	99 units fixed out of 118 units	85%
	(v)	Gas piping (if any)	N/A	
	(other than flat/units)			
	(vi)	Lifts installation	Completed	100%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	Completed	100%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Yes	
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Yes	
18.	Waterproofing of terraces		Completed	100%
19.	Entrance lobby finishing		Completed	100%

20.	Status of construction of compound wall	Completed	100%
-----	---	-----------	------

Progress for Tower wise- T-13 as on date 31.03.2025

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total
	Sub-Structure Status			
1.	Excavation		Completed	100%
2.	Laying of foundation			
	(i)	Raft	Completed	100%
	(ii)	Pile	N/A	
3.	Number of basement(s)			
	(i)	Basement Level 1	Completed	100%
	(ii)	Basement level 2*	N/A	
4.	Waterproofing of the above sub-structure (wherever applicable)		Completed	100%
	Super-Structure Status			
5.	Total floors in the tower/ building		B+G+19 Floor	100%
6.	Total area on each floor		606.08	100%
7.	Stilt floor/ ground floor		607.54	100%
8.	Status of laying of slabs floor wise		Completed	100%
	Slab Works		Completed	100%
9.	Status of construction			
	(i)	Walls on floors	Completed	100%
	(ii)	Staircase	Completed	100%
	(iii)	Lift wells along with water proofing	Completed	100%
	(iv)	Lift lobbies/ common areas floor wise	Completed	100%
10.	Fixing of door and window frames in flats/ units		Completed	100%

11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Completed		100%	
	(ii)	Electrical works including wiring	Completed		100%	
	(iii)	Plumbing works	Completed		100%	
12.	Status of wall plastering					
	(i)	External plaster	Completed		100%	
	(ii)	Internal plaster	Completed		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Completed		100%	
	(ii)	In kitchen	Completed		100%	
14.	Status of flooring					
	(i)	Common areas	Completed		100%	
	(ii)	Units/ flats	Completed		100%	
15.	Status of white washing					
	(i)	Internal walls	Completed		100%	
	(ii)	External walls	Completed		100%	
16.	Status of finishing					
	(i)	Staircase with railing	Completed		100%	
	(ii)	Lift wells	Completed		100%	
	(iii)	Lift lobbies/ common areas floor wise	Completed		100%	
17.	Status of installation					
	(within flat/unit)					
	(i)	Doors and windows panels	Completed		100%	
	(ii)	Sanitary fixtures	99 units fixed out of 119 units		85%	
	(iii)	Modular kitchen	N/A			
	(iv)	Electrical fittings/ lighting	100 units fixed out of 119 units		88%	
	(v)	Gas piping (if any)	N/A			
	(other than flat/units)					
	(vi)	Lifts installation	Completed		100%	
	(vii)	Overhead tanks	Completed		100%	
	(viii)	Underground water tank	Completed		100%	

	(ix)	Firefighting fitting and equipment's as per CFO NOC	Yes	
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Yes	
18.		Waterproofing of terraces	Completed	100%
19.		Entrance lobby finishing	Completed	100%
20.		Status of construction of compound wall	Completed	100%


 Deepak Vashista
 CA/2003/32557

Physical Progress for Common areas and facilities amenities as on 31.03.2025

Sr. No.	Common areas and facilities amenities	Proposed (Yes/	Percentage of work done	Remarks
B-1	Services			
1.	Internal roads & pavements	Yes	Completed	-
2.	Parking	Yes		-
	Covered no. . . . 801	Yes	Completed	-
	Open no. 267	Yes		-
3.	Water supply	Yes	Completed	-
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	Completed	-
5.	Storm water drains	Yes	Completed	-
6.	Landscaping & tree plantation	Yes	Completed	-
7.	Parks and playgrounds	Yes	Completed	-
	Fixing of children play equipment's	Yes	Completed	-
	Benches	Yes	Completed	-
8.	Shopping area	Yes	Completed	-
9.	Street lighting/ electrification	Yes	Completed	-
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	Completed	-
11.	Solid waste management & disposal	Yes	Completed	-
12.	Water conservation, rain water, harvesting, percolating well/ pit	N/A	N/A	-
13.	Energy management (solar)	N/A	N/A	-
14.	Fire protection and fire safety requirements	Yes	Completed	-
15.	Electrical meter room, sub-station, receiving station	Yes	Completed	-
B-2	Community building to be transferred to RWA			
17.	Community center	N/A	N/A	-
18.	others			-
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	Yes	Completed by 3 rd party	-
20.	Dispensary	Yes	Completed by 3 rd party	-
21.	Club	Yes	Completed	-
22.	Others		N/A	-
B-4	Services/ facilities to be transferred to competent authority	N/A	N/A	-

Note: (*) extend as per requirement


 Deepak Vashista
 CA/2003/32557