

**Nivedita & Uday Pande Consultants***An ISO 9001:2000 Certified Company*ARCHITECTS, ENGINEERS URBAN & REGIONAL PLANNERS &
PROJECT MANAGEMENT CONSULTANTS

B-224, Okhla Industrial Area,

Phase-I, New Delhi – 110020


Tel: +91-11-46818113

Email: nuparch@nupc.net, info@nplusu.in,

Website: www.nplusu.in

Annexure-A

Architect's Certificate			
Report for quarter ending		31st March 2025	
Subject		Certificate of progress of construction work	
1.	I/We have undertaken an assignment as architects for certifying the progress of construction work in the below-mentioned project as per the approved plans		
	Sr. No.	Particulars	Information
	1.	Project/Phase of the project	The Edge Towers (Tower A to G, N & O)
	2.	Location	Ramprastha City, Sector 37D, Teh. Kadipur, Gurugram
	3.	Licensed area in acres	60.511 Acres
	4.	Area for registration in acres	7.57 Acres
	5.	HARERA registration no.	RC No. 279 of 2017 dated 09.10.2017 Extended vide RC No. 279 of 2017/7(3)/2021/5 Dated 20.08.2021
	6.	Name of licensee	• Ramprastha Promoters & Developers Pvt. Ltd. (previously, S.A. Infratech Pvt. Ltd.) • Ramprastha Realtors Pvt. Ltd. • Ramprastha Developers Pvt. Ltd. • Ramprastha Promoters Pvt. Ltd. • S.A. Infracon Pvt. Ltd. • Ramprastha Buildtech Pvt. Ltd. • Ramprastha Township Pvt. Ltd. • B S Y Infrastructure Pvt. Ltd. • B S Y Developers Pvt. Ltd.
	7.	Name of collaborator	Ramprastha Promoters & Developers Pvt. Ltd.
8.	Name of developer	Ramprastha Promoters & Developers Pvt. Ltd.	


UDAY PANDE
Architect-Urban Regional Planner
CA/87/10856-FITP-86/26



2.	Details related to inspection are as under		
	1.	Date of certifying of the percentage of construction work/ site inspection	31/03/2025
	2.	Name of Architect/ Architect's firm	Nivedita and Uday Pande Consultants
	3.	Date of site inspection	31/03/2025
3.	Following technical professionals are appointed by promoter: - (as applicable)		
	Sr. No.	Consultants	Name
	1.	Site engineer	Mr. Suresh Pal
	2.	Structural consultant	Mr. V D Sharma (Optimum Design Pvt. Ltd.)
	3.	Proof consultant	
	4.	MEP consultant	Mr. Tanveer Husain (NUPC)
	5.	Site supervisor/in charge	Mr. Arun Sharma
4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.		
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.		

Date : 31/03/2025

Yours faithfully,

Place : Delhi

Council of architects (CoA) :
registration no.

Council of architects (CoA) : 31/12/2029
registration valid till (date)


UDAY PANDE
Architect-Urban Regional Planner
CA/87/10856-FITP-86/26

Signature & name (in block
letters) with stamp of architect



Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			Tower A		
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		-	534.17	100
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		-	1,740.37	100
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	48.57	710.42	82
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			
4.	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	40.33	749.14	85
	4.2	External (plaster, painting, façade, etc.)			

UDAY PANDE
Architect-Urban Regional Planner
CA/87/10856-FITP-86/26



Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			Tower B		
B1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Substructure (inclusive of excavation, foundation, basements, water proofing, etc.)		-	539.38	100
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		-	1,725.52	100
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	48.57	702.90	78
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			
4.	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	40.33	747.60	77
	4.2	External (plaster, painting, facade, etc.)			


UDAY PANDE
 Architect-Urban Regional Planner
 CA/87/10856-FITP-86/26



Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			Tower C		
C1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		-	449.98	100
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		-	1,461.51	100
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	48.57	618.89	84
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			
4.	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	40.33	634.32	84
	4.2	External (plaster, painting, facade, etc.)			


UDAY PANDE
 Architect-Urban Regional Planner
 CA/87/10856-FITP-86/26



Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		Tower D			
D1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work	
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	-	450.63	100	
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	-	1,475.09	100	
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	48.57	604.12	87
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			
4.	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	40.33	645.11	87
	4.2	External (plaster, painting, facade, etc.)			




Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			Tower E		
E1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		-	407.26	100
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		-	1,330.64	100
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	41.22	761.18	100
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			
4.	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	37.70	772.21	100
	4.2	External (plaster, painting, facade, etc.)			


UDAY PANDE
 Architect-Urban Regional Planner
 CA/87/10856-FITP-86/26




Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			Tower F		
F1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		-	338.66	100
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		-	1,118.50	100
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	41.22	688.03	100
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			
4.	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	37.67	700.08	100
	4.2	External (plaster, painting, facade, etc.)			


UDAY PANDE
 Architect-Urban Regional Planner
 CA/87/10856-FITP-86/26



Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			Tower G		
G1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		-	471.61	100
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		-	1,513.60	100
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	38.82	840.45	100
	3.2	Electrical (conducting, wiring, fixtures, etc.)			
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			
4.	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	36.48	838.46	100
	4.2	External (plaster, painting, facade, etc.)			


UDAY PANDE
 Architect-Urban Regional Planner
 CA/87/10856-FITP-86/26



Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			Tower N		
N1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		-	331.06	100
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		-	1044.12	100
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	-	562.16	100
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			
4.	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	-	611.19	100
	4.2	External (plaster, painting, facade, etc.)			


UDAY PANDE
 Architect-Urban Regional Planner
 CA/87/10856-FITP-86/26



Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			Tower 0		
01	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		-	331.74	100
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		-	1046.25	100
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	-	563.31	100
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			
4.	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	-	612.44	100
	4.2	External (plaster, painting, facade, etc.)			

*The expense for quarter has been apportioned amongst the three towers i.e. Tower E, F & G equally as certain expenditures were common, and it was difficult to apportion them.


UDAY PANDE
 Architect-Urban Regional Planner
 CA/87/10856-FITP-86/26



Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work	
	Sub-Structure Status				
1.	Excavation		General Excavation	Completed	
2.	Laying of foundation				
	(i)	Raft	RCC Raft	Completed	
	(ii)	Pile	N/A		
3.	Number of basement(s)				
	(i)	Basement Level 1	RCC	Completed	
	(ii)	Basement level 2	RCC	Completed	
4.	Waterproofing of the above sub-structure (wherever applicable)		Polymer modified Cement Grout	Completed	
	Super-Structure Status				
5.	Total floors in the tower/ building		G+19	Completed	
6.	Total area on each floor		Carpet Area - 108987 Sq. mtr.	Completed work	Structure
7.	Stilt floor/ ground floor		Yes	Completed work	Structure
8.	Status of laying of slabs floor wise		RCC	Completed	
	Cumulative number of slabs in the building/ tower		180 Slabs across 9 towers	Completed	
9.	Status of construction				
	(i)	Walls on floors	Brickwork	98.5% Completed	
	(ii)	Staircase	RCC	99.5% Completed	
	(iii)	Lift wells along with water proofing	RCC & bricks	Completed	
	(iv)	Lift lobbies/ common areas floor wise	Brick, finished in stones	89% Completed	
10.	Fixing of door and window frames in flats/ units		Flush door and UPVC	In progress (92%)	


UDAY PANDE
 Architect-Urban Regional Planner
 CA/87/10856-FITP-86/26



11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Lift, Ventilation, Etc		92% Completed	93% Completed
	(ii)	Electrical works including wiring	PVC Conducting, copper wire		90% Completed	93% Completed
	(iii)	Plumbing works	CPVC supply Pipes, UPVC drains		90% Completed	93% Completed
12.	Status of wall plastering					
	(i)	External plaster	Cement Sand Plaster		94%	
	(ii)	Internal plaster	Cement Sand Plaster		93%	
13.	Status of wall tiling					
	(i)	In bathroom	Ceramics Tiles		92%	
	(ii)	In kitchen	Ceramics and Vitrified Tiles		93%	
14.	Status of flooring					
	(i)	Common areas	Granite Stone		95%	
	(ii)	Units/ flats	Vitrified Tiles		95%	
15.	Status of white washing					
	(i)	Internal walls	Plastic Emulsion Paint		92%	
	(ii)	External walls	Exterior Acrylic Emulsion		93%	
16.	Status of finishing					
	(i)	Staircase with railing	Granite and Kota stone, Steel		95%	
	(ii)	Lift wells	Plaster and White Wash		94%	
	(iii)	Lift lobbies/ common areas floor wise	Granite Stone		94%	
17.	Status of installation					
	(within flat/unit)					
	(i)	Doors and windows panels	Wooden Flush Doors, UPVC		92%	


UDAY PANDE
 Architect-Urban Regional Planner
 CA/87/10856-FITP-86/26



18.	(ii)	Sanitary fixtures	Chinaware	90%
	(iii)	Modular kitchen	Stainless Steel	NA
	(iv)	Electrical fittings/ lighting	Modular Fittings	NA
	(v)	Gas piping (if any)	PNG pipeline with meter	NA
	(other than flat/units)			
	(vi)	Lifts installation	Kone Elevators	89%
	(vii)	Overhead tanks	RCC Tanks	89%
	(viii)	Underground water tank	RCC Tanks	95%
	(ix)	Firefighting fitting and equipment as per CFO NOC	Fully compliant, MS piping	94%
	(x)	Electrical fittings in common areas	Approved fittings	86%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Fully compliant as per norms	100%
19.	Waterproofing of terraces		Brick Koba	88%
20.	Entrance lobby finishing		Granite and Italian Stone	87%
21.	Status of construction of compound wall		RCC and Brick Work	88%

NOTE: Occupation Certificate (OC) has been obtained for Tower N & O while the company has also applied for OC for tower E, F & G.

Table - B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	Remarks
B-1	Services			
1.	Internal roads & pavements	Yes	90%	
2.	Parking	No		
	Covered no. 808	Yes	87%	
	Open no. NIL	No		
3.	Water supply	Yes	95%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	96%	
5.	Storm water drains	Yes	95%	
6.	Landscaping & tree plantation	Yes	0%	
7.	Parks and playgrounds	Yes	80%	
	Fixing of children play equipment's			
	Benches			


UDAY PANDE
 Architect-Urban Regional Planner
 CA/87/10856-FITP-86/26



8.	Shopping area			
9.	Street lighting/ electrification	Yes	85%	
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	100%	
11.	Solid waste management & disposal	Yes	95%	
12.	Water conservation, rain water, harvesting, percolating well/ pit	NA	-	
13.	Energy management (solar)	No	100%	
14.	Fire protection and fire safety requirements	Yes	98%	
15.	Electrical meter room, sub-station, receiving station	Yes	95%	
16.	Underground Water Tank	Yes	100%	
B-2	Community building to be transferred to RWA			
17.	Club House	Yes	55%	
18.	Others			
	1 School	No		
	2 Dispensary and Nursing Home	No		
	3 Religious Building	No		
	4 Taxi Stand1	No		
	5 Taxi Stand 2	No		
	6 Crèche	No		
	7 Milk & Veg booth	No		
	8 Multipurpose Hall	No		
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	No		
20.	Dispensary	No		
21.	Club	No		
22.	Others	No		
B-4	Services/ facilities to be transferred to competent authority			
23.	Others	No		

Yours faithfully


UDAY PANDE
 Architect-Urban Regional Planner
 CA/87/10856-FITP-86/26

FOR NIVEDITA AND UDAY PANDE CONSULTANTS