



Nivedita & Uday Pande Consultants

An ISO 9001 : 2015 Certified Company

ARCHITECTS, ENGINEERS, URBAN & REGIONAL PLANNERS AND PROJECT MANAGEMENT CONSULTANTS

Studio: B-224, Okhla Industrial Area, Phase-1

New Delhi - 110020, INDIA

Tel.: +91-11-46818113

E-mail: nuparchi@npuce.net, info@nplusa.in

Website: www.nplusa.in

Annexure A

Architect's Certificate		
Report for quarter ending		31st March 2025
Subject		Certificate of progress of construction work
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans	
	Sr. No.	Particulars
	1.	Project/Phase of the project
	2.	Location
	3.	Licensed area in acres
	4.	Area for registration in acres
	5.	HARERA registration no.
	6.	Name of licensee
	7.	Name of collaborator
	8.	Name of developer
2.	Details related to inspection are as under	
	1.	Date of certifying of the percentage of construction work/ site inspection

Uday Pande

UDAY PANDE
Architect-Urban Regional Planner
CA/87/10858-FITP-86/28

	2.	Name of Architect/ Architect's firm	Nivedita and Uday Pande Consultants
	3.	Date of site inspection	02/04/2025
3.	Following technical professionals are appointed by promoter: - (as applicable)		
	Sr. No.	Consultants	Name
	1.	Site engineer	Mr. Suresh Pal
	2.	Structural consultant	Mr. Sunil Aggarwal (Aggarwal Structural Consultants P. Ltd.)
	3.	Proof consultant	-
	4.	MEP consultant	Mr. Tanveer Husain (NUPC)
	5.	Site supervisor/in charge	Mr. Arun Sharma
4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable), and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.		
5.	I also certify that as of the date, the percentage of work done in the project for each of the building/towers of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activities of the entire project/ phase is detailed in table A and table B.		

Date : 04/04/2025

Yours faithfully,

Place :

UD Pande

Council of architects (CoA) :
registration no.

Signature & name (in block
letters) with stamp of architect

Council of architects (CoA) :
registration valid till (date)

UDAY PANDE
Architect-Urban Regional Planner
CA/87/10856-FITP-86/26

Table - A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		Tower A			
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work	
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	0.94	343.89	100	
2.	Super structure (slabs, brickwork, block work, staircase lift wells, machine rooms, water tank, etc.)	3.18	1,043.83	99.75	
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	11.72	372.94	12.58
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			38.00
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			28.20
4.	Finishing				
	4.1	Internal (plaster, tiling, flooring, painting, etc. within units and common areas)	10.38	417.83	69.00
	4.2	External (plaster, painting, facade, etc.)			95.50


UDAY PANDE
 Architect-Urban Regional Planner
 CA/87/10856-FITP-86/26

30Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		Tower B		
B1	Cumulative progress of the project/phase at the end of the quarter.			
Sr. No.	Project components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	0.94	343.89	100
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	5.32	1,045.25	99.75
3.	MEP			
	3.1 Mechanical (lifts, ventilation, etc.)	12.81	372.94.	26.03
	3.2 Electrical (conduiting, wiring, fixtures, etc.)			43.50
	3.3 Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			30.00
4.	Finishing			
	4.1 Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	10.24	419.40	65.25
	4.2 External (plaster, painting, facade, etc.)			99.50


UDAY PANDE
 Architect-Urban Regional Planner
 CA/87/10853-FITP-86/26

Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			Tower C		
C1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		1.01	394.97	100
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		5.38	1,196.80	99.75
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	11.31	411.50	13.45
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			36.75
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			44.00
4.	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	10.56	458.82	67.00
	4.2	External (plaster, painting, facade, etc.)			99.50

Uday Pande

UDAY PANDE
Architect-Urban Regional Planner
CA/87/10856-FITP-86/26

Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		Tower D			
D1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work	
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	1.01	394.97	100	
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	5.48	1,197.93	99.75	
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	10.35	412.93	15.43
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			45.00
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			39.50
4.	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	10.12	456.64	62.80
	4.2	External (plaster, painting, facade, etc.)			95.50

UD Pande

UDAY PANDE
Architect-Urban Regional Planner
CA/87/10856-FITP-86/26

Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		Tower E			
E1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work	
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	0.99	395.16	100	
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	4.48	1,195.22	98.50	
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	10.26	414.21	12.23
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			37.70
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			28.00
4.	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	11.62	458.14	25.00
	4.2	External (plaster, painting, facade, etc.)			95.00

Uday Pande

UDAY PANDE
Architect-Urban Regional Planner
CA/87/10856-FITP-86/26

Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			Tower F		
F1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, waterproofing, etc.)		0.83	343.49	100
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		5.18	1,045.18	99.25
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	10.06	370.56	13.58
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			37.70
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			26.00
4.	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	10.89	413.58	28.10
	4.2	External (plaster, painting, facade, etc.)			98.25

Uday Pande

UDAY PANDE
Architect-Urban Regional Planner
CA/87/10803-FITP-86/25

Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			Tower G		
G1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		0.84	343.30	100
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		5.38	1,047.32	99.00
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	11.07	369.91	14.43
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			36.95
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			35.00
4.	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	10.98	413.67	58.00
	4.2	External (plaster, painting, facade, etc.)			97.00

Uday Pande

UDAY PANDE
Architect-Urban Regional Planner
CA/57/100 P. ETP 26/26

Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			Tower H		
H1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		0.83	343.49	100
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		5.18	1,046.43	99.50
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	11.23	369.19	13.48
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			39.00
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			31.00
4.	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	10.93	413.00	66.00
	4.2	External (plaster, painting, facade, etc.)			98.50

UD Pande

UDAY PANDE
Architect-Urban Regional Planner
CA/87/108 FIP-86/25

Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		Tower I		
EWS	Cumulative progress of the project/phase at the end of the quarter.			
Sr. No.	Project components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	0.84	343.30	100
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	5.48	1,047.30	100
3.	MEP			
	3.1 Mechanical (lifts, ventilation, etc.)	10.22	368.35	15.08
	3.2 Electrical (conduiting, wiring, fixtures, etc.)			40.00
	3.3 Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			29.00
4.	Finishing			
	4.1 Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	10.73	412.80	68.50
	4.2 External (plaster, painting, facade, etc.)			99.02

Uday Pande

UDAY PANDE
Architect-Urban Regional Planner
CA/87/10853-FITP-86/26

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		General Excavation		Completed	
2.	Laying of foundation					
	(i)	Raft	RCC Raft		Completed	
	(ii)	Pile	N/A			
3.	Number of basement(s) – 1					
	(i)	Basement Level 1	RCC		Completed	
4.	Waterproofing of the above sub-structure (wherever applicable)		Polymer modified Cement Grout		Completed	
	Super-Structure Status					
5.	Total floors in the tower/ building		G+18		Completed	
6.	Total area on each floor		Carpet Area – 96356.904 Sq. mtr.			
7.	Stilt floor/ ground floor		Yes		96%	
8.	Status of laying of slabs floor wise		RCC		Completed	
	Cumulative number of slabs in the building/ tower		684 Slabs across 9 towers			
9.	Status of construction					
	(i)	Walls on floors	Brickwork		98% Completed	
	(ii)	Staircase	RCC		97% Completed	
	(iii)	Lift wells along with water proofing	RCC & bricks		97.50% Completed	
	(iv)	Lift lobbies/ common areas floor wise	Brick, finished in stones		83% Completed	
10.	Fixing of door and window frames in flats/ units		Flush door and UPVC		In progress (40%)	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	(lifts, ventilation, etc.)		15.15%	
	(ii)	Electrical works including wiring	PVC Conduiting, copper wire		39.00%	
	(iii)	Plumbing works	CPVC supply Pipes, UPVC drains		28.70%	
12.	Status of wall plastering					
	(i)	External plaster	Cement Sand Plaster		95%	
	(ii)	Internal plaster	Cement Sand Plaster		55%	
13.	Status of wall tiling					

	(i)	In bathroom	Anti Skid Tiles	50%
	(ii)	In kitchen	Ceramics Tiles	50%
14.	Status of flooring			
	(i)	Common areas	Granite Stone	65%
	(ii)	Units/ flats	Vetrified Tiles	60%
15.	Status of whitewashing			
	(i)	Internal walls	Plastic Emulsion Paint	62%
	(ii)	External walls	Exterior Acrilic Emulsion	85%
16.	Status of finishing			
	(i)	Staircase with railing	Granite and Kota stone, Steel	45%
	(ii)	Lift wells	Plaster and White Wash	43%
	(iii)	Lift lobbies/ common areas floor wise	Granite Stone	43%
17.	Status of installation (within flat/unit)			
	(i)	Doors and windows panels	Wooden Flush Doors, UPVC	60%
	(ii)	Sanitary fixtures	Chinaware	50%
	(iii)	Modular kitchen	Stainless Steel	NA
	(iv)	Electrical fittings/ lighting	Modular Fittings	NA
	(v)	Gas piping (if any)	PNG pipeline with meter	Yet to commence
	(other than flat/units)			
	(vi)	Lifts installation		Yet to commence
	(vii)	Overhead tanks	RCC Tanks	88%
	(viii)	Underground water tank	RCC Tanks	85%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Fully compliant, MS piping	40%
	(x)	Electrical fittings in common areas	Approved fittings	58%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Fully compliant as per norms	
18.	Waterproofing of terraces		Brick Koba	90%
19.	Entrance lobby finishing		Granite and Italian Stone	35%
20.	Status of construction of compound wall		RCC and Brick Work	85%

UDAY PANDE
Architect-Urban Regional Planner
CA/87/108 26/26

Uday Pande

Table - B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services			
1.	Internal roads & pavements	Yes	35%	
2.	Parking			
	Covered no. 1086	Yes	Incl. in structure work	
	Open no. NIL	No		
3.	Water supply	Yes	40%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	45%	
5.	Storm water drains	Yes	42%	
6.	Landscaping & tree plantation	Yes	20%	
7.	Parks and playgrounds	Yes	0%	
	Fixing of children play equipment's			
	Benches			
8.	Shopping area		100%	
9.	Street lighting/ electrification	Yes	40%	
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	40%	
11.	Solid waste management & disposal	Yes	35%	
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	100%	
13.	Energy management (solar)	No		
14.	Fire protection and fire safety requirements	Yes	30%	
15.	Electrical meter room, sub-station, receiving station	Yes	35%	
16.	Underground Water Tank	Yes	80%	
B-2	Community building to be transferred to RWA			
17.	Club House	Yes	0%	
18.	Others - Not Applicable, as doesn't form part of this phase.			
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	No		
20.	Dispensary	No		
21.	Club	No		
22.	Others	No		
B-4	Services/ facilities to be transferred to competent authority			
23.	Others	No		


UDAY PANDE
 Architect-Urban Regional Planner
 CA/87/10855-FITP-86/26