

Architect's Certificate ¹		
Report for quarter ending		1/10/2024
Subject		Certificate of progress of construction work
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans	
Sr. No.	Particulars	Information
1.	Project/Phase of the project	Heritage Max
2.	Location	Sector-102, Gurugram, Haryana
3.	Licensed area in acres	11.25 Acre
4.	Area for registration in acres	1.579 Acres
5.	HARERA registration no.	08 dated - 23/07/2018
6.	Name of licensee	Dream Home Infrastructure Pvt. Ltd
7.	Name of collaborator	N/A
8.	Name of developer	Dream Home Infrastructure Pvt. Ltd
2.	Details related to inspection are as under	
1.	Date of certifying of percentage of construction work/ site inspection	1/10/2024
2.	Name of Architect/ Architect's firm	Arcop Associates Pvt Ltd
3.	Date of site inspection	30/09/2024

Labib Alam, Architect
Council of Architecture
Registration No.: CA/2001/27447

¹ On the letter head of the architect firm

Annexure C

3.	Following technical professionals are appointed by promoter: - (as applicable)		
	Sr. No.	Consultants	Name
	1.	Site engineer	Mr. Hemansh Rastogi
	2.	Structural consultant	Technical Projects Consultants Pvt. Ltd.
	3.	Proof consultant	Civtech Consultants Pvt. Ltd.
	4.	MEP consultant	Plumbing & Fire Fighting – Paradise Consultants. Electrical Consultant – Ampower Consultancy services
	5.	Site supervisor/incharge	Mr. Kamlesh Sharma
4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.		
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.		

Date

:

Yours faithfully,

Place

:

Signature & name (in block letters) with stamp of architect



Labib Alam, Architect
Council of Architecture
Registration No.: CA/2001/27447

Council of architects (CoA) : CA/2001/27447
registration no.

Council of architects (CoA) : 31.12.2027
registration valid till (date)

Annexure C


Table - A				
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		Tower - F (Excluding Internal Development Work Cost)		
A1	Cumulative progress of the project/phase at the end of the quarter.			
Sr. No.	Project components	Work done value during the quarter (In Lacs)	Cumulative work done value till date (In Lacs)	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	0.0	465.9	100%
2.	Super structure (slabs, brick work, block work, staircase, lift wells, machine rooms, water tank, etc.)	0.0	1743.7	100%
3.	MEP			
	3.1 Mechanical (lifts, ventilation, etc.)	0.0	252.9	100%
	3.2 Electrical (conduiting, wiring, fixtures, etc.)	0.0	342.7	100%
	3.3 Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0.0	286.2	100%
4.	Finishing			
	4.1 Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0.0	473.8	99%
	4.2 External (plaster, painting, facade, etc.)	0.0	295.5	100%


Habib Alam, Architect


 Labib Alam, Architect
 Council of Architecture
 Registration No.: CA/2001/27447

Annexure C

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
Sub-Structure Status						
1.	Excavation		Complete		100%	
2.	Laying of foundation					
	(i)	Raft	Complete		100%	
	(ii)	Pile	Complete		100%	
3.	Number of basement(s) <u>1</u>					
	(i)	Basement Level 1	Complete		100%	
	(ii)	Basement level 2*	N/A			
4.	Waterproofing of the above sub-structure (wherever applicable)		Complete		100%	
Super-Structure Status						
5.	Total floors in the tower/ building		S/G+26			
6.	Total area on each floor		Typical Floor FAR: 368.934 sqm			
7.	Stilt floor/ ground floor		Completed		100%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower <u>27</u> laid by end of quarter		Completed		100%	
9.	Status of construction					
	(i)	Walls on floors	Completed		100%	
	(ii)	Staircase	Completed		100%	
	(iii)	Lift wells along with water proofing	Completed		100%	
	(iv)	Lift lobbies/ common areas floor wise	Completed		100%	
10.	Fixing of door and window frames in flats/ units		Completed		100%	
11.	Status of MEP		Internal (within Flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Completed.		100%	
	(ii)	Electrical works including wiring	Completed.		100%	
	(iii)	Plumbing works	Completed.		100%	
12.	Status of wall plastering					
	(i)	External plaster	Completed.		100%	


 Labib Alam, Architect
 Council of Architecture
 Registration No.: CA/2001/27447

Annexure C

	(ii)	Internal plaster	Completed.	100%
13.	Status of wall tiling			
	(i)	In bathroom	Completed.	100%
	(ii)	In kitchen	Completed.	100%
14.	Status of flooring			
	(i)	Common areas	Completed.	100%
	(ii)	Units/ flats	Completed.	100%
15.	Status of white washing			
	(i)	Internal walls	Completed.	100%
	(ii)	External walls	Completed.	100%
16.	Status of finishing			
	(i)	Staircase with railing	Completed.	100%
	(ii)	Lift wells	Completed.	100%
	(iii)	Lift lobbies/ common areas floor wise	Completed.	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Completed.	100%
	(ii)	Sanitary fixtures	Completed.	100%
	(iii)	Modular kitchen	In Progress and material available at Store.	98%
	(iv)	Electrical fittings/ lighting	Completed.	100%
	(v)	Gas piping (if any)	N/A.	
	(other than flat/units)			
	(vi)	Lifts installation	Completed.	100%
	(vii)	Overhead tanks	Completed.	100%
	(viii)	Underground water tank	Completed.	100%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Completed.	100%
	(x)	Electrical fittings in common areas	Completed.	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC		
18.	Waterproofing of terraces		Completed.	100%
19.	Entrance lobby finishing		Completed.	100%
20.	Status of construction of compound wall		Completed.	100%

Labib Alam, Architect
Council of Architecture
Registration No.: CA/2001/27447

Annexure C

Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		Community Centre (Excluding Internal Development Work Cost)		
A1		Cumulative progress of the project/phase at the end of the quarter.		
Sr. No.	Project components	Work done value during the quarter (Amt in Lacs)	Cumulative work done value till date (Amt in Lacs)	Percentage of work done to the total proposed work
5.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	0.0	36.5	100%
6.	Super structure (slabs, brick work, block work, staircase, lift wells, machine rooms, water tank, etc.)	0.0	88.7	100%
7.	MEP			
3.1	Mechanical (lifts, ventilation, etc.)	0.0	19.8	100%
3.2	Electrical (conduiting, wiring, fixtures, etc.)	0.0	26.1	100%
3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0.0	22.4	100%
8.	Finishing			
4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0.0	242.8	100%
4.2	External (plaster, painting, facade, etc.)	0.0	26.1	100%

Labib Alam, Architect
Council of Architecture
Registration No.: CA/2001/27447

Annexure C

Sr. No.	Tasks/ Activity	Description of work done	Percentage of total proposed work
	Sub-Structure Status		
21.	Excavation	Complete	100%
22.	Laying of foundation		
	(iii) Raft	Complete	100%
	(iv) Pile	Complete	100%
23.	Number of basement(s) <u>1</u>		
	(iii) Basement Level 1	Complete	100%
	(iv) Basement level 2*	N/A	
24.	Waterproofing of the above sub-structure (wherever applicable)	Complete	100%
	Super-Structure Status		
25.	Total floors in the tower/ building	1 Nos.	
26.	Total area on each floor	969.007 Sqm (Ground Coverage).	
27.	Stilt floor/ ground floor	Completed	100%
28.	Status of laying of slabs floor wise		
	Cumulative number of slabs in the building/ tower <u>1</u> laid by end of quarter	Completed	100%
29.	Status of construction		
	(v) Walls on floors	Completed	100%
	(vi) Staircase	Completed	100%
	(vii) Lift wells along with water proofing	N/A	
	(viii) Lift lobbies/ common areas floor wise	Completed	100%
30.	Fixing of door and window frames in flats/ units	Completed	100%
31.	Status of MEP	Internal (within Flat)	External works
	(iv) Mechanical works	Completed	100%
	(v) Electrical works including wiring	Completed	100%
	(vi) Plumbing works	Completed.	100%
32.	Status of wall plastering		
	(iii) External plaster	Completed.	100%

Labib Alam, Architect
Council of Architecture
Registration No.: CA/2001/27447

Annexure C

	(iv)	Internal plaster	Completed.	100%
33.		Status of wall tiling		
	(iii)	In bathroom	Completed.	100%
	(iv)	In kitchen	Completed.	100%
34.		Status of flooring		
	(iii)	Common areas	Completed.	100%
	(iv)	Units/ flats	Completed.	100%
35.		Status of white washing		
	(iii)	Internal walls	Completed.	100%
	(iv)	External walls	Completed.	100%
36.		Status of finishing		
	(iv)	Staircase with railing	Completed.	100%
	(v)	Lift wells	N/A	
	(vi)	Lift lobbies/ common areas floor wise	Completed.	100%
37.		Status of installation		
		(within flat/unit)		
	(xii)	Doors and windows panels	Completed.	100%
	(xiii)	Sanitary fixtures	Completed.	100%
	(xiv)	Modular kitchen	N/A.	
	(xv)	Electrical fittings/ lighting	Completed.	100%
	(xvi)	Gas piping (if any)	N/A.	
		(other than flat/units)		
	(xvii)	Lifts installation	N/A	
	(xviii)	Overhead tanks	Completed.	100%
	(xix)	Underground water tank	Completed.	100%
	(xx)	Firefighting fitting and equipment's as per CFO NOC	Completed.	100%
	(xxi)	Electrical fittings in common areas	Completed	100%
	(xxii)	Compliance to conditions of environment/ CRZ NOC		
38.		Waterproofing of terraces	Completed.	100%
39.		Entrance lobby finishing	Completed.	100%
40.		Status of construction of compound wall	Completed.	100%


 Labib Alam, Architect
 Council of Architecture
 Registration No.: CA/2001/27447

Annexure C

Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		Shopping Complex (Excluding Internal Development Work Cost)		
A1	Cumulative progress of the project/phase at the end of the quarter.			
Sr. No.	Project components	Work done value during the quarter (Amt in Lacs)	Cumulative work done value till date (Amt in Lacs)	Percentage of work done to the total proposed work
9.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	0.0	8.8	100%
10.	Super structure (slabs, brick work, block work, staircase, lift wells, machine rooms, water tank, etc.)	0.0	16.3	100%
11.	MEP			
	3.1 Mechanical (lifts, ventilation, etc.)			
	3.2 Electrical (conduiting, wiring, fixtures, etc.)	0.0	1.3	100%
	3.3 Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0.0	1.3	100%
12.	Finishing			
	4.1 Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0.0	4.9	100%
	4.2 External (plaster, painting, facade, etc.)	0.0	1.3	100%

Labib Alam, Architect
Council of Architecture
Registration No.: CA/2001/27447

Annexure C

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
41.	Excavation		Completed.		100%	
42.	Laying of foundation					
	(v)	Raft	Completed.		100%	
	(vi)	Pile	N/A			
43.	Number of basement(s)		N/A			
	(v)	Basement Level 1	N/A			
	(vi)	Basement level 2*	N/A			
44.	Waterproofing of the above sub-structure (wherever applicable)		N/A			
	Super-Structure Status					
45.	Total floors in the tower/ building		1 Nos.			
46.	Total area on each floor		223.105 Sqm (Covered Area)			
47.	Stilt floor/ ground floor		Completed		100%	
48.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower 1 laid by end of quarter		Completed		100%	
49.	Status of construction					
	(ix)	Walls on floors	Completed		100%	
	(x)	Staircase	Completed		100%	
	(xi)	Lift wells along with water proofing	N/A			
	(xii)	Lift lobbies/ common areas floor wise	Completed		100%	
50.	Fixing of door and window frames in flats/ units		Completed		100%	
51.	Status of MEP		Internal (within Flat)	External works	Internal (within flat)	External works
	(vii)	Mechanical works	N/A.			
	(viii)	Electrical works including wiring	Completed.		100%	
	(ix)	Plumbing works	Completed.		100%	
52.	Status of wall plastering					
	(v)	External plaster	Completed.		100%	
	(vi)	Internal plaster	Completed.		100%	

Labib Alam, Architect
Council of Architecture
Registration No.: CA/2001/27447

Annexure C

53.	Status of wall tiling			
	(v)	In bathroom	Completed.	100%
	(vi)	In kitchen	Completed.	100%
54.	Status of flooring			
	(v)	Common areas	Completed.	100%
	(vi)	Units/ flats	Completed.	100%
55.	Status of white washing			
	(v)	Internal walls	Completed.	100%
	(vi)	External walls	Completed.	100%
56.	Status of finishing			
	(vii)	Staircase with railing	Completed.	100%
	(viii)	Lift wells	N/A	
	(ix)	Lift lobbies/ common areas floor wise	Completed.	100%
57.	Status of installation			
	(within flat/unit)			
	(xxiii)	Doors and windows panels	Completed.	100%
	(xxiv)	Sanitary fixtures	Only for Common Toilets	100%
	(xxv)	Modular kitchen	N/A.	
	(xxvi)	Electrical fittings/ lighting	Completed.	100%
	(xxvii)	Gas piping (if any)	N/A.	
	(other than flat/units)			
	(xxviii)	Lifts installation	N/A	
	(xxix)	Overhead tanks	Completed.	100%
	(xxx)	Underground water tank	Completed.	100%
	(xxxi)	Firefighting fitting and equipment's as per CFO NOC	Completed.	100%
	(xxxii)	Electrical fittings in common areas	Completed.	100%
	(xxxiii)	Compliance to conditions of environment/ CRZ NOC		
58.	Waterproofing of terraces		Completed.	100%
59.	Entrance lobby finishing		Completed.	100%
60.	Status of construction of compound wall		Completed.	100%

Labib Alam, Architect
 Council of Architecture
 Registration No.: CA/2001/27447

Annexure C

Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		School Building (Excluding Internal Development Work Cost)		
A1	Cumulative progress of the project/phase at the end of the quarter.			
Sr. No.	Project components	Work done value during the quarter (Amt in Lacs)	Cumulative work done value till date (Amt in Lacs)	Percentage of work done to the total proposed work
13.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	0.0	17.1	100%
14.	Super structure (slabs, brick work, block work, staircase, lift wells, machine rooms, water tank, etc.)	0.0	34.1	100%
15.	MEP			
	3.1 Mechanical (lifts, ventilation, etc.)	N/A	N/A	
	3.2 Electrical (conduiting, wiring, fixtures, etc.)	0.0	7.3	100%
	3.3 Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0.0	6.1	100%
16.	Finishing			
	4.1 Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0.0	37.1	100%
	4.2 External (plaster, painting, facade, etc.)	0.0	7.1	100%

Labib Alam, Architect
Council of Architecture
Registration No.: CA/2001/27447


Annexure C

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
61.	Excavation		Completed.		100%	
62.	Laying of foundation					
	(vii)	Raft	Completed.		100%	
	(viii)	Pile	N/A			
63.	Number of basement(s)		N/A			
	(vii)	Basement Level 1	N/A			
	(viii)	Basement level 2*	N/A			
64.	Waterproofing of the above sub-structure (wherever applicable)		N/A			
	Super-Structure Status					
65.	Total floors in the tower/ building		1 Nos.			
66.	Total area on each floor		264.238 Sqm (Ground Coverage)			
67.	Stilt floor/ ground floor		Completed.		100%	
68.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower 1 laid by end of quarter		Completed		100%	
69.	Status of construction					
	(xiii)	Walls on floors	Completed.		100%	
	(xiv)	Staircase	N/A			
	(xv)	Lift wells along with water proofing	N/A			
	(xvi)	Lift lobbies/ common areas floor wise	Completed.		100%	
70.	Fixing of door and window frames in flats/ units		Completed.		100%	
71.	Status of MEP		Internal (within Flat)	External works	Internal (within flat)	External works
	(x)	Mechanical works	N/A.			
	(xi)	Electrical works including wiring	Completed.		100%	
	(xii)	Plumbing works	Completed.		100%	
72.	Status of wall plastering					
	(vii)	External plaster	Completed.		100%	
	(viii)	Internal plaster	Completed.		100%	

Labib Alam, Architect
Council of Architecture
Registration No.: CA/2001/27447

Annexure C

73.	Status of wall tiling			
	(vii)	In bathroom	Completed.	100%
	(viii)	In kitchen	N/A	
74.	Status of flooring			
	(vii)	Common areas	Completed.	100%
	(viii)	Units/ flats	Completed.	100%
75.	Status of white washing			
	(vii)	Internal walls	Completed.	100%
	(viii)	External walls	Completed.	100%
76.	Status of finishing			
	(x)	Staircase with railing	N/A	
	(xi)	Lift wells	N/A	
	(xii)	Lift lobbies/ common areas floor wise	Completed.	100%
77.	Status of installation			
	(within flat/unit)			
	(xxxi)	Doors and windows panels	Completed.	100%
	(xxxv)	Sanitary fixtures	Completed.	100%
	(xxxv)	Modular kitchen	N/A.	
	(xxxv)	Electrical fittings/ lighting	Completed.	100%
	(xxxv)	Gas piping (if any)	N/A.	
	(other than flat/units)			
	(xxxi)	Lifts installation	N/A	
	(xl)	Overhead tanks	Completed.	100%
	(xli)	Underground water tank	N/A	
	(xlii)	Firefighting fitting and equipment's as per CFO NOC	Completed.	100%
	(xlili)	Electrical fittings in common areas	Completed.	100%
	(xliv)	Compliance to conditions of environment/ CRZ NOC		
78.	Waterproofing of terraces		Completed.	100%
79.	Entrance lobby finishing		Completed.	100%
80.	Status of construction of compound wall		Completed.	100%


 Labib Alam, Architect
 Council of Architecture
 Registration No.: C.A/2001/27447

Annexure C

Table - B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	Remarks
B-1	Services			
1.	Internal roads & pavements	Yes	100%	
2.	Parking			
	Covered no <u>102</u>	Yes	100%	
	Open no <u>17</u>	Yes	100%	
3.	Water supply	Yes	100%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%	
5.	Storm water drains	Yes	100%	
6.	Landscaping & tree plantation	Yes	100%	
7.	Parks and playgrounds	Yes	100%	
	Fixing of children play equipment's	No		
	Benches	No		
8.	Shopping area	Yes	100%	
9.	Street lighting/ electrification	Yes	100%	
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	100%	
11.	Solid waste management & disposal	No		
12.	Water conservation, rainwater harvesting, percolating well/ pit	No		Exempted.
13.	Energy management (solar)	Yes	100%	
14.	Fire protection and fire safety requirements	Yes	100%	
15.	Electrical meter room, sub-station, receiving station	Yes	100%	
16.	Other (option to add more)			
B-2	Community building to be transferred to RWA			
17.	Community centre	NO		N/A
18.	Others.	NO		
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	Yes	100%	N/A
20.	Dispensary	No		N/A
21.	Club	Yes	100%	
22.	Commercial	Yes	100%	
B-4	Services/ facilities to be transferred to competent authority			
23.	*			

Labib Alam, Architect
Council of Architecture
Registration No.: CA/2001/27447