



K K AND ASSOCIATES

Architect Surveyors and Consulting Engineers

120 / 305, N. G. Compd., Ideal Building, 1st Flr, Opp. Post Office, College Road, Dhamankar Naka, Bhiwandi-Mumbai-421 302, Dist. Thane. Tel.: 02522-232010 / 233093 / 692070, Fax : 222039 / 235896

Website : www.kkdurraj.com, Email : info@kkdurraj.com
kkengrach@gmail.com, kkengarch@yahoo.com

FORM 1 [see Regulation 3]

ARCHITECT'S CERTIFICATE

Date: 30-09-2024

To

Mr. Mahesh Gala and 2 others

Room no. 202, 2nd floor, 388 sterling heritage, Shankar matthan road, matunga central
Mumbai - 400019

Subject: Certificate of Percentage of Completion of Construction Work of "KALYAN NAGARI" 3 No. of Building(s). Building A, Building B1 and B2 having A Wing & B Wing of the Project having MahaRERA Registration number (P51700016054) being developed by **Mr. Mahesh Gala and 2 Others.**

Sir,

We KK and Associates have undertaken assignment as Architect /Licensed Surveyor of certifying Percentage of Completion of Construction Work of the 3 No. of Building(s). Of "KALYAN NAGARI" 3 No. of Building(s). Building A, Building B1 and B2 having A Wing & B Wing of the 1 Phase of the Project having MahaRERA Registration number (P51700016054) being developed by **Mr. Mahesh Gala and 2 Others.**

Following technical professionals are appointed by Owner / Promoter:-

- (i) M/S KK and Associates as L.S. / Architect.
- (ii) M/S KK and Associates as Structural Consultant.
- (iii) M/s. Elcon Engineers as MEP Consultant.
- (iv) Mr. Naveeduzzaman Isa Shaikh as Site Supervisor.

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered vide number (P51700016054) under MahaRERA is as per table A herein below.

The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.



K K AND ASSOCIATES

Architect Surveyors and Consulting Engineers

120 / 305, N. G. Compd., Ideal Building, 1st Flr, Opp. Post Office, College Road, Dhamankar Naka, Bhiwandi-Mumbai- 421 302, Dist. Thane. Tel.: 02522-232010 / 233093 / 692070, Fax : 222039 / 235899

Website : www.kkdurraj.com, Email : info@kkdurraj.com, kkengrarch@gmail.com, kkengarch@yahoo.com

TABLE-A
Building A

Sr. No.	Tasks /Activity	Percentage of work done
1	Excavation	100%
2	Nil Basement(s) and 1 no. of Plinth	100%
3	Number of Podiums	Nil
4	Stilt Floor	100%
5	9 number of Slabs of Super Structure	67%
6	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises.	70%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	70%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	55%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	62%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as maybe required to obtain Occupation / Completion Certificate.	70%
11	Overall Percentage of Completion of work done for entire building / wing	68%

TABLE-A
Building B1 /Wing A

Sr. No.	Tasks /Activity	Percentage of work done
1	Excavation	100%
2	Nil Basement(s) and 1 no. of Plinth	100%
3	Number of Podiums	Nil
4	Stilt Floor	100%
5	10 number of Slabs of Super Structure	100%



K K AND ASSOCIATES

Architect Surveyors and Consulting Engineers

120 / 305, N. G. Compd., Ideal Building, 1st Flr, Opp. Post Office, College Road, Dhamankar Naka, Bhiwandi-Mumbai- 421 302, Dist. Thane. Tel.: 02522-232010 / 233093 / 692070, Fax : 222039 / 235895

Website : www.kkduraj.com, Email : info@kkduraj.com, kkengrach@gmail.com, kkengarch@yahoo.com

6	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises.	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as maybe required to obtain Occupation / Completion Certificate.	100%
11	Overall Percentage of Completion of work done for entire building / wing	100%

TABLE-A
Building B1 /Wing B

Sr. No.	Tasks /Activity	Percentage of work done
1	Excavation	100%
2	Nil Basement(s) and 1 no. of Plinth	100%
3	Number of Podiums	Nil
4	Stilt Floor	100%
5	10 number of Slabs of Super Structure	100%
6	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises.	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%



K K AND ASSOCIATES

Architect Surveyors and Consulting Engineers

120 / 305, N. G. Compd., Ideal Building, 1st Flr, Opp. Post Office, College Road, Dhamankar Naka, Bhiwandi-Mumbai- 421 302, Dist. Thane. Tel.: 02522-232010 / 233093 / 692070, Fax : 222039 / 235895

Website : www.kkdurraj.com, Email : info@kkdurraj.com
kkengrach@gmail.com, kkengarch@yahoo.com

6	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises.	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as maybe required to obtain Occupation / Completion Certificate.	100%
11	Overall Percentage of Completion of work done for entire building / wing	100%

TABLE-A
Building B1 /Wing B

Sr. No.	Tasks /Activity	Percentage of work done
1	Excavation	100%
2	Nil Basement(s) and 1 no. of Plinth	100%
3	Number of Podiums	Nil
4	Stilt Floor	100%
5	10 number of Slabs of Super Structure	100%
6	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises.	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%



K K AND ASSOCIATES

Architect Surveyors and Consulting Engineers

120 / 305, N. G. Compd., Ideal Building, 1st Flr, Opp. Post Office, College Road, Dhamankar Naka, Bhiwandi-Mumbai- 421 302, Dist. Thane. Tel.: 02522-232010 / 233093 / 692070, Fax : 222039 / 235895

Website : www.kkduraj.com, Email : info@kkduraj.com
kkengrach@gmail.com, kkengarch@yahoo.com

10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as maybe required to obtain Occupation / Completion Certificate.	100%
11	Overall Percentage of Completion of work done for entire building / wing	100%

TABLE-A
Building B2 /Wing A

Sr. No.	Tasks /Activity	Percentage of work done
1	Excavation	100%
2	Nil Basement(s) and 1 no. of Plinth	100%
3	Number of Podiums	Nil
4	Stilt Floor	100%
5	13 number of Slabs of Super Structure	100%
6	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises.	100%
7	Sanitary Fittings within the Flat/ Premises, Electrical Fittings within the Flat/ Premises.	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as maybe required to obtain Occupation / Completion Certificate.	100%
11	Overall Percentage of Completion of work done for entire building / wing	100%

**K K AND ASSOCIATES**

Architect Surveyors and Consulting Engineers

120 / 305, N. G. Compd., Ideal Building, 1st Flr, Opp. Post Office, College Road, Dhamankar Naka, Bhiwandi-Mumbai-421 302, Dist. Thane. Tel.: 02522-232010 / 233093 / 692070, Fax : 222039 / 235896

Website : www.kkdurraj.com, Email : info@kkdurraj.com
kkengrarch@gmail.com, kkengarch@yahoo.com**TABLE-A**
Building B2 /Wing B

Sr. No.	Tasks /Activity	Percentage of work done
1	Excavation	100%
2	Nil Basement(s) and 1 no. of Plinth	100%
3	Number of Podiums	Nil
4	Stilt Floor	100%
5	13 number of Slabs of Super Structure	100%
6	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises.	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as maybe required to obtain Occupation / Completion Certificate.	100%
11	Overall Percentage of Completion of work done for entire building / wing	100%

TABLE-B**Internal and External Development Works in respect of the entire Registered Phase.**

S.No.	Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentage of Work done	Details
1	Internal Roads &Footpaths.	Yes	100%	Work Completed
2	Water Supply	Yes	100%	The water supply will be provide by Grampanchyat or MMRDA after completion
3	Sewerage chamber, lines, Septic Tank, STP).	Yes	100%	Work Completed



K K AND ASSOCIATES

Architect Surveyors and Consulting Engineers

120 / 305, N. G. Compd., Ideal Building, 1st Flr, Opp. Post Office, College Road, Dhamankar Naka, Bhiwandi-Mumbai- 421 302, Dist. Thane. Tel.: 02522-232010 / 233093 / 692070, Fax : 222039 / 235895

Website : www.kkdurraj.com, Email : info@kkdurraj.com
kkengrach@gmail.com, kkengarch@yahoo.com

4	Storm Water Drains	Yes	100%	Work Completed
5	Landscaping & Tree Planting.	Yes	100%	Work Completed
6	Street Lighting	Yes	100%	Work Completed
7	Community Buildings	Yes	100%	Work Completed
8	Treatment and disposal of sewage and sullage water.	Yes	100%	Include in sewerage (Chamber line, Septic tank, STP)
9	Solid Waste management & Disposal.	Yes	100%	Work Completed
10	Water conservation, Rain water harvesting.	Yes	50%	Work in progress
11	Energy management	Yes	66%	Work in progress
12	Fire protection and fire safety requirements.	Yes	80%	Work in progress
13	Electrical meter room, sub-station, receiving station.	Yes	100%	Work Completed
14	Aggregate area of recreational open space	Yes	100%	1944.12 sq.mtrs. area provided
15	Open Parking	Yes	100%	70 nos.
16	Covered Parking	Yes	100%	42 nos.

Agreed and accepted by:

Yours Faithfully

Mr.Mahesh Gala and 2 others

Date: 30-09-2024

For HONEST DEVELOPERS

PARTNER

K. K. & ASSOCIATES

Architects, Surveyors & Consulting Engineers
120/305, N.G. Compound, Ideal Building,
1st Floor, Opp. Post Office, College Road,
Dhamankar Naka, Bhiwandi-421305 (Thane)