

FORM 1
ARCHITECT'S CERTIFICATE

31/12/2024

To
HORIZON PROJECTS PVT LIMITED
5th Floor, Runwal & Omkar E-square,
Off Eastern Express Highway,
Opp. Sion Chunabhatti Signal,
Sion East, Mumbai – 400 022

Subject: Certificate of Percentage of Completion of Construction Work of Tower 1 to Tower 6, My City phase II - Cluster 5 – Part I, having MahaRERA Registration Number P51700019085 being developed by HORIZON PROJECTS PVT LIMITED.

Sir,

I Mr. Sandeep Prabhu have undertaken assignment as Architect of certifying Completion of Construction Work of Tower 1, My City Phase II – Cluster – 5 Part I, having MahaRERA Registration Number P51700019085 being developed by HORIZON PROJECTS PVT LIMITED.

Based on Site Inspection, with respect to Building of the aforesaid Real Estate Project, I certify that as on **31/12/2024**, the Percentage of Work done for each of the building of the Real Estate Project under MahaRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.



TABLE A

Tower – 1

Sr. No.	Tasks / Activity	Percentage of work done
1	Excavation	100%
2	1 number Plinth	100%
3	2 number of Podium	100%
4	Stilt Floor	100%
5	26 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats / Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	100%
8	Staircase, Lifts Wells and Lobbies at each floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Wing	100%
10	Installation of Lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to common areas, electro, mechanical equipment, Compliance to conditions of environment / CRZ NOC, Finishing to entrance lobby, plinth protection, paving of areas appurtenant to Wing, Compound Wall and all other requirements as may be required to Obtain Occupation / Completion Certificate	100%



TABLE A

Tower – 2

Sr. No.	Tasks / Activity	Percentage of work done
1	Excavation	100%
2	1 number Plinth	100%
3	2 number of Podium	100%
4	Stilt Floor	100%
5	26 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats / Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	100%
8	Staircase, Lifts Wells and Lobbies at each floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Wing	100%
10	Installation of Lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to common areas, electro, mechanical equipment, Compliance to conditions of environment / CRZ NOC, Finishing to entrance lobby, plinth protection, paving of areas appurtenant to Wing, Compound Wall and all other requirements as may be required to Obtain Occupation / Completion Certificate	100%

TABLE A

Tower - 3

Sr. No.	Tasks / Activity	Percentage of work done
1	Excavation	100%
2	1 number Plinth	100%
3	2 number of Podium	100%
4	Stilt Floor	100%
5	26 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats / Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	100%
8	Staircase, Lifts Wells and Lobbies at each floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Wing	100%
10	Installation of Lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to common areas, electro, mechanical equipment, Compliance to conditions of environment / CRZ NOC, Finishing to entrance lobby, plinth protection, paving of areas appurtenant to Wing, Compound Wall and all other requirements as may be required to Obtain Occupation / Completion Certificate	100%



TABLE A

Tower – 4

Sr. No.	Tasks / Activity	Percentage of work done
1	Excavation	100%
2	1 number Plinth	100%
3	2 number of Podium	100%
4	Stilt Floor	100%
5	26 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats / Premises, Doors and Windows to each of the Flat/ Premises	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	85%
8	Staircase, Lifts Wells and Lobbies at each floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Wing	100%
10	Installation of Lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to common areas, electro, mechanical equipment, Compliance to conditions of environment / CRZ NOC, Finishing to entrance lobby, plinth protection, paving of areas appurtenant to Wing, Compound Wall and all other requirements as may be required to Obtain Occupation / Completion Certificate	100%

TABLE A

Tower – 5

Sr. No	Tasks / Activity	Percentage of work done
1	Excavation	100%
2	1 number Plinth	100%
3	2 number of Podium	100%
4	Stilt Floor	100%
5	26 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats / Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	75%
8	Staircase, Lifts Wells and Lobbies at each floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Wing	100%
10	Installation of Lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to common areas, electro, mechanical equipment, Compliance to conditions of environment / CRZ NOC, Finishing to entrance lobby, plinth protection, paving of areas appurtenant to Wing, Compound Wall and all other requirements as may be required to Obtain Occupation / Completion Certificate	100%

TABLE A

Tower – 6

Sr. No.	Tasks / Activity	Percentage of work done
1	Excavation	100%
2	1 number Plinth	100%
3	2 number of Podium	100%
4	Stilt Floor	100%
5	26 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats / Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	60%
8	Staircase, Lifts Wells and Lobbies at each floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	90%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Wing	95%
10	Installation of Lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to common areas, electro, mechanical equipment, Compliance to conditions of environment / CRZ NOC, Finishing to entrance lobby, plinth protection, paving of areas appurtenant to Wing, Compound Wall and all other requirements as may be required to Obtain Occupation / Completion Certificate	85%

TABLE-B
Tower – 1 - 6
Common Areas (Internal & External Development Works) in Respect of the Registered
Phase/ Project Number

S. No	Common areas and Facilities	Proposed (Yes/No)	Percentage of Work done (As on date of the certificate)	Details
1.	Internal Roads & Footpaths	Yes	75%	Work in progress
2.	Water Supply	Yes	60%	Work in progress
3.	Sewerage (chamber, lines, Septic Tank , STP)	Yes	80%	Work in progress
4.	Storm Water Drains	Yes	100%	Completed
5.	Landscaping & Tree Planting	Yes	75%	Work in progress
6.	Street Lighting	Yes	47%	Work in progress
7.	Community Buildings	Yes	0%	
8.	Treatment and disposal of sewage and sullage water	Yes	90%	Work in progress
9.	Solid Waste management & Disposal	Yes	80%	Work in progress
10.	Water conservation, Rain water harvesting	Yes	70%	Work in progress
11.	Energy management	Yes	05%	Work in progress
12.	Fire protection and fire safety requirements	Yes	85%	Work in progress
13.	Electrical meter room, sub-station, receiving station	Yes	85%	Work in progress
14.	Others			

Yours Faithfully,



SANDEEP PRABHU
(Reg No. CA-92/14860)

Agreed & Accepted By

SAURABH SHANKAR NATU
Digitally signed by
SAURABH SHANKAR NATU
Date: 2025.02.06
15:04:47 +05'30'



SAURABH NATU

Director, Horizon Projects Pvt. Ltd.