



ARCHITECTS & ENGINEERS

- 15/2, Jeelani manzil, Opp. Portuguese Church
Gokhale Road (N), Dadar(W), Mumbai - 400 028
- E-mail : vinnidesai1@gmail.com

**FORM - 1
ARCHITECT'S CERTIFICATE**

Date: 12th April 2024

To,

MACROTECH DEVELOPERS LIMITED
412-4, 17G Vardhman Chamber,
Cawasji Patel Road, Horniman Circle,
Fort. Mumbai – 400001

**Subject: Certificate of Percentage of Completion of Construction Work of “VIOLET E & F “
having MahaRERA registration number “P51700022825” being developed by
MACROTECH DEVELOPERS LIMITED**

Sir,

We have undertaken assignment as Architect /Licensed Surveyor of certifying Percentage of Completion of Construction Work of the **VIOLET E & F** having MahaRERA registration number **“P51700022825”** being developed by MACROTECH DEVELOPERS LIMITED

Based on site inspection, with respect to Layout/ each of the Building/ Wing of the aforesaid Real Estate Project. We certify that as on the date of this certificate, the percentage of work done for each of the building/wing of the real estate project under MahaRERA is as per Table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

TABLE-A**Building Violet - E**

Sr. No.	Tasks / Activity	Percentage of work done as on 31st March 2024
1	Excavation	100%
2	0 number of Basements (S) and Plinth	100%
3	0 number of podiums	-
4	Stilt Floor	-
5	13 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation / Completion Certificate	100%

Building Violet - F

Sr. No.	Tasks / Activity	Percentage of work done as on 31st March 2024
1	Excavation	100%
2	0 number of Basements (S) and Plinth	100%
3	0 number of podiums	-
4	Stilt Floor	-
5	13 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas	100%

	appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation / Completion Certificate	
--	---	--

Building
Violet - J

Sr. No.	Tasks / Activity	Percentage of work done as on 31st March 2024
1	Excavation	100%
2	0 number of Basements (S) and Plinth	100%
3	0 number of podiums	-
4	Stilt Floor	-
5	13 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	75%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	35%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	65%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	90%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation / Completion Certificate	70%




Table B - Common Areas & Amenities (Project level)

Sr. No.	Common areas and Facilities, Amenities	Percentage of work done as on 31st March 2024
1	Internal Roads & Foothpath	75%
2	Water Supply	90%
3	Sewarage (Chamber, lines, Septic Tank, STP)	90%
4	Storm Water Drains	90%
5	Landscaping & Tree Planting	66%
6	Street Lighting	66%
7	Community Buildings	66%
8	Treatment and disposal of sewage and sullage water	90%
9	Solid Waste management & disposal	90%
10	Water conservation, Rain water	90%
11	Energy management	66%
12	Fire protection and fire safety requirements	66%
13	Electrical meter room, sub-station receiving station	90%
14	Aggregate area of recreational Open Space	66%
15	Open Parking	66%
16	Closed Parking	NA
17	Others (Option to Add more)	-

Yours Faithfully

For Vilas Desai & Associates



Architect: Vini Vilas Desai
Registration No.: CA/2008/43203

For MACROTECH DEVELOPERS LIMITED


Authorised Signatory