

architect sachin potdar

Office no.04, 2nd floor, Girnar Society,
Eduji road, Opp. Makhmali talao,
Thane (W), Maharashtra- 400602

sachin@in-asp.com, sachinpotdar21@gmail.com
www.architectsachinpotdar.com



DATE : 30/09/2025

To,
SHUBHASHISH DEVELOPERS
Office No. D/107 & 108, 1st Floor,
Shubhashish, Opp. Mahila Bhavan,
Near Marigold Layout,
Mira Road (E), Thane- 401107.

SUBJECT:- Certificate Of Percentage Of Completion Of Construction Work Of **SHUBHASHISH DEVELOPERS** Building No – 7A, 7B, 8A & 8B (As Per Approved Plan) And Wing B,C,A & D (As Per Sale Plan) Of The Project Situated On The Plot Bearing Survey No. 422 New Survey No.103 Hissa No. 9, Old Survey No. 420 New Survey No.116 Hissa No. 2, Old Survey No.420 New Survey No.116 Hissa No.3, Old Survey No.422, New Survey No.103 Hissa No. 11, Old Survey No.422, New Survey No.103 Hissa No. 10, Old Survey No.419 New Survey No.106, And Old Survey No.423 New Survey No.105 New Hissa No.5/D, Demarcated By Its Boundaries (Latitude And Longitude Of The End Points) (Bldg. Name N.G VIBRANCY And 6 Meter Internal Road) To The North, (M.B.M.C. Mayor Bungalow) To The South, (Survey No. 442) To The East, (18.00mt D.P. Road And Marigold Bldg. No. 1) To The West Situated, Lying And Being At Village Navghar, Bhayandar, Taluka And District Thane-401107 Admeasuring **4313.22 Sq.Mts** Area Being Developed By **M/S. SHUBHASHISH DEVELOPERS**.

REFERENCE : MahaRERA Registration No. **P51700024319**.

Sir,

I/We ARCHITECT SACHIN POTDAR Have undertaken assignment as L.S/Consulting Engineer of certifying Percentage of completion of construction work of M/S. **SHUBHASHISH DEVELOPERS** Building No – 7A, 7B, 8A & 8B (As per approved plan) and Wing B,C,A & D (As per sale plan) of Project situated on the plot bearing survey No. 422 New Survey No.103 Hissa No.9, Old Survey No. 420 New Survey No.116 Hissa No. 2, Old Survey No.420 New Survey No.116 Hissa No.3, Old survey No.422, New Survey No.103 Hissa No. 11, Old survey No.422, New Survey No.103 Hissa No. 10, Old survey No.419 New Survey No.106, and Old survey No.423 New Survey No.105 New Hissa No.5/D demarcated by its boundaries (latitude and longitude of the end points) **(Bldg. Name N.G VIBRANCY and 6 meter Internal Road) to the North, (M.B.M.C. Mayor Bungalow) to the South, (Survey No. 442) to the East, (18.00mt D.P. Road and Marigold Bldg. No. 1) to the west** situated, lying and being at Village Navghar, Bhayandar, Taluka and District Thane-401107 admeasuring **4313.22 sq.mts** area being developed by **M/s. SHUBHASHISH DEVELOPERS**.

Following technical Professionals are appointed by owner / Promoter:-

- i) M/s. Architect Sachin Potdar as L.S/Consulting Engineer
- ii) M/s. Profiles Structural Consultant as Structural Consultant
- iii) Mr. Jiten Patel as Site Supervisor & quantity surveyor
- iv) Mr. Mukesh Prabhakar as Site Engineer
- v) M/s. Aqualine Engineers as Plumbing Consultant

architect sachin potdar

Office no.04, 2nd floor, Girnar Society,
Eduji road, Opp. Makhmali talao,
Thane (W), Maharashtra- 400602

sachin@in-asp.com, sachinpotdar21@gmail.com
www.architectsachinpotdar.com



Based on information given to me by you, with respect to each of the building/Wing of the aforesaid real Estate Project, I certify that as on the date of this certificate, the percentage of work done for each of the building/wing of the Real Estate Project registered under MahaRERA vide registration no. P51700024319 is as per table A herein below. The Percentage of the work executed with respect to each of the activity of the entire phase is detailed in table B.

Table A

Shubhashish Building No – 7A, 7B, 8A & 8B (As per approved plan) and Wing B,C,A & D (As per sale plan),

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	Plinth	100%
3	Podiums	NIL
4	Stilt Floor	100%
5	15 NUMBER OF SLABS OF SUPER STRUCTURE	
	WING -A	55%
	WING -B	55%
	WING -C	55%
	WING -D	55%
6	Internal walls, Internal Plaster Flooring within Flats/Premises, Doors and windows to each of the Flat/Premises	NIL
7	Sanitary fitting within the Flat/premises, Electrical fitting within the flat/premises	NIL
8	Staircase, Lifts wells and Lobbies at each Floor Level Connecting Staircase and Lifts, Overhead and Underground Water Tanks.	10%
9	The External Plumbing and external plaster elevation completion of Terraces with water proofing of the building/wing.	NIL
10	Installation of lifts, water Pump, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fitting to common areas, electro. Mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, Plinth Protection, Paving of ears apartment to building/Wing Compound Wall and all other requirements as may be required to obtain occupation/completion certificate.	NIL

architect sachin potdar

Office no.04, 2nd floor, Girnar Society,
Eduji road, Opp. Makhmali talao,
Thane (W), Maharashtra- 400602

sachin@in-asp.com, sachinpotdar21@gmail.com
www.architectsachinpotdar.com



Table B

Internal & External Development Works in respect of the entire Registered Phase

Sr. No.	Common areas and Facilities Amenities	Proposed (Yes/No)	Percentage of work done	Details
1	Internal Roads & Footpaths	NO	NIL	NIL
2	Water Supply	YES	NIL	NIL
3	Sewerage (Chamber, lines, Septic tank STP)	YES	NIL	NO S. T. P.
4	Storm water Drains	YES	NIL	NIL
5	Landscaping & tree Planting	YES	NIL	NIL
6	Street Lighting	NO	NIL	NIL
7	Community Building/ Club House	NO	NIL	NIL
8	Treatment and disposal of Sewage and Sullage water	NO	NIL	NIL
9	Solid Waste Management & Disposal	NO	NIL	NIL
10	Water Conservation Rain water harvesting	YES	NIL	NIL
11	Energy Management	YES	NIL	SOLAR WATER HEATER
12	Fire Protection and fire safety requirement	YES	NIL	NIL
13	Electrical meter room, sub-station receiving station	YES	NIL	NIL
14	Other (Option to Add more)	NO	NIL	NIL

Yours faithfully



For SHUBHASHISH DEVELOPERS

ARCHITECT SACHIN POTDAR
CA/2007/40779