

H. J. THAKUR ARCHITECTS PVT. LTD.

3rd Floor, Srishti House, N.S.B. Road, Mulund (West), Mumbai - 400 080.
Tel.: 2590 5050 Telefax : 2590 5445

FORM1

ARCHITECT'S CERTIFICATE

Date: 31.12.2018

To
Shivkrupa Enterprises
Srishti House, 1st Floor,
Opp. Vikas Centre, NSB Road,
Mulund (W), Mumbai -80

Subject: Certificate of percentage of Completion of Construction work of 1 wing(s) of the First phase of the Project situated on the Plot Bearing CTS 479(PT) of Village Nahur, at mulund goregaon link road. Bhandup west Mumbai - 400078, demarcated by its boundaries (Latitude and longitude of the end points) 191000.1N , 725555.0E to the North 190953.8N , 725555.0E to the south 190957.4N , 725558.4E to the East 190958.8N , 725552.4E to the West of Division, Village Nahur, at mulund goregaon link road. Bhandup west Mumbai - 400078 admeasuring 16323.10Sq.mts. are being developed by M/s. Shivkrupa Enterprises.

Sir,

I/We **H.J. Thakur Architects Pvt. Ltd.**, have under taken assignment as Architect/Licensed Surveyor of certifying Percentage of Completion of Construction Work of **SRISHTI OASIS (PALMS)** the Building(s)/**1** Wing(s) of the **FIRST** Phase of the Project ,situated on the Plot Bearing CTS 479(PT) of Village Nahur, at mulund goregaon link road. Bhandup west Mumbai - 400078 admeasuring **16323.10**Sq.mts. out of which First Phase area is 615.00 Sq.mts. being developed by M/s. Shivkrupa Enterprises.

1. Following technical professionals are appointed by Owner/ Promoter:-

- (i) M/s. **H.J. Thakur Architects Pvt Ltd.**, as Architect ;
- (ii) M/s. **J.W. Consultants LLP** as Structural Consultant

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project , I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered vide

Number **NIL** under Maha RERA is as per table 'A' herein below.

The Percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table 'B'.

Table A

Building/Wing Number **'A'(PALMS)** (to be prepared separately for each Building/Wing of the Project)

S.no.	Tasks / Activity	Percentage of Work done %
1)	Excavation	100%
2)	2 number of Basement(s) and Plinth	100%
3)	number of Podiums	N.A.
4)	Stilt Floor	100%
5)	22 Number of Slabs of Super Structure	100%
6)	Internal walls, Internal Plaster, Floorings within Flats /Premises, Doors and windows to each of the Flat / Premises	100%
7)	Sanitary Fittings within the Flat Premises, Electrical Fittings within the Flat /Premises	100%
8)	Staircases, Lifts wells and Lobbies at each Floor Floor level connecting Staircass and Lifts, Overhead and Underground Water Tanks	100%
9)	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building / Wing	100%
10)	Installation of Lifts, water pumps, Fire Fighting Fittings and Euipment as per CFO NOC, Electrical fittings to Common Areas, Electro, Mechanical Equipment, Compliance to condition of environment /CRZ NOC, Finishing to entrance lobbys, plinth protection, paving of areas appurtenant to Building /Wing, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate.	100%

TABLE -B

Internal&ExternalDevelopmentWorksInRespectoftheentireRegisteredPhase

S.no.	Common areas & Facilities, Amenities	Proposed (Yes/No)	Percentage of Work done %	Details
1)	Internal Roads & Foot paths	Yes	80%	Work in progress
2)	Water Supply	Yes	100%	Work completed
3)	Sewarage (chamber, lines Septic Tank, STP)	Yes	100%	Work completed
4)	Storm Water Drains	Yes	100%	Work completed
5)	Landscapping& Tree Planting	Yes	100%	Work completed
6)	Street Lighting	Yes	100%	Work completed
7)	Community Buildings	Yes	0%	Completed in phase 2
8)	Treatment and disposal of sewage and sullage water	Yes	0%	Completed in phase 2
9)	Solid Waste Management & Disposal	Yes	100%	Work completed
10)	Water conservation, Rain water harvesting	Yes	100%	Work completed
11)	Energy Management	Yes	0%	Completed in phase 2
12)	Fire Protection and Fire Safety requirements	Yes	100%	Work completed
13)	Electrical meter room, sub-station, receiving station	Yes	100%	Work completed
14)	Others (Option to Add more)	----	----	----

Yours Faithfully,

For **H.J. THAKUR ARCHITECTS PVT LTD.,**

**HARI J
THAKUR**

Digitally signed by HARI J THAKUR
DN: c=IN, o=Personal, CID = 6547695,
2.5.4.20=ab485f191286debbd21a560fc
6184e7a18392d6b77e3673dbf2a84e5
2d7fb103, postalCode=400080,
st=Maharashtra,
serialNumber=ab2e5f1b855591e1aa47
7f3c92c044ad5cee0dc1f2f97c9830e54
42d133f69a1, cn=HARI J THAKUR
Date: 2019.02.28 11:39:22 +05'30'

Signature of Architect

Name :Shri H.J. Thakur

(License NO. CA/78/4641)