



Date: 30-06-2025

To,
Shri. Virendrakumar S. Singh,
Partner of M/s. Thakur Brothers Agri. Farm,
Thakur House, Ashok Nagar,
Kandivali (E), Mumbai-400101

Subject: Certificate of Percentage of completion of construction work for Development of Construction of Building **TW Gardens** situated on Plot bearing CTS No. **809/A/1/19A/1/5 and 809/A/1/19A/1/6** of **Konkan** division & demarcated by its boundaries - latitude and longitude of the end points **19°12' 35.32" N, 72°52' 32.16" E** the North **18.3 Mt. wide existing road** to the South **13.40 Mt. wide existing road** to the East **Hospital reservation plot** to the West **Saraswati Building**. Plinth area admeasuring **4318.84 sq.mts** being developed by **Shri. Virendrakumar S. Singh**, Partner of M/s. Thakur Brothers Agri. Farm.

Sir,

I, **Ketan H. Mehta** have undertaken assignment as Licensed Surveyor of certifying Percentage of Completion of Construction Work of Building of the Project situated on Plot bearing CTS No. **809/A/1/19A/1/5 and 809/A/1/19A/1/6** of **Konkan** division & demarcated by its boundaries - latitude and longitude of the end points **19°12' 35.32" N, 72°52' 32.16" E** the North **18.3 Mt. wide existing road** to the South **13.40 Mt. wide existing road** to the East **Hospital reservation plot** to the West **Saraswati Building** . Plinth area admeasuring **4318.84 sq.mts** being developed by **M/s Vasudev C Wadhwa Construction (Wadhwa)**.

Following Technical Professionals are appointed by Owner / Promoter :-

- i. Mr. Ketan H. Mehta as Licensed Surveyor
- ii. M/s IRA Structural Consultants as Structural Consultant
- iii. M/s Urja Building services consultants as MEP Consultant.
- iv. Shri. Birju Nath Goswami as Site Supervisor

Based on Site Inspection, with respect to the Building of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for the building of the Real Estate Project as registered vide number **P51800024368** under MahaRERA is as per table A herein below. The approximate percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.



Table A-1

Building / Wing – Wing A

Sr. No	Tasks /Activity	Percentage of work done
1	Excavation	100%
2	2 Basements & 1 number of Plinth	100%
3	5 number of Podiums	100%
4	1 Stilt Floor	100%
5	30 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	95%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	70%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	95%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	95%

**Table A-2****Building / Wing – Wing B**

Sr. No	Tasks /Activity	Percentage of work done
1	Excavation	100%
2	2 Basements & 1 number of Plinth	100%
3	5 number of Podiums	100%
4	1 Stilt Floor	100%
5	30 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	95%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	100%

**TABLE-B****Internal & External Development Works in Respect of the entire Phase**

S. No	Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentage of Work done	Details
1	Internal Roads & Footpaths	No	NA	As per Master Plan
2	Water Supply	Yes	100%	Connection after OC
3	Sewerage (chamber, lines, Septic Tank , STP)	Yes	100%	STP
4	Storm Water Drains	Yes	100%	As per SWD remarks
5	Landscaping & Tree Planting	Yes	90%	On podium level
6	Street Lighting	No	NA	
7	Community Buildings	No	NA	
8	Treatment and disposal of sewage and sullage water	Yes	80%	STP
9	Solid Waste management & Disposal	Yes	0%	Organic Waste convertor
10	Water conservation, Rain water harvesting	Yes	100%	As per rain water harvesting remark
11	Energy management	Yes	100%	Currently as per electricity supplier guidelines
12	Fire protection and fire safety requirements	Yes	100%	As per CFO NOC of the project
13	Electrical meter room, sub-station, receiving station	Yes	90%	Currently as per electricity supplier guidelines
14	Swimming Pool	Yes	100%	
15	Society Office	Yes	100%	As per MCGM norms
16	Fitness Center	Yes	100%	As per masterplan

Yours Faithfully,

Digitally signed by
Ketan Himatlal Mehta
Date: 2025.07.16
16:46:19 +05'30'

Mr. Ketan H. Mehta
Licensed Surveyor
License No: K/404/LS

Agreed and Accepted by:

Digitally signed by
Navin Amarlal Makhija
Date: 2025.07.16
16:56:55 +05'30'

Authorized Signatory
Name :
Date :