

Annexure A
FORM 1
[See regulation 3]
CERTIFICATE

Date :-22.04.2025

To,
M/s. AVA Lifespaces Pvt. Ltd.
Co-Developers IIFL facilities Service Ltd.
Shop No. 3, Indira Nagar, Raheja Estate,
Kulupwadi, Borivali (East), Mumbai - 400 066

Subject: Certificate of percentage of completion of construction work of proposed Slum Rehabilitation Scheme known as "Sangharsh SRA CHS Ltd." Sale building known as **Maple** of the phase of the project having [Maha RERA Registration P51800078650], situated on plot bearing C.T.S. No. 510, 510/1 to 8, 1, 1/1 to 16, 514, 514/1 to 5, 518A/2 (pt.), 561, 561/1 to 14 & 518 A/1 (pt.), Demarcated as its boundaries Lat. 19°13'40.418"N Lon. 72°51'52.797" to the north, Lat. 19°13'36.795" N Lon. 72°51'52.362" E to the south, Lat. 19°13'38.794" N Lon. 72°51'53.209" E to the East, Lat. 19°13'38.095" N Lon. 72°51'50.457" E to the west, of Village - Kanheri, Taluka - Borivali, Kulupwadi, Borivali (East), Mumbai - 400 066, Admeasuring 7757.80 Sq. Mt. area, site being developed by **M/s. AVA Lifespaces Private Limited.**

Sir,

I Swapnil H. Chinchawade of M/s. Liesha Space Planners, have undertaken assignment as Licensed Surveyor of certificate percentage of Completion of construction work of the Sale building know as **Maple**, phase of the project, situated on the plot bearing C.T.S. No. 510, 510/1 to 8, 1, 1/1 to 16, 514, 514/1 to 5, 518A/2 (pt.), 561, 561/1 to 14 & 518 A/1 (pt.), of Village - Kanheri, Taluka - Borivali, Kulupwadi, Borivali (East), Mumbai - 400 066, having Maha RERA Registration P51800078650, being developed by **M/s. AVA Lifespaces Private Ltd..**

Based On site Inspection, with respect to layout / each of the building/Wing of the aforesaid real estate project. I certify that as on the date of this certificate, the percentage of work done for each of the building/Wing of the Real estate project under MahaRera is as per Table A herein Below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B

TABLE-A

Sale building known as “Maple” proposed slum Rehabilitation Known as
“Sangharsh SRA CHS Ltd.”

Sr no	Task and activity	Percentage of Actual Work Done (As on date of the Certificate)
1	Excavation	0%
2	Basement (if any)	0%
3	Podiums (if any)	0%
4	Plinth	0%
5	Stilt Floor	0%
6	Slab of super Structure	0%
7	Internal walls, Internal plaster, floorings, Doors and windows within Flats/Premises	0%
8	Sanitary Fittings within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level Overhead and underground water tanks.	0%
10	External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0%
11	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings mechanical equipment, Compliance to conditions of environment /CRZ NOC, finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to complete project as per specifications in agreement of sale. Any other activities.	0%

TABLE B

Common areas (internal and external road development works) in respect of the registered phase
/ project number

Sr no	Common areas and Facilities	Proposed (Yes/No)	Percentage of Actual Work Done	Details
1	Internal Roads & Footpaths	No	-	-
2	Water Supply	Yes	0%	-
3	Sewerage (Chamber,	Yes	0%	-

