

# Vehicle Load & Compliance Report

Front Axle	GVM	Rear Axle	TBM	GCM	
1470	3150	1770	350	6250	
1241	2987	1746	238	5489	
-229	-163	-24	-112	-761	
OK	OK	OK	OK	OK	

ATM
3200
2740
-460
OK

Car Load  
Front 2 ADULTS  
Rear CHOOSE  
Fuel FULL

Caravan Load  
Van Water FULL

Advisory Only

Van to Car Ratio <85% 84%  
Tow Ball % 8 to 10% 9%  
Amplitude VAN Axle group 3200  
Actual Axle Group 2502  
Possible Spare Capacity 320 see below

Advisory BTC Ratio  
IDEAL <80% 78%

Information provided is true and correct at the time of weighing, however Vanweight bears no responsibility for changes in weights or circumstances after the printing of this document.

The document is a design only and cannot be used for Licensing or insurance purposes. Please note that if this report shows any areas of your vehicle that are overloaded, your vehicle may not be safe to drive and may pose a safety risk to yourself and other road users. It is now an optionality to resolve any vehicle overloading issues prior to driving the vehicle any further. We accept no liability or responsibility if you continue to drive your vehicle once we have provided with a report