

GEOSPATIAL INTELLIGENCE FOR

Smarter Watershed Development

Visualize, analyze and interpret geo-coded images and satellite data to understand watershed conditions and monitor development outcomes.

Get Started



Trusted by



Satellite
Data



Geo-coded
Images



GIS
Analysis



Sustainable
Future

Land Use

Vegetation

Water Bodies

Drainage

Interventions



GEOSPATIAL INTELLIGENCE FOR

Smarter Watershed Development

Explore geospatial data to visualize, analyze, and monitor watershed conditions for smarter development.



Welcome Back

Sign in to access watershed insights and geospatial tools



User



Organisation



Username



Password



Login →



Watershed Explorer

Visualize, analyze and interpret watershed conditions



Maps

[Land Use Map](#)[Drainage Map](#)[Vegetation Map](#)[Watershed Intervention](#)

Land Use Map



Bhojpur Watershed, Madhya Pradesh, India



Legend

Land Use Map

-  Forest / Vegetation
-  Agriculture
-  Water Body
-  Built-up Area
-  Barren / Land Degradation
-  Watershed Boundary



Map Information


	Location	Bhojpur Watershed, Madhya Pradesh, India
	Data Source	SRISHTI-DRISHTI Platform
	Resolution	30 m
	Last Updated	Apr 28, 2025 10:24 AM

Maps

[Land Use Map](#)[Drainage Map](#)[Vegetation Map](#)[Watershed Intervention](#)

Drainage Map

 Bhojpur Watershed, Madhya Pradesh, India



Legend

Drainage Layers

 Mainstream

 Tributaries

 Drainage Channels



Map Information


	Location	Bhojpur Watershed, Madhya Pradesh, India
	Data Source	SRISHTI-DRISHTI Platform
	Resolution	30 m
	Last Updated	Apr 28, 2025 10:24 AM

Maps

[Land Use Map](#)[Drainage Map](#)[Vegetation Map](#)[Watershed Intervention](#)

Vegetation Map

 Bhojpur Watershed, Madhya Pradesh, India



Legend

Vegetation Layers



Dense Vegetation



Moderate Vegetation



Sparse Vegetation



Map Information



Location

Bhojpur Watershed,
Madhya Pradesh, India



Data Source

SRISHTI-DRISHTI Platform



Resolution

30 m



Last Updated


Apr 28, 2025 | 10:24 AM

Maps

[Land Use Map](#)[Drainage Map](#)[Vegetation Map](#)[Watershed Intervention](#)

Watershed Intervention Map

 Bhojpur Watershed, Madhya Pradesh, India



Legend

Watershed Interventions



Afforestation

8



Check Dam

6



Contour Trenching

5



Water Harvesting Structure

7

Map Status



Completed

12



Ongoing

08



Planned

05



Map Information



Location

Bhojpur Watershed,
Madhya Pradesh, India

Data Source

SRISHTI-DRISHTI Platform



Resolution

30 m



Last Updated

Apr 28, 2025 | 10:24 AM

Maps

[Land Use Map](#)[Drainage Map](#)[Vegetation Map](#)[Watershed Intervention](#)

Watershed Intervention Map

 Bhojpur Watershed, Madhya Pradesh, India

Completed

Afforestation

 Bhojpur Watershed, Madhya Pradesh, India



Before



After



Analysis & Intervention Details



2,500 saplings planted across 12 hectares of degraded land.



Native species used to restore local biodiversity and soil health.



Significant increase in vegetation cover and reduction in soil erosion.



Impact: Improved soil stability | Enhanced water retention | Greener ecosystem



Legend

Watershed Interventions



Afforestation

8



Check Dam

6



Contour Trenching

5



Water Harvesting Structure

7

Map Status



Completed

12



Ongoing

08



Planned

05



Map Information



Location

Bhojpur Watershed,
Madhya Pradesh, India



Data Source

SRISHTI-DRISHTI Platform



Resolution

30 m



Last Updated

Apr 28, 2025 | 10:24 AM

Maps



Land Use Map



Drainage Map



Vegetation Map



Watershed Intervention



< Back to Map

Completed



Afforestation

Bhojpur Watershed, Madhya Pradesh, India



Upload Geotag Photos



Before



1 / 5

Degraded land with sparse vegetation

After



1 / 5

Developed forest cover with healthy vegetation



Key Parameters

Parameter	Before	After	Change
Vegetation Cover	42%	60%	+18% ↑
Water Spread	21%	33%	+12% ↑
Barren Land	35%	26%	-9% ↓
Agricultural Area	38%	42%	+4% ↑
Soil / Land Condition	Moderate	Good	Improved



Project Impact



Global Warming Reduction

-1.8°C

(estimated impact from afforestation)



Trees Planted

50,000

(approx.)



CO₂ Sequestered

≈ 2,800 tCO₂e

(estimated)



Forest Cover Increase

+18%



Watershed Impact



Positive change detected: Increased vegetation and water availability, with a reduction in barren land after watershed intervention.



Site Information



Location

Bhojpur Watershed,
Madhya Pradesh, India



Area Covered

12 hectares



Latitude / Longitude

25.6384° N, 77.1234° E



Elevation

520 m



Intervention Details



Intervention Type

Afforestation



Area Treated

12 hectares

Tree Species

Neem, Peepal, Jamun, Bamboo



Implementation Period

Apr 2023 - Mar 2024



Funding & Duration



Total Project Cost (Nidhi)

₹ 48,00,000



Nidhi Utilized

₹ 44,50,000 (92%)



Duration

12 months



Implementing Authority



Department

Madhya Pradesh Watershed
Development Department



Executing Agency

District Watershed Committee,
Bhojpur



Contact

dwsd.mp@gov.in | +91 7555 123456

Maps



Land Use Map



Drainage Map



Vegetation Map



Watershed Intervention



Back to Map

Planned



Contour Trenching

Bhojpur Watershed, Madhya Pradesh, India

Planned (Design View)



1 / 5



Key Parameters (Planned)

Parameter	Current Status	Expected Change (After Implementation)
Vegetation Cover	42%	↑ ~+15-25%
Water Spread	21%	↑ ~+10-18%
Barren Land	35%	↓ ~-8-15%
Agricultural Area	38%	↑ ~+3-8%
Soil / Land Condition	Moderate	→ Improved



Watershed Impact (Planned)



Expected positive impact: Improved vegetation, better water retention, reduced soil erosion and increased agricultural productivity after the intervention.



Upload Geotag Photos



What will be built?



Contour Trenches

Series of contour trenches across the slope to slow down runoff, increase infiltration and reduce soil erosion.



Type
Soil & Water Conservation



Area Covered
5.6 hectares



Implementation Period
Apr 2025 – Nov 2025



Project Impact (Predicted)



Reduced Runoff

Helps in better water retention and groundwater recharge.



Improved Soil Health

Prevents soil loss and increases fertility over time.



Increased Vegetation

Supports natural regeneration and biodiversity.



Greater Water Availability

Ensures better moisture retention in the watershed.



Site Information



Location
Bhojpur Watershed,
Madhya Pradesh, India



Area Covered
5.6 hectares



Latitude / Longitude
25.6384° N, 77.1234° E



Elevation
520 m



Project Details



Intervention Type
Contour Trenching



Area Treated
5.6 hectares



Tree Species
Neem, Peepal, Jamun, Bamboo



Implementation Period
Apr 2025 – Nov 2025



Funding & Duration



Estimated Project Cost (Nidhi)
₹ 32,50,000 (Approx.)



Nidhi Utilized
— (Planned)



Duration
8 months



Implementing Authority



Department
Madhya Pradesh Watershed
Development Department



Executing Agency
District Watershed Committee,
Bhojpur



Contact
dwsd.mp@gov.in | +91 7555 123456



Upload Geotagged Photos

Add field photos with location data to support this watershed intervention.

[View Uploaded Photos](#) 

Drag & drop your photos here
or click to browse

Supported formats: JPG, PNG | Max size: 10 MB per photo



Search Location



OR



Uploaded Photos

4 photos selected



Clear All



23.6847° N, 77.1234° E
 Vegetation Cover
 Apr 28, 2025 · 10:24 AM



23.6851° N, 77.1256° E
 Soil Conservation
 Apr 28, 2025 · 11:02 AM



23.6823° N, 77.1267° E
 Water Spread
 Apr 28, 2025 · 12:36 PM



23.6809° N, 77.1290° E
 Plantation
 Apr 28, 2025 · 01:15 PM



Selected Location (from photo metadata)

23.6847° N, 77.1234° E

Location Name

Bhojpur Watershed, Madhya Pradesh, India



Important Guidelines



Enable Location

Make sure location services are ON while capturing photos.



Clear Images

Use clear and focused photos for better analysis.



Include Key Areas

Cover all relevant intervention areas (upstream, midstream, downstream).



File Size

Each image should be less than 10 MB.



Why Geotagged Photos?

Geotagged photos help us verify ground conditions, track changes over time and improve the accuracy of watershed analysis.



Validate intervention activities



Track vegetation and water changes



Improve data accuracy



Support impact assessment



Photo Tips



Capture photos from consistent points.



Include landmarks for better location accuracy.



Take photos in good lighting conditions.



Cover multiple angles of the same area.





Analysis Tools



Select Area



Land Use



Drainage



Vegetation



Soil Moisture



Water Bodies



Land Degradation



Interventions



Reports



Select Analysis Area



Search village, watershed, district or coordinates...



or



Select Area on Map



Selected Area

Active

Bhojpur Watershed

District: Bhojpur

State: Madhya Pradesh

Area: 25.64 km²

Coordinates: 25.6384° N, 77.1234° E

Time Period: Apr 2024 – Mar 2025



Analysis Period

Before

2022

After

2025



Generate Analysis Report



Key Indicators



Vegetation Cover

--

No data yet

↑ Change



Water Spread

--

No data yet

↑ Change



Soil Moisture

--

No data yet

↑ Change



Land Degradation

--

No data yet

↑ Change



Agricultural Area

--

No data yet

↑ Change



Water Bodies

--

No data yet


↑ Change



Spatial Change Detection

Before

After



Change Detection Legend

- Increased vegetation
- Increased water
- Land degradation
- Agricultural expansion
- No significant change

Detected Changes

Areas showing significant land-cover or water-resource changes are highlighted spatially.



Trend Analysis

Vegetation

Water Spread

Soil Moisture

Land Degradation



Land Use Distribution



- Forest 42%
- Agriculture 28%
- Barren Land 15%
- Built-up 8%
- Water Body 7%




Thematic Analysis

Land Use

Drainage

Vegetation

Soil Moisture



- Forest
- Agriculture
- Barren Land
- Built-up
- Water Body



Geo-tagged Photos

View All



25.6384° N, 77.1234° E
Vegetation Cover
Apr 28, 2025



25.6881° N, 77.1256° E
Water Body
Apr 28, 2025



25.6800° N, 77.1290° E
Plantation
Apr 28, 2025



Data Sources

- SRISHTI-DRISHTI satellite data (30 m)
- Geo-tagged field photographs
- Watershed boundary
- Thematic layers
- Remote sensing products
- GIS derived layers

Spatial Resolution
30 m (where applicable)



Watershed Condition



Vegetation

↑ Improving



Water Resources

↔ Stable



Soil Condition

↔ Stable



Land Degradation

↓ Decreasing



Intervention Coverage

⚡ Partial



Insights & Recommendations

- Vegetation cover shows improvement in upper catchment.
- Water spread increased in mid-catchment areas.
- Focus on soil conservation in degraded zones.
- Expand plantation in identified priority areas.



Better data. Healthier watersheds. A greener future.



Analysis Tools



Select Area



Land Use



Drainage



Vegetation



Soil Moisture



Water Bodies



Land Degradation



Interventions



Reports



Better data. Healthier
Watersheds. A greener future.

Land Use Analysis

Explore the current land use pattern, understand area distribution and track changes over time.



Selected Area



Bhojpur Watershed

Madhya Pradesh, India

Time Period



2022



-

2025



Generate Report

Land Use Map

Change Detection

Comparison



Land Use Legend

- Forest
- Agriculture
- Barren Land
- Built-up
- Water Body




Geo-tagged Photos

4 photos in this area

View Photos →

Land Use Trend (Area in km²)



Land Use Change (2022 → 2025)

Forest	↑	+2.3%
Agriculture	↑	+1.8%
Barren Land	↓	-1.2%
Built-up	↑	+0.7%
Water Body	↑	+0.4%



Land Use Summary

The watershed has a diverse land use pattern with significant forest and agricultural cover. Over the selected period, there is a positive trend in vegetation and water bodies, with a slight increase in built-up area and reduction in barren land.

Land Use Breakdown



Forest	42%
Agriculture	28%
Barren Land	15%
Built-up	8%
Water Body	7%

Land Use Details

Class	Area (km²)	% of Total
Forest	10.75	42%
Agriculture	7.18	28%
Barren Land	3.84	15%
Built-up	2.05	8%
Water Body	1.82	7%

Key Insights

- Forest cover is dominant in the northern and eastern parts of the watershed.
- Agricultural land is concentrated in the central and southern regions.
- Built-up area is limited and mostly near road networks and villages.
- Water bodies are mainly concentrated in the central low-lying areas.

Data Sources

- SRISHTI-DRISHTI satellite data (30 m)
- Geo-tagged field photographs
- Watershed boundary
- Thematic layers
- Remote sensing products
- GIS derived layers



Spatial Resolution
30 m (where applicable)



Analysis Tools

[Select Area](#)[Land Use](#)[Drainage](#)[Vegetation](#)[Soil Moisture](#)[Water Bodies](#)[Land Degradation](#)[Interventions](#)[Reports](#)

Drainage Analysis

View and analyze the drainage network, water flow patterns and watershed hydrology.



Time Period


2022



→ 2025



Drainage Map



Drainage Legend

- Mainstream
- Tributaries
- Drainage Channels
- Water Bodies
- Watershed Boundary
- Flow Direction

Map Layers

- Drainage Network ☒
- Watershed Boundary ☒
- Water Bodies ☒
- Flow Direction ☐



Drainage Statistics

- Total Drainage Length — km
- Mainstream Length — km
- Tributary Length — km
- Drainage Channels — km
- Drainage Density — km/km²
- No. of Streams —
- Stream Order (max) —



Drainage Characteristics

- Mainstream pattern
(e.g., dendritic / parallel / trellis)
- Tributary distribution
(even / clustered / sparse)
- Stream density
(low / moderate / high)
- Flow direction
(e.g., NW → SE)
- Areas with concentrated drainage
(identified from flow accumulation)



Drainage Network Analysis

Stream Length by Order



Drainage Density



Flow Direction



Selected Drainage Feature



Type: Tributary
Stream Order: 2nd
Length: 6.4 km
Flow Direction: → East
Connected to: Mainstream

[View Detailed Information](#)

Key Insights

- The drainage network shows a dendritic pattern with the main stream flowing from west to east.
- Higher drainage density is observed in the central and eastern parts of the watershed.
- Several first-order streams contribute to the main reservoir in the south-east.
- Areas with concentrated drainage indicate potential zones for water harvesting and conservation.



Recommendations

- Strengthen drainage channels in high runoff zones.
- Promote check dams and water harvesting structures.
- Protect sensitive areas with high erosion risk.
- Maintain natural flow paths and avoid encroachment.



Better data. Healthier Watersheds. A greener future.



Analysis Tools

- Select Area >
- Land Use >
- Drainage
- Vegetation** >
- Soil Moisture >
- Water Bodies >
- Land Degradation >
- Interventions >
- Reports >



Vegetation Analysis

Analyze vegetation cover, health, density and changes over time using satellite and field data.


Select Area

Bhojpur Watershed

Time Period

2022 → 2025

Vegetation Map



Vegetation Index (NDVI)

- Very High (0.7 – 1.0)
- High (0.5 – 0.7)
- Moderate (0.3 – 0.5)
- Low (0.1 – 0.3)
- Very Low (-1.0 – 0.1)

Map Layers

- Vegetation Index (NDVI)
- Land Use Boundary
- Watershed Boundary
- Water Bodies
- Geo-tagged Photos



Key Vegetation Indicators



Vegetation Cover

—
 % (vs. previous period)



Forest Area

—
 ha (vs. previous period)



Plantation Area

—
 ha (vs. previous period)



NDVI (Avg.)

—
 (vs. previous period)



Vegetation Health

—
 (vs. previous period)



Reforestation Coverage

—
 % (vs. previous period)



Vegetation Insights

- Vegetation cover is improving in most parts of the watershed.
- Higher NDVI values are observed in the northern and central regions.
- Plantation and forest areas are expanding compared to the previous period.
- Areas with low vegetation index are mainly in the south-eastern region (possible degradation risk).



Data Sources

- SRISHTI-DRISHTI satellite data (30 m)
- Geo-tagged field photographs
- Watershed boundary
- Thematic layers
- Remote sensing products
- GIS derived layers

Spatial Resolution
30 m (where applicable)



Vegetation Cover Trend

2022 2025



Vegetation Condition



- Dense Forest 42%
- Moderate Vegetation 28%
- Sparse Vegetation 15%
- Agriculture (Veg. Cover) 10%
- Degraded / Barren 5%

Change Detection (2022 → 2025)



Vegetation Change Summary

- Increase in vegetation cover
- Improved forest density
- Reduction in barren land
- Slight increase in degraded areas
- Overall vegetation health



Greener Tomorrow

Better vegetation today,
stronger watershed tomorrow.

Healthier Watersheds.
Greener Future.



Analysis Tools

[Select Area](#)[Land Use](#)[Drainage](#)[Vegetation](#)[Soil Moisture](#)[Water Bodies](#)[Land Degradation](#)[Interventions](#)[Reports](#)

Soil Moisture Analysis

Visualize soil moisture levels, identify dry/wet zones and assess water availability in the selected area(s)



Select Area

Bhojpur Watershed



Time Period




2022



2025



Soil Moisture Map



Soil Moisture Legend

- Very High (> 40%)
- High (30 – 40%)
- Moderate (20 – 30%)
- Low (10 – 20%)
- Very Low (< 10%)
- Watershed Boundary

Map Layers

- Soil Moisture (active) ☒
- Watershed Boundary ☒
- Water Bodies ☒
- Land Use (optional) ☐



Key Soil Moisture Insights

- Highest soil moisture in forested and riparian areas (30 – 45%).
- Moderate moisture in agricultural lands (20 – 30%).
- Low moisture in barren and degraded areas (5 – 15%).
- Overall, soil moisture is higher in the eastern part of the watershed compared to the western part.



Soil Moisture Statistics

Parameter	Value
Average Soil Moisture	24.6%
Highest Value	43.2%
Lowest Value	6.8%
Area (High Moisture)	18.7% km ² (22%)
Area (Low Moisture)	12.4% km ² (15%)
Total Area Analyzed	84.3% km ²



Soil Moisture Trend



Soil Moisture Distribution



Data Sources

- SRISHTI-DRISHTI satellite data (30 m)
- Geo-tagged field photographs
- Watershed boundary
- Thematic layers
- Remote sensing products
- GIS derived layers

Spatial Resolution
30 m (where applicable)



Moisture Zones (Map View)



Change Detection (2022 → 2025)

- Increase in moisture +12.4% (20.3 km²)
- Stable moisture +48.7% (41.1 km²)
- Decrease in moisture -8.9% (7.5 km²)



Key Takeaways

- Moisture levels are improving in the eastern region.
- Western region shows signs of moisture stress.
- Focus on soil conservation and water harvesting in low moisture zones.
- Maintain vegetation cover to improve soil moisture retention.



Healthier Watersheds.
Greener Future.



Analysis Tools



Select Area



Land Use



Drainage



Vegetation



Soil Moisture



Water Bodies



Land Degradation



Interventions



Reports



Water Bodies Analysis

Map and analyze water bodies, their extent, condition and changes over time.



Select Area

Bhojpur Watershed



Time Period




2022



2025



Water Bodies Map



Water Body Legend

- River / Stream
- Lake / Reservoir
- Pond / Tank
- Wetland
- Water Body Boundary
- Watershed Boundary

Map Layers

- Water Bodies ☒
- Rivers & Streams ☒
- Watershed Boundary ☒
- Geo-tagged Photos ☒



Water Body Statistics

Total Water Body Area	12.46 km ²
Total Number of Water Bodies	34
Largest Water Body	Bhojpur Reservoir (2.43 km ²)
Smallest Water Body	0.01 km ²
Average Size	0.37 km ²
Total Perimeter	48.21 km
Water Spread (from satellite)	12.46 km ²
Change in Water Spread (2022 → 2025)	↑ +8.7%



Key Insights

- ✓ The watershed has 3 major water bodies (reservoir/lake).
- ✓ Water spread increased by 8.7% compared to 2022.
- ✓ Most water bodies are located in the southern and central parts of the watershed.
- ✓ Several small ponds have shown seasonal variation in water extent.




Water Body Types




Water Spread Trend

+ 2022 + 2025



Water Body Change Detection



Data Sources

- ✓ SRISHTI-DRISHTI satellite data (30 m)
- ✓ Geo-tagged field photographs
- ✓ Watershed boundary
- ✓ Thematic layers
- ✓ Remote sensing products
- ✓ GIS derived layers

Spatial Resolution
30 m (where applicable)

Detailed Water Body Information

ID	Type	Name	Area (km ²)	Condition	Trend (2022 → 2025)
WB-01	Reservoir	Bhojpur Reservoir	2.43	Good	↑ +12.5%
WB-02	River	Madhya River	4.12	Good	↑ +6.8%
WB-03	Pond	Kallu Pond	0.36	Moderate	↑ +3.2%
WB-04	Lake	Chhoti Lake	1.08	Good	↑ +9.7%
WB-05	Wetland	East Wetland	0.41	Fair	↑ +4.3%



Water Body Insights

- Total water body area increased by 8.7% from 2022 to 2025.
- Reservoir shows significant improvement in water spread.
- Seasonal variation observed in small ponds and wetlands.
- Most water bodies show good health, with few areas of moderate condition.

Healthier Watersheds.
Greener Future.



Analysis Tools

- Select Area
- Land Use
- Drainage
- Vegetation
- Soil Moisture
- Water Bodies
- Land Degradation
- Interventions
- Reports



Land Degradation Analysis

Identify and assess areas of land degradation using satellite data, vegetation indices and change detection.



Select Area

Bhojpur Watershed



Time Period




2022



2025



Land Degradation Map



Degradation Legend

- Severe Degradation
- Moderate Degradation
- Slight Degradation
- Stable / No Degradation
- Water Body
- Watershed Boundary
- River/Stream

Map Layers

- Degradation Layer
- Watershed Boundary
- Rivers & Streams
- Water Bodies
- Geo-tagged Photos



Land Degradation Statistics

Total Area Analyzed	25.64 km²
Severe Degradation	18.7%
Moderate Degradation	32.4%
Slight Degradation	27.1%
Stable / No Degradation	21.8%

Degradation Trend (2022 → 2025)

↑ +6.8%

Overall degradation increased by 6.8% in the selected period.



Key Insights

- Severe degradation is concentrated in the eastern and southern parts of the watershed.
- Moderate degradation is observed in agricultural lands with low vegetation cover.
- Stable areas are mainly forested regions and protected zones.
- Soil erosion risk is high in sloped areas with sparse vegetation.




Data Sources

- SRISHTI-DRISHTI satellite data (30 m)
- Geo-tagged field photographs
- Watershed boundary
- Thematic layers
- Remote sensing products
- GIS derived layers

Spatial Resolution
30 m (where applicable)



Degradation Area Chart



Degradation by Land Use



Change Detection (2022 → 2025)



Land Degradation Summary

The analysis shows a moderate increase in land degradation from 2022 to 2025, with severe degradation concentrated in the eastern and southern parts of the watershed. Agricultural lands and barren areas are most affected, while forested regions remain relatively stable.



Recommended Actions

- Promote soil and water conservation in degraded areas.
- Implement afforestation and vegetation restoration.
- Control erosion through contour bunding and check dams.
- Monitor high-risk zones regularly using satellite data.



Healthier Watersheds.
Greener Future.

Analysis Tools

- Select Area >
- Land Use >
- Drainage >
- Vegetation >
- Soil Moisture >
- Water Bodies >
- Land Degradation >
- Watershed Interventions >
- Reports >



Watershed Intervention Analysis

Locate, monitor and assess watershed interventions using geospatial data and field evidence.



Select Area

Rani Khet Watershed



Time Period



2022 – 2025



Generate Report

Intervention Map



Intervention Legend

- Completed 12
- Ongoing 7
- Planned 6

Total Interventions 25

Intervention Types

- Afforestation
- Check Dam
- Contour Trenching
- Water Harvesting Structure

Selected Intervention Details

Completed



Afforestation



Location: Khardi Village (West Zone)



Coordinates: 20.3124° N, 73.8567° E



Area Covered: 2.4 ha



Implementation Period: Jun 2023 – Dec 2023

Before



< 1 / 5 >

After



< 1 / 5 >

Key Parameters

Parameter	Before	After	Change
Vegetation Cover	22 %	68 %	↑ +46 %
Water Spread	3.2 ha	8.7 ha	↑ +5.5 ha
Barren Land	18 %	7 %	↓ -11 %
Agricultural Area	45 %	40 %	↓ -5 %
Soil Condition	Poor	Good	↑ Improved

Site Information

- Location: Khardi Village
- Area: 2.4 ha
- Latitude: 20.3124° N
- Longitude: 73.8567° E
- Elevation: 612 m

Intervention Details

- Type: Afforestation
- Area Treated: 2.4 ha
- Duration: 12 months
- Description: Native tree plantation with soil conservation measures.

Funding & Duration

- Project Cost: ₹ 15,00,000
- Nidhi Utilized: ₹ 12,50,000
- Duration: Jan 2023 – Dec 2023

Implementing Authority

- Department: Forest & Environment
- Agency: Watershed Development Cell
- Contact: 98765 43210




Project Impact

- Vegetation Change: +46% (Increased)
- Water Spread Change: +5.5 ha (Increased)
- Soil Condition: Improved
- Land Degradation: Decreased

Intervention Summary



Intervention Distribution



Intervention Locations on Map

- Completed 12
- Ongoing 7
- Planned 6



Click on a marker to view intervention details.

Insights

- Afforestation interventions are concentrated in the eastern region.
- Check dams are effective in increasing water spread in lower catchment.
- Contour trenching is planned in high erosion risk zones.
- Overall, interventions show positive impact on vegetation and water availability.

Healthier Watersheds.
Greener Future.



Analysis Tools

[Select Area](#)[Land Use](#)[Drainage](#)[Vegetation](#)[Soil Moisture](#)[Water Bodies](#)[Land Degradation](#)[Interventions](#)[Reports](#)

District Watershed Report

Comprehensive overview of watershed conditions, changes and key insights for the selected district using satellite data, GIS and field observations.



District Name
Raigad



Total Area
4,892 km²



Reporting Period
2022 – 2025

[Download PDF](#)[Share Report](#)

Key Indicators (District Level)



Vegetation Cover

41.7%

↑ +6.8%



Water Resources

4.6%

↑ +2.1%



Soil Moisture

32.8%

↑ +4.5%



Land Degradation

14.2%

↓ -3.7%




Interventions

36

(22 Completed, 9 Ongoing, 5 Planned)

District Watershed Map



Land Use / Land Cover

- Agricultural Land
- Forest / Dense Vegetation
- Sparse Vegetation
- Built-up / Settlement
- Water Bodies
- Barren / Open Land
- Wasteland / Degraded Land

- Watershed Boundary
- Rivers / Drainage

Overall Health Summary



Good	62%
Moderate	24%
Poor	14%




The district shows an overall GOOD health status with improving vegetation cover and water resources.

Key Findings

- Vegetation cover increased by 6.8% compared to previous period.
- Water spread area increased by 2.1% with improved storage capacity.
- Land degradation reduced by 3.7% with successful soil conservation measures.
- Drainage network remains stable with good flow connectivity.
- 5 out of 8 interventions are completed with visible positive impact.

District Parameter Comparison



Spatial Change Detection



Top 5 Areas Requiring Attention

- Southern Valley - High Degradation
- Northern Ridge - Low Vegetation Cover
- Eastern Zone - Soil Moisture Deficit
- Western Hills - Erosion Prone
- Central Watershed - Monitoring Required

Major Interventions (District Level)



Completed	22 (61%)
Ongoing	9 (25%)
Planned	5 (14%)

Intervention Types

Afforestation	14
Check Dam	8
Contour Trenching	6
Water Harvesting Structure	8
Others	2

Project Impact (Overall)

Vegetation Change	+6.8% (Increased)
Water Spread Change	+2.1% (Increased)
Soil Condition	Improved
Land Degradation	Decreased



Key Takeaway

The district shows overall improvement in vegetation cover, water resources and soil condition, with reduced land degradation and good intervention impact.

Healthier Watersheds.
Greener Future.