

LINE PATROL REPORT - 230 kV LINE L2 (SUBSTATION B - SUBSTATION C)

Date: 2026-09-14      Patrol crew: Line crew 4 (ground patrol)      Report time: 17:05

Finding: flashover marks on the insulator strings of phases B and C at tower 18 (suspension tower), with a burnt bird nest on the crossarm between the two phases. No damage to conductors. No marks on phase A. No contact with ground or structure found (phase-to-phase flashover).

Location: tower 18 is 6.5 km from Substation B along line L2 (span table L2, chainage 6.50 km).

Action: nest removed, insulators washed and inspected, line L2 released for service at 18:30.