BLACKPOINT

Professional Vehicle Testing Services

BLACKPOINT

Professional Vehicle Testing Services
VEHICLE INSPECTION REPORT

Ref #	15	Date	02-Aug-2025 02:41 PM	
Customer	Salman Ahmed	VIN #	54321226	
Vehicle	toyota lexus	Model	2020	
Color	Gray	Mileage	50000	
Inspector	Salman Ahmed	Phone	03320469696	

PAINT & BODY					
Front Panel اللوحة الأمامية	/Dent/Crack Deformation مقعر/شق/تشویه	Rear Panel اللوحة الخلفية	/Dent/Crack Deformation مقعر/شق/تشویه		
Rear Bumper المصد الخلفي	Repaired/Painted مصلح/مطلي	Front Windshield الزجاج الأمامي	/Dent/Crack Deformation مقعر/شق/تشویه		

التعليقات: :Comments

good