CEDAR VALLEY MANUFACTURING

MONTHLY PORTABLE FIRE EXTINGUISHER INSPECTION

Site: Building A Ref: INS-0021 Date: 10/21/2026 Inspector: Maria Chen

UNIT	LOCATION	GAUGE	PIN/SEAL	ACCESS	TAG	RESULT	NOTES
FE-112	Office lobby	OK	OK	OK	OK	PASS	
FE-113	Office corridor north	OK	OK	OK	OK	PASS	
FE-114	Office corridor south	OK	OK	OK	OK	PASS	
FE-115	Warehouse aisle 2	RED	OK	OK	OK	**FAIL**	Gauge in red zone, low pressure
FE-116	Warehouse aisle 4	OK	OK	OK	OK	PASS	
FE-117	Warehouse aisle 6	OK	OK	OK	OK	PASS	
FE-118	Warehouse aisle 8	OK	OK	OK	OK	PASS	
FE-119	Warehouse dock door 2	OK	OK	BLOCKED	OK	**FAIL**	Blocked by pallets
FE-120	Warehouse dock door 4	OK	OK	OK	OK	PASS	
FE-121	Battery charging station	OK	OK	OK	OK	PASS	
FE-122	Warehouse east exit	OK	OK	OK	OK	PASS	
FE-123	Shipping office	OK	OK	OK	OK	PASS	

Units inspected: 12 Passed: 10 Failed: 2

Inspector signature: M. Chen