CeEst
CENTER ESTATES TASK TRACKER

CeEst Workplace
Your command center for all operations

Search properties, tenants, tickets, assets, documents...

12 5 Albin Sigei System Administrator

- Workplace
- Operations Center
- My Tasks 18
- Approvals 7
- Calendar
- Reports & BI
- Documents
- Notifications
- Settings
- Help & Support

Quick Support
0722 574 400
support@ceest.co.ke
Mon - Fri 8:00AM - 6:00PM

Collapse Menu

Good Morning, Albin 👋

Here's what's happening across your operations today.

Thursday, 24 July 2026
08:30 AM EAT

Access Your Modules

Property Management
Manage properties, leases, tenants, billing and collections
24 Properties | KES 4.2M Rent Collected (MTD)

Facility Management
Assets, maintenance, compliance, utilities and sustainability
18 Open Jobs | 92% PPM Compliance

Valuation Tracker
Track valuation instructions, inspections and reports
5 New Jobs | 3 Reports Due

Visitor Management
Register visitors, contractors and manage access
12 Visitors Today | 8 Pre-registered

Help Desk
Raise issues, track requests and get support
7 Open Tickets | 3 High Priority

Procurement
Purchase requisitions, RFQs, POs and supplier management
4 Pending PRs | 12 POs in Progress

Tender Management
Manage tenders, evaluations and contract awards
2 Active Tenders | 1 Closing Soon

Reports & BI
Analytics, dashboards and performance reports
20+ Dashboards | 15 Recent Reports

Clients & CRM
Manage clients, contacts and communications
85 Active Clients | 34 New Leads

Administration
User management, system settings and configurations
12 System Users | 6 Roles

At a Glance

Total Properties	Total Tenants	Monthly Revenue	Open Maintenance	Compliance Score
24	186	KES 12.8M	18	92%
↑ 2 this month	↑ 6 this month	↑ 8.5% vs last month	↓ 4 vs yesterday	↑ 3% vs last month

Critical Alerts 6

- Lift certificate for Finance House expires in 7 days — 24 Jul 2026
- 12 Payment Vouchers awaiting your approval — View now
- Water leakage reported at ABC Towers - Floor 2 — Ticket #MNT-2026-000123
- Lease for Tenant KAL001 expires in 14 days — 07 Aug 2026

View all alerts

My Tasks 18

Approve Payment Voucher	6
Review Maintenance Tickets	5
Approve Purchase Requisitions	4
Review Valuation Reports	2
Tenant Lease Renewals	1

Go to My Tasks

Quick Links

- Add New Property
- New Maintenance Request
- New Purchase Requisition
- New Valuation Instruction

CeEst
FACILITY MANAGEMENT WORKPLACE

Facility Management

Manage your facilities, assets, maintenance and services.

Search assets, work orders, locations, vendors...

12 6 Albin Sigei
Facility Manager

- Workspace
- Operations Center
- My Tasks 18
- Approvals 7
- Calendar

FACILITY MANAGEMENT

- Dashboard
- Buildings & Locations
- Assets & Inventory
- Maintenance
  - Work Orders
  - Planned Maintenance
  - Service Requests
- Facilities Operations
- Energy & Utilities
- Vendors & Contracts
- Inspections
- Reports & BI
- Documents

- Settings
- Help & Support

Quick Support
0722 574 400
support@ceest.co.ke
Mon - Fri 8:00AM - 6:00PM

Collapse Menu

Good Morning, Albin 👋


Here's what's happening with your facilities today.

Thursday, 24 July 2026
08:30 AM EAT

Total Buildings	Active Assets	Open Work Orders	Preventive Maintenance	Energy Usage
12	846	34	92%	1,245 kWh
Active Locations	Total Asset Value KES 245.6M	Urgent 7	Compliance	↓ 8% vs yesterday
View all	View assets	View work orders	View schedule	View utilities

Work Orders Overview

View all



- 7 Overdue
- 12 In Progress
- 10 Pending
- 5 Completed Today

Recent Work Orders

WO-2026-1789	Lift not functioning - Finance House	Overdue
WO-2026-1788	AMC Service - Generator (Utalii House)	In Progress
WO-2026-1787	Lighting repair - Basement Parking	Pending
WO-2026-1786	AC not cooling - Office 3B	Completed

Maintenance Compliance



Target: 90%
↑ 3% vs last month

Critical Alerts 6

- Fire extinguisher expired — Finance House - Floor 5 — 24 Jul 2026
- Water leakage reported — Utalii House - Floor 2 — Ref: SR-2026-00123
- Generator PM overdue — Uchumi House — 23 Jul 2026

View all alerts

My Tasks 18

Approve Work Order	6
Review Inspection Reports	4
Approve Purchase Request	3
Review Contract Renewal	2
Utility Bill Review	3

Go to My Tasks

Assets by Category



HVAC	28%
Electrical	20%
Mechanical	18%
Fire Safety	15%
Plumbing	10%
Other	9%

View all assets

Monthly Maintenance Trend

This Year



Service Requests

New Requests	7
In Progress	15
Resolved Today	9
Avg. Resolution Time	2.4 hrs

View all requests

Quick Actions

- New Work Order
- New Service Request
- Schedule Maintenance
- Add New Asset
- Report an Issue

Total Floor Area	Occupancy Rate	Total Vendors	Open Contracts	Monthly Spend
125,420 m²	93%	28	16	KES 3.8M
				↓ 5% vs last month

Workspace
Operations Center
My Tasks 18
Approvals 7
Calendar

FACILITY MANAGEMENT
Dashboard
Buildings & Locations
Assets & Inventory
Maintenance
Work Orders
Planned Maintenance
Service Requests
Facilities Operations
Energy & Utilities
Vendors & Contracts
Inspections
Reports & BI
Documents

Settings
Help & Support

Quick Support
0722 574 400
support@ceest.co.ke
Mon - Fri 8:00AM - 6:00PM

Collapse Menu

Buildings & Locations

View and manage all your buildings, sites and locations.

+ Add New Building

12	8	125,420 m²	93%	KSh 3.8M
Total Buildings	Locations	Total Floor Area	Average Occupancy	Monthly Operations Cost
Across all locations	Active sites	Gross floor area	All buildings	All buildings

Search buildings or locations... | All Locations | Building Type | Status | More Filters | Map View

Locations Overview

Nairobi Head Office	Nairobi County	5 Buildings
Mombasa Branch	Mombasa County	2 Buildings
Kisumu Office	Kisumu County	1 Building
Eldoret Office	Uasin Gishu County	1 Building
Nakuru Office	Nakuru County	1 Building
Nyeri Office	Nyeri County	1 Building
Meru Office	Meru County	1 Building
Remote Sites	Various Counties	2 Buildings

Location Map



All Buildings (12)

Export

Building Name	Location	Building Type	Floor Area (m²)	Occupancy	Status	Monthly Cost	Actions
Finance House Building ID: BLD-001	Nairobi Head Office Nairobi County	Commercial Office	25,000 m²	98%	Active	KSh 850,000	...
Uchumi House Building ID: BLD-002	Nairobi Head Office Nairobi County	Commercial Office	18,500 m²	92%	Active	KSh 620,000	...
Utalii House Building ID: BLD-003	Nairobi Head Office Nairobi County	Commercial Office	22,000 m²	95%	Active	KSh 710,000	...
Mombasa Offices Building ID: BLD-004	Mombasa Branch Mombasa County	Commercial Office	8,500 m²	85%	Active	KSh 280,000	...

CeEst
CENTER ESTATES TASK TRACKER

Facility Management
Assets & Inventory

Search assets, QR code, serial no., location...

12 6 Albin Sigei Facility Manager

FACILITY MANAGEMENT
- Dashboard
- Buildings & Locations
- Assets & Inventory
- Maintenance
  - Work Orders
  - Planned Maintenance
  - Inspections
  - Service Requests
- Contractors
- Compliance
- Utilities
- Reports & BI

INVENTORY & PROCUREMENT
- Inventory
- Purchase Orders

- Settings
- Help & Support

Quick Support
0722 574 400
support@ceest.co.ke
Mon - Fri 8:00AM - 6:00PM

Collapse Menu

Assets | Inventory

Total Assets	Operational	Under Maintenance	Out of Service	Total Asset Value	Average Asset Health
1,248	1,074	98	76	KES 245.6M	82%
All Buildings	86% of total assets	8% of total assets	6% of total assets	Replacement cost	Good

View all assets >

FILTERS
Clear All

Search filters...

Building: All Buildings
Floor / Location: All Floors
Category: All Categories
Asset Type: All Types
Status: All Status
Condition: All Conditions
Vendor: All Vendors
Installation Date: Select date range

Apply Filters | Reset

Assets (1,248)
Export | Import | + Add New Asset

Asset ID	Asset Name	Category	Location	Status	Condition	Health Score	Actions
AST-0001248	OTIS Lift - Lift 1	Lift Systems	Cradle Building Ground Floor	Operational	Good	92%	...
AST-0001247	Fire Pump Set 1	Fire Safety	Cradle Building Basement	Operational	Good	89%	...
AST-0001246	Main DB - MDB 1	Electrical Systems	Cradle Building Ground Floor	Operational	Good	90%	...
AST-0001245	Water Tank - 20,000L	Water Supply	Roof Level	Operational	Good	85%	...
AST-0001244	CCTV Camera - CAM 12	CCTV / Access Control	Block A - Lobby	Operational	Good	83%	...
AST-0001243	Generator 500KVA	Electrical Systems	Generator Room	Under Maintenance	Fair	65%	...
AST-0001242	Plumbing Booster Pump	Plumbing & Drainage	Basement	Operational	Good	87%	...
AST-0001241	Water Heater - WH 2	Water Supply	Furnished Apt - 5th Floor	Out of Service	Poor	30%	...

Showing 1 to 8 of 1,248 assets
< 1 2 3 4 5 ... 156 > 10 / page

ASSET DETAILS



OTIS Lift - Lift 1
Operational
AST-0001248
Scan QR Code

Overview | History | Documents | Images

Category	Lift Systems
Location	Cradle Building, Ground Floor
Manufacturer	OTIS
Model	Gen2 Comfort
Serial Number	OT-G2-12345
Installation Date	15 Jan 2021
Warranty Expiry	14 Jan 2026
Expected Life	20 Years
Replacement Cost	KES 12,500,000
Current Condition	Good
Health Score	92%
Last Maintenance	22 Jul 2026
Next Maintenance	22 Aug 2026

View Full Details

Inventory Overview

Total Items	In Stock	Low Stock	Out of Stock	Inventory Value
3,246	2,145	378	156	KES 18.6M
All Locations	66% of total items	12% of total items	4% of total items	Total stock value

View inventory >

Recent Low Stock Items
View all

Item Name	Category	Current Stock	Reorder Level	Status
Fire Extinguisher CO2 (4.5kg)	Fire Safety	5	10	Low
Lift Motor Brake	Lift Systems	2	5	Low
Pressure Relief Valve	Plumbing	1	3	Low
CCTV Camera Dome	CCTV Systems	3	6	Low

CeEst
CENTER ESTATES TASK TRACKER

Facility Management
Maintenance Overview

Search assets, work orders, tickets, locations...

Albin Sigei
Facility Manager

FACILITY MANAGEMENT

- Dashboard
- Buildings & Locations
- Assets & Inventory
- Maintenance
  - Overview
  - Work Orders
  - Planned Maintenance
  - Inspections
  - Service Requests
  - Permit to Work
- Contractors
- Compliance
- Utilities
- Reports & BI

INVENTORY & PROCUREMENT

- Inventory
- Purchase Orders

- Settings
- Help & Support

Quick Support
0722 574 400
support@ceest.co.ke
Mon - Fri 8:00AM - 6:00PM

Collapse Menu

Maintenance Overview

Monitor maintenance performance, compliance and asset reliability in real time.

Quick Actions | + Create Work Order

PPM Compliance 92% — Target ≥ 95% — View PPM Calendar >

Open Work Orders 134 — ↓ 8 vs yesterday — View all work orders >

Overdue Work Orders 27 — ↓ 5 vs yesterday — View overdue >

Avg. Resolution Time 6.2 hrs — Target 24 hrs — View SLA Performance >

Asset Health Index 82% — Good — View Asset Health >

Work Orders by Status



- 27 Overdue
- 42 In Progress
- 38 Open
- 18 Pending
- 9 On Hold

Recent Work Orders

View all

Overdue	WO-2026-1789	Lift not functioning - Finance House — Finance House • Lift 1	Overdue	High	
In Progress	WO-2026-1788	Generator not starting — Utalii House • Generator 1	In Progress	High	
Open	WO-2026-1787	Water leakage - Basement Parking — Cradle Building • Water Line	Open	Medium	
Open	WO-2026-1786	CCTV Camera not working - Lobby — Cradle Building • CAM 12	Open	Low	
Completed	WO-2026-1785	Fire extinguisher inspection — Finance House • Fire Safety	Completed	Low	

SLA Performance (This Month)

View all



Within SLA	88%	(236)
At Risk	7%	(19)
Breached	5%	(13)

Work Orders by Priority

View all

Critical	38	
High	52	
Medium	28	
Low	16	

Planned Preventive Maintenance (PPM)

May 2026

Mon	Tue	Wed	Thu	Fri	Sat	Sun
		1	2	3	4	5
6	7	8	9	10	11	12
13	14	15	16	16	18	19
20	21	22	23	24	25	26
27	28	29	30	31		

Completed · Scheduled · Overdue

Upcoming PPM Tasks

View all

MAY 17	Lift Monthly Service - Lift 1 & 2 — Finance House • Lift Systems	Technician: Elevate Ltd.	Priority: High	
MAY 18	Fire Pump Test — Utalii House • Fire Safety Systems	Technician: FireTech Services	Priority: High	
MAY 19	Water Tank Cleaning — Cradle Building • Water Supply	Technician: Aqua Solutions	Priority: Medium	
MAY 20	Generator Servicing — Finance House • Electrical Systems	Technician: PowerGen Ltd.	Priority: Medium	
MAY 21	CCTV System Check — Cradle Building • CCTV / Access	Technician: SecureEye Ltd.	Priority: Low	

Maintenance Cost (This Month)

View report

KES 4.25M
Total Cost

↓ 8.5%
vs last month

Top Cost by Category

Electrical Systems	KES 1.45M	34%
Lift Systems	KES 1.20M	28%
Plumbing & Drainage	KES 860K	20%
HVAC Systems	KES 450K	11%
Fire Safety Systems	KES 290K	7%

Defects by Category (Open)

View all



Electrical Systems	42	(31%)
Plumbing & Drainage	28	(21%)
Lift Systems	24	(18%)
Fire Safety	20	(15%)
CCTV / Access Control	12	(9%)
Others	8	(6%)

Quick Access

Create Work Order | Create Service Request | PPM Calendar | Inspection Checklist | Permit to Work | Asset Register | Contractor Directory

FACILITY MANAGEMENT
Dashboard
Buildings & Locations
Assets & Inventory
Maintenance
Overview
Work Orders
Planned Maintenance
Inspections
Service Requests
Permit to Work
Contractors
Compliance
Utilities
Reports & BI
INVENTORY & PROCUREMENT
Inventory
Purchase Orders
Settings
Help & Support

Quick Support
0722 574 400
support@ceest.co.ke
Mon - Fri 8:00AM - 6:00PM

Collapse Menu

← Back to Work Orders

WO-2026-1787

In Progress

Actions | Print | Edit

Water leakage from basement parking ceiling near lift lobby

Building	Location	Asset	Category	Reported By	Reported On
Cradle Building	Basement 1 - Parking	Water Pipe Line - WL-0034	Plumbing & Drainage	John Mwangi (Tenant)	24 Jul 2026, 09:15 AM

Overview | Details | Tasks & Updates | Costs | Attachments | Asset History | Audit Trail

Work Order Details

Work Order Type	Corrective Maintenance	Status	In Progress
Priority / Severity	High ↑	Current Stage	Repair in Progress
SLA Response Time	Within 4 hours	Progress	60%
SLA Resolution Time	Within 48 hours		
Assigned To	James Kariuki, Building Technician	Created By	System
Contractor	AquaFix Ltd. Assigned	Created On	24 Jul 2026, 09:15 AM
Planned Start	24 Jul 2026, 11:00 AM	Last Updated	24 Jul 2026, 01:45 PM
Due Date	26 Jul 2026, 11:00 AM	Updated By	James Kariuki

Description

Tenant reported water leakage from the basement parking ceiling near lift lobby area. Water dripping observed, causing wet floor and corrosion risk to electrical conduits. Initial inspection confirms leakage from 2" cold water supply pipe joint.

Scope of Work

- Locate and isolate leakage point
- Repair / replace damaged pipe joint
- Test and confirm no further leakage
- Clean affected area and dispose waste

Root Cause (Preliminary)
Pipe joint seal failure due to aging.

Photo Evidence

Reported Image	Inspection Image	Work In Progress	Completed Work
			
24 Jul 2026, 09:18 AM	24 Jul 2026, 10:12 AM	24 Jul 2026, 11:35 AM	24 Jul 2026, 01:35 PM

Parts & Materials

Item	Description	Quantity	Unit	Unit Cost (KES)	Amount (KES)
PIP-CPVC-2IN	CPVC Pipe 2 Inch	2.0	Meter	850.00	1,700.00
PIP-ELBOW-2IN	CPVC Elbow 2 Inch	1.0	Piece	450.00	450.00
SEAL-TAPE	PTFE Thread Seal Tape	1.0	Roll	120.00	120.00
CLAMP-2IN	Pipe Clamp 2 Inch	1.0	Piece	200.00	200.00

+ Add Item

Labor Cost	KES 2,500.00
Parts Cost	KES 2,470.00
Other Cost	KES 300.00
Total Cost	**KES 5,270.00**

SLA Countdown



Response SLA
Within 4 hours
Target: 24 Jul 2026, 01:15 PM
Elapsed: 1h 44m

Resolution SLA
Within 48 hours
Target: 26 Jul 2026, 11:15 AM
Elapsed: 4h 30m

Work Order Timeline

- 24 Jul 09:15 AM — **Work order created** — System
- 24 Jul 09:20 AM — **Assigned to technician** — James Kariuki
- 24 Jul 10:05 AM — **Technician arrived on site** — James Kariuki
- 24 Jul 10:20 AM — **Inspection completed** — James Kariuki — Leakage point identified
- 24 Jul 10:45 AM — **Contractor assigned** — AquaFix Ltd.
- 24 Jul 11:30 AM — **Repair in progress** — James Kariuki
- Next: Work in progress

Remarks


Repair in progress. Expect completion within the next 2 hours.


– James Kariuki
24 Jul 2026, 11:40 AM

Approval

Pending approval from Resident Manager

Request Approval


CeEst
FACILITY MANAGEMENT
Planned Maintenance
Maintenance > Planned Maintenance
Search assets, tasks, teams...
12
5
Albin Sigei
Facility Manager
FACILITY MANAGEMENT
Dashboard
Buildings & Locations
Assets & Inventory
Maintenance
Overview
Work Orders
Planned Maintenance
Inspections
Service Requests
Permit to Work
Contractors
Compliance
Utilities
Reports & BI
INVENTORY & PROCUREMENT
Inventory
Purchase Orders
Settings
Help & Support
Quick Support
0722 574 400
support@ceest.co.ke
Mon - Fri 8:00AM - 6:00PM
Collapse Menu
PPM Compliance (This Month)
92%
Target ≥ 95%
View compliance report
Completed Tasks
168
of 183 scheduled
View completed
Upcoming Tasks
24
Next 7 days
View schedule
Overdue Tasks
7
Require attention
View overdue
Technicians Assigned
18
Active this week
View team workload
Maintenance Cost (MTD)
KES 1.45M
↓ 8.4% vs last month
View cost report
Calendar View
List View
Gantt View
Task Templates
Maintenance Plans
May 12 – May 18, 2026
All Buildings
All Categories
All Status
All Technicians
Filters
Create PPM Task
Maintenance Plans
View all
Lift Systems Maintenance
Monthly
Fire Safety Systems
Quarterly
18 / 20 90%
Generator Maintenance
Monthly
8 / 12 67%
Water Supply Systems
Monthly
9 / 12 75%
Electrical Systems
Monthly
14 / 16 88%
CCTV & Access Control
Monthly
7 / 8 88%
Plumbing & Drainage
Monthly
6 / 10 60%
Add New Maintenance Plan
Mon 12 May
Tue 13 May
Wed 14 May
Thu 15 May
Fri 16 May
Sat 17 May
Sun 18 May
All Day
08:00
09:00
10:00
11:00
12:00
13:00
14:00
15:00
16:00
17:00
Generator Monthly Service
GEN-001
Fire Pump Test
FP-01, FP-02
Lift Inspection
LIFT-1, LIFT-2
Water Tank Cleaning
WT-1
CCTV System Check
CCTV-01 to 08
Lift Preventive Maintenance
LIFT-1
Generator Service
GEN-002
Fire Extinguisher Check
FE-01 to 35
Electrical DB Inspection
DB-MDB-1
Water Pump Service
WP-1, WP-2
HVAC Filter Cleaning
AHU-1 to 3
Lift Inspection
LIFT-3
Generator Load Test
GEN-001
Plumbing Inspection
PL-01 to 10
Access Control Audit
AC-01 to 06
CCTV Camera Check
CAM-01 to 16
Fire Alarm Test
FA-01
Electrical Load Test
DB-FL-1
Water Tank Disinfection
WT-2
Lift Preventive Maintenance
LIFT-2
Generator Oil Change
GEN-005
Sprinkler System Test
SP-01
CCTV NVR Check
NVR-01
Pump Pressure Test
WP-3
Drain Line Cleaning
DR-01 to 06
PPM Compliance Trend
View report
This Month
100%
75%
50%
25%
0%
1 May
7 May
13 May
19 May
25 May
31 May
Compliance %
Target (95%)
Upcoming PPM Tasks
View all
Task ID
Task Name
Asset
Building / Location
Frequency
Due Date
Assigned To
Status
Actions
PPM-2026-0456
Lift Preventive Maintenance
LIFT-2
Cradle Building - Block A
Monthly
15 May 2026, 09:00 AM
James Kariuki
Scheduled
PPM-2026-0457
Fire Pump Test
FP-02
Cradle Building - Basement
Monthly
15 May 2026, 10:00 AM
Peter Mwangi
Scheduled
PPM-2026-0458
Electrical DB Inspection
DB-MDB-1
Cradle Building - Ground Floor
Monthly
15 May 2026, 09:30 AM
David Ochieng
Scheduled
PPM-2026-0459
Water Tank Cleaning
WT-1
Cradle Building - Roof
Monthly
15 May 2026, 08:30 AM
Aqua Solutions Ltd.
In Progress
PPM-2026-0460
CCTV System Check
CCTV-01 to 08
Cradle Building - All Floors
Monthly
16 May 2026, 09:00 AM
SecureEye Ltd.
Scheduled


CeEst
FACILITY MANAGEMENT
Dashboard
Buildings & Locations
Assets & Inventory
MAINTENANCE
Work Orders
Planned Maintenance
Inspections
Service Requests
Permit to Work
Contractors
Compliance
UTILities
Reports & BI
Settings
Help & Support
Quick Support
0722 574 400
support@ceest.co.ke
Mon - Fri 8:00AM - 6:00PM
Collapse Menu
Inspections
Maintenance > Inspections
Search assets, inspections, locations...
12
5
Albin Sigei
Facility Manager
Total Inspections (This Month)
56
↑ 12% vs last month
Completed
42
75%
In Progress
8
14%
Overdue
6
11%
Defects Found
38
This month
Compliance Score
92%
↑ 8% vs last month
Inspection List
Calendar View
Templates
Checklists
Reports
Search inspections...
All Buildings
All Categories
All Types
All Status
May 12 - May 18, 2026
Filters
Export
New Inspection
Inspection ID
Inspection Name
Asset / System
Building / Location
Type
Inspector
Date
Status
Score
Actions
INSP-2026-0056
Lift Safety Inspection
LIFT-1
Lift
Cradle Building
Ground Floor
Statutory
James Kariuki
Lead Technician
18 May 2026
09:30 AM
Completed
96%
INSP-2026-0055
Fire Extinguisher Check
FE-01 to 35
Fire Safety
Cradle Building
All Floors
Routine
Peter Mwangi
Technician
18 May 2026
08:45 AM
Completed
94%
INSP-2026-0054
Water Tank Inspection
WT-1
Water Supply
Cradle Building
Roof
Routine
Aqua Solutions Ltd.
Contractor
17 May 2026
11:15 AM
Completed
90%
INSP-2026-0053
Electrical DB Inspection
DB-MDB-1
Electrical
Cradle Building
Basement
Routine
David Ochieng
Electrician
17 May 2026
10:20 AM
In Progress
–
INSP-2026-0052
Generator Inspection
GEN-001
Generator
Cradle Building
Generator Room
Preventive
PowerGen Ltd.
Contractor
16 May 2026
04:00 PM
Completed
98%
INSP-2026-0051
CCTV System Check
CCTV-01 to 16
CCTV
Cradle Building
All Floors
Routine
SecureEye Ltd.
Contractor
16 May 2026
02:30 PM
Overdue
72%
INSP-2026-0050
Plumbing System Inspection
PL-01 to 10
Plumbing
Cradle Building
All Floors
Routine
John Mwangi
Technician
15 May 2026
01:20 PM
Completed
91%
INSP-2026-0049
HVAC System Inspection
AHU-1 to 3
HVAC
Cradle Building
5th Floor
Preventive
Elevate Ltd.
Contractor
15 May 2026
10:10 AM
Completed
89%
Showing 1 to 8 of 56 inspections
1
2
3
4
5
...
7
10 / page
INSP-2026-0056
Completed
Lift Safety Inspection
LIFT-1 • Cradle Building - Ground Floor
Overview
Checklist
Findings (2)
Photos (6)
Documents
Inspection Type
Statutory
Duration
1h 25m
Inspection Date
18 May 2026, 09:30 AM
Template
Lift Safety Inspection
Inspector
James Kariuki
Lead Technician
Compliance Standard
KEBS / EAC 81-1
Next Inspection
18 Jun 2026
Overall Score
96%
Inspection Summary
Lift operating within acceptable parameters. All safety interlocks functional.
12
Items Inspected
12
Passed
0
Failed
0
N/A
Recent Findings
Car Door Interlock
All doors closing and locking properly.
Passed
Emergency Light
Battery backup below recommended level.
Minor
View Full Report
Create Work Order

CeEst
FACILITY MANAGEMENT

- Dashboard
- Buildings & Locations
- Assets & Inventory
- Service Requests
- Work Orders
- Inspections
- Service Requests
- To Work
- Contractors
- Compliance
- Utilities
- Reports & BI
- Settings
- Help & Support

Service Requests

Home > Service Requests

Search service requests, assets, locations...

12 5 Albin Sigei Facility Manager

Total Requests (This Month)	Open	In Progress	Completed	Overdue	Avg. Response Time	Satisfaction Score
128	38	45	40	5	1.8 hrs	4.6 / 5
↑ 18% vs last month	29.7%	35.2%	31.3%	3.9%	Target: 4 hrs	↑ 0.3 vs last month

All Requests | My Requests | Open | In Progress | Completed | Cancelled

Search requests... | All Buildings | All Categories | All Priority | All Status | May 12 – May 18, 2026

Request ID	Title	Category	Location	Priority	Status	Reported By	Reported On	SLA	Actions
SR-2026-0187	Toilet flush not working Men's washroom – 3rd Floor	Plumbing	Cradle Building 3rd Floor	High	In Progress	John Mwangi Tenant	18 May 2026 09:15 AM	1h 45m Remaining	⋮
SR-2026-0186	LED light flickering Reception area	Electrical	Cradle Building Ground Floor	Medium	Open	Mary Wanjiku Tenant	18 May 2026 08:40 AM	3h 10m Remaining	⋮
SR-2026-0185	AC not cooling properly Office 2A	HVAC	Cradle Building 2nd Floor	High	In Progress	Peter Ndungu Tenant	18 May 2026 08:05 AM	1h 20m Remaining	⋮
SR-2026-0184	Door closer damaged Main entrance	Carpentry	Cradle Building Ground Floor	Low	Open	Security Office Staff	17 May 2026 06:30 PM	21h 30m Remaining	⋮
SR-2026-0183	Fire extinguisher gauge low Near lift lobby	Fire Safety	Cradle Building All Floors	High	In Progress	David Ochieng Staff	17 May 2026 03:20 PM	2h 05m Remaining	⋮
SR-2026-0182	Water leakage on ceiling Parking – P2	Plumbing	Cradle Building Parking P2	High	Open	James Kariuki Tenant	17 May 2026 02:15 PM	3h 45m Remaining	⋮
SR-2026-0181	CCTV camera not working Gate 2	CCTV / Security	Cradle Building All Gates	Medium	Open	Security Office Staff	17 May 2026 11:10 AM	18h 40m Remaining	⋮
SR-2026-0180	Generator making noise Generator room	Mechanical	Cradle Building Basement	Medium	Completed	Aqua Solutions Contractor	16 May 2026 05:00 PM	Completed	⋮

Showing 1 to 8 of 128 requests

< 1 2 3 4 5 ... 16 > 10 / page

Requests by Category (This Month)



Plumbing	32 (25%)
Electrical	24 (19%)
HVAC	18 (14%)
Fire Safety	16 (13%)
CCTV / Security	14 (11%)
Carpentry	10 (8%)
Others	14 (11%)

Requests by Priority

High	Medium	Low
48	46	34
37.5%	35.9%	26.6%

Top Requesters

John Mwangi	18
Mary Wanjiku	14
Security Office	12
James Kariuki	10
Peter Ndungu	9

SR-2026-0187 In Progress

Toilet flush not working

Cradle Building • 3rd Floor • Men's washroom

Priority	Category	Reported On
High	Plumbing	18 May 2026, 09:15 AM

Overview | Updates (2) | Photos (2) | Tasks (1) | Related

Status
In Progress

SLA Response Time
4 hours

SLA Resolution Time
48 hours

Response Due
18 May 2026, 01:15 PM

Resolution Due
20 May 2026, 09:15 AM

Reported By
John Mwangi (Tenant)

Contact
0712 345 678

Assigned To
James Kariuki
Plumbing Technician

Contractor
Aqua Solutions Ltd.

Created By
John Mwangi

Description

The flush is not working in the men's washroom near lift lobby. Water does not refill after flush.

Location on Map / Floor Plan



View full map >

Edit Request | Cancel Request

Add Update

CeEst
FACILITY MANAGEMENT

MAIN NAVIGATION

- Dashboard
- Buildings & Locations
- Assets & Inventory
- Maintenance
  - Work Orders
  - Planned Maintenance
  - Inspections
  - Service Requests
  - Permit to Work
- Contractors
- Compliance
- Utilities
- Reports & BI

SUPPORT

- Settings
- Help & Support

Quick Support
0722 574 400
support@ceest.co.ke

Utility Management

Dashboard > Utility Management

Cradle Building | May 12 – May 18, 2026

Total Energy (kWh) 125,430 ↑ 8.6% vs last period

Water Consumption (m³) 1,245 ♥ -5.3% vs last period


Generator Fuel (L) 3,240 ↑ 12.1% vs last period

Gas Consumption (kg) 620 ♥ -3.6% vs last period

Overview | Electricity | Water | Generator Fuel | Solar | Gas | Waste | Reports


Utility Consumption Trend

Daily



Utility Cost Trend (KES)

Daily



Electricity Summary

This Month

Total Consumption
125,430 kWh
↑ 8.6% vs last month

Total Cost
KES 412,560
↑ 7.9% vs last month



HVAC	35%	(43,901 kWh)
Lighting	20%	(25,086 kWh)
Power Sockets	18%	(22,571 kWh)
Lifts & Escalators	12%	(15,048 kWh)
Others	15%	(18,824 kWh)

View Electricity Details →

Water Summary

This Month

Total Consumption
1,245 m³
♥ -5.3% vs last month

Total Cost
KES 98,450
♥ -3.2% vs last month



Toilets	40%	(498 m³)
HVAC	25%	(311 m³)
Irrigation	15%	(187 m³)
Pantry	10%	(124 m³)
Others	10%	(125 m³)

View Water Details →

Latest Meter Readings

Utility Cost Breakdown (This Month)

CeEst
FACILITY MANAGEMENT

MAIN NAVIGATION

- Dashboard
- Buildings & Locations
- Assets & Inventory
- Maintenance
  - Work Orders
  - Planned Maintenance
  - Inspections
  - Service Requests
  - Permit to Work
- Contractors
- Compliance
- Utilities
- Reports & BI

SUPPORT

- Settings
- Help & Support

Quick Support
0722 574 400
support@ceest.co.ke
Mon - Fri 8:00AM - 6:00PM

Collapse Menu

Contractors

Home > Contractors > All Contractors

Search contractors, services, categories...

12 5 Albin Sigei Facility Manager

+ Add Contractor

Total Contractors	Active Contractors	Average Rating	Avg. Response Time	Contracts Expiring	Total Spend (YTD)
68	56	4.3 / 5	2.6 hrs	7	KES 45.67M
↑ 7 this month	82% of total	↑ 0.2 vs last month	↑ 0.4 hrs vs last month	Next 30 days	↑ 12.6% vs last year
View all contractors →	View active →	View performance →	View SLA report →	View expiring →	View spend report →

All Contractors | By Category | By Performance | Approved | Blacklisted

Search contractors... | All Categories | All Status | All Risk Levels | Filters | Export

Contractor	Category / Specialization	Status	Performance Rating	Avg. Response Time	Active Contracts	Spend (YTD)	Actions
Aqua Solutions Ltd. 0721 345 678	Plumbing & Drainage Water Systems	Active	4.6 ★★★★½ (23)	2.1 hrs	5	KES 6.45M	⋮
PowerGen Ltd. 0712 654 321	Electrical Systems Generators	Active	4.4 ★★★★½ (18)	2.4 hrs	4	KES 8.72M	⋮
FireTech Services 0733 987 654	Fire Safety Systems Extinguishers, Alarms	Active	4.8 ★★★★½ (31)	1.8 hrs	6	KES 7.15M	⋮
Elevate Ltd. 0709 876 543	Lift Systems Elevators & Escalators	Active	4.5 ★★★★½ (16)	2.2 hrs	3	KES 5.30M	⋮
SecureEye Ltd. 0725 111 222	CCTV / Access Control Security Systems	Active	4.2 ★★★★☆ (12)	3.1 hrs	4	KES 4.80M	⋮
CoolMax Systems 0731 222 333	HVAC Systems Air Conditioning	Active	4.1 ★★★★½ (14)	3.6 hrs	3	KES 3.95M	⋮
BuildCare Maintenance 0720 333 444	General Maintenance Building Fabric	Active	4.0 ★★★★☆ (10)	3.8 hrs	6	KES 6.20M	⋮
GreenClean Ltd. 0714 555 888	Cleaning Services Waste Management	Inactive	3.9 ★★★★☆ (8)	–	0	KES 1.10M	⋮
Rapid Fix Ltd. 0788 999 111	Specialized Repairs Civil & Structural	Blacklisted	2.1 ★☆☆☆☆ (4)	–	0	KES 0	⋮

Showing 1 to 9 of 68 contractors

< 1 2 3 4 5 ... 8 > 10 / page

Contractor Details

Aqua Solutions Ltd. Active
Plumbing & Drainage • Water Systems
0721 345 678 • info@aquasolutions.co.ke

Overview | Contracts (5) | Performance | Documents | History

Registration No.	C-2018-25487	SLA Response Time	2 hrs
TIN Number	123-456-789	SLA Resolution Time	24 hrs
Risk Level	Low	Payment Terms	30 Days
Insurance Expiry	12 Dec 2026	Last Evaluation	15 May 2026
Years with CeEst	4 years	Next Evaluation	15 Aug 2026

Performance Summary

View full report →

Overall Rating
4.6 / 5
★★★★½
(23 Reviews)

Quality of Work	4.7 / 5
Timeliness	4.5 / 5
Communication	4.6 / 5
Safety Compliance	4.4 / 5

Spend Summary (YTD)

KES 6.45M ↑ 12.3% vs last year



View Profile | Edit Contractor | View Contracts

CeEst
FACILITY MANAGEMENT

MAIN NAVIGATION

- Dashboard
- Buildings & Locations
- Assets & Inventory
- Maintenance
  - Work Orders
  - Planned Maintenance
  - Inspections
  - Service Requests
  - Permit to Work
- Contractors
- Utilities
- Compliance
- Reports & BI
- Settings
- Help & Support

Quick Support
0722 574 400
support@ceest.co.ke
Mon - Fri 8:00AM - 6:00PM

2025 CeEst FM System

Reports & BI

Home > Reports & BI > Overview

All Buildings | May 12 - May 18, 2026 | Compare with Apr 12 - May 11, 2026

12 | 5 | Albin Sigei, Facility Manager

Overview | Performance | Maintenance | Compliance | Financial | Utilities | Work Orders | Sustainability | Custom Reports

Export | Schedule Report


PPM Compliance	Work Orders Completed	Avg. Response Time (All)	Open Work Orders	Total Maintenance Cost	Compliance Score	Satisfaction Score
92%	248	1.8 hrs	38	KES 645,780	95%	4.6 / 5
↑ 4.3% vs last period	↑ 18.2% vs last period	↓ 0.3 hrs vs last period	↓ 12.6% vs last period	↑ 6.8% vs last period	↑ 3.4% vs last period	↑ 0.2 vs last period

Work Order Status Breakdown



View Work Order Report →

Work Orders by Category



View Detailed Report →

Maintenance Cost Trend (KES)

Monthly | Quarterly



Report Center

- **Executive Summary** — High level overview of all KPIs
- **Maintenance Performance** — PPM, response time, workload analysis
- **Compliance & Statutory** — Certifications, inspections & compliance status
- **Financial Summary** — Maintenance cost, budget vs actual
- **Asset Condition Report** — Condition assessment & lifecycle
- **Utility Performance** — Energy, water, fuel & utility analysis
- **Contractor Performance** — SLA, ratings & performance scorecard
- **Sustainability Report** — ESG, carbon savings & green initiatives

View All Reports →

PPM Compliance Trend



View PPM Compliance Report →

Compliance Status Overview



View Compliance Report →

Top 5 Cost by Category (KES)



View Cost Analysis Report →

Monthly KPI Summary

KPI	Dec 2025	Jan 2026	Feb 2026	Mar 2026	Apr 2026	May 2026	Trend
PPM Compliance (%)	89%	90%	91%	90%	90%	92%	
Avg. Response Time (hrs)	2.2	2.1	2.0	1.9	2.1	1.8	
Work Orders Completed	186	201	217	198	210	248	
Open Work Orders	52	48	45	42	44	38	
Maintenance Cost (KES)	535,600	612,430	598,210	641,230	605,450	645,780	
Satisfaction Score (/5)	4.3	4.4	4.5	4.4	4.5	4.6	

View KPI Trend Report →

Recent Reports

Report Name	Period	Generated On	Generated By	Action
Executive Summary Report	May 12 - May 18, 2026	May 18, 2026 08:00 AM	Albin Sigei	
Maintenance Performance Report	May 12 - May 18, 2026	May 18, 2026 08:00 AM	Albin Sigei	
Statutory Compliance Report	May 12 - May 18, 2026	May 18, 2026 08:00 AM	Albin Sigei	
Utility Performance Report	May 12 - May 18, 2026	May 18, 2026 08:00 AM	Albin Sigei	
Contractor Performance Report	May 12 - May 18, 2026	May 18, 2026 08:00 AM	Albin Sigei	

View All Reports →