

Car Inspection Functionality Result

Inspector Info

<div><div></div><div><div>?</div></div></div>	Full Name : samuael adnew birhane
---	-----------------------------------

Garage Information

Name : NewGarage

Inspection Info

Driver Name : tefera		
Vehicle Model : model223122		
Vehicle Year : 1997		
Vehicle Make : Europe		
Vehicle Color : red		
License Plate : 23424243		
Vin Number : sdfhsfkjahsdkjhasdjk		
Title	Result	Reason
Hand Brake	"PASS"	"PASS"
Steering System	"PASS"	"PASS"
Brake System	"PASS"	"PASS"
Seat Belt	"PASS"	"PASS"
Door And Window	"PASS"	PASSED
Dash Board Light	"PASS"	"PASS"
Wind Shield	"PASS"	"PASS"
Baggage Door Window	"FAILED"	Some Other Value
Gear Box	"PASS"	"PASS"
Shock Absorber	"PASS"	"PASS"
Front High And Low Beam Light	"PASS"	"PASS"
Rear Light And Brake Light	"PASS"	"PASS"
Wiper Operation	"PASS"	"PASS"
Car Horn	"PASS"	"PASS"

Side Mirrors	"PASS"	"PASS"
General Body Condition	"PASS"	PASSED
Driver Performance	PASSED	PASSED
Balancing	PASS	PASSED
Hazard	PASSED	PASSED
Signal Light Usage	PASSED	PASSED
	Vehicle Failed Test	