


Car Inspection Functionality Result

Inspector Info

| | |
|--|-----------------------------------|
|  | Full Name : samuael adnew birhane |
|--|-----------------------------------|

Garage Information

| |
|------------------|
| Name : NewGarage |
|------------------|

Inspection Info

| Driver Name : tefera | | |
|-----------------------------------|----------|------------------|
| Vehicle Model : model223122 | | |
| Vehicle Year : 1997 | | |
| Vehicle Make : Europe | | |
| Vehicle Color : red | | |
| License Plate : 23424243 | | |
| Vin Number : sdfhsfkjahsdkjhasdjk | | |
| Title | Result | Reason |
| Hand Brake | "PASS" | "PASS" |
| Steering System | "PASS" | "PASS" |
| Brake System | "PASS" | "PASS" |
| Seat Belt | "PASS" | "PASS" |
| Door And Window | "PASS" | PASSED |
| Dash Board Light | "PASS" | "PASS" |
| Wind Shield | "PASS" | "PASS" |
| Baggage Door Window | "FAILED" | Some Other Value |
| Gear Box | "PASS" | "PASS" |
| Shock Absorber | "PASS" | "PASS" |
| Front High And Low Beam Light | "PASS" | "PASS" |
| Rear Light And Brake Light | "PASS" | "PASS" |
| Wiper Operation | "PASS" | "PASS" |
| Car Horn | "PASS" | "PASS" |
| | | |

| | | |
|------------------------|---------------------|--------|
| Side Mirrors | "PASS" | "PASS" |
| General Body Condition | "PASS" | PASSED |
| Driver Performance | PASSED | PASSED |
| Balancing | PASS | PASSED |
| Hazard | PASSED | PASSED |
| Signal Light Usage | PASSED | PASSED |
| | Vehicle Failed Test | |