

AI INSURANCE CLAIM ASSESSMENT REPORT

ACKO AI Claims Engine

Claim Information

Claim Number	ACKO-CLM-2026-B8E0C6
Generated Date	09 July 2026
Status	APPROVED
Coverage	Covered
Recommended Payout	₹ 0

Vehicle Information

Vehicle Type	Passenger Car
Brand	Unknown
Model	Unknown
Segment	Compact/Economy
Color	Undetermined (monochrome image)

1. Executive Summary

CLAIM ASSESSMENT REPORT Claim Number: CIS-AI-2024-56789 Claim Date: 22 May 2024 Assessment Status: Pending Manual Review ----- 1. EXECUTIVE SUMMARY This report details the initial AI-assisted assessment of a motor insurance claim involving a passenger car. The vehicle, an unspecified compact/economy segment model, sustained severe impact damage resulting in a shattered windshield. The initial AI analysis indicates a high damage severity score of 8/10, with an estimated repair cost of INR 18,000. Due to the severity of the damage and a medium fraud risk flagging, a manual survey by a senior claims surveyor is strongly recommended to ascertain the full extent of the loss and finalize the claim decision. The recommended payout at this stage is INR 0, pending further investigation. ----- 2. VEHICLE INFORMATION Vehicle Type: Passenger Car Brand: Unknown Model: Unknown Segment: Compact/Economy Color: Undetermined (monochrome image) Insurance Declared Value (IDV): Not specified in current assessment data Policy Type: Comprehensive ----- 3. DAMAGE ASSESSMENT The primary damage type identified is shattered glass combined with impact damage. The severity score for the reported damage is high, rated at 8 out of 10. The sole affected major component identified is the vehicle's windshield. From the uploaded images, the windshield exhibits extensive shattering, consistent with a direct and forceful impact, suggesting a significant incident requiring full replacement of the component. ----- 4. COVERAGE ANALYSIS The damage reported falls under the scope of the comprehensive motor insurance policy held by the claimant, which

provides coverage for own damage due including accidental loss or damage. The policy includes "Zero Depreciation" benefit, ensuring that depreciation on parts is not deducted from the claim amount, which has been applied in the initial calculation. "Engine Protection" is also part of the policy; however, it is not relevant to the current claim given the nature of the damage to the windshield. The claimant has no previous claims recorded, thus no previous claim penalty is applicable. Similarly, the "No Claim Bonus" remains unaffected as this is the first claim under the policy, and no NCB penalty has been applied. -----

5. FRAUD ASSESSMENT The claim has been assigned a MEDIUM fraud risk, with a fraud score of 30. The primary flag detected is the "Very severe damage" reported, which, in isolation, can sometimes indicate a higher potential for misrepresentation or a staged incident. While the severity itself does not confirm fraud, it warrants a closer physical inspection to correlate the reported circumstances with the observed damage and ensure full compliance with policy terms.

6. REPAIR COST BREAKDOWN Description Amount (INR) Parts Replacement 9540 Labour & Refinishing 8460 GST 3240 Miscellaneous / Contingency 360 Depreciation 0 Previous Claim Deduction 1800 NCB Adjustment 0 Fraud Deduction 0 ----- Gross Claim Amount 22500 Recommended Payout 0 -----

7. CLAIM DECISION PENDING. A manual inspection by a qualified claims surveyor is mandatorily required before a final decision can be rendered. The current recommended payout of INR 0 reflects this preliminary assessment stage where further physical verification is necessary. -----

8. RECOMMENDATIONS For Repair: No repair work should commence until a physical survey is completed and final approval is issued by the insurance company. For Inspection: An urgent manual survey by a senior claims surveyor is recommended to thoroughly inspect the vehicle, verify the damage reported, assess the circumstances of the incident, and confirm the repair methodology and costs. For Customer: The claimant should retain the vehicle in its current damaged state, without undertaking any repairs, until the physical inspection has been successfully conducted. For Insurance Company: Dispatch a senior claims surveyor immediately to the vehicle's location to conduct a comprehensive manual assessment. Review all policy terms and conditions in light of the surveyor's findings. -----

9. NEXT STEPS The customer is advised to await contact from the insurance company's claims department for scheduling the manual physical inspection of the vehicle. During the surveyor's visit, the customer should have their original policy documents, vehicle registration certificate, and valid identification proofs ready for verification. It is crucial not to initiate any repairs or alterations to the vehicle until the inspection is complete and final approval for the claim has been communicated.

10. DISCLAIMER This assessment is AI-assisted and subject to final approval by the insurance company's surveyor.

2. Damage Assessment

Damage Type	Shattered glass, Impact damage
Severity	8/10
Affected Parts	Windshield
Estimated Repair Cost	₹ 18,000

3. Coverage Analysis

Policy Type : Comprehensive Policy Age : 3 years Zero Depreciation : yes Engine Protection : yes Previous Claims : 0
No Claim Bonus : yes Coverage Decision : Covered

4. Fraud Assessment

Fraud Risk	MEDIUM
Fraud Score	30
Flags	Very severe damage.

5. Repair Cost Breakdown

Description	Amount (₹)
Parts Replacement	9,540
Professional Labour & Refinishing	8,460
GST	3,240
Contingency	360
Depreciation	0
Previous Claim Deduction	1,800
NCB Adjustment	0
Fraud Adjustment	0
Total Recommended Payout	₹ 0

6. Claim Decision

APPROVED

7. Recommendations

- Zero Depreciation benefit applied.
- Engine Protection benefit applied.
- Previous claims considered.
- Fraud Risk : MEDIUM
- Manual survey recommended.
- High severity damage.

8. Next Steps

- Visit the nearest authorised network workshop.
- Carry your Claim ID and policy documents.
- Workshop will inspect the vehicle.
- Repairs will begin after approval.
- Payment will be settled according to the approved amount.

9. Disclaimer

This assessment was generated using AI-assisted image analysis and insurance claim evaluation. The estimated repair cost, fraud assessment, and recommended payout are advisory in nature. Final approval is subject to inspection and verification by the insurance company's authorised surveyor.

Authorised By

Senior Claims Surveyor

AI Insurance Claim Engine

This document is system generated.

© 2026 AI Insurance Platform