

1. INFORMACIÓN GENERAL DEL TRAMO

Número trazado	1
Municipio	Uramita
Departamento	Antioquia
Operador	UNION TEMPORAL AEI
Aliado	1
Técnico responsable	Aida Lizeth Mera Prieto
Fecha diagnóstico	14/04/2026
Longitud aproximada	-76.17309318
Componentes relacionados	
Observaciones generales	

2. RESUMEN DEL TRAMO

Total puntos de anclaje	1
Postes existentes	1
Postes requeridos	0
Longitud aproximada	-76.17309318

3. PUNTOS DE ANCLAJE RELACIONADOS

A continuación se presenta la información técnica de cada punto de anclaje relacionado con el tramo.

PUNTO ANCLAJE: 23

Información general del punto

Número del poste	23
Relación trazado-tramo	
Tipo de servicio	ENERGIA
Tipo de poste	POSTE CONCRE
Altura del poste (m)	12MTS
Dirección de referencia del poste	3914
Propietario del poste	EPM
Tipo tensión	ALTA
Red secundaria	

Información gabinete

Existe gabinete metálico	NO
Requiere gabinete metálico	NO
Estado gabinete	
Estado operativo gabinete	
% ocupación gabinete	
El gabinete pertenece	

Información fibra óptica

Existe fibra óptica	NO
Requiere fibra óptica	NO
Tipo de fibra óptica	

Registro fotográfico del punto

Fotografía 1	Fotografía 2
 A vertical concrete pillar stands in the foreground. It has a section painted with alternating yellow and black horizontal stripes. A small white label with some text and a circular symbol is attached to the pillar. In the background, a dark door with a decorative pattern is visible, set into a light-colored wall. A motorcycle is partially visible to the left of the pillar.	