

1. INFORMACIÓN GENERAL DEL TRAMO

Número trazado	3
Municipio	Betania
Departamento	Antioquia
Operador	ELEPHAS SAS
Aliado	1
Técnico responsable	Andrés Felipe Escobar
Fecha diagnóstico	21/02/2026
Longitud aproximada	-75.97740333333333
Componentes relacionados	
Observaciones generales	

2. RESUMEN DEL TRAMO

Total puntos de anclaje	1
Postes existentes	0
Postes requeridos	0
Longitud aproximada	-75.97740333333333

3. PUNTOS DE ANCLAJE RELACIONADOS

A continuación se presenta la información técnica de cada punto de anclaje relacionado con el tramo.

PUNTO ANCLAJE: 5

Información general del punto

Número del poste	5
Relación trazado-tramo	
Tipo de servicio	
Tipo de poste	
Altura del poste (m)	
Dirección de referencia del poste	
Propietario del poste	
Tipo tensión	
Red secundaria	

Información gabinete

Existe gabinete metálico	NO
Requiere gabinete metálico	NO
Estado gabinete	
Estado operativo gabinete	
% ocupación gabinete	
El gabinete pertenece	

Información fibra óptica

Existe fibra óptica	SI
Requiere fibra óptica	
Tipo de fibra óptica	FO_MONO_24H

Registro fotográfico del punto

Fotografía 1	Fotografía 2
 A photograph of a utility pole with a dense network of wires. A person is riding a horse in the lower-left foreground. A yellow sign is attached to the pole, and a mountain range is visible in the background under a cloudy sky.	 A close-up photograph of a utility pole with many wires. The sky is cloudy.