

RUINA MOTOR VEHICLE CRASH REPORT

1 Motor Vehicles

0 Non-motorists

Crash Severity: Possible Injury

Reporting *Officer or Citizen*: Civilian

Crash Identifier: Crash id

Agency Crash Identifier: Agency id

Reporting Agency: 123456789

signature

CRASH DATE, TIME, AND LOCATION		
Crash Date and Time 2022/4/6 10:2	Crash County Worcester County	Within Interchange Area No
Time of Roadway Clearance 11:12	Crash City/Place Worcester	Specific Location Non-Junction
Overall Intersection Geometry Not Applicable/Not an Intersection	Overall Traffic Control Device No Controls	Latitude
		Longitude
Ownership Private Property	Characteristics Trafficway, On Road	Number of Approaches Not an Intersection

CRASH FACTORS AND CONDITIONS		
Secondary Crash No	Weather Condition Clear	Number of Non-Fatally Injured Persons
First Harmful Event Curb	Light Condition	Alcohol Involvement
Location of First Harmful Event Relative to the Trafficway Roadside	Roadway Surface Condition Dry	Drug Involvement
	Contributing Circumstances - Roadway Environment None	School Bus-Related? No
Manner of Crash/Collision Impact Angle		Construction or Work Zone Related? No

CRASH DESCRIPTION

Test crash

CRASH DIAGRAM

Motor Vehicle 1

Occupants:

OWNERSHIP AND INSURANCEJack M Mao
1000 Olin Way
Needham, MA 02492**Insurance Company Name**
Unknown**NAIC #**
Unknown**Policy #**
Unknown**VEHICLE DETAILS****Vehicle Identification Number**
99999**Vehicle Unit Type**
Parked Motor Vehicle**Body Type Category**
Passenger Car**Vehicle Registration Identifier****Vehicle Make**
Tesla**Vehicle Size**
Light (10,000 lbs. or less
GVWR/GCWR)**Vehicle Registration Year**
2022**Vehicle Model**
S**Number of Trailing Units**
2**License Plate Number**
P1000**Vehicle Model Year**
2020**Hazardous Materials Placard?**
No**FIRST TRAILER BEHIND TRACTOR****License Plate Number**
null**Make**
Deer**Model and Year**
Unknown 2020**VIN**
121213**Total Number of Axles**
9

SECOND TRAILER BEHIND TRACTOR

License Plate Number	Make Deer	Model and Year 2021
VIN 393993	Total Number of Axles 8	

MOTOR CARRIER IDENTIFICATION

John 1000 Olin Way Needham, MA 02492	Identification Type US DOT Number	Identification Number 7758258
	Country/State Code Us code	Type of Carrier Interstate Carrier

VEHICLE CONFIGURATION

Configuration Vehicle 10,000 lbs. or less placarded for hazardous materials	Special Sizing No special sizing	Permitted? Non-Permitted Load
	Number of Axles on Tractor 9	Cargo Body Type Bus

FACTORS AND CONDITIONS		
Posted/Statutory Speed Limit 60	Travel Directions One-Way	Travel Direction Before Crash Not on Roadway
Traffic Control Devices (TCDs) No Controls	Inoperative or Missing TCDs	Vehicle Maneuver/Action
		Barrier Type No Barrier
Divided? Not Divided	Towed Due to Disabling Damage	Contributing Circumstances from Vehicle None
Location of Damage Area(s)	Initial Point of Contact Non-Collision	Resulting Extent of Damage
	HOV/HOT Lanes	Crash Related to HOV/HOT?
Sequence of Events Cross Centerline	Emergency Motor Vehicle Use Not Applicable	Special Function in Transport
Vehicle's Most Harmful Event Cargo/Equipment Loss or Shift	Horizontal Alignment Straight	Total Through Lanes 1
Hit and Run? No, Did Not Leave Scene	Grade Level	Total Auxiliary Lanes 1
Has Automated System(s)? No	Automated System Levels (ASLs)	ASLs Engaged during Crash

Driver of Motor Vehicle 1

Injury Status: No Apparent Injury

Incident Responder?: No

DRIVER AND LICENSE INFORMATION

Jack M Mao DOB:2000/06/13 Sex: Male 39 Seaver Farm Lane NA South Grafton, MA 01560	License Type	Name of Jurisdiction MA
	License Number	License Endorsements None/Not Applicable
	License Class Class M	Commercial Driver License (CDL)? Yes

LARGE VEHICLES AND HAZARDOUS MATERIAL INFORMATION

CMV License Status Valid	Compliance with CDL Endorsement(s) No Endorsement(s) Required for the Vehicle
------------------------------------	---

FACTORS AND CONDITIONS

Seating Position Front	Speeding-Related? No	Suspected Alcohol Use? No
Restraint Systems or Motorcycle Helmet Use None Used - Motor Vehicle Occupant	Actions at Time of Crash No Contributing Action	Alcohol Test Status
		Alcohol Test Type
Indication of Improper Use? No	Violation Codes 42069	Suspected Drug Use? No
Air Bag Deployed? Not Deployed	Condition at Time of Crash Apparently Normal	Drug Test Status
		Drug Test Type
Ejection? Not Ejected	Source of Distraction	Attempted Avoidance Maneuver
Distraction Type		