

2015 TATA LPT 3118 TC 56




VARANASI



Vehicle Rating And Pricing

Autoinspekt Rating

8



Tyre Life



90% Life

Transmission



Manual

Odometer



0 KM

V-DE-DUPE
+ve

VALUATION PRICE ₹
17,10,000



Registration Number
Vehicle Type

UP65DT3952
TRANSPORT



No Damage
Reported



Manufacturing Month / Year
Registration Month / Year

Feb 2015
Mar 2015

Retail



Vehicle Ownership

2 Owners , ATUL KUMAR

RC Status

YADAV

Original

Report Request By
**HDB Financial Services
Limited**



Insurance & Tax
HPA Status , HPA Bank

19/04/2023, 31/05/2022
No, NA



NO DAMAGE VEHICLE



Chassis Number
Engine Number

MAT466388F5B02132
51A84203702

Inspection Location
7VG9F9M, Kaneri, Uttar Pradesh
221302, India

Rating	Vehicle Condition	Engine Condition
10 or 9	Excellent	Excellent
8 or 7	Good	Good

Vehicle Summary :
ASSET IS IN RUNNING CONDITION,
CHASSIS PUNCHING ORIGINAL



Approved by



Rupesh Waghmare,
License No.: 61624.
www.autoinspekt.com

6 or 5	Average	Average
4 or 3	Bad	Bad
2 or 1	Scrap	No Engine



Use your smart
phone to scan the
QR code and get
detailed
autoinspekt report

Page 1/5

Report Generated Date :09/05/2022 07:05
pm

 Autoinspekt


This Autoinspekt Vehicle

 VAHAN DETAILS

Owner Name	ATUL KUMAR YADAV	REGISTRATION NUMBER	UP65DT3952	REGISTRATION DATE	03-Mar-2015
Present Address	RAMGADAVAN , KHETALPUR . CHAUBEPUR . 0 221104	Registered at RTO	VARANASI RTO, Uttar Pradesh	RC Status	A
Permanent Address	RAMGADAVAN , KHETALPUR . CHAUBEPUR . 0 221104	OWNER SERIAL NUMBER	2	Manufacturing Date	2/2015
Financier	NA	Vehicle Make	TATA MOTORS LTD	Vehicle Model	LPT3118
Insurer	ICICI LOMBARD	Color	WHITE	Fuel	DIESEL
Chassis Number	MAT466388F5B02132	Engine Number	51A84203702	Fuel Norms	EURO 2
Vehicle Category	HGV	Vehicle Class Description	Goods Carrier	Engine Cubic Capacity	5883.0
Body Type	TRUCK (FULL BODY)	Mobile No	--	NCRB Status	--
RC Fitness Validity	26-Apr-2024	RC Tax Validity	31-May-2022	Blacklist Status	NA
Insurance Policy Number	3005/245307446/00/000	Insurance Validity	19-Apr-2023	NOC Details	NA
				Permit No	NA
				Permit Issue Date	NA
				Permit Valid from Date	NA
				Permit Valid upto Date	NA
				Permit Type	NA
				RC Status as on	09-May-2022



LOAD BODY



LOAD BODY TYPE

FULLY BUILT VEHICLE

LOAD BODY BUILD

Normal body

TAIL GATE

Good

8/10

LEFT SIDE GATE (FIXED)

Good

8/10

RIGHT SIDE GATE (FIXED)

Good

8/10

LOAD FLOOR

Good

8/10

OVERALL LOAD BODY

Good

8/10

CHASSIS CONDITION

Good

8/10

NO OF TYRES

12 TYRES

FUEL

DIESEL

TANKER BODY TYPE

NA



CABIN



BUMPER

Good

8/10

HEAD LAMPS

Good

8/10

DOOR - LEFT

Good

8/10

DOOR - RIGHT

Good

8/10

DASHBOARD

Good

8/10

NUMBER OF SEATS

4 SEATS

DRIVER SEAT

Good

AC



CO - DRIVER SEAT

Good

ABS





SYSTEMS & FUNCTIONS



• • •

BATTERY	Satisfactory
STARTER MOTOR	Good
ALTERNATOR	Good
CUBIC CAPACITY (CC)	5883 cc

ENGINE

CONDITION	Good
AXLE CONFIGURATION	8X4
ENGINE OIL LEAKS	No
RADIATOR/CONDENSER	Good 8/10
DIESEL PUMP	Good 8/10
IGNITION SYSTEM	Good 8/10
TRANSMISSION	Good 8/10
GEARSHIFT	Good 8/10
CLUTCH ENGAGEMENT	Good 8/10
STEERING (MANUAL)	Good 8/10
BRAKE (NORMAL)	Good 8/10
DIFFERENTIAL	Good 8/10
SUSPENSION	Good 8/10

FUNCTIONALITY

VEHICLE CRANKS	No
DRIVES FORWARD	Yes
DRIVES REVERSE	Yes
BRAKE PEDAL FUNCTIONS	Yes



VEHICLE CONDITION & DOCUMENT DETAILS



Vehicle Condition

Running



Parking Location

RESIDENT

Insurance Type

COMP

RC Status

ORIGINAL

FC Validity

26/04/2024

Road Permit


09/05/2022

Vehicle Last Service

09/05/2022



VEHICLE VIDEO



Page 4/5

Report Generated Date :09/05/2022 07:05
pm

Autoinspekt




Tyre Life 50%



Tyre Life 50%



Tyre Life 75%




Tyre Life 50%



Tyre Life 25%



Tyre Life 50%



Tyre Life 50%



Tyre Life 50%



Tyre Life 50%



Tyre Life 50%

[Disclaimer](#)

Page 5/5

Report Generated Date :09/05/2022 07:05

pm

This Autoinspekt Vehicle Evaluation Report Is Based On physical Verification

 Autoinspekt