



CALIFORNIA
ASSOCIATION
OF REALTORS®

AGENT VISUAL INSPECTION DISCLOSURE

(CALIFORNIA CIVIL CODE § 2079 ET SEQ.)

For use by an agent when a transfer disclosure statement is required or when a seller is exempt from completing a TDS

(C.A.R. Form AVID, Revised 6/24)

This inspection disclosure concerns the residential property situated in the City of Copperopolis,
County of CALAVERAS, State of California, described as 695 Feather Dr.

("Property").

☐ This Property is a duplex, triplex, or fourplex, or otherwise has additional dwelling units. An AVID is required for all units. This AVID form is for ALL units (or ☐ only unit(s) _____).

Inspection Performed By (Real Estate Broker Firm Name) BRADLEY AND SANTOS REALTY

California law requires, with limited exceptions, that a real estate broker or salesperson (collectively, "Agent") conduct a reasonably competent and diligent visual inspection of reasonably and normally accessible areas of certain properties offered for sale and then disclose to the prospective purchaser material facts affecting the value or desirability of that property that the inspection reveals. The duty applies regardless of whom that Agent represents. The duty applies to residential real properties containing one-to-four dwelling units, and manufactured homes (mobilehomes). The duty applies to a stand-alone detached dwelling (whether or not located in a subdivision or a planned development) or to an attached dwelling such as a condominium. The duty also applies to a lease with an option to purchase, a ground lease or a real property sales contract of one of those properties.

California law does not require the Agent to inspect the following:

- Areas that are not reasonably and normally accessible
- Areas off site of the property
- Public records or permits
- Common areas of planned developments, condominiums, stock cooperatives and the like.

Agent Inspection Limitations: Because the Agent's duty is limited to conducting a reasonably competent and diligent visual inspection of reasonably and normally accessible areas of only the Property being offered for sale, there are several things that the Agent will not do. What follows is a non-exclusive list of examples of limitations on the scope of the Agent's duty.

Roof and Attic: Agent will not climb onto a roof or into an attic.

Interior: Agent will not move or look under or behind furniture, pictures, wall hangings or floor coverings. Agent will not look up chimneys or into cabinets, or open locked doors.

Exterior: Agent will not inspect beneath a house or other structure on the Property, climb up or down a hillside, move or look behind plants, bushes, shrubbery and other vegetation or fences, walls or other barriers.

Appliances and Systems: Agent will not operate appliances or systems (such as, but not limited to, electrical, plumbing, pool or spa, heating, cooling, septic, sprinkler, communication, entertainment, well or water) to determine their functionality.

Size of Property or Improvements: Agent will not measure square footage of lot or improvements, or identify or locate boundary lines, easements or encroachments.

Environmental Hazards: Agent will not determine if the Property has mold, asbestos, lead or lead-based paint, radon, formaldehyde or any other hazardous substance or analyze soil or geologic condition.

Off-Property Conditions: By statute, Agent is not obligated to pull permits or inspect public records. Agent will not guarantee views or zoning, identify proposed construction or development or changes or proximity to transportation, schools, or law enforcement.

Analysis of Agent Disclosures: For any items disclosed as a result of Agent's visual inspection, or by others, Agent will not provide an analysis of or determine the cause or source of the disclosed matter, nor determine the cost of any possible repair.

What this means to you: An Agent's inspection is not intended to take the place of any other type of inspection, nor is it a substitute for a full and complete disclosure by a seller. Regardless of what the Agent's inspection reveals, or what disclosures are made by sellers, California Law specifies that a buyer has a duty to exercise reasonable care to protect himself or herself. This duty encompasses facts which are known to or within the diligent attention and observation of the buyer. Therefore, in order to determine for themselves whether or not the Property meets their needs and intended uses, as well as the cost to remedy any disclosed or discovered defect, **BUYER SHOULD: (1) REVIEW ANY DISCLOSURES OBTAINED FROM SELLER; (2) OBTAIN ADVICE ABOUT, AND INSPECTIONS OF, THE PROPERTY FROM OTHER APPROPRIATE PROFESSIONALS; AND (3) REVIEW ANY FINDINGS OF THOSE PROFESSIONALS WITH THE PERSONS WHO PREPARED THEM. IF BUYER FAILS TO DO SO, BUYER IS ACTING AGAINST THE ADVICE OF BROKER.**

© 2024, California Association of REALTORS®, Inc.

AVID REVISED 6/24 (PAGE 1 OF 3)

Buyer's Initials

AR



AGENT VISUAL INSPECTION DISCLOSURE (AVID PAGE 1 OF 3)

BRADLEY AND SANTOS REALTY, 3505 Spangler Ln. Ste. 103 Copperopolis CA 95228
Dee Bradley

Phone: 2097702335

Fax: 2097857355

695 Feather Dr.

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201

www.lwolf.com

If this Property is a duplex, triplex, or fourplex, or otherwise has additional dwelling units this AVID is for unit # _____.

THE UNDERSIGNED, BASED ON A REASONABLY COMPETENT AND DILIGENT VISUAL INSPECTION OF THE REASONABLY AND NORMALLY ACCESSIBLE AREAS OF THE PROPERTY, STATES THE FOLLOWING:

Entry (excluding common areas): Front entry light fixture is hanging. Raw wood on porch. Hole in metal porch cover.

Living Room: Different color of wood covering hole. Marks on the paneling. No plug covers. Formal dining room attached to living room center window under the large window is missing. In living room hole on ceiling is patched with piece of material and tape. Paint mark above light switch in living room.

Dining Room: See comment listed above

Kitchen: Molding on island is loose. Right of sink loose board on countertop. Dishwasher will not close. No exhaust fan above the stove.

Other Room: Bar area. Flooring by tile needs repair.

Hall/Stairs (excluding common areas): _____

Bedroom # 1 : No window screens

Bedroom # 2 : Paneling has some corner molding broken. Paneling under dressing table has paint on it. Doors part of the closet area do not match

Bedroom # 3 : Located in back area. Writing on the door. Broken window. No closet doors

Bedroom # _____ :

Bath # 1 : No light cover. Door has marks on it.

Bath # 2 : Shower doors not installed. Toilet area along the floor needs attention. Located in master bedroom

Bath # 3 : In the back area. Stain in sink. No cover wall light. Trim board right of sink needs repaired.

Bath # _____ :

If this Property is a duplex, triplex, or fourplex, or otherwise has additional dwelling units this AVID is for unit # _____.

Other: Back room added on several wall panels broken. No door on the storage closet.

Other: _____

Other: _____

☐ See Addendum for additional rooms/structures: _____

Garage/Parking (excluding common areas): Some repairs needed on corner of the carport of house. Blacktop has some holes in it. Some old equipment and wood stove stored under the carport.

Exterior Building and Yard - Front/Sides/Back: Facing house left side of back of home needs repairs. Holes in siding. Cover for crawl space is not attached and needs repair. Outside could be painted.

Other Observed or Known Conditions Not Specified Above: Old shed in back needs repairs.

This disclosure is based on a reasonably competent and diligent visual inspection of reasonably and normally accessible areas of the Property on the date specified above.

Real Estate Broker (Name of Firm that performed the inspection): BRADLEY AND SANTOS REALTY

Inspection Performed By (Name of individual agent or broker): DEE BRADLEY

Inspection Date/Time: 08/05/2026 11 AM Weather conditions: SUNNY HOT

Other persons present: _____

By DEE BRADLEY Date 08/05/26
(Signature of Associate Licensee or Broker who performed the inspection)

Reminder: Not all defects are observable by a real estate licensee conducting an inspection. The inspection does not include testing of any system or component. Real Estate Licensees are not home inspectors or contractors. BUYER SHOULD OBTAIN ADVICE ABOUT AND INSPECTIONS OF THE PROPERTY FROM OTHER APPROPRIATE PROFESSIONALS. IF BUYER FAILS TO DO SO, BUYER IS ACTING AGAINST THE ADVICE OF BROKER.

I/we acknowledge that I/we have read, understand and received a copy of this disclosure.

Buyer Ashley Robinson Ashley Robinson Date 08/07/26

Buyer Bert Andrews Date _____

I/we acknowledge that I/we have received a copy of this disclosure.

(The initials below and Broker signature are not required but can be used as evidence that the initialing or signing party has received the completed form.)

Seller CJ / _____

Real Estate Broker (that did NOT fill out this AVID) Legacy Properties

By James Beyersdorf Date 08/07/26

(Associate Licensee or Broker Signature)

© 2024, California Association of REALTORS®, Inc. United States copyright law (Title 17 U.S. Code) forbids the unauthorized distribution, display and reproduction of this form, or any portion thereof, by photocopy machine or any other means, including facsimile or computerized formats. THIS FORM HAS BEEN APPROVED BY THE CALIFORNIA ASSOCIATION OF REALTORS®. NO REPRESENTATION IS MADE AS TO THE LEGAL VALIDITY OR ACCURACY OF ANY PROVISION IN ANY SPECIFIC TRANSACTION. A REAL ESTATE BROKER IS THE PERSON QUALIFIED TO ADVISE ON REAL ESTATE TRANSACTIONS. IF YOU DESIRE LEGAL OR TAX ADVICE, CONSULT AN APPROPRIATE PROFESSIONAL. This form is made available to real estate professionals through an agreement with or purchase from the California Association of REALTORS®.

Published and Distributed by: REAL ESTATE BUSINESS SERVICES, LLC, a subsidiary of the California Association of REALTORS®

AVID REVISED 6/24 (PAGE 3 OF 3)

AGENT VISUAL INSPECTION DISCLOSURE (AVID PAGE 3 OF 3)

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwof.com

695 Feather Dr.

