



CALIFORNIA
ASSOCIATION
OF REALTORS®

AGENT VISUAL INSPECTION DISCLOSURE

(CALIFORNIA CIVIL CODE § 2079 ET SEQ.)

For use by an agent when a transfer disclosure statement is
required or when a seller is exempt from completing a TDS

(C.A.R. Form AVID, Revised 6/24)

This inspection disclosure concerns the residential property situated in the City of Copperopolis,
County of Calaveras, State of California, described as 695 Feather Dr

COPPER COVE UNIT 8 A LOT 49

("Property").

☐ This Property is a duplex, triplex, or fourplex, or otherwise has additional dwelling units. An AVID is required for all
units. This AVID form is for ALL units (or ☐ only unit(s) _____).

Inspection Performed By (Real Estate Broker Firm Name) _____

Legacy Properties

California law requires, with limited exceptions, that a real estate broker or salesperson (collectively, "Agent") conduct
a reasonably competent and diligent visual inspection of reasonably and normally accessible areas of certain properties
offered for sale and then disclose to the prospective purchaser material facts affecting the value or desirability of that
property that the inspection reveals. The duty applies regardless of whom that Agent represents. The duty applies to
residential real properties containing one-to-four dwelling units, and manufactured homes (mobilehomes). The duty applies
to a stand-alone detached dwelling (whether or not located in a subdivision or a planned development) or to an attached
dwelling such as a condominium. The duty also applies to a lease with an option to purchase, a ground lease or a real
property sales contract of one of those properties.

California law does not require the Agent to inspect the following:

- Areas that are not reasonably and normally accessible
- Areas off site of the property
- Public records or permits
- Common areas of planned developments, condominiums, stock cooperatives and the like.

Agent Inspection Limitations: Because the Agent's duty is limited to conducting a reasonably competent and diligent visual
inspection of reasonably and normally accessible areas of only the Property being offered for sale, there are several things that
the Agent will not do. What follows is a non-exclusive list of examples of limitations on the scope of the Agent's duty.

Roof and Attic: Agent will not climb onto a roof or into an attic.

Interior: Agent will not move or look under or behind furniture, pictures, wall hangings or floor coverings. Agent will not
look up chimneys or into cabinets, or open locked doors.

Exterior: Agent will not inspect beneath a house or other structure on the Property, climb up or down a hillside, move or
look behind plants, bushes, shrubbery and other vegetation or fences, walls or other barriers.

Appliances and Systems: Agent will not operate appliances or systems (such as, but not limited to, electrical, plumbing,
pool or spa, heating, cooling, septic, sprinkler, communication, entertainment, well or water) to determine their
functionality.

Size of Property or Improvements: Agent will not measure square footage of lot or improvements, or identify or locate
boundary lines, easements or encroachments.

Environmental Hazards: Agent will not determine if the Property has mold, asbestos, lead or lead-based paint, radon,
formaldehyde or any other hazardous substance or analyze soil or geologic condition.

Off-Property Conditions: By statute, Agent is not obligated to pull permits or inspect public records. Agent will not
guarantee views or zoning, identify proposed construction or development or changes or proximity to transportation,
schools, or law enforcement.

Analysis of Agent Disclosures: For any items disclosed as a result of Agent's visual inspection, or by others, Agent will not
provide an analysis of or determine the cause or source of the disclosed matter, nor determine the cost of any possible
repair.

What this means to you: An Agent's inspection is not intended to take the place of any other type of inspection, nor is it
a substitute for a full and complete disclosure by a seller. Regardless of what the Agent's inspection reveals, or what
disclosures are made by sellers, California Law specifies that a buyer has a duty to exercise reasonable care to protect
himself or herself. This duty encompasses facts which are known to or within the diligent attention and observation of the
buyer. Therefore, in order to determine for themselves whether or not the Property meets their needs and intended uses,
as well as the cost to remedy any disclosed or discovered defect, **BUYER SHOULD: (1) REVIEW ANY DISCLOSURES
OBTAINED FROM SELLER; (2) OBTAIN ADVICE ABOUT, AND INSPECTIONS OF, THE PROPERTY FROM OTHER
APPROPRIATE PROFESSIONALS; AND (3) REVIEW ANY FINDINGS OF THOSE PROFESSIONALS WITH THE
PERSONS WHO PREPARED THEM. IF BUYER FAILS TO DO SO, BUYER IS ACTING AGAINST THE ADVICE OF
BROKER.**

© 2024, California Association of REALTORS®, Inc.

AVID REVISED 6/24 (PAGE 1 OF 3)

Buyer's Initials

AR



AGENT VISUAL INSPECTION DISCLOSURE (AVID PAGE 1 OF 3)

Legacy Properties, 4149 Cedar Ctr Angels Camp CA 95212
Sara Casper

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201

Phone: 209.994.9666

Fax:

www.lwof.com

695 Feather Dr

Authentisign ID: E07C5958-2690-F111-B337-000D3A1FE58D

If this Property is a duplex, triplex, or fourplex, or otherwise has additional dwelling units this AVID is for unit # _____.

THE UNDERSIGNED, BASED ON A REASONABLY COMPETENT AND DILIGENT VISUAL INSPECTION OF THE REASONABLY AND NORMALLY ACCESSIBLE AREAS OF THE PROPERTY, STATES THE FOLLOWING:

Entry (excluding common areas): front steps not stained. skirting near front steps is broken. screen door has damage and scrapes floor when open. porch light is not fastened to wall. missing doorbell button.

Living Room: tape patch where chimney was.

Dining Room: missing lower window pane from large picture window. , staining on the ceiling near back wall. Blue paint on wall near kitchen entry. damage to wall on wall to the right of the entry to the kitchen.

Kitchen: refrigerator leans back. some laminate peeling on counters. tile around stove counter has damage.

Other Room: _____

Hall/Stairs (excluding common areas): _____

Bedroom # 1 : (small bed in main part of house) damage to bathroom door.

Bedroom # 2 : large bed in main part of house - missing outlet cover on front wall. open circuit panel in closet shared with bathroom. damage to wall between closet and back window.

Bedroom # 3 : cracked window on back wall. window from kitchen opens to this room.

Bedroom # _____:

Bath # 1 : shared bath in front of house- missing light cover.

Bath # 2 : ensuite bath - damage to wall near tub. shower doors are in the tub, not installed. window looks into bathroom in added portion on rear of house.

Bath # 3 : half bath in rear of house. window leads to ensuite bath in bedroom 2

Bath # _____:

AVID REVISED 6/24 (PAGE 2 OF 3)

Buyer's Initials

AR



AGENT VISUAL INSPECTION DISCLOSURE (AVID PAGE 2 OF 3)

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

695 Feather Dr

If this Property is a duplex, triplex, or fourplex, or otherwise has additional dwelling units this AVID is for unit # _____.

Other: Room outside of kitchen leading to back door. damage to the ceiling tiles. patch on wall going to rear bedroom.

Other: there is an outbuilding - purpose unknown. siding shows damage.

Other: _____

☐ See Addendum for additional rooms/structures: _____

Garage/Parking (excluding common areas): carport is missing shingles on some of the roof. some of roof decking is damaged.

Exterior Building and Yard - Front/Sides/Back: damage to skirting in several places. some skirting missing. rear steps bare wood.

Other Observed or Known Conditions Not Specified Above: Home is an older manufactured home that has additions added. exterior siding has some damage. some debris near home in field. abandoned truck parked near property.

This disclosure is based on a reasonably competent and diligent visual inspection of reasonably and normally accessible areas of the Property on the date specified above.

Real Estate Broker (Name of Firm that performed the inspection): Legacy Properties

Inspection Performed By (Name of individual agent or broker): James Beyersdorf

Inspection Date/Time: 08/03/2026 3:00pm Weather conditions: _____

Other persons present: _____

By James Beyersdorf Date 08/04/26
(Signature of Associate Licensee or Broker who performed the inspection)

Reminder: Not all defects are observable by a real estate licensee conducting an inspection. The inspection does not include testing of any system or component. Real Estate Licensees are not home inspectors or contractors. BUYER SHOULD OBTAIN ADVICE ABOUT AND INSPECTIONS OF THE PROPERTY FROM OTHER APPROPRIATE PROFESSIONALS. IF BUYER FAILS TO DO SO, BUYER IS ACTING AGAINST THE ADVICE OF BROKER.

I/we acknowledge that I/we have read, understand and received a copy of this disclosure.

Buyer Ashley Robinson Ashley Robinson Date 08/04/2026

Buyer _____ Date _____

I/we acknowledge that I/we have received a copy of this disclosure.

(The initials below and Broker signature are not required but can be used as evidence that the initialing or signing party has received the completed form.)

Seller CJ

Real Estate Broker (that did NOT fill out this AVID) Bradley and Santos Realty

By Dee Bradley Date 8-5-26
(Associate Licensee or Broker Signature)

© 2024, California Association of REALTORS®, Inc. United States copyright law (Title 17 U.S. Code) forbids the unauthorized distribution, display and reproduction of this form, or any portion thereof, by photocopy machine or any other means, including facsimile or computerized formats. THIS FORM HAS BEEN APPROVED BY THE CALIFORNIA ASSOCIATION OF REALTORS®, NO REPRESENTATION IS MADE AS TO THE LEGAL VALIDITY OR ACCURACY OF ANY PROVISION IN ANY SPECIFIC TRANSACTION. A REAL ESTATE BROKER IS THE PERSON QUALIFIED TO ADVISE ON REAL ESTATE TRANSACTIONS. IF YOU DESIRE LEGAL OR TAX ADVICE, CONSULT AN APPROPRIATE PROFESSIONAL. This form is made available to real estate professionals through an agreement with or purchase from the California Association of REALTORS®.

Published and Distributed by: REAL ESTATE BUSINESS SERVICES, LLC, a subsidiary of the California Association of REALTORS®

AVID REVISED 6/24 (PAGE 3 OF 3)

AGENT VISUAL INSPECTION DISCLOSURE (AVID PAGE 3 OF 3)

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwtr.com

695 Feather Dr

