

Well Inspection

June 28, 2026

On 6/24/2026, Sierra Water Well Service conducted a well inspection at 433 Highway 4, Murphy's Ca.

Well pump produced an average of 33 GPM, over a two-hour time frame.

The system consists of a 1hp pump set at a depth of 100'.

The pump and motor were replaced early June. There are a 40-60 pressure switch and a 119-gallon pressure tank all in good working condition.

Overall, well system is in great working order.

Signed

Rob Dunn, owner Sierra Water Well Service