

The Walk-Around Vehicle Inspection Report



☐ Customer's personal settings returned (steering wheel, mirrors, seat position, infotainment and automatic headlights)	KMHD84LF0JU580583	MOUNTAIN HYUNDAI	
☐ Recalls checked and completed if required	NIV	Dealership	
☐ Reset all applicable service reminders	LUIS NAVARRO	RY16305	66950
☐ Customer declined Manufacturer's required maintenance	Customer Name	R.O.#	Odometer
	ELANTRA 2018		2025-07-29
	Model Year Service #	License Plate Number	Date

The Hyundai Walk-Around Vehicle Inspection is a series of thorough vehicle system checks and visual examinations performed by our Service Advisors and factory-trained Technicians. The focus of this inspection is to ensure that your Hyundai vehicle continues to perform at an optimal level.

In the event that additional service is recommended on a listed item, your Service Advisor will be happy to speak with you about service options.

Checked & Okay At This Time	May Require Further Attention	Requires Immediate Attention
Visually Check Following Components ☒ Windshield ☒ Wiper Blades, Washer Spray ☒ Horn ☒ Interior lights ☒ Exterior Lights	Body Condition Check 	

Check Tires & Tread Depth (Requirements may vary based on Province) All Season Tires ☒ 7/32 or greater ☒ 4/32 to 6/32 ☒ 3/32 or less Winter Tires ☒ 9/32 or greater ☒ 6/32 or greater ☒ 5/32 or less <table border="0"> <tr> <td>Measurements</td> <td>Wear pattern</td> <td colspan="2">Wear pattern/damage</td> </tr> <tr> <td>LF ☒ ☒ ☒ 7 /32</td> <td></td> <td></td> <td></td> </tr> <tr> <td>LR ☒ ☒ ☒ 7 /32</td> <td></td> <td>Camber Wear</td> <td>Toe Wear</td> </tr> <tr> <td>RF ☒ ☒ ☒ 7 /32</td> <td></td> <td></td> <td></td> </tr> <tr> <td>RR ☒ ☒ ☒ 7 /32</td> <td></td> <td>Cupping</td> <td>Cutting</td> </tr> </table> Requires: Rotation ☐ Alignment ☐ Replacement ☐ Tire pressure set to factory recommendations (PSI): Front: 35 Back: 35	Measurements	Wear pattern	Wear pattern/damage		LF ☒ ☒ ☒ 7 /32				LR ☒ ☒ ☒ 7 /32		Camber Wear	Toe Wear	RF ☒ ☒ ☒ 7 /32				RR ☒ ☒ ☒ 7 /32		Cupping	Cutting	Check Brakes Brake inspection ☐ Brake service ☐ ☒ OVER 5 mm (DISC) or OVER 2 mm (DRUM) ☒ 3 to 5 mm (DISC) or 1.01 to 2 mm (DRUM) ☒ LESS THAN 3 mm (DISC) or 1 mm or LESS (DRUM) LF ☒ ☒ ☒ 7 mm RF ☒ ☒ ☒ 7 mm LR ☒ ☒ ☒ 6 mm RR ☒ ☒ ☒ 6 mm
Measurements	Wear pattern	Wear pattern/damage																			
LF ☒ ☒ ☒ 7 /32																					
LR ☒ ☒ ☒ 7 /32		Camber Wear	Toe Wear																		
RF ☒ ☒ ☒ 7 /32																					
RR ☒ ☒ ☒ 7 /32		Cupping	Cutting																		
Check Battery ☒ Battery Voltage (12V) Cold Cranking Amps ☒ Battery Cables & Connections Factory Specs: 640 Actual: 60	Check & Fill <table border="0"> <tr> <td>Engine Oil</td> <td>OK ☒ FILLED ☐</td> <td>Brake</td> <td>OK ☒ FILLED ☐</td> </tr> <tr> <td>Coolant</td> <td>OK ☒ FILLED ☐</td> <td>Transmission</td> <td>OK ☒ FILLED ☐</td> </tr> <tr> <td>Window Washer</td> <td>OK ☒ FILLED ☐</td> <td>Clutch (If required)</td> <td>OK ☒ FILLED ☐</td> </tr> </table>	Engine Oil	OK ☒ FILLED ☐	Brake	OK ☒ FILLED ☐	Coolant	OK ☒ FILLED ☐	Transmission	OK ☒ FILLED ☐	Window Washer	OK ☒ FILLED ☐	Clutch (If required)	OK ☒ FILLED ☐								
Engine Oil	OK ☒ FILLED ☐	Brake	OK ☒ FILLED ☐																		
Coolant	OK ☒ FILLED ☐	Transmission	OK ☒ FILLED ☐																		
Window Washer	OK ☒ FILLED ☐	Clutch (If required)	OK ☒ FILLED ☐																		
Check Following Systems & Components * <table border="0"> <tr> <td>Service 1</td> <td>Service 2</td> <td>Service 3</td> </tr> <tr> <td> ☒ Engine Oil & Filter ☒ Driveshafts & Boots ☒ Gear Box, Linkages & Boots/Ball Joints ☒ Vacuum Hose ☒ All Latches, Hinges & Locks ☒ Brake System: Lines, Hoses & Parking Brake ☒ Exhaust System & Muffler </td> <td> ☒ Cooling System Hoses & Connections ☒ Suspension Mounting Bolts ☒ Parking Brake & Clutch/Brake Pedal Free Play ☒ Air Intake Hose ☒ AC Heating Function ☒ AC Compressor Function ☒ Cabin Air Filter (Replace) ☒ Engine Air Filter (Inspect) </td> <td> ☒ Fuel Filler Cap ☒ Fuel Tank ☒ Fuel Lines, Hoses & Connections ☒ Vapor Hose ☒ Canister ☒ Engine Air Filter (Replace) </td> </tr> </table>	Service 1	Service 2	Service 3	☒ Engine Oil & Filter ☒ Driveshafts & Boots ☒ Gear Box, Linkages & Boots/Ball Joints ☒ Vacuum Hose ☒ All Latches, Hinges & Locks ☒ Brake System: Lines, Hoses & Parking Brake ☒ Exhaust System & Muffler	☒ Cooling System Hoses & Connections ☒ Suspension Mounting Bolts ☒ Parking Brake & Clutch/Brake Pedal Free Play ☒ Air Intake Hose ☒ AC Heating Function ☒ AC Compressor Function ☒ Cabin Air Filter (Replace) ☒ Engine Air Filter (Inspect)	☒ Fuel Filler Cap ☒ Fuel Tank ☒ Fuel Lines, Hoses & Connections ☒ Vapor Hose ☒ Canister ☒ Engine Air Filter (Replace)	Safety Floor Liners Installed Correctly Yes ☐ No ☐ Appropriate Tires Equipped Yes ☐ No ☐														
Service 1	Service 2	Service 3																			
☒ Engine Oil & Filter ☒ Driveshafts & Boots ☒ Gear Box, Linkages & Boots/Ball Joints ☒ Vacuum Hose ☒ All Latches, Hinges & Locks ☒ Brake System: Lines, Hoses & Parking Brake ☒ Exhaust System & Muffler	☒ Cooling System Hoses & Connections ☒ Suspension Mounting Bolts ☒ Parking Brake & Clutch/Brake Pedal Free Play ☒ Air Intake Hose ☒ AC Heating Function ☒ AC Compressor Function ☒ Cabin Air Filter (Replace) ☒ Engine Air Filter (Inspect)	☒ Fuel Filler Cap ☒ Fuel Tank ☒ Fuel Lines, Hoses & Connections ☒ Vapor Hose ☒ Canister ☒ Engine Air Filter (Replace)																			

Additional Recommendations All Weather Genuine Floor Liners Installed Yes ☐ No ☐ Fuel Injector Cleaner Added Yes ☐ No ☐ Seasonal Tires Changed Yes ☐ No ☐ Sealant (from TMK) within expiration date Yes ☐ No ☐	Comments
---	---------------------

* Please note that service items may vary based on frequency, model as well as model year. Please consult the Maintenance Section of your Owner's Manual for more information.

Next Service Visit Date: 2025-07-29 Time: KM: Factory recommended service: ☐ 1 ☐ 2 ☐ 3 At your guaranteed price of: \$	This Inspection Was Completed By Your Hyundai Service Team Service Advisor SHWETA GANGADEEN Technician WALTER DEPAZ Customer Signature
--	--