



Field Visit & Data Collection Sites – Panauti Region

Concrete Bridges

- **Punyamati River Bridge (Main Entry)**

Coordinates: 27.5781° N, 85.5147° E

Crack Potential: Expansion joints, edges

Safety Note: Normal

- **Triveni Confluence Bridge**

Coordinates: 27.5759° N, 85.5166° E

Crack Potential: Sides, lower sections

Safety Note: Normal

- **Khware Footbridge**

Coordinates: 27.5772° N, 85.5172° E

Crack Potential: Surface wear, corners

Safety Note: Normal

- **Balthali Route Bridge**

Coordinates: 27.5735° N, 85.5250° E

Crack Potential: Slab cracks

Safety Note: Normal

- **Dhobikhola Culvert Bridge**

Coordinates: 27.5719° N, 85.5154° E

Crack Potential: Pavement joints

Safety Note: Normal

Old Buildings

- **Panauti Durbar Square Structures**

Coordinates: 27.5755° N, 85.5168° E

Crack Potential: Wall cracks, plaster peeling

Safety Note: Caution in weak zones

- **Old Municipal Building**

Coordinates: 27.5747° N, 85.5140° E

Crack Potential: Exterior wall cracks

Safety Note: Normal

School/College Campuses

- **Panauti Higher Secondary School**

Coordinates: 27.5783° N, 85.5189° E

Crack Potential: Wall/floor cracks

Safety Note: Need permission

- **Kathmandu University (Old Blocks)**

Coordinates: 27.6195° N, 85.5393° E

Crack Potential: Beam/wall cracks

Safety Note: Need permission

Construction Sites

- **Panauti Ring Road Drainage Work**

Coordinates: 27.5742° N, 85.5202° E

Crack Potential: Pavement & early-stage cracks

Safety Note: Safety gear needed

- **Bridge Work - Kushadevi Road**

Coordinates: 27.5715° N, 85.5281° E

Crack Potential: Slabs, foundation cracks

Safety Note: Safety gear needed

Summary Table

#	Location Name	Type	Coordinates	Crack Potential	Safety Note
1	Punyamati River Bridge	Concrete Bridge	27.5781° N, 85.5147° E	Expansion joints, edges	Normal
2	Triveni Confluence Bridge	Concrete Bridge	27.5759° N, 85.5166° E	Sides, lower sections	Normal
3	Khware Footbridge	Concrete Footbridge	27.5772° N, 85.5172° E	Surface wear, corners	Normal
4	Balthali Route Bridge	Concrete Bridge	27.5735° N, 85.5250° E	Slab cracks	Normal
5	Dhobikhola Culvert Bridge	Concrete Culvert	27.5719° N, 85.5154° E	Pavement joints	Normal
6	Panauti Durbar Square Structures	Old Buildings	27.5755° N, 85.5168° E	Wall cracks, plaster peeling	Caution in weak zones
7	Old Municipal Building	Old Building	27.5747° N, 85.5140° E	Exterior wall cracks	Normal
8	Panauti Higher Secondary School	School Campus	27.5783° N, 85.5189° E	Wall/floor cracks	Need permission
9	Kathmandu University (Old Blocks)	College Campus	27.6195° N, 85.5393° E	Beam/wall cracks	Need permission
10	Panauti Ring Road Drainage Work	Construction Site	27.5742° N, 85.5202° E	Pavement & early-stage cracks	Safety gear needed
11	Bridge Work - Kushadevi Road	Construction Site	27.5715° N, 85.5281° E	Slabs, foundation cracks	Safety gear needed

Additional Notes

- Obtain permission from school authorities or site managers before visiting campuses or restricted areas.
- Use appropriate safety gear (helmet, boots, reflective vest) at construction sites.
- Carry measuring tools, camera, and field notebook for systematic documentation.
- For navigation, you can use these coordinates in any GPS or mapping app.