

FIELD INSPECTION FORM

Inspection Ref:	INSP-2026-002
Inspection Date:	2026-08-16
Site Location:	Substation 4B
Inspector Name:	Alice Smith
Asset Ref:	AST-44102
Inspection Status:	NEEDS_ATTENTION
Observation Finding:	Minor coolant leak on valve 3.
Action Required:	Replace gasket seals.
Followup Date:	2026-09-01
Form Completeness:	COMPLETE