

FIELD INSPECTION FORM

Inspection Ref: INSP-2026-003

Inspection Date: 2026-08-18

Site Location: Warehouse Depot 12

Inspector Name: Robert Vance

Asset Ref: AST-88192

Inspection Status: FAIL

Observation Finding: Heavy corrosion on structural beam.

Action Required: Immediate safety audit & beam replacement

Followup Date: 2026-08-25

Form Completeness: COMPLETE