

FIELD INSPECTION FORM

Inspection Ref:	INSP-2026-004
Inspection Date:	2026-08-20
Site Location:	Solar Array Field 7
Inspector Name:	Maria Garcia
Asset Ref:	AST-33019
Inspection Status:	PASS
Observation Finding:	Dust buildup on panel surface.
Action Required:	Schedule monthly cleaning.
Followup Date:	2026-09-20
Form Completeness:	COMPLETE