NIHVA
NIHVA TECHNOLOGIES PVT. LTD.

PRE-DISPATCH INSPECTION REPORT

NIHVA - PRJ - F - 03

Client Name : - AMULYA TRADERS			Report No : -
Project Name :- AMULYA TRADERS	Location :- Pune		Date :-
Product Name :- NIHVA MAKE HIGH SPEED DOOR	Size:- 3000X4000	Qty :- 01 Nos	Work Order No.: - WO/20-21-007

Sr.No.	Part Name	Drawing No.	Specification	Observation	Remarks
1	Clear opening width	NIHVA/20-21/0031	3000 mm	3000 mm	OK
2	Clear opening height		4000 mm	4000 mm	OK
3	RAL Shade		RAL 9006	Found same shade	OK
4	Aluminium Panel		19 mm	19 mm thk	OK
5	LH Guide		check for finish	found ok	OK
6	RH Guide		check for finish	found ok	OK
7	Hood cover		check for finish	found ok	OK
8	Control panel		check for wiring & defect	no any defect , all wiring ok	OK
9	Hood cover		check for defect & finish	found ok	OK
10	Photocell		check for defect & operation	found ok	OK
11	Safety Edge		check for defect & operation	found ok	OK
12	Radar Sensor		check for defect & operation	found ok	OK
13	Crank Handle		check for defect & operation	found ok	OK
14	Door operation		check for defect & operation	found ok	OK
15	Any noise during operation		check for defect & operation	No any noise observed	OK
16	Remove burrs & corner		check for burrs	found ok	OK

Inspected By	Checked By	Approved By
Siddheshwar M Shelake	Siddheshwar M Shelake	Amit Kurhade